

CC 4, ECU 180 11737, Uka39

LKK:
IDAC:

Surveyor:

M. A. Lewis

DOI:

ASSIGNMENT

12/6/18

Date / Time:

27/6/18

Registered in Meritmen:

Pre-assign / CCU / FTE

SLT 3655T

PM181001134-JG



Insured Vehicle No.:

Claim No.:

Name of Insured:

CHIA AN CHEN

Policy No.:

Insured Tel No.:

HP:

Make / Model:

7-Axis

Excess Sec II :S\$

D.O.A.:

29-4-18

Place of Accident:

Bendemeer Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

SEBASTIAN KOH CHAN YONG

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

91091519 199378073 (V/L YES / NO)

Insured Liability:

%

Final ? Yes / No

FBM 2474K



INSRS:

WSP:

Tel:

Liability:

RMKS:

Erofin



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

5/7/19

FBM 2474K-X, SLT 3655T-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

12/7/19

After call ltr to OI:

Vivian

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

3/7/19

Sent By:

Hwa

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

4/7/19

Confirm with:

LEE LEE

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

2200.00

Loss of Rental (LOR):

S\$

-

(

days)

Loss of Use (LOU):

S\$

140.00

(520 x 7

days)

Loss of Income (LOI):

S\$

-

(5

x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

2340.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

2340.00

Name 1:

Erofin Motor Trading Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
6/9/19

OK

6/9

OK

ASSIGNMENT

From: _____ Date: _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: F3M2474Kat Workshop m/s Enofu

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

ID/C Accident Rpt: _____ Consistent?: Yes or No

ID/C PR Seen: ✓ Consistent?: Yes or NoEst. Repairs: 5 days Res.: Yes or NoLump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: F3M2474K Yr Regn: 9 / 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Yamaha / BR125 C.C. 124Colour: Black A/C: Insured / Std / NI / NASp. Reading: 44313 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LBPRE101000058580

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 2.75-18R: 90-50-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ChaoYang

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 29/4/18D.O.I. 27/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rtr. 115 Body
The U/C / Chassis frame / Body Structure affected due to collision.Date / Time Action / Instruction LIA 55754/9/19. Confirm LS \$2200.00 with 5 working days

(Ord - \$ 3106.50

59%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: DM18HO01134-JG
Our ref: CC4/EQ118011737/Uua3

Date: 03.07.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

FBM 2474K

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.06.2018 at the premises of M/s Erofia Motor Trading Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,306.50
Revised Estimate Amount	: S\$	2,785.30
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	2,785.30
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Front portion & N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : S.H. Cycle Pte Ltd

Accident Date : 29-Apr-18

Vehicle No : FBM 2474 K

Vehicle Model : Yamaha YBR 125

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 320 65.00 —
1	Top cowling	\$ Cne 105.00 —
1	Windshield	\$ Cne 55.00 —
1	Headlamp	\$ SCR 105.00 —
2	Fork inner tubes	\$ LR 270.00 x
2	Fork outer tubes	\$ n 290.00 x
1	Fork under bracket	\$ n 145.00 x
1	Front brake disc	\$ n 155.00 x
1	Front rim shaft	\$ n 45.00 x
1	Front sport rim	\$ n 320.00 —
2	Front signals	\$ SCR 116.00 —
1	Handle bar	\$ SCR 95.00 —
1	Handle bar end	\$ NF 32.00 x
1	Handle bar grip (1 set)	\$ n 50.00 —
1	Brake lever	\$ Cne 30.00 —
1	Clutch lever	\$ SCR 30.00 —
2	Side mirrors	\$ Cne 100.00 —
1	Meter assy	\$ Cne 450.00 —
1	Side panel -L/H	\$ Cne 55.00 —
1	Front footrest bracket	\$ SCR 45.00 —
2	Front footrest rubbers	\$ n 56.00 —
1	Brake pedal	\$ n 48.00 x
1	Gear pedal	\$ n 48.00 x
1	Side board -L/H	\$ n 45.00 x
1	Rear footrest	\$ Cne 35.00 —
1	Rear footrest bracket	\$ n 80.00 x
1	Rear signal	\$ n 65.00 x
1	Exhaust pipe	\$ n 485.00 x
1	Exhaust protector	\$ Cne 35.00 —
1	Side stand	\$ n 75.00 x
1	Main stand	\$ n 90.00 x
1	Rear fender	\$ n 75.00 x
		\$ 3,695.00
	Less 10%	\$ 369.50
		\$ 3,325.50

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : S.H. Cycle Pte Ltd

Accident Date : 29-Apr-18

Vehicle No : FBM 2474 K

Vehicle Model : Yamaha YBR 125

Estimated Repair Costs

<u>Special Nett Items</u>		
1	Number plate (1 set)	\$ <i>mu</i> 28.00 <i>10</i>
1	Fork oil	\$ <i>mu</i> 15.00 <i>-</i>
1	Fork oil seal	\$ <i>mu</i> 28.00 <i>-</i>
1	Steering cone (1 set)	\$ <i>mu</i> 85.00 <i>-</i>
1	Rear box (Special Made)	\$ <i>cu</i> 750.00 <i>500</i>
1	ERP IU	\$ <i>cu</i> 170.00 <i>165</i>
		\$ 1,076.00

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service.	\$ 45.00 <i>30</i>
2	To check wiring and reset headlamp focusing.	\$ <i>na</i> 80.00 <i>X</i>
3	To provide labour.	\$ 380.00 <i>300</i>
4	To repair body frame.	\$ <i>11</i> 400.00 <i>X</i>
		\$ 905.00

Grand Total

\$ 5,306.50

Dollars: Five Thousand Three Hundred Six And Fifty Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after survey printing
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

2815.3
2252.24

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	FBM2474K
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Chassis No.:	LBPREF101000058580
Propellant:	Petrol
Engine No.:	E3F5E043581
Engine Capacity:	124 cc
Maximum Power Output:	-
Maximum Laden Weight:	320 kg
Unladen Weight:	114 kg
Year Of Manufacture:	2017
Original Registration Date:	06 Sep 2017
Lifespan Expiry Date:	-
COE Category:	D - Motorcycle
Quota Premium:	\$6,001.00
COE Expiry Date:	05 Sep 2027
Road Tax Expiry Date:	05 Sep 2018
Inspection Due Date:	05 Sep 2020
Intended Transfer Date:	19 Jun 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 05 Sep 2018. You may renew the road tax from 06 Jun 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 05 Sep 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 06 Sep 2018 to 05 Mar 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	32.00	-	32.00
Total Amount Payable:			57.00

Amount Payable (From 06 Sep 2018 to 05 Sep 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	64.00	-	64.00
Total Amount Payable:			89.00

You may print this page for reference.

OK

Print

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	0420C

Vehicle Details

Vehicle No.:	FBM2474K
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jun 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	E3F5E043581
Chassis No.:	LBPRI101000058580
Maximum Power Output:	-
Open Market Value:	\$1,908.00
Original Registration Date:	06 Sep 2017
First Registration Date:	06 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$287.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	05 Sep 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,001.00
COE Rebate Amount:	\$5,515.00
Total Rebate Amount:	\$5,515.00

The information contained herein is correct as at 27 Jun 2018

OK

Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Wednesday, 27 June, 2018 11:31 AM
To: assignments
Subject: FW: Request pre-repair inspection for accident involving SLP3655T(EQ) and FBM2474K on 29 April 2018 (DM18HO01134-JG)
Attachments: FBM2474K - DOC.PDF

2.05pm @ 27/6/2018
person @ lky
vehicle in
sup @ Marus

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]
Sent: Wednesday, 27 June 2018 11:23 AM
To: erofia@singnet.com.sg
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Request pre-repair inspection for accident involving SLP3655T(EQ) and FBM2474K on 29 April 2018 (DM18HO01134-JG)

Without Prejudice

Dear Lee Lee

We will arrange accordingly.

Dear LKK

Kindly assist on this PRS and direct settlement.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify ti

From: Erofia Motor - LeeLee Tan [mailto:erofia@singnet.com.sg]

Sent: Tuesday, June 26, 2018 6:37 PM

To: Joel Goh

Subject: RE: Request pre-repair inspection for accident involving SLP3655T(EQ) and FBM2474K on 29 April 2018 (DM18HO01134-JG)

Dear Sir

KINDLY ARRANGE LKK AUTO CONSULTANTS PTE LTD

THANK YOU

REGARDS

LEELEE TAN

EROFIA MOTOR TRADING PTE LTD

TEL: 67527740

FAX: 67528669

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]

Sent: 26 June, 2018 2:35 PM

To: erofia@singnet.com.sg

Subject: RE: Request pre-repair inspection for accident involving SLP3655T(EQ) and FBM2474K on 29 April 2018 (DM18HO01134-JG)

Without Prejudice

Dear LeeLee

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155 Contact person : Joey/Joseh	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon Kho
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108

Contact Person: Ricky Teng	
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t/

From: Erofia Motor - LeeLee Tan [mailto:erofia@singnet.com.sg]

Sent: Tuesday, June 26, 2018 2:13 PM

To: Joel Goh

Cc: EQI PRS

Subject: Request pre-repair inspection for accident involving SLP3655T and FBM2474K on 29 April 2018

Dear Sir

With reference to the above mentioned, attached necessary documents for your arrangement of pre-repair inspection for

Motorcycle No: FBM2474K

Workshop:
Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62
AutoBay @ Kaki Bukit
Singapore 417883

Tel: 67527740

Thank you

Regards
LeeLee Tan
Erofia Motor Trading Pte Ltd
Tel: 67527740
Fax: 67528669

Mei Kwan (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Tuesday, 3 July, 2018 6:05 PM
To: 'Joel Goh'
Cc: Thin Thin (LKKAuto); Vivian Lau (LKKAuto); Admin A
Subject: RE: Request pre-repair inspection for accident involving SLP3655T(EQ) and FBM2474K on 29 April 2018 (DM18HO01134-JG)
Attachments: TP ESTIMATE - MARKED.pdf; LKK SURVEY PHOTO.pdf; Preliminary Advice.pdf
Categories: HMK

WITHOUT PREJUDICE

Your ref: DM18HO01134-JG
LKK ref: CC4/EQ18011737/Uua3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: FBM 2474K

We have not authorized repairs.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Please take note that the case handler in-charge is Thin Thin and she can be contacted at DID 6841 2360.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 27 June, 2018 2:08 PM
To: 'Joel Goh' <joel.goh@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Request pre-repair inspection for accident involving SLP3655T(EQ) and FBM2474K on 29 April 2018 (DM18HO01134-JG)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

TEL: 67527740
FAX: 67528669

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]

Sent: 26 June, 2018 2:35 PM

To: erofia@singnet.com.sg

Subject: RE: Request pre-repair inspection for accident involving SLP3655T(EQ) and FBM2474K on 29 April 2018 (DM18HO01134-JG)

Without Prejudice

Dear LeeLee

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please **revert within 2 working days** if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155 Contact person : Joey/Joseh	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon Kho
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62

AutoBay @ Kaki Bukit

Singapore 417883

Tel: 67527740 Fax: 67528669

E-Mail: erofia@singnet.com.sg

Co Registration No: 201202259N

Our Ref: EMT1348/18/lt/FBM2474K

WITHOUT PREJUDICE

Your reference: To Be Advised

BY HAND TO LKK

31 July 2018

EQ Insurance Co Ltd
5 Maxwell Road #17-00
Tower Block MND Building
Singapore 069110

Attn: Officer-In-Charge (Motor Claims Department)

Dear Sir/Madam

Re: ACCIDENT INVOLVING SLT3655T AND FBM2474K ON 29 APRIL 2018

We are instructed by our client S H Cycle Pte Ltd to claim damages against your insured SLT3655T in connection with a road traffic accident on 29 April 2018 at about 15.00hours along Woodsville Underpass towards PIE with our client's motorcycle registration number FBM2474K.

As a result of the accident, our client's motorcycle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1.	Cost of Repair as per surveyor's recommendation	S\$ 2,200.00
2.	Loss of Use (7 days X S\$20.00/day)Repair & PR	S\$ 140.00
	Total to Claim	<u>S\$ 2,340.00</u>

Attached final repair bill for your early process of our claim

Thank you

Yours faithfully
Erofia Motor Trading Pte Ltd

Teo Hwa Heng





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/EQ118011737/Uwa3

17 JULY 2019

CHUA AI CHIEN
BLK 340A SEMBAWANG CLOSE
#02-85
SINGAPORE 751340

Dear Sir/Madam,

**ACCIDENT INVOLVING SLT 3655T AND FBM 2474K ALONG/AT
BENDEEMEER ROAD ON 29/04/2018**

We refer to the above accident where we are acting for EQ Insurance Company Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is not in your driver's favour as your vehicle changed lane and collided with third party. Under Motor Accident Guide, vehicles should keep in the proper lane and change lane only when it is safe. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Claims

Tel : 6841 8625

Fax: 6741 4108

Email : vivianlau@lkkauto.com

c.c. EQ Insurance Company Ltd
(Motor Claims Dept)

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67527740 Fax: 67528669
Co Registration No: 201202259N

AUTHORISATION TO ACT

I/We, S.H. Cycle pte ltd ("the third party claimant") of
235 Rangoon Road S218466 (address), owner of
FBM 2474K (vehicle no.) hereby authorize Erofia Motor Trading Pte Ltd ("the
workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of
use ("claim") for my vehicle no. FBM 2474K That was damaged pursuant to the
accident which occurred on 29-04-2018 (date)
Along woodsville underpass towards PIE (location) involving vehicle no/s
SLT 3655 T ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deemed fit and the workshop is further authorized to receive payment further to settlement of my
claim with payment cheque/s being made in favour of the workshop - **EROFIA MOTOR
TRADING PTE LTD**

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the
other vehicle/s is concerned.

Dated this 14 (day) of 05 (month) 20 18 (year)



Signed by "the third party claimant"
(With company stamp if applicable)



Signed by "the workshop"
(With company stamp)

Provide always that this discharge of my
claim for damages relating to the damage to
my vehicle shall not prejudice or affect or
preclude me from making a further claim for
general and special damages for my personal
injuries sustained in the same accident.

EROFIA MOTOR TRADING PTE LTD (201202259N)

1 Kaki Bukit Ave 6 #02-62
Singapore 417883
Tel: 67527740 Fax: 67528669
H/P: 90696165 (Mr Teo)

INVOICE

Number	Date	Page
093/18 (FBM2474K)	31-Jul-18	1

VEHICLE NO: FBM2474K
MAKE/MODEL: YAMAHA YZFR25
NAME: S H CYCLE PTE LTD
ADDRESS: 235 RANGOON ROAD
SINGAPORE 218466

ACCIDENT INVOLVING SLT3655T AND FBM2474K ON 29 APRIL 2018

FINAL REPAIR BILL AS PER SURVEYOR'S RECOMMENDATION

S\$ 2,200.00

SUB-TOTAL: S\$ 2,200.00

SINGAPORE DOLLARS: TWO THOUSAND AND TWO HUNDRED ONLY

TOTAL : S\$ 2,200.00

EROFIA MOTOR TRADING PTE LTD



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 18/09/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLT 3655T (Insd Veh)	Your Ref. No. : DM18HO01134-JG
	FBM 2474K (TP Veh)	Our Ref. No. : CC4/EQ18011737/Uwa3q2
Date of Accident	29/4/2018	

Liability	100%	
Final Repair Cost	: \$ 2,200.00	
Loss of Use	: \$ 140.00	7 days
Rental (If any)	: \$	days
Others:	: \$	
	: \$	
	2,340.00	
Final Settlement Sum	: \$ 2,340.00	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1	EROFIA MOTOR TRADING PTE LTD	: \$ 2,340.00
		: \$

JOANNE LEE


LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ18011737/Uwa3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 18-09-2019	
			Code : EQ1	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLT 3655T	Veh. Inspected	FBM 2474K	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM18HO01134-JG	Excess (\$)	0.00	
Assign From	JOEL GOH	Assign Date	27/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA YBR125	c.c	124	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	LBPRI101000058580	Colour	BLACK	
Odometer	44313	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	2.75-18	CHAO YANG	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90-90-18	CHAO YANG	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/04/2018	Inspection Date	27/06/2018	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 2474K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	BROKEN	65.00	65.00
1	TOP COWLING	CRACKED	105.00	105.00
1	WINDSHIELD	CRACKED	55.00	55.00
1	HEADLAMP	SCRATCHED	105.00	105.00
2	FORK OUTER TUBES	NOT NECESSARY	290.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	145.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	155.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	45.00	-
1	FRONT SPORT RIM	DENTED / BENT	320.00	320.00
2	FRONT SIGNALS	SCRATCHED	116.00	116.00
1	HANDLE BAR	BENT	95.00	95.00
1	HANDLE BAR END	NOT FITTED	32.00	-
1	SET HANDLE BAR GRIP	TORN	50.00	50.00
1	BRAKE LEVER	CRACKED	30.00	30.00
1	CLUTCH LEVER	SCRATCHED	30.00	30.00
2	SIDE MIRRORS	CUT	100.00	100.00
1	METER ASSY	CUT	450.00	450.00
1	SIDE PANEL -L/H	CRACKED	55.00	55.00
1	FRONT FOOTREST BRACKET	BENT	45.00	45.00
2	FRONT FOOTREST RUBBERS	TORN	56.00	56.00
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	48.00	-
1	GEAR PEDAL	NOT NECESSARY	48.00	-
1	SIDE BOARD -L/H	NOT NECESSARY	45.00	-
1	REAR FOOTREST	CUT	35.00	35.00
1	REAR FOOTREST BRACKET	NOT NECESSARY	80.00	-
1	REAR SIGNAL	NOT NECESSARY	65.00	-
1	EXHAUST PIPE	NOT NECESSARY	485.00	-
1	EXHAUST PROTECTOR	CUT	35.00	35.00
1	SIDE STAND	TO REPAIR SEE LABOUR	75.00	-

Report Ref No. CC4/EQI18011737/Uwa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MAIN STAND	TO REPAIR SEE LABOUR	90.00	-
1	REAR FENDER	TO REPAIR SEE LABOUR	75.00	-
	LESS 10% DISCOUNT		-342.50	-174.70
			3,082.50	1,572.30
2	FORK INNER TUBES (LOCAL REPAIR) (SN)	BENT	270.00	80.00
	LESS 10% DISCOUNT		-27.00	-
			243.00	80.00
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN)	NECESSARY	28.00	10.00
1	FORK OIL (SN)	NECESSARY	15.00	15.00
1	FORK OIL SEAL(SN)	NECESSARY	28.00	28.00
1	SET STEERING CONE (SN)	NECESSARY	85.00	85.00
1	REAR BOX (SPECIAL MADE) (SN)	CRACKED	750.00	500.00
1	ERP IU (SN)	CUT	170.00	165.00
			1,076.00	803.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		45.00	30.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR INCLUSIVE OF THE REPAIR OF BRAKE PEDAL, SIDE STAND, MAIN STAND AND REAR FENDER.		380.00	300.00
	TO REPAIR BODY FRAME.	NOT NECESSARY	400.00	-
			905.00	330.00
	GRAND TOTAL		5,306.50	2,785.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,200.00

Report Ref No. CC4/EQ118011737/Uwa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.