

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : S.H. Cycle Pte Ltd

Accident Date : 29-Apr-18

Vehicle No : FBM 2474 K

Vehicle Model : Yamaha YBR 125

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender	\$ 320 65.00 —
1	Top cowling	\$ cne 105.00 —
1	Windshield	\$ cne 55.00 —
1	Headlamp	\$ scd 105.00 —
2	Fork inner tubes <i>sent LR for S.N</i>	\$ LR 270.00 x
2	Fork outer tubes	\$ n 290.00 x
1	Fork under bracket	\$ n 145.00 x
1	Front brake disc	\$ n 155.00 x
1	Front rim shaft	\$ n 45.00 x
1	Front sport rim	\$ 20/ \$ 320.00 —
2	Front signals	\$ scd 116.00 —
1	Handle bar	\$ scd 95.00 —
1	Handle bar end	\$ NF 32.00 x
1	Handle bar grip (1 set)	\$ 70.00 50.00 —
1	Brake lever	\$ cne 30.00 —
1	Clutch lever	\$ scd 30.00 —
2	Side mirrors	\$ cny 100.00 —
1	Meter assy	\$ cny 450.00 —
1	Side panel -L/H	\$ cne 55.00 —
1	Front footrest bracket	\$ sent 45.00 —
2	Front footrest rubbers	\$ 70.00 56.00 —
1	Brake pedal	\$ n 48.00 x
1	Gear pedal	\$ n 48.00 x
1	Side board -L/H	\$ n 45.00 x
1	Rear footrest	\$ cny 35.00 —
1	Rear footrest bracket	\$ n 80.00 x
1	Rear signal	\$ n 65.00 x
1	Exhaust pipe	\$ n 485.00 x
1	Exhaust protector	\$ cny 35.00 —
1	Side stand	\$ n 75.00 x
1	Main stand	\$ n 90.00 x
1	Rear fender	\$ n 75.00 x
		\$ 3,695.00
Less 10%		\$ 369.50
		\$ 3,325.50

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : S.H. Cycle Pte Ltd

Accident Date : 29-Apr-18

Vehicle No : FBM 2474 K

Vehicle Model : Yamaha YBR 125

Estimated Repair Costs

<u>Special Nett Items</u>		
1	Number plate (1 set)	\$ <i>mu</i> 28.00 <i>10</i>
1	Fork oil	\$ <i>mu</i> 15.00 <i>-</i>
1	Fork oil seal	\$ <i>mu</i> 28.00 <i>-</i>
1	Steering cone (1 set)	\$ <i>mu</i> 85.00 <i>-</i>
1	Rear box (Special Made)	\$ <i>cu</i> 750.00 <i>500</i>
1	ERP IU	\$ <i>cu</i> 170.00 <i>165</i>
		\$ 1,076.00

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service.	\$ 45.00 <i>30</i>
2	To check wiring and reset headlamp focusing.	\$ <i>mu</i> 80.00 <i>X</i>
3	To provide labour.	\$ 380.00 <i>300</i>
4	To repair body frame.	\$ <i>11</i> 400.00 <i>X</i>
		\$ 905.00

Grand Total

\$ 5,306.50

Dollars: Five Thousand Three Hundred Six And Fifty Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

PAGE 2 OF 2

2815.3
2252.24