



## Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
5 Benoi Place Singapore 629926  
Tel: 6861 0908 Fax: 6515 2948

Date: 27.06.2018

AXA Insurance Singapore Pte Ltd  
8 Shenton Way #27-01/02  
AXA Tower  
Singapore 068811

Attn: Motor Claims Dept

### RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2266X TOYOTA AXIO HYBRID (2016)

#### To Supply

1 )	1pc	Rear bumper	\$	de✓	700.00
2 )	1set	Rear bumper clip	\$	nei✓	30.00
3 )	1pc	Rear bumper left side retainer	\$	nei✓	60.00
4 )	1pc	Rear boot lid	\$	bt✓	680.00
5 )	1pc	Rear boot lid "corolla" emblem	\$	nei✓	59.60
6 )	1pc	Rear boot lid "Axio" emblem	\$	nei✓	48.60
7 )	1pc	Rear boot lid "Hybrid Synergy Drive" emblem	\$	nei✓	61.70
8 )	1pc	Rear boot lid "Toyota" emblem	\$	nei✓	60.00
9 )	1pc	Rear boot lid weatherstrip	\$	int✓	120.00
10 )	1pc	Rear end panel	\$	Rp	380.00
11 )	1pc	Rear end panel top garnish	\$	de✓	180.00
12 )	1set	Rear end panel top garnish clip	\$	nei✓	30.00
13 )	1pc	Left tail lamp	\$	cut✓	450.00
14 )	1pc	Front bumper (No color)	\$	ora✓	563.60
15 )	1pc	Front bumper clip	\$	nei✓	30.00
16 )	1pc	Front bumper left side retainer	\$	nei✓	97.00
17 )	1pc	Front bumper sponge	\$	?	90.00
18 )	1pc	Front bumper reinforcement	\$	?	340.00
19 )	1pc	Left head lamp	\$	?	825.00

Sub total Parts	\$	4,805.50
Less: 25% discount	\$	1,201.37
	\$	3,604.13

To Supply S.Nett Parts

- |   |                      |
|---|----------------------|
| 1 ) 1pc "Dial -A-Cab" sticker             | \$ <i>net</i> 45.00  |
| 2 ) 1pc "Prime Taxi" sticker              | \$ <i>net</i> 55.00  |
| 3 ) 1pc Rear bumper advertisement sticker | \$ <i>net</i> 100.00 |

Sub total S.Nett Parts \$ 200.00

L/charges

- |  |                          |
|--|--------------------------|
| 1 ) Towing charges (Using King Dolley)   | \$ ✓ 80.00               |
| 2 ) To focus head lamp. Check wiring   | \$ ? 30.00               |
| 3 ) To remove front bumper, front bumper reinforcement, left head lamp, retainer & etc. Replace front bumper, front bumper reinforcement, left head lamp, retainer & the above parts. Align & adjust front bumper. | \$ <sup>200</sup> 300.00 |
| 4 ) To putty, respray painting front bumper. To polish   | \$ <sup>200</sup> 300.00 |
| 5 ) To tuff kote rear portion  | \$ <sup>30</sup> 50.00   |
| 6 ) To remove rear boot lid trim board, glass & mechanism parts  | \$ <sup>40</sup> 60.00   |
| 7 ) To remove rear bumper, knock / welding rear end panel & floor panel, replace rear boot lid, rear bumper, left tail lamp. Align rear boot lid & rear bumper   | \$ 800.00 <sup>700</sup> |
| 8 ) To putty, respray painting rear boot lid inner & outer, rear bumper, rear end panel & floor panel. To polish   | \$ <sup>700</sup> 900.00 |

Sub total L/charges \$ 2,520.00  
Estimated Grand Total \$ 6,324.13

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tanjil 97495749  
JWP  
27/6/10 @ 1015  
Lumpsum  
Review after repair.  
7 days  
sur @ lkkauto.com.