

CS. REC. BY:

REF: CS/EG118011742/TIVbnz Special Instruction

Surveyor Taufik ASSIGNMENT (Office)

From (Person): Yee Pei Li of EG1 Date/Time: 27062018 854am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 3938H Insured: YP 327CG

at Workshop in/s Seng Hong Kee Tel: 9699 6650

of Blk 4 Woodlands Rd 393F

Policy No: \_\_\_\_\_ Claim No: YP327CG/SL/pl

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 20062018  
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi 27062018 H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 27062018 2pm Person Contacted: An Bee Vehicle IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	<u>SLS 3938H - X</u>
	<u>YP 327CG - X</u>
<u>29/6/18</u>	<u>Email preli revised to Pei Li</u>
<u>9/7/18</u>	<u>LS \$ 5600 confirmed by email (Ref 2688.16, 327)</u>





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EG18011742/T1vb	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 27-06-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 3272G	Veh. Inspected	SLS 3938H
Policy No.		Coverage (\$)	0.00
Claim No.	YP3272G/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	27/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/06/2018	Inspection Date	28/06/2018
Survey held at	SENG HONG KEE CO BLOCK 4, 393F WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677976.		
5a. Remarks			



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: YP3272G/SL/pl  
Our ref: CS/EGH18011742/T1vb

Date: 29/6/2018

The Motor Claims Department  
M/s: ERGO INSURANCE PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.SLS 3938H**


We thank you for your instruction on 27/6/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28/6/2018 at the premises of M/s SENG HONG KEE CO and have the following to report:-

Workshop Estimate Amount	: S\$8,288.16
Revised Estimate Amount	: S\$7,447.84
"Check" Items Amount	: S\$107.68
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,  
MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automobile Assessor

## Catherine Chong (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Wednesday, 27 June, 2018 8:54 AM  
**To:** 'admin-d@lkkauto.com'  
**Cc:** ASSIGNMENTS@LKKAUTO.COM  
**Subject:** OI : YP3272G / TP : SLS3938H/LKK / DOA : 20/06/2018  
**Attachments:** SLS3938H - SAS.pdf; SLS3938H - ESTIMATE.pdf; SLS3938H - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SENG HONG KEE CO**,

ADDRESS : BLK 4 WOODLANDS ROAD 393-F  
YEW TEE INDUSTRIAL ESTATE  
SINGAPORE 677976

PERSON TO CONTACT : LEE AH BEE @ 9699 6650

ERGO OFFICER-IN-CHARGE : STEVE LIM

*Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.*

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are estimate and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

### Yee Pei Li

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Date: 26.06.2018  
 Our Reference: YP 3272G/SL/pl  
 Your Reference: SLS 3938H  
 To: SENG HONG KEE CO

Sent via Fax   
 or   
 Email  ahbeelee@hotmail.sg

**Pre-Repair Survey (PRS) Acknowledgement**

Vehicle For Inspection: SLS 3938H  
 Insured's Vehicle: YP 3272G  
 Date Of Accident: 20.06.2018

We acknowledge receipt of your request for PRS on: 25.06.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\* LKK Auto Consultants P/L

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- Your request for inspection does not have your client's GIA report, kindly forward a copy.
- We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- Our Insured's driver has not reported the accident to us todate.
- Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<b>FAX : 6829 9247</b>


**Assessor use only:**  
 Assignment Date: \_\_\_\_\_  
 Assignment Time: \_\_\_\_\_

**Workshop use only:**  
**Assessor attended workshop on:**  
 Date: \_\_\_\_\_  
 Time: \_\_\_\_\_  
 Inspector: \_\_\_\_\_

Remarks:

Vehicle not available at the appointed date and time.  
 Kindly acknowledge our Assessor presence for the above job.

**SENG HONG KEE CO**

  
 \_\_\_\_\_  
 Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 29 June 2018 12:31 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR  
**Subject:** RE: YP3272G / TP : SLS3938H/LKK / DOA : 20/06/2018  
**Attachments:** SLS 3938H PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLS 3938H  
Date of survey: 28/6/2018  
Number of days : 6 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 27 June 2018 2:03 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>  
**Cc:** assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: YP3272G / TP : SLS3938H/LKK / DOA : 20/06/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Wednesday, 27 June, 2018 8:54 AM  
**To:** 'admin-d@lkkauto.com' <admin-d@lkkauto.com>  
**Cc:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Subject:** OI : YP3272G / TP : SLS3938H/LKK / DOA : 20/06/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SENG HONG KEE CO,**

ADDRESS : BLK 4 WOODLANDS ROAD 393-F  
YEW TEE INDUSTRIAL ESTATE  
SINGAPORE 677976

PERSON TO CONTACT : LEE AH BEE @ 9699 6650

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are estimate and third party's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 10 July 2018 9:38 AM  
**To:** 'lee ahbee'  
**Cc:** SUR  
**Subject:** RE: Finalize - SLS3938H

Dear Ah Bee,

Noted with thanks.

Final invoice and all supporting documents sent over to ERGO INSURANCE

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** lee ahbee [mailto:ahbeelee@hotmail.sg]  
**Sent:** Monday, 9 July 2018 9:26 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** Re: Finalize - SLS3938H

Dear Veron,

WITHOUT PREJUDICE

We refer to the email below.

Lump Sum \$5600 @ 6 working days is okay. Please proceed.

Thank you !

Best Regards

Ah Bee Lee

Seng Hong Kee Co

Blk 4 Woodlands Road 393-F Singapore 677976

HP: 9699 6650 Tel: 6760 5120 Fax: 6760 2129

Sent from Outlook

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Monday, July 9, 2018 5:05 PM  
**To:** lee ahbee; Taufikh (LKKAuto)  
**Cc:** SUR  
**Subject:** RE: Finalize - SLS3938H

Dear Ah Bee,

WITHOUT PREJUDICE

Offer Lump Sum \$5600 @ 6 working days.

Tailgate glass price is \$1380/-

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** lee ahbee [mailto:ahbeelee@hotmail.sg]  
**Sent:** Sunday, 8 July 2018 7:25 AM  
**To:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** Finalize - SLS3938H

Good Morning Sir,

Attached are the damaged and after paint photos and Estimated with revised figures.

Please finalize is the repair cost Lump sum \$5,900.00 okay ?

Thanks And Regards

Ah Bee Lee

Seng Hong Kee Co

Blk 4 Woodlands Road 393-F

Singapore 677976 HP:9699 6650

Sent from Outlook

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8045E
<b>Vehicle Details</b>	
Vehicle No.:	SLS3938H
Vehicle to be Exported:	No
Intended De-registration Date:	29 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	FREED 1.5G A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	L15A2330963
Chassis No.:	GB31030595
Maximum Power Output:	87.0 kW (116 bhp)
Open Market Value:	\$20,062.00
Original Registration Date:	24 Mar 2009
First Registration Date:	24 Mar 2009
Transfer Count:	1
Actual ARF Paid:	\$20,062.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Mar 2019
PARF Rebate Amount:	\$10,031.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Mar 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$5,889.00
COE Rebate Amount:	\$324.00
<b>Total Rebate Amount:</b>	<b>\$10,355.00</b>

The information contained herein is correct as at 29 Jun 2018

OK

# 勝 峰 記 公 司

## SENG HONG KEE CO.

BLOCK 4, 393-F WOODLANDS ROAD (YEW TEE INDUSTRIAL ESTATE)  
SINGAPORE 677976 TEL: 6760 5120 FAX: 6760 2129

REG No: 270675/00X  
\* 車輛修理, 焊接與噴漆等 \*  
Motor Vehicles Repairing, Welding and Spray Painting

Our Ref: 3253/18/SHK

Date: 25 June 2018

KHOR LAI HENG  
Blk 250 Choa Chu Kang Avenue 2 #08-466  
Singapore 680250

**Estimated cost of repair to vehicle Registration No: SLS 3938 H**

Qty	List items	Price (\$)	Price (\$)
1 pc.	Tailgate <i>1460.30</i>	1,460.30 <i>bt</i>	
1 pc.	Tailgate lock assy.	189.00 <i>dd</i>	
1 pc.	Tailgate frame weatherstrip	120.00 <i>hwi</i>	
1 pc.	Tailgate 'Honda' logo	37.00 <i>na</i>	
1 pc.	Tailgate 'Freed' emblem	40.00 <i>ner</i>	
1 pc.	Tailgate wiper motor	280.00 <i>bt</i>	
1 pc.	Tailgate wiper arm	45.00 <i>cut</i>	
1 pc.	Tailgate wiper blade	48.00 <i>cut</i>	
1 pc.	Tailgate inner trim board	206.80 <i>de</i>	
2 pcs.	Tailgate absorbers @\$140.00	280.00 <i>Re</i>	
1 pc.	Tailgate glass	1,800.00 <i>brw</i>	
1 pc.	Tailgate glass top seal	95.60 <i>ner</i>	
2 pcs.	Taillamps @\$458.20 <i>@490.80</i>	916.20 <i>wa</i>	
1 pc.	Rear number plate lamp	35.80 <i>x nn</i>	
1 pc.	Rear number plate lamp garnish	287.30 <i>de</i>	
1 pc.	Rear bumper <i>1177</i>	490.30 <i>de</i>	
2 pcs.	Rear bumper side brackets @\$28.00	56.00 <i>ner</i>	
2 pcs.	Rear bumper arms @67.30	134.60 <i>? x nn</i>	
1 pc.	Rear end panel <i>580.30</i>	520.30 <i>bt</i>	
1 pc.	Rear end panel garnish	80.50 <i>de</i>	
		<u>7,122.70</u>	
	Less 20% dis.	<u>1,424.54</u>	5,698.16
<b>Special nett item</b>			
1 tube.	Windscreen sealant	<i>ner</i> 30.00	
1 set.	Reverse sensor	<i>ner</i> 200.00	230.00
<b>Labour charge</b>			
01.	To refix tailgate glass	120.00 ✓	
02.	To refix tailgate parts and attachments	120.00 <i>GO</i>	
03.	To refix rear end seats and floor covering	100.00 <i>GO</i>	340.00
	Balance c/f...		<u>6,268.16</u>

*too high  
1380*

# 勝峰記公司 SENG HONG KEE CO.

BLOCK 4, 393-F WOODLANDS ROAD (YEW TEE INDUSTRIAL ESTATE)  
SINGAPORE 677976 TEL: 6760 5120 FAX: 6760 2129

REG No: 270675/00X  
\* 車輛修理 ; 焊接與噴漆等 \*  
Motor Vehicles Repairing, Welding and Spray Painting

Our Ref: 3253/18/SHK

Date: 25 June 2018

KHOR LAI HENG  
Blk 250 Cho Chu Kang Avenue 2 \$08-466  
Singapore 680250

## Estimated cost of repair to vehicle Registration No: SLS 3938 H

Balance b/f...	6,268.16
03. To remove all listed parts, straighten, reshape and re-position rear end floor panel and inner structures. Cut and weld rear end panel Refix and re-align same.	1,000.00 <del>800</del>
04. To spray paint on affected areas	900.00 <del>800</del>
05. To anti-rust affected areas	120.00 <del>40</del>
	<u>2,020.00</u>
	<u>8,288.16</u>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Taufik 97495749  
'WP'  
28/6/18 @ 12pm  
sur@lkkauto.com  
taufikh@lkkauto.com  
6 days  
Lumpsum  
Resurvey after repair.

*[Signature]*  
29/6/18

# 勝峰記公司 SENG HONG KEE CO.

BLOCK 4, 393-F WOODLANDS ROAD (YEW TEE INDUSTRIAL ESTATE)  
SINGAPORE 677976 TEL: 6760 5120 FAX: 6760 2129

REG No: 270675/00X  
\* 車輛修理, 焊接與噴漆等 \*  
Motor Vehicles Repairing, Welding and Spray Painting

Our Ref: 3253/18/SHK

Date: 25 June 2018

KHOR LAI HENG  
Blk 250 Choa Chu Kang Avenue 2 #08-466  
Singapore 680250

## Estimated cost of repair to vehicle Registration No: SLS 3938 H

Qty	List items	Price (\$)	Price (\$)	
		1,460.30	bt	
1 pc.	Tailgate	189.00	dd	
1 pc.	Tailgate lock assy.	120.00	hi	
1 pc.	Tailgate frame weatherstrip	37.00	nei	
1 pc.	Tailgate 'Honda' logo	40.00	nei	
1 pc.	Tailgate 'Freed' emblem	280.00	bt	
1 pc.	Tailgate wiper motor	45.00	cut	
1 pc.	Tailgate wiper arm	48.00	cut	
1 pc.	Tailgate wiper blade	206.80	de	
1 pc.	Tailgate inner trim board	280.00	ry	
<del>2 pcs.</del>	<del>Tailgate absorbers @\$140.00</del>	<del>280.00</del>		
1 pc.	Tailgate glass	1,800.00	brw	
1 pc.	Tailgate glass top seal	95.60	nei	
2 pcs.	Taillamps @\$458.20	916.20	wa	
<del>4 pc.</del>	<del>Rear number plate lamp</del>	<del>35.80</del>	x	
1 pc.	Rear number plate lamp garnish	287.30	de	
1 pc.	Rear bumper	490.30	de	
2 pcs.	Rear bumper side brackets @\$28.00	56.00	nei	
<del>2 pcs.</del>	<del>Rear bumper arms @67.30</del>	<del>134.60</del>	ry	
1 pc.	Rear end panel	520.30	bt	
1 pc.	Rear end panel garnish	80.50	de	
		<u>7,122.70</u>	20% 6672.30	
		1,424.54	1334.46	5337.84
	Less 20% dis.		5,698.16	
	<b>Special nett item</b>			
1 tube.	Windscreen sealant	nei 30.00		
1 set.	Reverse sensor	nei 200.00	230.00	230.00
	<b>Labour charge</b>			
01.	To refix tailgate glass	120.00	✓	
02.	To refix tailgate parts and attachments	120.00	GO	
03.	To refix rear end seats and floor covering	100.00	GO	240.00
	Balance c/f...		340.00	5807.84
			<u>6,268.16</u>	

# 勝峰記公司 SENG HONG KEE CO.

BLOCK 4, 393-F WOODLANDS ROAD (YEW TEE INDUSTRIAL ESTATE)  
SINGAPORE 677976 TEL: 6760 5120 FAX: 6760 2129

REG No: 270675/00X  
• 車輛修理；焊接與噴漆等 •  
Motor Vehicles Repairing, Welding and Spray Painting

Our Ref: 3253/18/SHK

Date: 25 June 2018

KHOR LAI HENG  
Blk 250 Cho Chu Kang Avenue 2 S08-466  
Singapore 680250

**Estimated cost of repair to vehicle Registration No: SLS 3938 H**

Balance b/f...	6,268.16	5807.84
03. To remove all listed parts, straighten, reshape and re-position rear end floor panel and inner structures. Cut and weld rear end panel Refix and re-align same.	1,000.00 <del>800</del>	
04. To spray paint on affected areas	900.00 <del>800</del>	
05. To anti-rust affected areas	120.00 <del>40</del>	
	2,020.00	1640.00
	8,288.16	7447.84
		20% 1489.57
		5958.27

*lump sum \$ 5,900.00*

*Taufikh 97495749  
WP  
26/6/18 @ 12pm  
sur@lkkauto.com  
taufikh@lkkauto.com  
6 days  
Lumpsum  
Resuming after repair.*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18011742/T1vbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 11-07-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 3272G	Veh. Inspected	SLS 3938H
Policy No.		Coverage (\$)	0.00
Claim No.	YP3272G/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	27/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA FREED	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GB31030595	Colour	GREY
Odometer	140488	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	PIRELLI	6 mm
L/H Front Tyre	195/60 R15	PIRELLI	6 mm
R/H Rear Tyre	195/60 R15	PIRELLI	6 mm
L/H Rear Tyre	195/60 R15	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/06/2018	Inspection Date	28/06/2018
Survey held at	SENG HONG KEE CO BLOCK 4, 393F WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677976.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 3938H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAILGATE	BENT	1,460.30	1,460.30
1	TAILGATE LOCK ASSY	DENTED	189.00	189.00
1	TAILGATE FRAME WEATHERSTRIP	TWISTED	120.00	120.00
1	TAILGATE "HONDA" LOGO	NECESSARY	37.00	37.00
1	TAILGATE "FREED" EMBLEM	NECESSARY	40.00	40.00
1	TAILGATE WIPER MOTOR	BENT	280.00	280.00
1	TAILGATE WIPER ARM	CUT	45.00	45.00
1	TAILGATE WIPER BLADE	CUT	48.00	48.00
1	TAILGATE INNER TRIM BOARD	DEFORMED	206.80	206.80
2	TAILGATE ABSORBERS @\$140.00	TO REPAIR SEE LABOUR	280.00	-
1	TAILGATE GLASS	BROKEN	1,800.00	1,380.00
1	TAILGATE GLASS TOP SEAL	NECESSARY	95.60	95.60
2	TAILLAMPS @\$458.20	CRACKED	916.20	916.20
1	REAR NUMBER PLATE LAMP	NOT NECESSARY	35.80	-
1	REAR NUMBER PLATE LAMP GARNISH	DEFORMED	287.30	287.30
1	REAR BUMPER	DEFORMED	490.30	490.30
2	REAR BUMPER SIDE BRACKETS @\$28.00	NECESSARY	56.00	56.00
2	REAR BUMPER ARMS @\$67.30	NOT NECESSARY	134.60	-
1	REAR END PANEL	BENT	520.30	520.30
1	REAR END PANEL GARNISH	DEFORMED	80.50	80.50
	LESS 20% DISCOUNT		-1,424.54	-1,250.46
			5,698.16	5,001.84
<b>SPECIAL NETT ITEMS</b>				
1	TUBE WINDSCREEN SEALANT (SN)	NECESSARY	30.00	30.00
1	SET REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
			230.00	230.00
<b>LABOUR</b>				
	TO REFIX TAILGATE GLASS.		120.00	120.00
	TO REFIX TAILGATE PARTS AND ATTACHMENTS.		120.00	60.00

Report Ref No. CS/EG18011742/T1vbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REFIX REAR END SEATS AND FLOOR COVERING.		100.00	60.00
	TO REMOVE ALL LISTED PARTS, STRAIGHTEN, RESHAPE AND RE-POSITION REAR END FLOOR PANEL AND INNER STRUCTURES. CUT AND WELD REAR END PANEL REFIX AND RE-ALIGN SAME INCLUSIVE OF THE REPAIR OF TAILGATE ABSORBERS.		1,000.00	800.00
	TO SPRAY PAINT ON AFFECTED AREAS.		900.00	800.00
	TO ANTI-RUST AFFECTED AREAS.		120.00	40.00
			2,360.00	1,880.00
	<b>GRAND TOTAL</b>		<b>8,288.16</b>	<b>7,111.84</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,600.00</b>

Report Ref No. CS/EGI18011742/T1vbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.