

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0712/2018/PH 12-Jul-18 CHANG 1 of 1 SKM 1731 T Audi Q5 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum / regas to pressurise cooling system. S/N	\$ 1,100.00	\$ 1,100.00
2	To dismantle and renew front (lock carrier) bonnet and RHS headlight. Align to position. <i>bumper</i>	\$ 4,000.00	\$ 1,750.00 <i>1250</i>
3	To respray bonnet. <i>Repaired</i>	\$ 900.00	\$ 550.00 <i>X</i>
TOTAL LABOURS :		\$ 6,000.00	\$ 3,400.00
Parts			
1	BONNET	\$ 3,562.00	\$ 2,849.60
2	FRONT LOCK CARRIER	\$ 1,124.00	\$ 899.20
3	HEADLIGHT MOUNTING - RH	\$ 103.00	\$ 82.40
4	FRONT BUMPER TOP COVER	\$ 109.00	\$ 87.20
5	FRONT BUMPER CLOSING ELEMENT - RH	\$ 95.00	\$ 75.84
6	LED HEADLIGHT - RH	\$ 7,112.00	\$ 5,689.60
7	COOLANT	\$ 133.00	\$ 65.28
8	SIGN ' CAUTION ' STICKER	\$ 12.00	\$ 9.28
9	STICKER FOR AIR CONDITIONER	\$ 17.00	\$ 13.44
10	HEADLIGHT LOCK MECHANISM	\$ 17.00	\$ 13.04
11	Front No Plate <i>CA) see</i> s/n	\$ 25.00	\$ 25.00
TOTAL PARTS :		\$ 12,309.00	\$ 9,809.88
GRAND TOTAL :		\$ 18,309.00	

For Premium Automobiles Pte Ltd

Authorized Signature

23090.92