





kh



# BH AUTO SERVICES PTE LTD

Blk L, Sector C, Sun Ming Industrial Estate #01-111 113 115 117 Singapore 575636  
Tel: 6559 8944 Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd  
AIG Building  
78 Shenton Way #08-16  
Singapore (079120)  
ATTN: MOTOR CLAIM DEPARTMENT  
Tel: 6119 3000 Fax: 6835 7416

*Not Notified*  
*L1 Ser B 22501*  
*Presony After Party*

ACCIDENT REPAIR ON : SKB3302T  
MODEL FORD MONDEO  
POLICY NO : GA126811  
CHASSIS NO : WF0DXXGBBDBD84677  
MANUFACTURING YEAR 2011  
DATE / TIME OF ACCIDENT: 25/06/2018 Time: 2030Hrs ALONG WEST COAST HIGHWAY TWDS CITY  
THIRD PARTY VEHICLE NO : SKU6128K

Date 20/06/2018  
Page 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle.

Replacement Of Parts	Quantity	Unit Price	Condition	Amount
S/N		SS		SS
1 Bootlid	1	2363.00	NEW	R 2,363.00 X
2 Bootlid Emblem	1	138.00		138.00 +
3 Bootlid Lettering "Mondeo"	1	140.00		140.00 -
4 Bootlid Lettering "Ecoboost"	1			
5 Bootlid Finisher	1	328.00		CMF 328.00 -
6 Bootlid Weatherstrip	1	316.00		Per 316.00 X
7 Boot Lid Lamp LH	1	570.00		Per 570.00 X
8 Boot Lid Lamp RH	1	570.00		Per 570.00 X
9 Bootlid Gasket LH	1			
10 Bootlid Gasket RH	1			
11 Rear Bumper	1	1560.00		Per 1,560.00 -
12 Rear Bumper Side Retainer LH	1	110.00		Per 110.00 X
13 Rear Bumper Side Retainer RH	1	110.00		Per 110.00 -
14 Rear Bumper Centre Bracket	1	120.00		R 120.00 X
15 Rear Bumper Bracket (17B930)	1	55.00		R 55.00 X
16 Rear Bumper Lower Spoiler	1	550.00		Per 550.00 X
17 Rear Bumper Sensor	4	120.00		Per 480.00 X
18 Rear Bumper Sensor Ring	4			
19 Rear Bumper Reflector LH	1	103.00		Per 103.00 X
20 Rear Bumper Reflector RH	1	103.00		Per 103.00 X
21 Rear Bumper Tow Cover	1	55.00		Per 55.00 -
22 Rear Bumper Reinforcement	1	1095.00		R 1,095.00 X
23 Rear Bumper Sponge	1			
24 Rear Bumper Lock Assy	1			
25 Rear End Panel	1	395.00		R 395.00 X
26 Rear End Panel Top Garnish	1	170.00		Per 170.00 X
27 Tail Lamp LH	1	703.00		Per 703.00 X
28 Tail Lamp RH	1	703.00		Per 703.00 X
29 Tail Lamp Bracket LH	1			
30 Tail Lamp Bracket RH	1			
31 Rear Fender LH	1	2420.00		R 2,420.00 X
32 Rear Fender RH	1	2420.00		R 2,420.00 X
33 Rear Fender Shield LH	1	395.00		Per 395.00 X
34 Rear Fender Shield RH	1	395.00		Per 395.00 X

35 Exhaust Silencer Tip

1

1250.00

*1250.00* 1,250.00 X

Sub-Total: 17,617.00

Less Discount 20% 3,523.40

**Total Parts: 14,093.60**

*2,100.00*  
*3,100.00*

**Special Nett Items**

1	Anti-rust coating	4	80.00
2	Rear Bumper Clips	10	5.00
3	Rear End Panel Top Garnish Clips	10	6.00
4	Rear Fender Shield Clips	20	4.00

*320.00* X  
*35.00* ✓  
*60.00* X  
*80.00* X

**Total Parts: 460.00**

**Labour Charges For Front and Side Portion**

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,500.00
2	Provide skill labour & material to puty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,500.00
3	Provide skill labour to disconnect and check electrical wiring	30.00
4	Remove and refit rear end panel lining and garnish to facilitate repair	100.00
5	Remove and replace bumper sensors	100.00
6	Realign Exhaust Pipe	50.00
7	Remove and replace exhaust pipe/system to facilitate repair recommended specification	120.00
<b>Total Labour:</b>		<b>3,400.00</b>

*400*  
*600*  
*20*  
*100.00* X  
*600*  
*120.00* X

**Total Parts & Labour: 17,953.60**

**GST 7% 1,256.75**

**Grand Total: 19,210.35**

**Estimate Repair Duration**

10 days

*4 days*

ACCIDENT VEHICLE OF : SKB3302T

Page . 2 of 2

Remark: **Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by

Name \_\_\_\_\_

Company \_\_\_\_\_

Date \_\_\_\_\_

Time \_\_\_\_\_

Contact No. \_\_\_\_\_

Email \_\_\_\_\_

*P.T. = \$17,953.60*

*GST = \$1,256.75*

*Total = \$19,210.35*

*10 days*

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sui Ming Industrial Estate #01-111 113 115 117 Singapore 575636  
Tel: 6559 8944 Fax: 6269 2404

**AIG Asia Pacific Insurance Pte. Ltd**  
AIG Building  
78 Shenton Way #08-16  
Singapore (079120)  
ATTN: MOTOR CLAIM DEPARTMENT  
Tel: 6419 3000 Fax: 6835 7416

*Not Authored  
21/06/18  
Resurvey After Repair*

Date: 20/06/2018  
Page: 1 of 2

**ACCIDENT REPAIR ON : SKB3302T**  
MODEL : **FORD MONDEO**  
POLICY NO : **GA126811**  
CHASSIS NO : **WF0DXXGBBDBD84677**  
MANUFACTURING YEAR : **2011**  
DATE / TIME OF ACCIDENT: **25/06/2018** Time: **2030Hrs** **ALONG WEST COAST HIGHWAY TWDS CITY**  
THIRD PARTY VEHICLE NO : **SKU6128K**

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price S\$	Condition	Amount S\$
S/N					
1	Bootlid <i>R ?</i>	1			
2	Bootlid Emblem <i>C</i>	1			
3	Bootlid Lettering "Mondeo" <i>MC -</i>	1			
4	Bootlid Lettering "Ecoboost" <i>MC -</i>	1			
5	Bootlid Finisher <i>CR -</i>	1			
6	Bootlid Weatherstrip <i>Sm x</i>	1			
7	Boot Lid Lamp LH <i>Sm x</i>	1			
8	Boot Lid Lamp RH <i>Sm x</i>	1			
9	Bootlid Gasket LH <i>Sm x</i>	1			
10	Bootlid Gasket RH <i>Sm x</i>	1			
11	Rear Bumper <i>RMC ✓</i>	1			
12	Rear Bumper Side Retainer LH <i>Sm x</i>	1			
13	Rear Bumper Side Retainer RH <i>Dis -</i>	1			
14	Rear Bumper Centre Bracket <i>?</i>	1			
15	Rear Bumper Bracket (17B930) <i>?</i>	1			
16	Rear Bumper Lower Spoiler <i>?</i>	1			
17	Rear Bumper Sensor <i>?</i>	1			
18	Rear Bumper Sensor Ring <i>?</i>	1			
19	Rear Bumper Reflector LH <i>Sm x</i>	1			
20	Rear Bumper Reflector RH <i>Sm x</i>	1			
21	Rear Bumper Tow Cover <i>RD -</i>	1			
22	Rear Bumper Reinforcement <i>?</i>	1			
23	Rear Bumper Sponge <i>?</i>	1			
24	Rear Bumper Lock Assy <i>R x</i>	1			
25	Rear End Panel <i>R x</i>	1			
26	Rear End Panel Top Garnish <i>Sm x</i>	1			
27	Tail Lamp LH <i>Sm x</i>	1			
28	Tail Lamp RH <i>Sm x</i>	1			
29	Tail Lamp Bracket LH <i>R ✓</i>	1			
30	Tail Lamp Bracket RH <i>R x</i>	1			
31	Rear Fender LH <i>R x</i>	1			
32	Rear Fender RH <i>R x</i>	1			
33	Rear Fender Shield LH <i>Sm x</i>	1			
34	Rear Fender Shield RH <i>Sm x</i>	1			

35 Exhaust Silencer Tip

SA X :

Sub-Total:	-
Less Discount 20%:	-
<b>Total Parts:</b>	-

**Special Nett Items**

1	Anti-rust coating	4	80.00	~	320.00	X
2	Rear Bumper Clips	10		~	-	✓
3	Rear End Panel Top Garnish Clips	10		~	-	X
4	Rear Fender Shield Clips	20		~	-	X
<b>Total Parts:</b>					<b>320.00</b>	

**Labour Charges For Front and Side Portion**

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.				1,500.00	4001
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities				1,500.00	6001
3	Provide skill labour to disconnect and check electrical wiring				30.00	201
4	Remove and refit rear end panel lining and garnish to facilitate repair			~	100.00	X
5	Remove and replace bumper sensors				100.00	601
6	Realign Exhaust Pipe			~	50.00	X
7	Remove and replace exhaust pipe/system to facilitate repair recommended specification				~ 120.00	X
<b>Total Labour:</b>					<b>3,400.00</b>	
<b>Total Parts &amp; Labour:</b>					<b>3,720.00</b>	
<b>GST 7%</b>					<b>260.40</b>	
<b>Grand Total:</b>					<b>3,980.40</b>	

Estimate Repair Duration 10 days  
*4 days*

ACCIDENT VEHICLE OF : SKB3302T

Page : 2 of 2

**Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by

Name : Kennerth  
 Company : CKA  
 Date : 29/6/18  
 Time : 10 am  
 Contact No : 96910663  
 Email : \_\_\_\_\_

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NPIC  
 Owner ID: 0634E

### Vehicle Details

Vehicle No: SK83302T  
 Vehicle to be Exported: No  
 Intended De-registration Date: 26 Jun 2018  
 Vehicle Make: FORD  
 Vehicle Model: MONDEO TITANIUM 2.0 AT ABS D AIRBAG 2WD  
 Primary Colour: Grey  
 Manufacturing Year: 2011  
 Engine No: SD84677  
 Chassis No: WF0DXXGB0BD84677  
 Maximum Power Output: 149.0 kW (199 bhp)  
 Open Market Value: \$25,809.00  
 Original Registration Date: 19 May 2011  
 First Registration Date: 19 May 2011  
 Transfer Count: 1  
 Actual ARF Paid: \$25,809.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 18 May 2021  
 PARF Rebate Amount: \$15,465.00

### Intended COE Rebate Details

COE Expiry Date: 18 May 2021  
 COE Category: B - Car (1601cc & above)  
 COE Period (Year(s)): 10  
 QP Paid: \$61,894.00  
 COE Rebate Amount: \$17,904.00  
**Total Rebate Amount: \$33,369.00**

The information contained herein is correct as at 26 Jun 2018.

OK

Post an Advertisement on sgCarMart.com for as little as \$58 until it's SOLD!



PRISTINE USED CARS AT GREAT PRICES. Click here to view our PRISTINE USED CARS AT GREAT PRICES

Browse by Category

Sort by Date Posted 20 results/page

MONDEO TITANIUM

1

Image	Model	Price	Registration	Drive Type	MPG	Year	View
	2011 MONDEO TITANIUM	\$48,800	01/2011	Front	19.5	2011	View
<p>1 Agent has sold 1 Base 199K. Accident free. New upgraded 1.6L 4-cyl. engine. 170hp. 170km/h. 17.5. Exchange with 2008P. 170hp. 170km/h. 17.5. Fuel Efficient Among The Most Spacious Car. And Thank U</p>							
	2011 MONDEO TITANIUM	\$48,800	01/2011	Front	19.5	2011	View

View 12 selected results for 2011 Mondeo Titanium

1 20 results/page

Follow sgCarMart.com

**Vic (LKKAuto)**

---

**From:** BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>  
**Sent:** Tuesday, 14 August 2018 3:22 PM  
**To:** Vic (LKKAuto); Admin A  
**Cc:** BHG - Johnny Lim; BHAS - Moo Wen Zheng; BHAS - Anthony Lau; BHAS - Bernard Kee  
**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKU6128K AND SKB3302T ON 25/06/2018 \*\*\* LKK REF: CC4/AIG18011760/Kha3  
**Attachments:** SKM\_C224e18081415190\_0001.jpg

Dear Vic,

Refer to attach file for our client sign DV.

Appreciate you can assist to proceed payment for us.

Original copy will be posted out to you by today.

Kindly look out for it.

Thank You & Best Regards,

Jacelyn Loh



Address: Blk L, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

**From:** Vic (LKKAuto) <vic@lkkauto.com>  
**Sent:** Tuesday, 14 August 2018 2:24 PM  
**To:** BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>  
**Cc:** BHG - Johnny Lim <johnny@bhglobal.com.sg>; BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vic@lkkauto.com>  
**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKU6128K AND SKB3302T ON 25/06/2018 \*\*\* LKK REF: CC4/AIG18011760/Kha3

Without Prejudice

Dear Bernard,

We refer to your below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we confirm acceptance of your offer of **\$2,809.50** (all in) to settle your client's claim.

Kindly confirm chop and sign the attached DV and **forward to us a copy together with the Correct Repair Invoice** for payment processing.

The above amount is to be made payable to **BH AUTO SERVICES PTE LTD.**

Thank you.

*Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely in respect of this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.*


Best Regards

**Vic Alpeh** - Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6547-1906 / email: [vicalpeh@lkkauto.com.sg](mailto:vicalpeh@lkkauto.com.sg) / fax: 6541-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25, S1408933



*Save the Earth. Print only when necessary.*

This e-mail contains confidential and privileged material and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

**From:** BIAS - Bernard Kee [<mailto:bernard.kee@bhauto.com.sg>]

**Sent:** Tuesday, 14 August 2018 1:36 PM

**To:** Vic (LKKAuto)

**Cc:** BHG - Johnny Lim; BIAS - Jacelyn Loh; BIAS - Moo Wen Zheng; BIAS - Anthony Lau

**Subject:** FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKU6128K AND SKB3302T ON 25/06/2018 \*\*\* LKK REF: CC4/AIG18011760/Kha3

Dear Vicalpeh

Kindly confirm the due course asap and send me the DV so that I can close up the case asap.

As your requested, please find the attached file (**LOD**) for your perusal.

Thank you

Best Regards,

*Bernard Kee*

**BH AUTO SERVICES PTE LTD**

(W) +65-6559 8945 (F) +65-6269 2404 (M) +65 9747 8383

[Bernard.kee@bhauto.com.sg](mailto:Bernard.kee@bhauto.com.sg) / <http://www.bhauto.com.sg>

**From:** BIAS - Bernard Kee

**Sent:** Tuesday, 7 August 2018 11:42 AM

**To:** 'vicalpeh@lkkauto.com' <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>

**Cc:** BIAS - Anthony Lau <[anthony.lau@bhauto.com.sg](mailto:anthony.lau@bhauto.com.sg)>; BIAS - Moo Wen Zheng

<[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHG - Johnny Lim <[johnny@bhglobal.com.sg](mailto:johnny@bhglobal.com.sg)>; BIAS - Jacelyn Loh

<[jacelyn.loh@bhauto.com.sg](mailto:jacelyn.loh@bhauto.com.sg)>

# BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE, SECTOR C 001-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

**PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING**

Your Reference: SKI 6128K

Our Reference: SKB3302I

Date: 01/08/2018

M/s AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#07-16  
Singapore 079120

BY EMAIL ONLY

Attention: Claims Department

**CLAIMANT: NG CHUN WAY KENNY**

**PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25/06/2018 ALONG WEST COAST HIGHWAY TWDS CITY INVOLVING VEHICLE NO SKB3302I & SKI 6128K**

We act for NG CHUN WAY KENNY who was the owner of motor vehicle no. SKB3302I.

We are instructed by the above named to claim damages against you your insured in connection with a road traffic accident on 25/06/2018 involving your client's vehicle registration number SKB3302I and vehicle registration number SKI 6128K driven by you your insured at the material time.

We are instructed that the accident was caused by you your insured's negligent driving and/or management of your you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows.

1	Cost of Repair (Included GST)	\$ 2407.50
2	Loss of Use (S 100.00 x 4days)	\$ 400.00
3	UFA Search Fee	\$ 2.00
	<b>Total:</b>	<b>\$ 2809.50</b>

We enclose a copy of each of the following documents for your consideration:

- (a) GDA Police report lodged by driver of;
- (b) Final Repair Bill
- (c) Rental Invoice - Loss of Use
- (d) UFA Search Fee Invoice
- (e) Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,

Jacelyn Loh  
Tel: 6559 8944 Fax: 6269 2404  
Email: jacelyn.loh@bhaut.com.sg





100, RAFFLES PLACE, RAFFLES INDUSTRIAL PARK, SINGAPORE 408601. TEL: (65) 62563500 FAX: (65) 62564333

10 JULY 2018

ZENG MINGDE RICHARD  
335D PASIR PANJANG ROAD  
SINGAPORE 118664

By Post & By Email

Dear Sir/Madam,

OUR REF : CC4/AIG18011760/Kha3  
YOUR REF : SKU 6128K  
ACCIDENT INVOLVING SKU 6128K AND SKB 3302T ALONG WEST COAST HIGH  
WAY ON 25.06.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SKB 3302T against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SKB 3302T. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [ycap.poh@kkauto.com](mailto:ycap.poh@kkauto.com) within 10 days from the date of this letter if not provided at AIG's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)

50, BELMONT ROAD, PAYA LEBER STREET PARK, SINGAPORE 089001 TEL: 65 67563611 FAX: 65 67564113

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

in the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lksauto.com](mailto:vicalpeh@lksauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively

Yours sincerely

Vic Alpeh  
*Case Handler*  
DID: 6841 2096  
FAX: 6741 4108  
Email: [vicalpeh@lksauto.com](mailto:vicalpeh@lksauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

*vicalpeh@lksauto.com*  
*(Email)*



To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [ajalpe@lkkauto.com](mailto:ajalpe@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively

Best Regards,

Vic Alpe - Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256 3561 email: [ajalpe@lkkauto.com](mailto:ajalpe@lkkauto.com) Fax: 6741 4168

111, Baya Lhi Industrial Park, A Sri Avenue 4, #03-25, S 108924

*For the company, please only when necessary*

AUTHORISATION

Name of owner of my vehicle Ng Chan Way Kenny

Address \_\_\_\_\_

NRIC no S8610534E

THE ACCIDENT ON 25/06/18 ALONG West Coast Highway (WSS City)

INVOLVING SKB 3302T & SCU 6128K

In consideration of BH AUTO SERVICES PTE LTD ("the Workshop") repairing my/our vehicle no SKB 3302T at my/our request, I/We the abovenamed owner of motor vehicle no SKB 3302T, hereby authorise the Workshop to demand claim, negotiate, settle my/our claim for cost of repairs loss of use and all other expenses and damages arising out of the above accident

I/We further authorise the Workshop to appoint solicitors to demand, claim, negotiate, settle and/or commence legal proceedings in my/our name for the above purpose and at the sole discretion of the Workshop. All sums recovered therefrom shall belong to the Workshop absolutely and I/We further authorize the Workshop to give absolute discharges on my/our behalf and to sign all discharge vouchers and other documents in relation to the same on my/our behalf. I/We further agree to fully co-operate with the solicitors appointed by the Workshop on my/our behalf and attend all Court hearings that are necessary to prosecute the claims maintained by the Workshop

I/We agree that in the event that the claim is rejected for whatsoever reason or the Workshop decides not to proceed with legal proceedings or for whatsoever reason the Workshop is unable to recover all of the repair costs or are only able to recover a portion of the same I/We hereby undertake to pay them the full repair costs and or any portion thereof that cannot be recovered and all expenses including legal costs that they may have incurred in pursuing the claim within 7 days from the date of the written notice for payment by them to my/our last known address

I/We hereby declare that I/We will always remain and be liable to the Workshop for the cost of repair to my/our motor vehicle and expenses incurred on my/our behalf. In the event that Workshop has to issue any notice or commence legal proceedings against me/us to enforce this undertaking against me/us, I/We shall be liable for the Workshop's expenses and legal cost (including solicitor and client cost) on an indemnity basis

I/We further authorise the Workshop to give to the other party/parties absolute discharges in respect of any liability and any sum, whether agreed or not made the Workshop or to the law firm appointed by the Workshop towards full settlement of my/our claim. It shall be regarded as full and final discharge of the claim

I/We further authorise the Workshop to settle the above mentioned claim in a manner that they deem fit and the Workshop is further authorised to receive payment further to settlement of my claim with payment cheques being made in favour of the Workshop

Date this 25 (day) of June (month) 2018 (year)

Signed \_\_\_\_\_

Owner of my vehicle SKB 3302T

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **BH AUTO SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2,407.50** (Repair Cost) **S\$400.00** (Loss of Rental/Use), **S\$2.00** (Disbursement), for vehicle no. **SKB 3302T** that was damaged pursuant to the accident which occurred on **25/06/2018** (date) along **WEST COAST HIGHWAY** (location) involving vehicle no/s **SKU 6128K**. This is pursuant to the inspection conducted on **29/06/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **NG CHUN WAY KENNY** ("the third party claimant") of vehicle no. **SKB 3302T** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SKB 3302T** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 14 (day) of 08 (month) **2018** (year).

  
\_\_\_\_\_  
Signed by appointed surveyor

  
\_\_\_\_\_  
Signed by "the work-shop" (with chop)

**BH AUTO SERVICES PTE LTD**

BLK 1 SIN MING INDUSTRIAL ESTATE  
SECTOR C #01-115 SINGAPORE 575636

Tel: 6743 3494

Fax: 6269 2404

CO REG NO 2010061066

GST REG NO 2010061066

**TAX INVOICE**

**Final Repair Bill**

Our Ref: SKB3302T

Date: 01/08/2018

M/s AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#07-16  
Singapore 079120

BY EMAIL ONLY

Vehicle No : **SKB3302T**  
Make/Model : **FORD MONDEO**  
Year of Manufacture : **2011**  
Chassis No. : **WF0DXXGBBDBD84677**  
Colour : **BLUE**  
D.O.A : **25 06 2018**

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
1.	Repair Cost for Motor Vehicle No. <b>SKB3302T</b> Type of repair: Lump Sum	:S\$ 2250.00
		GST @ 7% : S\$ 157.50
		<b>GRAND TOTAL:S\$ 2407.50</b>

Total : Singapore Dollars Two thousand Four Hundred and Seven Dollars and Fifty Cents Only.

Company Stamp & Signature



# GENERAL INSURANCE ASSOCIATION

## GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

### TAX INVOICE

Our Ref No: GR-18-096855  
 Date of Request: 26/06/2018  
 Your Ref No.:  
 Online Purchase

BH Auto Services Pte Ltd  
 Blk 1 Sin Ming Industrial Estate Sector C  
 #01-111/113/115/117  
 Singapore 575636

Dear Sir/Madam,

Enquiry Date: 26/06/2018  
 Enquiry By: Jacelyn Loh Cai Ling  
 Vehicle No: SKU6128K  
 Accident Date: 25/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

**...CLAIM SUBFOLDER...(Pending for Survey Report)**  
Fast Case

**CLAIM SUBFOLDER TRACKING**

Case No.	Reported On	Estimate No.	Adj. Rpt. No.	Adj. Rpt.	Est. Amount	Est. Amt. Paid	Status
Main	18 Jun 2018 <a href="#">Edit Reg</a>		25 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,250.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,250.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

[Created by adjuster]

Insured	<b>ZENG MINGDE RICHARD</b> ID: SH904717Z		
Main Claimant	<b>NG CHUN WAY KENNY</b> ID: S8610634E		
Vehicle Reg No.	<b>SKB3302T</b>	Date of Ins	25/05/2018 00:00:00 [85 Months and 6 Days from LTA Reg Date (Main Yr)]
Claim Type	<b>TP / J8U65132945G</b>	Policy/Cover Note No.	2100-121399 (Comprehensive)
Vehicle No (Insured)	<b>SKU6128K</b>	Policy No. (Claimant)	5A125811
Repairer	<b>BH Auto Services Pte Ltd (Sin Ming)</b> Bldg 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, S75636 Sin Ming To 6559 8944		
Handling Insurer	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> Tel: 65-6419 3000 [Handled by <b>Ler, Bernard-JQ</b> ] bernard@global.aig.com		
Claimant's Insurer	<b>AXA Insurance Pte Ltd (HQ)</b> Tel: 6336 7288		
Adjuster	<b>LKK Auto Consultants Pte Ltd (HQ)</b> Tel: 6258 3561 [Handled by <b>KENNETH KONG</b> ] [Final Rpt due 06/07/2018]		

**ASSOCIATED MAIL RECEIVED**

[View All](#) [Compose Case Mail](#)

- AIG\_SG128(06/07/2018): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS**

[View All](#) [Search tasks](#) [Create New task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Documents Checklist

[Reset](#) [Save](#) [Print](#)

### DOCUMENTS CHECKLIST

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
(can be manual and private unless you are in LKK or other parties)

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SKU6128K (Insd veh)	Model:	FORD MONDEO 2.0
	SKB3302T (TP veh)		TITANIUM ABS D/AIRBAG
Date of Accident:	25/06/2018		2WD (A)

Global Sum Settlement	Yes	No	
Repair Estimate		<input checked="" type="checkbox"/>	\$ 19,258.50
Final Repair Cost			\$ 2,407.50
Loss of Use			\$ 400.00
Rental (if any)			\$ 0.00
TPA / GIA Search Fee			\$ 2.00
Others			\$ 0.00
			\$
Final Settlement Sum			\$ 2,809.50

Is Third Party Workshop GIA Registered?  YES  NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_ 100 \_\_\_ (%)  
 BOLA Applicable Yes/ No BOLA Scenario No

B) For GIA Registered Workshop:  
 BOLA Liability: \_\_\_ (%) Assessed Liability (\*) \_\_\_ (%)  
 \* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown		
1)	BH Auto Services Pte Ltd	\$ 2,809.50
2)		\$
3)		\$

JOANNE LEE KHANG MIN  
 LKK Auto Consultants Pte Ltd  
 Date 20 Aug 2018

Please attach all the supporting documents to the form.  
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd

Co Reg No 199007195R;  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18011760/KHA3Q2  
Date: 20/08/2018

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte Ltd.	Policy No:	2100421899
<b>Claimant Vehicle No:</b> SKB33302T	<b>Insured Vehicle No:</b>	SKU6128K
Date of Loss: 25/06/2018	Nature of Claim:	TP
	Claim No:	2806518294SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKB33302T</b>	Engine No.	BD84677
Make & Model:	FORD MONDEO, 2.0 TITANIUM ABS D/AIRBAG 2WD (A)	Chassis No	WF0DXXG8BDBD84677
Reg. Date:	19/05/2011 (Man Year: 2011)	Odometer:	120317 km
Colour:	Metallik Grey		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre tread depth

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,588.60	1,789.40	12,799.20	87.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	1,060.00	2,330.00	68.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,998.60</b>	<b>2,869.40</b>	<b>15,129.20</b>	<b>84.06</b>
<b>Approved Total (Overridden) (S\$)</b>	<b>-</b>	<b>2,250.00</b>		
<b>(S\$)</b>	<b>17,998.60</b>	<b>2,250.00</b>	<b>15,748.60</b>	<b>87.50</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,259.90</b>	<b>157.50</b>	<b>1,102.40</b>	<b>87.50</b>
<b>Nett Amount (S\$)</b>	<b>19,258.50</b>	<b>2,407.50</b>	<b>16,851.00</b>	<b>87.50</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		<b>400.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>2,809.50</b>		

#### INSPECTION

Date of Assignment: 26/06/2018  
Date Inspected: 29/06/2018 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)  
Blk 1 Sin Ming Industrial Estate Sector C,  
#01/111/113/115/117  
Singapore 575636

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** VIC ALPEH

*NOTE: This report represents our findings of the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	2,363.00 FL	* FL
2	1		*BOOTLID EMBLEM	Not Necessary	138.00 FL	* FL
3	1		*BOOTLID LETTERING MONDEO	Necessary	140.00 FL	*140.00 FL
4	1		*BOOTLID LETTERING ECOBOOST (NPA)	Not Necessary	0.00 FL	* FL
5	1		*BOOTLID FINISHER	Cracked	328.00 FL	*328.00 FL
6	1		*BOOTLID WEATHERSTRIP	Serviceable	316.00 FL	* FL
7	1		*BOOT LID LAMP LH	Serviceable	570.00 FL	* FL
8	1		*BOOT LID LAMP RH	Serviceable	570.00 FL	* FL
9	1		*BOOTLID GASKET LH (NPA)	Not Necessary	0.00 FL	* FL
10	1		*BOOTLID GASKET RH (NPA)	Not Necessary	0.00 FL	* FL
11	1		*REAR BUMPER	Buckled	1,560.00 FL	*1,560.00 FL
12	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	110.00 FL	* FL
13	1		*REAR BUMPER SIDE RETAINER RH	Distorted	110.00 FL	*110.00 FL
14	1		*REAR BUMPER CENTRE BRACKET	Repair	120.00 FL	* FL
15	1		*REAR BUMPER BRACKET (17B930)	Repair	55.00 FL	* FL
16	1		*REAR BUMPER LOWER SPOILER	Serviceable	550.00 FL	* FL
17	4		*REAR BUMPER SENSOR	Serviceable	480.00 FL	* FL
18	4		*REAR BUMPER SENSOR RING (NPA)	Not Necessary	0.00 FL	* FL
19	1		*REAR BUMPER REFLECTOR LH	Serviceable	103.00 FL	* FL
20	1		*REAR BUMPER REFLECTOR RH	Serviceable	103.00 FL	* FL
21	1		*REAR BUMPER TOW COVER	Dented	55.00 FL	*55.00 FL
22	1		*REAR BUMPER REINFORCEMENT	Repair	1,095.00 FL	* FL
23	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	* FL
24	1		*REAR BUMPER LOCK ASSY (NPA)	Not Necessary	0.00 FL	* FL
25	1		*REAR END PANEL	Repair	395.00 FL	* FL
26	1		*REAR END PANEL TOP GARNISH	Serviceable	170.00 FL	* FL
27	1		*TAIL LAMP LH	Serviceable	703.00 FL	* FL
28	1		*TAIL LAMP RH	Serviceable	703.00 FL	* FL
29	1		*TAIL LAMP BRACKET LH (NPA)	Not Necessary	0.00 FL	* FL
30	1		*TAIL LAMP BRACKET RH (NPA)	Not Necessary	0.00 FL	* FL
31	1		*REAR FENDER LH	Repair	2,420.00 FL	* FL
32	1		*REAR FENDER RH	Repair	2,420.00 FL	* FL
33	1		*REAR FENDER SHIELD LH	Serviceable	395.00 FL	* FL
34	1		*REAR FENDER SHIELD RH	Serviceable	395.00 FL	* FL
35	1		*EXHAUST SILENCER TIP	Repair	1,250.00 FL	* FL
36	4		*ANTI-RUST COATING	Not Necessary	320.00 FS	* FS
37	10		*REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
38	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	* FS
39	20		*REAR FENDER SHIELD CLIPS	Not Necessary	80.00 FS	* FS

F=Franchise part S=SpcNett. L=Lsite=Disc

<b>Sub Total (\$\$)</b>	<b>18,112.00</b>	<b>2,228.00</b>
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,523.40	438.60
<b>Total Parts (\$\$)</b>	<b>14,588.60</b>	<b>1,789.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,500.00	400.00
2	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	1,500.00	600.00
3	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	30.00	20.00
4	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	100.00	0.00
5	REMOVE AND REPLACE BUMPER SENSORS	New	100.00	0.00
6	REALIGN EXHAUST PIPE	New	60.00	60.00
7	REMOVE AND REPLACE EXHAUST PIPE /SYSTEM TO FACILITATE REPAIR RECOMMENDED SPECIFICATION	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,410.00</b>	<b>1,080.00</b>

Report was unsubmitted during this print-out

< END OF ESTIMATES >