



吉维利企业 KIVILE ENTERPRISE

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2553

EMAIL: KIVILEPC@GMAIL.COM WEBSITE: KIVILEPC.COM

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBG234G model:honda cb 125

Handle Bar	/ BT	110	/
Brake Lever	/ Cut	65	/
Brake Pump	X NN	110	
Clutch Lever	X NN	65	
Grip	X NN	30	
Mirror	/ Cut	60	/
Meter	X NN	380	
Head Light	/ Cut	150	/
Head Light Cover	X NN	65	
Lamp Stay	X NN	75	
Signal Light RH	/ Cut	48	/
Signal Light LH	/ Cut	48	/
Front Mudguard	/ BT	75	/
Gear Paddle	/ BT	75	/
Footrest LH	X NN	65	
Footrest RH	/ Cut	65	/
Brake Paddle	/ Cut	75	/
Rear Footrest RH	/ Cut	65	/
Exhaust Pipe	/ DD	450	/
Exhaust Pipe Guard	/ Cut	85	/
Rear Box	/ Cut	160	/
Rear Box Carrier	X NN	85	
Front Number Plate	/ Cut	30	/
Fork Repair		300	60
Staying Cone	/ del.	165	/
Labour		350	120
Transport		50	40
spray		250	X NN
alignment		300	X NN
		3851	

49.075
METZELER
2.75 -18
3.00 -18

lumpsum 20% : 1400

Guo Qiy
82880282

28/6/18.

After repair photos.

3 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ATTN: Officer Incharge,

Pls arrange survey to inspect my FBG234G

Thks
Irene
67488645
27/6/18