



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 27.06.2018

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2885J TOYOTA VELLFIRE (2013)

To Supply

1) 1pc	Front bumper	\$ <i>le</i> 1,785.00
2) 1set	Front bumper clip	\$ <i>ne</i> 60.00
3) 1pc	Front bumper left retainer	\$ <i>ner</i> 120.35
4) 1pc	Front bumper left front sensor	\$ <i>x</i> 569.10
5) 1pc	Front bumper left front sensor cover	\$ <i>x</i> 44.50
6) 1pc	Front bumper left front tow hook cover	\$ <i>Ky</i> 59.80

Sub total parts	\$ 2,638.75
Less: 25% discount	\$ 659.68
	\$ 1,979.07

To Supply S.Nett Parts

1) 1pc	Front no. plate	\$ <i>X</i> 35.00
---------	-----------------	-------------------

Sub total S.Nett Parts	\$ 35.00
------------------------	----------

L/charges

1) To remove & refit front sensor, reset front sensor light. Check wiring. light. Check wiring	\$ <i>20</i> 40.00
2) To remove & replace front bumper. Align & adjust front bumper.	\$ <i>200</i> 250.00

3) To putty, respray painting front bumper, front sensor cover & tow hook
cover in pearl white. To polish

200
\$ 300.00

Sub total L/charges	\$ 590.00
Estimated Grand total	\$ 2,604.07

Tanpin 97495749

'wp'
26/6/18 @ 1020.

Longpin

Resurvey after repair

02 days

surellk auto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: