

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

FWD Singapore Pte Ltd

6 Temasek Boulevard

#18-01 Suntec Tower Four

Singapore 038986

*Not Wharfed
Penny B & pain*

ACCIDENT REPAIR ON : SKQ7188B

MODEL : OPEL INSIGNIA

POLICY NO : GA068895/1

CHASSIS NO : W0LGM5EE2A1130974

MANUFACTURING YEAR : 2011

DATE / TIME OF ACCIDENT : 24/06/2018 Time: 2050Hrs ALONG MALAYSIA CUSTOMS

THIRD PARTY VEHICLE NO : SJF4965P

Date: 28/06/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Front Bumper	1	1,450.00		1,450.00 X
2 Front Bumper Side Retainer LH	1	90.00		90.00 X
3 Front Bumper Side Retainer RH	1	90.00		90.00 X
4 Headlamp RH	1	1,600.00		1,600.00 X
5 Front Fender RH	1	800.00		800.00 ✓
6 Front Fender Shield RH	1	190.00		190.00 X
7 Side Mirror Assembly RH	1	1,400.00		1,400.00 ✓
8 Side Mirror Glass RH	1			-
9 Front Door Assy RH	1	1,800.00		1,800.00
10 Front Door Upper Hinge RH	1	200.00		200.00
11 Front Door Lower Hinge RH	1	200.00		200.00
12 Front Door Lock	1	400.00		400.00
13 Front Wheel Rim RH	1	1,200.00		1,200.00
14 Front Knuckle Arm RH	1	1,200.00		1,200.00
15 Front Knuckle Arm Bearing RH	1	550.00		550.00 X
16 Front Lower Arm RH	1	400.00		400.00
17 Front Stabilizer Link RH	1	90.00		90.00
18 Front Tie Rod RH	1	100.00		100.00
19 Front Tie Rod End RH	1	90.00		90.00
20 Front Absorber RH	1	350.00		350.00
21 Front Absorber Mounting RH	1	180.00		180.00
22 Front Absorber Stopper RH	1	65.00		65.00
23 Front ABS Sensor	1	180.00		180.00
Sub-Total:				12,625.00
Less Discount 10%				1,262.50
Total Parts:				11,362.50

Special Nett Items

<u>Other Parts Reqs:</u>						
1	Anti-rust coating		1	80.00	80.00	
2	Front Bumper Clips	~	12		-	X
3	Front Fender Shield Clips RH	~	12		-	X
4	Front Tyre RH		1	190.00	190.00	X
Total Parts:					<u>270.00</u>	

Labour Charges For Front and Side Portion

1 Provide skill labour to remove all damaged parts, panel beat, cut & weld	
--	--

- if necessary and align all panel and reinstall all damaged parts.
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
 - 3 Provide skill labour to disconnect and check electrical wiring
 - 4 Provide skill labour to check and re-adjust wheel alignment
 - 5 Provide skill labour to remove and replace wheel rim and tyre with balancing
 - 6 Provide skill labour to remove and replace window glass
 - 7 Provide skill labour to dismantle and transfer door fittings and mechanism to facilitate repair
 - 8 Provide skill labour to remove and replace/refit undercarriage

Total Labour:

Total Parts & Labour:

GST 7%

Grand Total:

4001
1,000.00

5001
800.00

60.00 201

nn 70.00 X

nn 80.00 X

160.00 } 601

80.00 }

nn 250.00 X

2,500.00

14,132.50

989.28

15,121.78

Estimate Repair Duration

10 days

4 days

ACCIDENT VEHICLE OF : SKQ7188B

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Kennerly

Company : LKK

Date : 9/7/18

Time : 3.05pm

Contact No: 96910663

Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: