

JAS Auto Services

6D Mandai Estate #03-02 M-Space, Singapore 729938

Tel: 6453 1967 (5 lines). Fax: 6457 3091

53255447K

M/s QBE Insurance(Singapore) Pte Ltd

1 Raffles Quay #29-10

Singapore 048583

Date : 02-Jul-18

Line: 62246633

Attn: Motor Claim Dept

Re: Accident on 20/06/2018. Between GBH684K AND GBE6688B(Your Insured).

Dear Sir;

We are pleased to submit herewith the estimate for repairs to the above mentioned accident damaged vehicle **Third Party Claim**.

Parts


1pc Rear door LH	1,462.30	\$1,530.60	CRU ✓
1pc Rear door RH		\$1,344.80	CRU ✓
1pc Rear door hinge LH	1,168.00	\$70.56	DM ✓
1pc Rear door hinge RH		\$70.56	DM ✓
1pc Rear door lock		\$150.60	BT ✓
1pc Rear door cable		\$85.60	DM ✓
1pc Rear bumper retainer LH		\$72.30	BR ✓
1pc Rear bumper retainer RH		\$72.30	BT ✓
1pc Rear bumper bracket LH		\$64.20	BD ✓
1pc Rear bumper bracket RH		\$64.20	X
1pc Taillamp LH		\$203.30	BR ✓
1pc Taillamp RH		\$203.30	BR ✓
1pc Taillamp panel LH		\$124.50	DIST ✓
1pc Taillamp panel RH		\$124.50	X
1pc Rear end panel		\$345.22	DIS ✓
1pc Rear end panel inner	485.40	\$850.10	BT ✓
1pc Spare tyre holder		\$90.60	R
1pc Clips S/N		\$50.00	NECV
1pc Front bumper		\$520.30	DD ✓
1pc Front number plate S/N		\$50.00	BT ✓
1pc Front reinforcement		\$535.00	BT ✓
1pc Headlamp LH		\$490.69	BR ✓
1pc Headlamp RH		\$490.69	BR ✓
1pc Radiator		\$368.58	DM ✓
1pc Condenser	427.40	\$675.20	DM ✓
1pc Bonnet lock		\$120.80	BT ✓
1pc Intercooler		\$1,855.65	BR ✓
1pc Spare tank		\$156.65	BR ✓
1pc Air intake hose		\$180.45	CUT ✓
1pc Reinforcement sponge		\$185.56	TN ✓
1pc Undercarriage garnish LH		\$123.50	CUT ✓
1pc Top panel		\$350.88	CRU ✓

Total:	\$11,621.19
Less: 10%	\$1,162.12
	<u>\$10,459.07</u>

To remove the affected parts, all relevant attachments, fittings to commence repairs, replace the damaged parts, reinstall & realign all necessary parts.
 To putty & respray paint on the relevant repaired areas.
 To rust proof affected areas where necessary.

\$1,800.00	1200.00
\$1,200.00	800.00
\$90.00	30.00

Parts & Labour Total: \$13,549.07

Your Faithfully,

 JAS AUTO SERVICES
 6D Mandai Estate
 #03-02 M-Space
 Singapore 729938
 JAS Auto Services

Sathya Sai
 4/7/2018

- Lump Sum Repair
 - Photo after paint

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JAS Auto Services

6D Mandai Estate #03-02 M-Space, Singapore 729938
Tel: 6453 1967 (5 lines). Fax: 6457 3091
53255447K

M/s QBE Insurance(Singapore) Pte Ltd
1 Raffles Quay #29-10
Singapore 048583

Date : 02-Jul-18

Line: 62246633

Attn: Motor Claim Dept

Re: Accident on 20/06/2018. Between GBH684K AND GBE6688B(Your Insured).

Dear Sir;

We are pleased to submit herewith the estimate for repairs to the above mentioned accident damaged vehicle Third Party Claim.

<u>Parts</u>	
1pc Rear door LH	1,462.30 \$1,530.60 CRU ✓
1pc Rear door RH	1,168.00 \$1,344.80 CRU ✓
1pc Rear door hinge LH	\$70.56 DM ✓
1pc Rear door hinge RH	\$70.56 DM ✓
1pc Rear door lock	\$150.60 BT ✓
1pc Rear door cable	\$85.60 DM ✓
1pc Rear bumper retainer LH	\$72.30 BR ✓
1pc Rear bumper retainer RH	\$72.30 BT ✓
1pc Rear bumper bracket LH	\$64.20 BD ✓
1pc Rear bumper bracket RH	\$64.20 X
1pc Taillamp LH	\$203.30 BR ✓
1pc Taillamp RH	\$203.30 BR ✓
1pc Taillamp panel LH	\$124.50 DIST ✓
1pc Taillamp panel RH	\$124.50 X
1pc Rear end panel	\$345.22 DIS ✓
1pc Rear end panel inner	485.40 \$850.10 BT ✓
1pc Spare tyre holder	\$90.60 R
1pc Clips S/N	\$50.00 NEG ✓
1pc Front bumper	\$520.30 DD ✓
1pc Front number plate S/N	\$50.00 BT ✓
1pc Front reinforcement	\$535.00 BT ✓
1pc Headlamp LH	\$490.69 BR ✓
1pc Headlamp RH	\$490.69 BR ✓
1pc Radiator	\$368.58 DM ✓
1pc Condenser	427.40 \$675.20 DM ✓
1pc Bonnet lock	\$120.80 BT ✓
1pc Intercooler	\$1,855.65 BR ✓
1pc Spare tank	\$156.65 BR ✓
1pc Air intake hose	\$180.45 CUT ✓
1pc Reinforcement sponge	\$185.56 TN ✓
1pc Undercarriage garnish LH	\$123.50 CUT ✓
1pc Top panel	\$350.88 CRU ✓


Total:	\$11,621.19
Less: 10%	\$1,162.12
	<u>\$10,459.07</u>

To remove the affected parts, all relevant attachments, fittings to commence repairs, replace the damaged parts, reinstall & realign all necessary parts.
 To putty & respray paint on the relevant repaired areas.
 To rust proof affected areas where necessary.

\$1,800.00	1200.00
\$1,200.00	800.00
\$90.00	30.00

Parts & Labour Total: \$13,549.07

Your Faithfully,


 JAS AUTO SERVICES
 6D Mandai Estate
 #03-02 M-Space
 Singapore 729938
 JAS Auto Services

Sathya Sai
 4/7/2018

- Lump Sum Repair
 - Photo after paint

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

10484.29
- 10%
<u>9435.861</u>
+ 1200.00
+ 800.00
+ 30.00
<u>11465.861</u>
- 20%

Page 2

L/S = \$ 9200 @ 8 days
 confirmed.

= 9172.69