

15/5/2011

INS. CASE OWNER:

CCP/III1801

1279, Fub302

LKK:

IDAC:

Surveyor:

Fenneth

DOI:

27/6/18

Date / Time:

27/6/18

Registered in Merimen:

27/6/18

Pre-assign / CCU / FTE

XE 955J

Claim No.:

MLW10/256V

Insured Vehicle No.:

WHTI WAM PETROLEUM HAWAII

Policy No.:

MY 93364

Name of Insured:

Insured Tel No.:

HP:

Make / Model:

MARD

Excess Sec II :SS

D.O.A.:

Place of Accident:

DUNGEREN RD

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age: MOHAMAD JAHNUN BIN ABUL

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.: 88086080

(V/L) YES / NO )

Insured Liability: %

Final ? Yes / No

SCY 9811A

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:POON  
SIANG  
SEOWINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

27/6/18  
TH

SUGGESTION - X

XE 955J - X

OI change lane and collided onto  
TP vehicle.

RECEIVED 17 JUL 2018

RECEIVED 01 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOB:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 27/7/18

Confirm with ALBERT

Email

Call

Final Liability:

%

100 (Agreed)

Assessed) BOLA S/N No. : 15

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

5600.00

Loss of Rental (LOR):

S\$

1155.60

( 6 days)

x180+ast

Loss of Use (LOU):

S\$

(S x days)

Loss of Income (LOI):

S\$

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent )

Legal Cost

S\$

Total:

S\$

6763.05

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

6763.05

Name 1:

POON SIANG SEOW

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1/8/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASS. REC. BY:

REF: 11 /

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

06 days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SCY 8811AYr Regn: Feb 12 2009Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: MerS300c.c. 2997Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading 176748

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD 2211542A 253404Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: \_\_\_\_\_

R: 235/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 5 mmL/Bal. 6 mmL/Bal. 5 mmD.O.A. 1/18D.O.I. 27/6/18

Survey held at \_\_\_\_\_

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/6

File pass to Catherine, GIA not ready

LIS - \$5600+ (Red. \$6406.00 / 53%.)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trlp: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS. \$

Photos

Others

TOTAL

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I.: (\$




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18011779/Kub3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 28-06-2018		
		Code : III2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XE 955J	Veh. Inspected	SCY 9811A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	27/06/2018	Inspection Date	27/06/2018	
Survey held at	POON SIANG SEOW No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**Catherine Chong (LKK Auto)**

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Wednesday, 27 June, 2018 1:45 PM  
**To:** Albert Poon; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Lalitha Krishnan - III  
**Subject:** RE: Emailing: SCY9811A  
**Attachments:** SCY9811A.PDF

Dear Sir / Mdm,

*SCY9811A*

Please conduct a survey on TP vehicle SHD2878E and let us have your report urgently.

This claim will be handled by Ms Lalitha.

\*Kindly upload this survey request email to merimen.

Thank You.

*27062018 @ 1:54pm*

*Albert vehin*

*Kenneth*

Best Regards,  
Gabriel Wee  
Motor Claims Dept.  
India International Insurance Pte Ltd  
64 Cecil Street | #05 IOB Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

-----Original Message-----

From: Albert Poon [mailto:sitti1@singnet.com.sg]  
Sent: 27 June, 2018 12:04 PM  
To: Motor Claim - III <motorclaim@iii.com.sg>  
Subject: RE: Emailing: SCY9811A

Hi sir  
Please send lkk auto consultants pte ltd

Thanks

Albert  
M: 96169634, 8458 1169

POON SIANG SEOW  
Sin Ming Autocity  
No.160 Sin Ming Drive, #05-13, S(575722)  
Tel: 6453 7511 Fax:6453 8046  
Email: sitti1@singnet.com.sg

-----Original Message-----

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]  
Sent: Wednesday, 27 June, 2018 11:28 AM

To: Albert Poon <sitti1@singnet.com.sg>

Subject: RE: Emailing: SCY9811A

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- \* Automobile Inspection Services Pte Ltd
- \* Autoprobe Consultants
- \* VP Appraisal
- \* Quantum Risk Management
- \* Ajax Inspection Services Pte Ltd
- \* Form Team Adjusters Pte Ltd
- \* Infiniti Appraisal Service
- \* JP Knights Adjusters
- \* LBS Auto Consultants Pte Ltd
- \* Premier Appraisers Services
- \* Priority Services
- \* RT Appraisal
- \* LKK Auto Consultants Pte Ltd
- \* Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,  
Gabriel Wee  
Motor Claims Dept.  
India International Insurance Pte Ltd  
64 Cecil Street | #05 IOB Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

-----Original Message-----

From: Albert Poon [mailto:sitti1@singnet.com.sg]

Sent: 27 June, 2018 11:09 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Emailing: SCY9811A

HI SIR

Please get your guy to come and inspect the vehicle

Thanks

Albert

M: 96169634, 8458 1169

POON SIANG SEOW

Sin Ming Autocity

No.160 Sin Ming Drive, #05-13, S(575722)

Tel: 6453 7511 Fax:6453 8046

Email: sitti1@singnet.com.sg

Your message is ready to be sent with the following file or link attachments:

SCY9811A

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.  
Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



[> Back to OneMotoring](#)

### Enquire Transfer Fee

#### Vehicle Details

Vehicle No. :	SCY9811A
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	MERCEDES BENZ
Vehicle Model :	S300L
Chassis No. :	WDD2211542A253404
Propellant :	Petrol
Engine No. :	27294631041491
Engine Capacity :	2997 cc
Maximum Power Output :	170.0 kW ( 227 bhp )
Maximum Laden Weight :	2505 kg
Unladen Weight :	1850 kg
Year Of Manufacture :	2008
Original Registration Date :	26 Feb 2009
Lifespan Expiry Date :	-
COE Category :	B - Car (1601cc & above)
Quota Premium :	\$4,889.00
COE Expiry Date :	25 Feb 2019
Road Tax Expiry Date :	25 Feb 2019
PARF Eligibility Expiry Date :	25 Feb 2019
Inspection Due Date :	25 Feb 2020
Intended Transfer Date :	16 Jul 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

#### Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

You may print this page for reference.

[OK](#)
[Print](#)



# 方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitt11@singnet.com.sg Regn. No. 05396600K

Ng Boo Wui  
24 Fourth Avenue  
Singapore 268664

*Not work  
11 Sep 8 5600h  
Repair After Paint  
6 days*

Dear sir

Estimate cost of repair to vehicle no. SCY 9811A

To supply

1. Rear tail lamp *545.00*
2. Tail lamp panel
3. Rear fender
4. Rear fender inlet air
5. Rear fender outer garish
6. Rear fender inner garish
7. Rear bumper *1840.*
8. Rear bumper moulding x2
9. Rear bumper retainer x2
10. w/s moulding
11. Rear bumper inner part

<i>CR</i>	989.00nett	✓
<i>R</i>	380.00nett	X
<i>B</i>	3,280.00nett	✓
<i>IL</i>	135.00nett	X
<i>IL</i>	320.00nett	X
<i>IL</i>	450.00nett	X
<i>IL</i>	1,946.00nett	✓
<i>IL</i>	212.00nett	✓
<i>IL</i>	164.00nett	✓
<i>IL</i>	230.00nett	✓
<i>IL</i>	250.00nett	X

Labour charges

Rust proofing

Panel beating

Spray painting

To remove and refit raer w/s glass and

Cushion

100.00 *300*  
1,800.00 *800*  
1,200.00 *500*  
550.00 *120*

Total

*11,454.00 12006*

Your faithfully

*for*

ALBERT POON

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:





# 方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Ng Boo Wui  
24 Fourth Avenue  
Singapore 268664

*Not withark*  
*11 Sep 8*  
*Re survey After Paint*  
*6 days*

Dear sir  
Estimate cost of repair to vehicle no. SCY 9811A

To supply

1. Rear tail lamp
2. Tail lamp panel
3. Rear fender
4. Rear fender inlet air
5. Rear fender outer garish
6. Rear fender inner garish
7. Rear bumper
8. Rear bumper moulding x2
9. Rear bumper retainer x2
10. w/s moulding
11. Rear bumper inner part

<i>CR</i>	989.00nett	✓
<i>R</i>	380.00nett	X
<i>B</i>	3,280.00nett	✓
	135.00nett	?
<i>I</i>	320.00nett	?
<i>Sm</i>	450.00nett	X
<i>B</i>	1,946.00nett	✓
<i>m</i>	212.00nett	✓
<i>ols p.1</i>	164.00nett	✓
<i>m</i>	230.00nett	✓
<i>Sm</i>	250.00nett	X

*108*

Labour charges

Rust proofing

Panel beating

Spray painting

To remove and refit raer w/s glass and

Cushion

100.00 *300*  
1,800.00 *800*  
1,200.00 *500*

550.00 *1200*

Total

*11,456.00*

Your faithfully

*for*

ALBERT POON

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:





## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jun 2018 <a href="#">Edit Reg</a>		27 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	<b>WATT WAH PETROLEUM HAULAGE PTE LTD</b> , Co. Reg. No.: -								
Main Claimant:	<b>NG BOO WUI</b> , ID: S14501008								
Vehicle Reg. No.:	<b>SCY9811A</b>	Date of Loss:	27/06/2018 00:00 - :59 [ <b>112</b> Months and <b>1</b> Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MC2018/2562</b>	Policy/Cover Note No.:	M496364 (Third Party Only)						
Vehicle Reg. No. (Insured):	<b>XE955J</b>	Policy No. (Claimant):	DMPG18000314						
		Excess:							
Repairer:	<b>Poon Siang Seow (HQ)</b> 160 Sin Ming Drive, #05-13 Sin Ming AutoCity, 575722 Sin Ming - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Lalitha Krishnan</b> - 6347 6139]								
Claimant's Insurer:	<b>ERGO Insurance Pte. Ltd. (HQ)</b> - Tel: 6829 9199								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 09/07/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>III_SG (30/07/2018): Alert - Adj Mandate Approved (S\$6763.05) - SCY9811A - Claim Handler: Lalitha Kri...</li> <li>III_SG (20/07/2018): Alert - Adj Mandate Approved (S\$6249.45) - SCY9811A - Claim Handler: Lalitha Kri...</li> <li>III_SG (06/07/2018): Alert - Adj Mandate Approved (S\$0.00) - SCY9811A - Claim Handler: Lalitha Krishn...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SCY9811A (MC2018/2562)  
[XE955J]  
TP  
NG BOO WUI  
Jun 27 2018 12:00AM  
[WATT WAH PETROLEUM HAULAGE PTE LTD]  
Poon Siang Seow

Upload Documents			Upload Photos			Compose New Letter			View		Use Viewer	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
2	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
3	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
4	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
5	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
6	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
7	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
8	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
9	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
10	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
11	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
12	20/07/18 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
									1 per page		<input checked="" type="checkbox"/>	
Documentation												
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	28/06/18 16:10	EMAIL FROM III DD 27062018								Load PDF		
2	28/06/18 17:57	TP ESTIMATE- MARKED								Load PDF		
3	02/07/18 10:35	TP GIA REPORT								Load PDF		
4	18/07/18 11:55	LTA SEARCH								Load PDF		
5	18/07/18 11:55	LOD								Load PDF		
6	02/08/18 15:30	AUTHORISATION TO ACT FORM								Load PDF		
7	02/08/18 15:30	DISCHARGE VOUCHER								Load PDF		
8	02/08/18 15:30	WORKSHOP INVOICE								Load PDF		
9	02/08/18 15:30	RENTAL RECEIPT								Load PDF		
No	Finalized On	India International Insurance Pte Ltd (HQ)								Thumbnail	Print	
1	29/06/18 14:30	Singapore Accident Statement-IV								Load PDF		

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid #ccc; height: 100px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18011779/KUB3N2

Date: 02/08/2018

## REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	M496364
Claimant Vehicle No :	SCY9811A	Insured Vehicle No :	XE955J
Date of Loss:	27/06/2018	Nature of Claim:	TP
		Claim No:	MC2018/2562

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SCY9811A	Engine No:	27294631041491
Make & Model:	MERCEDES-BENZ S300, 3.0 (A)	Chassis No:	WDD2211542A253404
Reg. Date:	26/02/2009 (Man. Year: 2008)	Odometer:	176748 km
Colour:	Metallic Black		
Engine Capacity:	2997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	235/55 R17	Rear Tyre Size:	235/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,356.00	5,570.10	2,785.90	33.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,450.00	2,200.00	60.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,006.00</b>	<b>7,020.10</b>	<b>4,985.90</b>	<b>41.53</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,006.00</b>	<b>5,600.00</b>	<b>6,406.00</b>	<b>53.36</b>
<b>+ Car Rental (6.0 x S\$180.00/day + 7.00% GST) (S\$)</b>		1,155.60		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>6,763.05</b>		

## INSPECTION

Date of Assignment:	27/06/2018	
Date Inspected:	27/06/2018 Inspected At:	Poon Siang Seow (HQ) 160 Sin Ming Drive, #05-13 Sin Ming AutoCity Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: THIN THIN HLAING



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2018)
<b>Parts:</b> 143	MERCEDES-BENZ S300 3.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SCY9811A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL LAMP	Cracked	989.00 F	*545.00 FN
2	1		*TAIL LAMP PANEL	Repair	380.00 F	*- FN
3	1		*REAR FENDER	Bent	3,280.00 F	*3,280.00 FN
4	1		*REAR FENDER INLET AIR	Serviceable	135.00 F	*- FN
5	1		*REAR FENDER OUTER GARISH	Serviceable	320.00 F	*- FN
6	1		*REAR FENDER INNER GARISH	Serviceable	450.00 F	*- FN
7	1		*REAR BUMPER	Bent	1,946.00 F	*1,840.00 FN
8	2		*REAR BUMPER MOULDING	Necessary	212.00 F	*212.00 FN
9	1		*REAR BUMPER RETAINER	O/S Distorted	164.00 F	*82.00 FN
10	1		*W/S MOULDING	Necessary	230.00 F	*230.00 FN
11	1		*REAR BUMPER INNER PART	Serviceable	250.00 F	*- FN

F=Franchise part. N=NetItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,356.00</b>	<b>6,189.00</b>
<b>- Nett Item Discount on N Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>618.90</b>
<b>Total Parts (\$\$)</b>	<b>8,356.00</b>	<b>5,570.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RUST PROOFING	New	100.00	30.00
2	PANEL BEATING	New	1,800.00	800.00
3	SPRAY PAINTING	New	1,200.00	500.00
4	TO REMOVE AND REFIT REAR W/S GLASS AND CUSHION	New	550.00	120.00
Gross Labour Cost (\$\$)			3,650.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >