



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Ng Boo Wui
24 Fourth Avenue
Singapore 268664

Not withash
61 Sep 8
Re survey After Paint
6 days

Dear sir
Estimate cost of repair to vehicle no. SCY 9811A

To supply

1. Rear tail lamp
2. Tail lamp panel
3. Rear fender
4. Rear fender inlet air
5. Rear fender outer garish
6. Rear fender inner garish
7. Rear bumper
8. Rear bumper moulding x2
9. Rear bumper retainer x2
10. w/s moulding
11. Rear bumper inner part

cm	989.00nett	✓
n	380.00nett	x
B	3,280.00nett	✓
	135.00nett	?
	320.00nett	?
sm	450.00nett	x
B	1,946.00nett	✓
m	212.00nett	✓
ols	164.00nett	✓
m	230.00nett	✓
sm	250.00nett	x

108

Labour charges
Rust proofing
Panel beating
Spray painting
To remove and refit raer w/s glass and
Cushion

100.00 *3cl*
1,800.00 *800l*
1,200.00 *500l*
550.00 *12cl*

Total

11,456.00

Your faithfully

for

ALBERT POON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: