



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

**ESTIMATION REPORT**

**Vehicle No** : SGM9007X  
**Make & Model** : TOYOTA,COROLLA ALTIS 1.6  
 AUTO,MR053ZEC107133660  
**Year of Manufacture** : 2006

**Estimation No.** : E18060054  
**DOA** : 26/06/2018

No	Description	Qty	U/P	Amt
<b>Section: List Items</b>				
1	Rear fender (LH) X Repair.	1.00	1,012.30	1,012.30
2	Rear fender cowling (LH) X	1.00	89.90	89.90
3	Rear fender inner trim (LH) X	1.00	390.80	390.80
4	Rear door (LH) X Repair.	1.00	1,038.00	1,038.00
5	Rear door lock (LH) X	1.00	0.00	0.00
6	Rear door hinge-up (LH) X	1.00	89.90	89.90
7	Rear door hinge-down (LH) X	1.00	89.90	89.90
8	Rear door checker X	1.00	92.70	92.70
9	Rear door weather strip (LH) X	1.00	182.70	182.70
10	Rear door protector (LH) / Ser	1.00	181.20	181.20
11	Rear door protector chrome piece (LH) - mbc	1.00	92.90	92.90
12	Rear door window moulding (LH) X	1.00	192.70	192.70
13	Rear door power window gear (LH) X	1.00	323.70	323.70
14	Rear door power window motor (LH) X	1.00	396.50	396.50
15	Rear door handle (LH) X	1.00	0.00	0.00
16	Rocker panel / side skirt (LH) X Repair	1.00	591.80	591.80
17	Front door (LH) / BT	1.00	867.20	867.20
18	Front door hinge-up (LH) X	1.00	89.90	89.90
19	Front door hinge-down (LH) X	1.00	89.90	89.90
20	Front door lock (LH) X	1.00	0.00	0.00
21	Front door checker (LH) X	1.00	92.70	92.70
22	Front door protector (LH) / Ser	1.00	210.00	210.00
23	Front door protector chrome piece (LH) - mbc	1.00	92.90	92.90
24	Front door weather strip (LH) X	1.00	0.00	0.00
25	Front door inner weather strip (LH) X	1.00	0.00	0.00

Continue on next page...



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

**ESTIMATION REPORT**

**Vehicle No** : SGM9007X  
**Make & Model** : TOYOTA,COROLLA ALTIS 1.6  
 AUTO,MR053ZEC107133660  
**Year of Manufacture** : 2006

**Estimation No.** : E18060054  
**DOA** : 26/06/2018

No	Description	Qty	U/P	Amt
26	Front door window garnish - black (LH) X	1.00	0.00	0.00
27	Front door window moulding (LH) X	1.00	192.90	192.90
28	Front door power window motor (LH) X	1.00	694.30	694.30
29	Front door power window gear (LH) X	1.00	414.50	414.50
30	Front door inner trim board (LH) X	1.00	1,201.00	1,201.00
31	Rear absorber (LH) X	1.00	261.70	261.70
32	Rear bearing (LH) X	1.00	496.70	496.70
33	Rear knuckle (LH) X	1.00	383.20	383.20
34	Rear lower arm (LH) X	1.00	0.00	0.00
35	Rear axle (LH) X	1.00	0.00	0.00

**Amt** S\$ 9,851.90  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 9,851.90

**Section: Special Nett Items**

36	Rear fender cowling clip (LH) X	1.00	50.00	50.00
37	Rear fender inner trim clip (LH) X	1.00	50.00	50.00
38	Rear fender sealant X	1.00	80.00	80.00
39	Front door inner trim board clips (LH) X	1.00	50.00	50.00
40	Rear rim (LH) X	1.00	900.00	900.00
41	Rear tyre (LH) X	1.00	500.00	500.00

**Amt** S\$ 1,630.00  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 1,630.00

**Section: Labour Items**

42	To R&R accident affected areas	1.00	1,000.00	1,000.00
43	To putty & respray accident affected areas	1.00	1,000.00	1,000.00

400  
800

Continue on next page...



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

**ESTIMATION REPORT**

**Vehicle No** : SGM9007X  
**Make & Model** : TOYOTA,COROLLA ALTIS 1.6  
AUTO,MR053ZEC107133660  
**Year of Manufacture** : 2006

**Estimation No.** : E18060054  
**DOA** : 26/06/2018

No	Description	Qty	U/P	Amt
44	To rust proof accident affected areas	1.00	60.00	60.00
45	To R&R front & rear door mechanism	1.00	160.00	160.00
46	To R&R rear under carriage	1.00	280.00	280.00
47	To do wheel alignment - before	1.00	120.00	120.00
48	To do wheel alignment - after	1.00	120.00	120.00

40  
60  
X  
X  
X

**Amt** S\$ 2,740.00  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 2,740.00

4 Days.

Lumpsum Repair

After repair photos.

Can. Kiay - 82880282

29/6/18

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**List Items Subtotal** S\$ 9,851.90  
**Special Nett Items** S\$ 1,630.00  
**Subtotal**  
**Labour Items Subtotal** S\$ 2,740.00  
**Total** S\$ 14,221.90