

ASS. REC. BY:

REF:

TM, / CC3/TM18011781/Kvb2

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5039X

Yr Regn:

12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour:

m. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

448690

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL15AUC 276037

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

M11 / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

23/6/18

D.O.I.

27/6/18

Survey held at

Des. of Damages: Fit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/6 File pass to Catherine  
 28/6/18 C/LR 8 6700 (Red 73,024.38, 9290)  
 29/6/18 Email GIA to TMI

SHC 5039X NA/HSS 09025139/W1  
 SLG 5099Y X

CLF 071109

RECEIVED 29 JUN 2018

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 29/6 - typist

Days Of Repair:

3

Resurvey No. of Trip:

-

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

250

S + RS. \$

10

Photos

Others

TOTAL

260

Report Format:

merimen

Lump Sum / I.B.I. (\$

6700/2

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2018		29 Jun 2018 10:48 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>						
Insured:	<b>JEE SEK HWEE</b> , ID: S0484703B, Tel: +6590045201, Email: ROBERTJEE2002@YAHOO.COM.SG								
Main Claimant:	<b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	<b>SHC5039X</b>	Date of Loss:	23/06/2018 21:00 - :59						
Claim Type:	<b>TP / M1803151</b>	Policy/Cover Note No.:	MV008843 (Comprehensive) Coverage: 05/10/2017 - 04/10/2018						
Vehicle Reg. No. (Insured):	<b>SLG5699Y</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Trans-cab Auto Services Pte Ltd (Ang Mo Kio)</b> 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Dillen Senthilan so Selvarajoo</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 10/07/2018]</b>								
Driver/Custodian (Insured):	JEE SEK HWEE (70 / Male), NRIC: S0484703B, Tel: +6590045201								
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE,THKS								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 29 June 2018 8:30 AM  
**To:** motorclaims@tokiomarine.com.sg  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 23/6/2018, SHC 5039X (TP VEHICLE), SLG 5699Y (OI VEHICLE)  
**Attachments:** EST.pdf; GIA.pdf; POLICE REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5039X , M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 27/6/2018

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

### Vehicle Details

Vehicle No.:	SHC5039X
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Jun 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000635
Chassis No.:	VF1ABL15AUC276037
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	02 Dec 2013
First Registration Date:	02 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Dec 2021
PARF Rebate Amount:	\$9,373.00

### Intended COE Rebate Details

COE Expiry Date:	01 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$62,740.00
COE Rebate Amount:	\$26,903.00
<b>Total Rebate Amount:</b>	<b>\$36,276.00</b>

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Jun 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/06/2018 16:06
Date Of Accident	23/06/2018 21:00
Exact Location Of Accident	JOO CHIAT PLACE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5039X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	TAN KIN HOCK
NRIC No	S6800146C
Date Of Birth	02/01/1968
Occupation	OUTDOOR
Date Of Driving Pass	30/07/2003
Driving Experience	14 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97646808
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 590A MONTREAL LINK #13-29
Postcode	751590
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180626/2087

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG5699Y
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name TAN KIN HOCK

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5039X

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Sketch Plan #2 Pg. 1

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

---

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180626/2087

1 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180626/2087

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 26/06/2018 14:30		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: tan kin hock			Address: SINGAPORE 751590		
ID Type / ID No.: NRIC NO / S6800146C			Contact No.: Home/Office: Mobile: 97646808		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 50	Date of Birth: 02/01/1968	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 23/06/2018 21:00	Type of Location: X-Junction
Location: Along Road 1 JOO CHIAT PLACE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHC5039X	Car	RENAULT	LATITUDE 2.0L DCI AUTO D/AB 4DR	Red	Seriously Damaged	0
SLG5699Y	Car	HONDA	CIVIC 1.5 TURBO VTIS SR	Grey	Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20180626/2087

2 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180626/2087

**CONTINUATION OF REPORT**

**Brief Details.**

I was travelling along joo chiat place towards joo chiat road. When I reach the x junction of joo chiat place and tenbeling road. suddenly got 1 car coming out from tenbeling road and I hit onto his rear right side. I did jam brake but there isn't enough time to stop. after that he shift his car away and we got off and exchange particulars. I felt dizzy and at that time there police car so I asked them stop. They ask if I need medical attention, I told them if around 10 minutes later I still feel dizzy then I will go hospital. but ultimately I was still send to hospital. I was send to CGH and was given 17 days of MC. I wished to state that he's suppose to stop at the white line but he didn't and he was driving really fast.



**SINGAPORE  
POLICE FORCE**



T/20180626/2087

3 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180626/2087

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

TP /  
NG JIN SHENG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

26/06/2018 14:30

Officer In Charge Of Case:

TP / GIT /  
SI THABAGESH JEYATHESH  
Contact No.: 65476232

Classification Of Case:

Authentication Stamp

NP168



**SINGAPORE  
POLICE FORCE**

Signature:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5039X****AAD1806-252***Not Authored  
61 Sep @ 6700L*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHC 5039X**  
VF1ABL15AUC276037  
RENAULT  
LATITUDE  
23.6.2018  
*BKio*

**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>CM</i>	1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>SL</i>	181.75	} X
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i>	394.68	
4	1	BUMPER RETAINER FRT LH	\$	<i>SL</i>	151.41	
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i>	123.88	
6	1	BUMPER RETAINER FRT RH	\$	<i>SLC DIX</i>	150.77	
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i>	123.88	
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i>	472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i>	266.80	} X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i>	207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i>	207.21	
12	1	BUMPER BEAM FRT	\$	<i>R</i>	914.08	
13	1	TOW COVER FRT	\$	<i>RM</i>	28.61	✓
14	1	RADIATOR GRILLE	\$	<i>CM</i>	1,707.78	✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>RM</i>	225.36	✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i>	1,353.75	✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i>	615.90	✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	X
19	1	FRONT BRACE PANEL	\$	<i>R</i>	177.22	X
20	1	HORN	\$	<i>SL</i>	314.17	X
21	1	HORN BRACKET	\$	<i>R</i>	40.45	X
22	1	HEADLAMP LH	\$	<i>RM</i>	1,184.43	✓
22	1	HEADLAMP HARNESS	\$	<i>SL</i>	928.29	X
22	1	HEADLAMP RH	\$	<i>M3CM</i>	1,184.43	✓
22	1	HEADLAMP HARNESS	\$	<i>SL</i>	928.29	X
22	1	HEADLAMP PANEL FRT LH	\$	<i>R</i>	152.15	X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i>	152.15	X
26	1	BONNET	\$	<i>R</i>	1,941.63	X

**Trans-cab Auto Services Pte Ltd****AAD1806-252**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5039X**

27	1	BONNET INSULATOR	\$	Su	405.73
28	1	BONNET STRUT LH	\$	Su	88.61
29	1	BONNET STRUT RH	\$	Su	88.61
30	1	BONNET HINGE LH	\$	W	348.31
31	1	BONNET HINGE RH	\$	W	348.31
32	1	BONNET LOCK	\$	W	305.48
33	1	BONNET CABLE	\$	Su	119.19
34	1	BONNET CABLE COVER	\$	Su	161.03
35	1	BONNET SEAL OUTER	\$	Su	92.36
36	1	BONNET SEAL INNER	\$	Su	157.28
37	1	FENDER PANEL FRT LH	\$	W	783.83
38	1	FENDER PANEL FRT RH	\$	W	783.83
39	1	WHEELARCH FRT LH	\$	Su	278.84
40	1	WHEELARCH FRT RH	\$	Su	278.84
41	1	FENDER BRACKET LOWER LH	\$	Su	15.79
42	1	FENDER BRACKET LOWER RH	\$	Su	15.79
43	1	FENDER INSULATOR LH	\$	Su	130.84
44	1	FENDER INSULATOR RH	\$	Su	130.84
45	1	WIPER RESERVOIR	\$	Su	348.25
46	1	WIPER RESERVOIR NECK	\$	Su	136.11
47	1	WIPER RESERVOIR MOTOR	\$	Su	270.06
48	1	AIR CLEANER LOWER	\$	Su	271.26
49	1	AIR CLEANER HOSE	\$	Su	76.14
55	1	ENGINE TOP COVER 2.0	\$	Su	555.12
56	1	ENGINE OIL SUMP	\$	Su	484.67
58	1	BASE BATTERY TRAY	\$	Su	363.40
59	1	AIR CLEANER BOX	\$	Su	464.20
60	1	TURBO DUCT	\$	Su	1,027.80
61	1	A/C HEATER VALVE	\$	Su	484.50
63	1	SUBFRAME OUTER FRT	\$	Su	2,652.45
64	1	SUBFRAME BRACKET OUTER LH	\$	Su	92.36
65	1	SUBFRAME BRACKET OUTER RH	\$	Su	92.36
66	1	ENGINE UNDERTRAY	\$	Su	564.98
67	1	A/C CONDENSER	\$	Su	2,020.37
68	1	A/C CONDENSER GARNISH LH UPPER	\$	Su	39.67
69	1	A/C CONDENSER GARNISH RH UPPER	\$	Su	39.67
70	1	A/C CONDENSER GARNISH LH	\$	Su	58.81
71	1	A/C CONDENSER GARNISH RH	\$	Su	59.60

**Trans-cab Auto Services Pte Ltd****AAD1806-252**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5039X**

72	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39
73	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72
74	1	A/C PIPE COMPRESSOR	\$	334.29
75	1	A/C PIPE	\$	658.72
76	1	A/C COMRPRESSOR	\$	2,684.61
77	1	AIR COOLER	\$	792.60
78	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13
79	1	AIR INTERCOOLER HOSE (Short)	\$	375.14
80	1	TRANSMISSION COOLER	\$	1,219.30
81	1	TRANSMISSION COOLER PAD	\$	17.96
82	1	RADIATOR	\$	1,202.20
83	2	RADIATOR STUD UPPER	\$	14.41
84	2	RADIATOR BUSH UPPER	\$	50.12
85	2	RADIATOR MTG LOWER	\$	55.85
86	1	RADAITOR FAN COWLING	\$	820.54
87	1	RADIATOR FAN MOTOR LH	\$	967.36
88	1	RADIATOR FAN MOTOR RH	\$	1,479.46
89	1	RADIATOR TANK	\$	324.62
90	1	RADIATOR HOSE UPPER	\$	240.56
91	1	RADIATOR HOSE LOWER	\$	491.18
92	1	RADIATOR TANK HOSE	\$	61.18
93	1	WINDSCREEN FRT	\$	1,364.06
94	1	AUTO COMPUTER	\$	5,032.17
95	1	INJECTION COMPUTER	\$	4,706.30
96	1	RHD HYDRAULIC POWER(RQCK&PINION)	\$	5,154.52
97	1	STEERING PUMP ELECTRIC	\$	2,306.90
98	1	STEERING PINION RACK	\$	4,413.11
99	1	ENGINE HARNESS	\$	4,084.54

<b>TOTAL</b>	<b>\$</b>	<b>70,846.53</b>
<b>10%</b>	<b>\$</b>	<b>7,084.65</b>
	<b>\$</b>	<b>63,761.88</b>

**Specical Nett**

1	1SET RADIATOR GRILLE FRAME CLIP	\$	52.00
2	1SET BUMPER CLIP FRT	\$	66.00

**Trans-cab Auto Services Pte Ltd****AAD1806-252**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5039X**

3	1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i>	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i>	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i>	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i>	10.50	
7	1	TOW COVER FRT	\$	<i>Asm</i>	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	<i>na</i>	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i>	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i>	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i>	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i>	30.00	
21	1	Windscreen moulding	\$	<i>na</i>	100.00	} <i>45.50</i>
22	1SET	Front licence plate with holder	\$	<i>Bro</i>	80.00	

<b>TOTAL</b>	<b>\$</b>	<b>562.50</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>64,324.38</b>

Panel beating, knocking and straightening the  
necessary portion, remove and renewal of parts,  
adjust and realign the same

\$ *5000*  
5,400.00

Towing Fees.

\$ 120.00 *500*

To apply paint protection system (PPS) maintain  
and enhancement

\$ *na* 380.00 X

Putty and spray painting of the affected portion.

\$ 5,000.00 *6600*

To rust-proofing of the affected areas.

\$ *na* 170.00 X

To remove and refit interior fittings, trimings,  
garnish, fittings and other, to enable repair.

\$ *na* 380.00 X

To check steering geometry and computer wheel  
alignment

\$ *na* 220.00 X



**Trans-cab Auto Services Pte Ltd****AAD1806-252**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5039X**

To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To lift-up engine with gear box and refit.	\$	440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	X
To remove and refit air bag system and reset.	\$	480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	<del>101</del>
To replace, refix and top up coolant for radiator	\$	170.00	<del>501</del>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary repair cost is subject to final approval from Insurance Company

**TOTAL \$ 15,400.00****Over All Total \$ 79,724.38****Repair Days (LUMP SUM)****20 DAYS****3 days**

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18011781/KVBN2

Date: 03/07/2018

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MV008843
Claimant Vehicle No :	SHC5039X	Insured Vehicle No :	SLG5699Y
Date of Loss:	23/06/2018	Nature of Claim:	TP
		Claim No:	M1803151

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHC5039X	Engine No:	M9R8839C000635
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC276037
Reg. Date:	02/12/2013 (Man. Year: 2013)	Odometer:	448690 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	64,324.39	6,966.71	57,357.68	89.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,400.00	1,380.00	14,020.00	91.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>79,724.39</b>	<b>8,346.71</b>	<b>71,377.68</b>	<b>89.53</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,700.00</b>		
<b>(S\$)</b>	<b>79,724.39</b>	<b>6,700.00</b>	<b>73,024.39</b>	<b>91.60</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>5,580.71</b>	<b>469.00</b>	<b>5,111.71</b>	<b>91.60</b>
<b>Nett Amount (S\$)</b>	<b>85,305.10</b>	<b>7,169.00</b>	<b>78,136.10</b>	<b>91.60</b>

## INSPECTION

Date of Assignment:	29/06/2018	
Date Inspected:	27/06/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2018)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5039X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER FRT	Cracked	1,259.42 FL	*1,259.42 FL
2	1	*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1	*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1	*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*- FL
5	1	*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1	*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*- FL
7	1	*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
8	1	*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
9	1	*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
10	1	*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
11	1	*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
12	1	*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
13	1	*TOW COVER FRT	Dented	28.61 FL	*28.61 FL
14	1	*RADIATOR GRILLE	Cracked	1,707.78 FL	*1,707.78 FL
15	1	*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
16	1	*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
17	1	*FRAME FULL SUPPORT PANEL	Cracked	615.90 FL	*615.90 FL
18	1	*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
19	1	*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
20	1	*HORN	Serviceable	314.17 FL	*- FL
21	1	*HORN BRACKET	Repair	40.45 FL	*- FL
22	1	*HEADLAMP LH	Dented	1,184.43 FL	*1,184.43 FL
23	1	*HEADLAMP HARNESS	Serviceable	928.29 FL	*- FL
24	1	*HEADLAMP RH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
25	1	*HEADLAMP HARNESS	Serviceable	928.29 FL	*- FL
26	1	*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
27	1	*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*- FL
28	1	*BONNET	Repair	1,941.63 FL	*- FL
29	1	*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
30	1	*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
31	1	*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
32	1	*BONNET HINGE LH	Repair	348.31 FL	*- FL
33	1	*BONNET HINGE RH	Repair	348.31 FL	*- FL
34	1	*BONNET LOCK	Repair	305.48 FL	*- FL
35	1	*BONNET CABLE	Serviceable	119.19 FL	*- FL
36	1	*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
37	1	*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
38	1	*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
39	1	*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
40	1	*FENDER PANEL FRT RH	Repair	783.83 FL	*- FL
41	1	*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
42	1	*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
43	1	*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
44	1	*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*-FL
46	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*-FL
47	1		*WIPER RESERVOIR	Serviceable	348.25 FL	*-FL
48	1		*WIPER RESERVOIR NECK	Serviceable	136.11 FL	*-FL
49	1		*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*-FL
50	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*-FL
51	1		*AIR CLEANER HOSE	Serviceable	76.14 FL	*-FL
52	1		*ENGINE TOP COVER 2.0	Serviceable	555.12 FL	*-FL
53	1		*ENGINE OIL SUMP	Serviceable	484.67 FL	*-FL
54	1		*BASE BATTERY TRAY	Serviceable	363.40 FL	*-FL
55	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*-FL
56	1		*TURBO DUCT	Serviceable	1,027.80 FL	*-FL
57	1		*A/C HEATER VALVE	Serviceable	484.50 FL	*-FL
58	1		*SUBFRAME OUTER FRT	Serviceable	2,652.45 FL	*-FL
59	1		*SUBFRAME BRACKET OUTER LH	Serviceable	92.36 FL	*-FL
60	1		*SUBFRAME BRACKET OUTER RH	Serviceable	92.36 FL	*-FL
61	1		*ENGINE UNDERTRAY	Serviceable	564.98 FL	*-FL
62	1		*A/C CONDENSER	Serviceable	2,020.37 FL	*-FL
63	1		*A/C CONDENSER GARNISH LH UPPER	Serviceable	39.67 FL	*-FL
64	1		*A/C CONDENSER GARNISH RH UPPER	Serviceable	39.67 FL	*-FL
65	1		*A/C CONDENSER GARNISH LH	Serviceable	58.81 FL	*-FL
66	1		*A/C CONDENSER GARNISH RH	Serviceable	59.60 FL	*-FL
67	1		*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	208.39 FL	*-FL
68	1		*A/C PIPE CONDENSER TO EXPENSION VALVE	Serviceable	658.72 FL	*-FL
69	1		*A/C PIPE COMPRESSOR	Serviceable	334.29 FL	*-FL
70	1		*A/C PIPE	Serviceable	658.72 FL	*-FL
71	1		*A/C COMPRESSOR	Serviceable	2,684.61 FL	*-FL
72	1		*AIR COOLER	Serviceable	792.60 FL	*-FL
73	1		*AIR INTERCOOLER HOSE (LONG)	Serviceable	1,014.13 FL	*-FL
74	1		*AIR INTERCOOLER HOSE (SHORT)	Serviceable	375.14 FL	*-FL
75	1		*TRANSMISSION COOLER	Serviceable	1,219.30 FL	*-FL
76	1		*TRANSMISSION COOLER PAD	Serviceable	17.96 FL	*-FL
77	1		*RADIATOR	Serviceable	1,202.20 FL	*-FL
78	2		*RADIATOR STUD UPPER	Serviceable	14.41 FL	*-FL
79	2		*RADIATOR BUSH UPPER	Serviceable	50.12 FL	*-FL
80	2		*RADIATOR MTG LOWER	Serviceable	55.85 FL	*-FL
81	1		*RADIATOR FAN COLWING	Serviceable	820.54 FL	*-FL
82	1		*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*-FL
83	1		*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*-FL
84	1		*RADIATOR TANK	Serviceable	324.62 FL	*-FL
85	1		*RADIATOR HOSE UPPER	Serviceable	240.56 FL	*-FL
86	1		*RADIATOR HOSE LOWER	Serviceable	491.18 FL	*-FL
87	1		*RADIATOR TANK HOSE	Serviceable	61.18 FL	*-FL
88	1		*WINDSCREEN FRT	Serviceable	1,364.06 FL	*-FL
89	1		*AUTO COMPUTER	Serviceable	5,032.17 FL	*-FL
90	1		*INJECTION COMPUTER	Serviceable	4,706.30 FL	*-FL
91	1		*RHD HYDRAULIC POWER (RACK & PINION)	Serviceable	5,154.52 FL	*-FL
92	1		*STEERING PUMP ELECTRIC	Serviceable	2,306.90 FL	*-FL
93	1		*STEERING PINION RACK	Serviceable	4,413.11 FL	*-FL
94	1		*ENGINE HARNESS	Serviceable	4,084.54 FL	*-FL
95	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
96	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
97	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*-FS
98	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*-FS
99	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*-FS
100	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*-FS
101	1		*TOW COVER FRT	Repeated	14.50 FS	*-FS
102	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
103	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
104	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
105	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
106	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
107	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
108	1		*SET FRONT LICENCE PLATE WITH HOLDER	Broken	80.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>71,409.05</b>	<b>7,722.68</b>
- List Item Discount on L Items 10.00/10.00% (\$\$)	7,084.66	755.97
<b>Total Parts (\$\$)</b>	<b>64,324.39</b>	<b>6,966.71</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	5,400.00	500.00
2	TOWING FEES	New	120.00	50.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	-
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	5,000.00	660.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	-
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
8	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
10	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	-
11	LABOUR CHARGE TO MONT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	-
12	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT	New	440.00	-
13	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	-
14	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET	New	480.00	-
15	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING	New	380.00	-
16	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDERSER	New	380.00	100.00
17	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	50.00
18	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	-
19	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
Gross Labour Cost (\$\$)			15,400.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >