

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLK9505B

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

Estimate No: ES1890712/WS
Date: 28 Jun 2018

TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Policy No:
 Veh Reg No: **SLK9505B**
 Make/Model: MITSUBISHI ATTRAGE
 1.2CVT

WS Ref: TP AIG
 Claim Type: Third Party
 Accident Date: 26/06/2018
 TP Veh Reg No: SLD9905S

Not Authorized
Repair by claim
12 days

Chassis No: MMBSTA13AHH004432
 Engine No:
 Reg. Date: 08/02/2017

Estimate Repair Cost to Vehicle No :SLK9505B

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 REAR BUMPER	708.00	1 PC	708.00	✓
2 REAR BUMPER REFLECTOR	28.00	2 PC	56.00	✓
3 REAR BUMPER SIDE RETAINER	26.00	2 PC	52.00	✓
4 REAR BUMPER CLIP	3.50	8 PC	28.00	✓
5 REAR BOOT	828.00	1 PC	828.00	✓
6 REAR BOOT LOGO	42.00	1 PC	42.00	✓
7 REAR BOOT EMBLEM -ATTRAGE	45.00	1 PC	45.00	✓
8 REAR BOOT MOULDING	318.00	1 PCS	318.00	✓
9 REAR BOOT TOP SPOILER	650.00	1 PC	650.00	?
10 REAR BOOT INNER LOCK	206.00	1 PC	206.00	✓
11 REAR BOOT INNER RUBBER	145.00	1 PC	145.00	✓
12 REAR BOOT HINGE	192.00	2 PCS	384.00	?
13 TAILLAMP	276.00	2 PCS	552.00	✓
14 TAILLAMP PANEL	95.00	2 PCS	190.00	✓
15 REAR CENTRE PANEL	551.00	1 PC	551.00	✓
16 REAR CENTRE PANEL INNER TOP GARNISH	62.00	1 PC	62.00	✓
17 REAR CENTRE PANEL TOP GARNISH CLIP	5.00	2 PC	10.00	✓
18 REAR SPARE TYRE TOP BOARD	185.00	1 PC	185.00	✓
19 REAR FENDER	715.00	2 PCS	1,430.00	2+
20 REAR FENDER INNER SHIELD CLIP	5.00	4 PC	20.00	?
			6,462.00	
		Less 10%	646.20	5,815.80
Special Net				
21 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
22 REVERSE SENSOR	200.00	1 PC	200.00	✓
23 REVERSE CAMERA	350.00	1 PC	350.00	?
			590.00	590.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES1890712/WS
Date: 28 Jun 2018
Policy No:
Veh Reg No: SLK9505B
Make/Model: MITSUBISHI ATTRAGE
 1.2CVT
Chassis No: MMBSTA13AHH004432
Engine No:
Reg. Date: 08/02/2017

WS Ref: TP AIG
 Claim Type: Third Party
 Accident Date: 26/06/2018
 TP Veh Reg No: SLD9905S

Estimate Repair Cost to Vehicle No :SLK9505B

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
24 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
25 REMOVE AND REFIX REAR BUMPER ASSY, TAILLAMPS, RR BOOT & ATTACHMENT; CUT, WELD AND RENEW RR BOTH FENDERS, RR CENTRE PANEL, TAILLAMP PANELS, STRAIGHTEN RR CHASSIS, KNOCK AND REPAIR RR SPARE TYRE COMPARTMENT AND RE-ALIGN TO SAME	2,000.00	1 LA	2,000.00	1600
26 REMOVE AND REFIX RR SEAT, CARPAT, TOP ROOF LINING, GARNISH ETC	120.00	1 LA	120.00	✓
27 PUTTY AND RESPRAY ON RR BOTH FENDEERS, RR BUMPER, BOOT, RR PANEL, TAILLAMP PANLE, RR SPARE TYRE COMPARTMENT AND RR AFFECTED AREAS	1,600.00	1 LA	1,600.00	1200
28 RUSTPROOFING	120.00	1 LA	120.00	90
			3,940.00	3,940.00
			Total	S\$ 10,345.80
			Add GST @ 7%	724.21
			Total Amount Payable	S\$ 11,070.01

For Cheng Hoe Motor Pte Ltd



 AUTHORISED SIGNATURE