

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

SKX 4435X

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1890792/YISHUN

Date: 16 Jul 2018

Policy No: DMPCSN3000071801

Veh Reg No: SKX4435X

Make/Model: BMW 520I AUTO ABS  
AIRBAG 2WD XENON

Chassis No: WBANT120X0CX30039

Engine No: A823I406N46B20BE

Reg. Date: 04/06/2009

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 22/06/2018

TP Veh Reg No: SLN2009Y

Not Notified

11 Sep 8 ?

Resurvey After Paint  
4 days

## Estimate Repair Cost to Vehicle No :SKX4435X

| Description                                                                            | U/Price  | Quantity | List Price           | Amount       |
|----------------------------------------------------------------------------------------|----------|----------|----------------------|--------------|
|                                                                                        |          |          | <u>S\$</u>           | <u>S\$</u>   |
| <b>List Price</b>                                                                      |          |          |                      |              |
| 1 FRONT RH FENDER                                                                      | 830.00   | 1 PC     | 830.00               | X            |
| 2 FRONT RH DOOR                                                                        | 1,646.00 | 1 PC     | 1,646.00             | ✓            |
| 3 FRONT RH DOOR INNER RUBBER                                                           | 175.00   | 1 PC     | 175.00               | 50/50        |
| 4 FRONT RH DOOR TOP INNER RUBBER                                                       | 80.00    | 1 PC     | 80.00                | ✓            |
| 5 FRONT RH DOOR FRAME STICKER                                                          | 71.00    | 1 PC     | 71.00                | ✓            |
|                                                                                        |          |          | 2,802.00             |              |
|                                                                                        |          | Less 10% | 280.20               | 2,521.80     |
| <b>Labour</b>                                                                          |          |          |                      |              |
| 6 REMOVE & REFIX FRT RH FENDER,FRT RH DOOR,TRANSFER DOOR ATTACHMENT & REALIGN THE SAME | 450.00   | 1 LA     | 450.00               | 400          |
| 7 REMOVE & REFIX FRT RH DOOR GLASS,CHECK CENTRAL LOCK & POWER MIRROR                   | 80.00    | 1 LA     | 80.00                | ✓            |
| 8 PUTTY & RESPRAY ON FRT RH FENDER,FRT RH DOOR                                         | 500.00   | 1 LA     | 500.00               | 450          |
| 9 RUSTPROOFING                                                                         | 30.00    | 1 LA     | 30.00                | ✓            |
|                                                                                        |          |          | 1,060.00             | 1,060.00     |
|                                                                                        |          |          | Total                | S\$ 3,581.80 |
|                                                                                        |          |          | Add GST @ 7%         | 250.73       |
|                                                                                        |          |          | Total Amount Payable | S\$ 3,832.53 |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE