

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 27/06/2018
TP Vehicle No. : SLK-7554-Y
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Owner : FUNZ CENTRE PTE LTD
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5076983791-02
Vehicle No. : GBE-5717-H
Make & Model : TOYOTA HIACE 3.0 DX A

Accident Date: 22/06/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAILGATE <i>2.0/5m</i>	\$2,212.70	—
1	TAILGATE LOCK <i>DD/5m</i>	\$265.13	—
1	EMBLEM LOGO <i>nee</i>	\$59.60	—
<i>sticker</i> 1	EMBLEM HIACE <i>nee</i>	\$49.50	—
1	REAR BUMPER <i>DD</i>	\$396.90	—
1	REAR BUMPER SIDE RETAINER RH <i>11</i>	\$27.80	X
1	REAR BUMPER SIDE RETAINER LH <i>11</i>	\$27.80	X
1	END PANEL <i>n</i>	\$329.20	X
1	WEATHER STRIP <i>11</i>	\$400.00	X
	Sub Total	\$3,768.63	
	Discount 25% on Parts	(\$942.16)	
		\$2,826.47	

Special Nett

10	REAR BUMPER CLIPS <i>nee</i>	\$30.00	✓
1	70 KM/H STICKER <i>nee</i>	\$30.00	10
1	ADVERTISEMENT STICKER <i>nee</i>	\$200.00	15-0
<i>1 set 2</i>	REVERSE SENSOR <i>shub</i>	\$250.00	200
1	REAR WINDSCREEN SEALANT <i>nee</i>	\$80.00	40
1	REAR WINDSCREEN INNER SEAL <i>nee</i>	\$80.00	30
	Sub Total	\$670.00	

Labour & Misc

LABOUR TO FACILIATE REPAIR	\$1,000.00	500
TO SPRAY PAINT ON AFFECTED AREAS	\$1,000.00	450
TO TRANSFER TAILGATE FITTING	\$120.00	60
TO REINSTALL REAR WINDSCREEN	\$150.00	120
TO RUST PROOF AFFECTED AREA	\$100.00	30
Sub Total	\$2,370.00	

Date : 27/06/2018
TP Vehicle No. : SLK-7554-Y
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Owner : FUNZ CENTRE PTE LTD
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5076983791-02
Vehicle No. : GBE-5717-H
Make & Model : TOYOTA HIACE 3.0 DX A

Accident Date: 22/06/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$5,866.47	
	GST 7%	\$410.65	
	Total	\$6,277.13	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: