

15/5/2010

INS. CASE OWNER:

Fran Chuan

CC 4/AXA1801

1790, KWB352

LKK:  
IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

9/9/18

Date / Time:

26/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

WC 8541P

Name of Insured:

GAW READY MIX P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

26/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: Mr Frank Lee

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S8MOON-AD154284

Policy No.:

PIR58473

Make / Model:

ISUZU

Place of Accident:

SOMMERVILLE PARK

OI GIA REPORT YES / NO: YES / NO

Insured Liability: % Final ? Yes / No

SJV 7287J

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Antonox

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time:

27/1/18  
min

SJV 7287J - x

WC 8541P - x

Smartclaim

TO GET LOA:

17/5/19

INFORMED OJO ABOUT TP CLAIM AND AWARE NCD ISSUES.

23/5/19

seek mandate via SMART.

29/5/19

mandate approve via SMART.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

( days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

%

If NO or B 28, Ass. Lia:

Repair Cost:

SS

9275.00

Loss of Rental (LOR):

SS

556.40

( 4 days)

x 130 + GST

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

(S

x

days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GLA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

9833.40

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

9833.40

Name 1:

Auto Worx House

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF: ALA/

W

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$ 4K

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time

Action / Instruction

4/7File pass to Carhenge23/5/19Confirm C/S \$ 9600.00 with 5 working days

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech Invs (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + P.S. \$ \_\_\_\_\_

: Fines

: Others

TOTAL

Veh No: STV 7287JYr Regn: 02 10Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Traller or AMake: JapvaXFc.c. 2967Colour: h. Black

A/C: Insured / Std / NI / NA

Sp. Reading 131582

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: SA JAC 0502 AFR 84932Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD / A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 245/40ZR19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 4 mmR/Bal. 7 mmL/Bal. 4 mmL/Bal. 7 mmD.O.A. 26/6/18D.O.I. 3/7/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
015 PM

The U/C / Chassis frame / Body Structure affected due to collision.

(Rd)-A 5393-30  
36.1)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                    |                           |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD                                                                                                                     |                                                                    | Ref : CC4/ASM18011790/wb3 |                                                                                     |
| 8 SHENTON WAY #24-01<br>AXA TOWERS SINGAPORE 068811                                                                                       |                                                                    | Date : 28-06-2018         |  |
|                                                                                                                                           |                                                                    | Code : ASM                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                    |                           |                                                                                     |
| Insured Veh.                                                                                                                              | WC 8541P                                                           | Veh. Inspected            | SJV 7287J                                                                           |
| Policy No.                                                                                                                                |                                                                    | Coverage (\$)             | 0.00                                                                                |
| Claim No.                                                                                                                                 |                                                                    | Excess (\$)               | 0.00                                                                                |
| Assign From                                                                                                                               |                                                                    | Assign Date               | 28/06/2018                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                    |                           |                                                                                     |
| Make & Model                                                                                                                              |                                                                    | c.c                       | 0                                                                                   |
| Engine No.                                                                                                                                | HIDDEN                                                             | Year of Reg.              |                                                                                     |
| Chassis No.                                                                                                                               |                                                                    | Colour                    |                                                                                     |
| Odometer                                                                                                                                  |                                                                    | Steering                  |                                                                                     |
| Brakes                                                                                                                                    |                                                                    | Modification              |                                                                                     |
| General                                                                                                                                   |                                                                    |                           |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                    |                           |                                                                                     |
|                                                                                                                                           | Size                                                               | Make                      | Balance                                                                             |
| R/H Front Tyre                                                                                                                            |                                                                    |                           | mm                                                                                  |
| L/H Front Tyre                                                                                                                            |                                                                    |                           | mm                                                                                  |
| R/H Rear Tyre                                                                                                                             |                                                                    |                           | mm                                                                                  |
| L/H Rear Tyre                                                                                                                             |                                                                    |                           | mm                                                                                  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                    |                           |                                                                                     |
|                                                                                                                                           |                                                                    |                           |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                    |                           |                                                                                     |
| Accident Date                                                                                                                             | 26/06/2018                                                         | Inspection Date           |                                                                                     |
| Survey held at                                                                                                                            | AUTOWORX HOUSE<br>176 SIN MING DRIVE<br>#02-01<br>SINGAPORE 575721 |                           |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                    |                           |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                    |                           |                                                                                     |



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 04/07/2018

### Survey Details:

|                     |                |
|---------------------|----------------|
| Date of loss        | 26-Jun-18      |
| Date of appointment | 28-Jun-18      |
| Date of survey      | 3-Jul-18       |
| Location of survey  | AUTOWORX HOUSE |

### Vehicle Details:

|                      |                                                 |
|----------------------|-------------------------------------------------|
| Claim Type:          | Third party                                     |
| Vehicle number       | SJV 7287J                                       |
| Make and Model       | JAGUAR XF 3.0 V6 LUXURY AT ABS D/AB HID 2WD 4DR |
| Date of registration | 8/2/2010                                        |
| Excess               |                                                 |
| Market Value         | \$48,000                                        |
| Parf Rebate          | \$36,607                                        |
| Nett Loss            | \$11,393                                        |

### Repair details:

|                  |              |
|------------------|--------------|
| Initial Estimate | \$ 14,993.30 |
|------------------|--------------|

### Proposed/Revised repair cost:

|                         |                     |
|-------------------------|---------------------|
| Parts                   | \$ 8,297.19         |
| Check items (estimate)  | \$ 3,487.49         |
| Labour                  | \$ 1,350.00         |
| <b>Total</b>            | <b>\$ 13,134.68</b> |
| Lump Sum(if applicable) | \$ -                |

|                           |   |
|---------------------------|---|
| Number of days for repair | 5 |
|---------------------------|---|



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607158R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

*We have not authorized repairs.*

**Mandate:**

| Liability(TP)         |    | % |
|-----------------------|----|---|
| Proposed repair cost  | \$ |   |
| Loss of use           | \$ |   |
| Loss of rental        | \$ |   |
| Loss of income        | \$ |   |
| LTA search fees       | \$ |   |
| Others                | \$ |   |
| <b>Proposed Total</b> |    |   |

*Kw*

# AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

SPT MOTORING LLP  
c/o 46 Lentor Plain  
Singapore 786548

*Not Authorized*  
*11 Sep 89600h*  
*Repair After Rain*  
*5 days* Date: 27/06/2018

| QUANTITY | PARTICULARS                                                                                                   | AMOUNT (\$)              |
|----------|---------------------------------------------------------------------------------------------------------------|--------------------------|
|          | <u>RE: JAGUAR XF / SJV 7287 J</u>                                                                             |                          |
| 1 pc     | front bumper                                                                                                  | <i>Bumper</i> 2,486.50 ✓ |
| 1 pc     | front bumper side grille                                                                                      | <i>GL</i> 375.80 X       |
| 1 pc     | front bumper side grille crome                                                                                | <i>GL</i> 411.00 X       |
| 1 pc     | front bumper side retainer                                                                                    | <i>GL</i> 169.00 ✓       |
| 1 pc     | front head lamp assy                                                                                          | <i>mglen</i> 2,969.30 ✓  |
| 1 pc     | front fender                                                                                                  | <i>B</i> 652.60 ✓        |
| 1 pc     | front fender dust cover                                                                                       | <i>GL</i> 138.20 ✓       |
| 1 pc     | front fender crome air duct grille                                                                            | <i>GL</i> 454.00 ✓       |
| 1 pc     | front door side mirror assy                                                                                   | <i>CM</i> 969.70 ✓       |
| 1 pc     | front door side mirror signal lamp                                                                            | <i>CM</i> 275.80 ✓       |
| 1 pc     | alloy rim                                                                                                     | <i>GL</i> 1,104.00 ✓     |
| 1 pc     | front lower arm                                                                                               | <i>GL</i> 575.90 ✓       |
| 1 pc     | front kunckle arm                                                                                             | <i>B</i> 636.20 ✓        |
| 1 pc     | front wheel bearing                                                                                           | <i>M</i> 385.70 ✓        |
| 1 pc     | front upper wish bone                                                                                         | <i>GL</i> 483.50 X       |
| 1 pc     | front shock absorber                                                                                          | <i>B</i> 793.80 ✓        |
| 1 pc     | front steering tie rod                                                                                        | <i>GL</i> 213.20 X       |
| 1 pc     | front steering tie rod end joint                                                                              | <i>GL</i> 107.50 X       |
| 1 pc     | front forward trust arm                                                                                       | <i>GL</i> 335.30 Y       |
|          | Sub-total                                                                                                     | 13,537.00                |
|          | Less 10%                                                                                                      | 1,353.70                 |
|          | Sub-total                                                                                                     | 12,183.30                |
|          | To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas. | <i>500</i> 900.00        |
|          | To check wiring system.                                                                                       | 30.00 <i>200</i>         |
|          | To spray painting on affected areas.                                                                          | <i>700</i> 950.00        |
|          | sub-total                                                                                                     | 14,063.30                |

|  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                  |       |
|--|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|-------|
|  | Balance brought forward.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 14,063.30        |       |
|  | To apply waterproof sealant on welded panels.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 2x 120.00        | X     |
|  | To apply rust proofing.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 3cl 120.00       |       |
|  | To remove and install front undercarriage parts to enable repair.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | ? 250.00         | 200cl |
|  | To replace 1 pc alloy rim & perform wheel balancing.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | 2cl 60.00        |       |
|  | To machine press 1 pc wheel bearing.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | ? 60.00          | 3cl   |
|  | To perform 4 wheels computerised alignment.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 8cl 100.00       |       |
|  | Diagnostic and re-programme electronic functions.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | 220.00           | 12cl  |
|  | <b>Total</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | <b>14,993.30</b> |       |
|  | <div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company.</li> </ul> <p>Acknowledged by Repairer<br/>Signature: _____<br/>Date: _____</p> </div> |                  |       |

Work Order: R026146  
 VIN: SJV7287J  
 Year: 10  
 Date: 3.7.18 16:08



SJV7287J

Jaguar : XF/XFR : 2010-15 (X250) : All Right-hand Drive Models/Japan (except India Diesel) : Rear Wheel Drive (except Supercharged)

| Front : Left |        |                 |                     | Front : Right |        |                 |
|--------------|--------|-----------------|---------------------|---------------|--------|-----------------|
| Actual       | Before | Specified Range |                     | Actual        | Before | Specified Range |
| 5°34'        | 5°34'  | -1°21' 0°09'    | Camber              | -2°26'        | -2°26' | -0°57' 0°33'    |
| -0°53'       | -0°53' | 6°08' 7°38'     | Caster              |               |        | 5°35' 7°05'     |
| 6°41'        | 6°41'  | 0°01' 0°13'     | Toe                 | -0°39'        | -0°39' | 0°01' 0°13'     |
| 6°26'        | 6°26'  |                 | SAI                 | 9°13'         | 9°13'  |                 |
|              |        |                 | Included Angle      | 6°47'         | 6°47'  |                 |
|              |        |                 | Turning Angle Diff. |               |        |                 |

|                  | Actual | Before | Specified Range |
|------------------|--------|--------|-----------------|
| Cross Camber     | 2°11'  | 2°11'  | -1°09' 0°21'    |
| Cross Caster     | -0°59' | -0°59' | -0°12' 1°18'    |
| Cross SAI        | -2°32' | -2°32' |                 |
| Total Toe        | -1°32' | -1°32' | 0°01' 0°25'     |
| Cross Turn Diff. |        |        |                 |

| Rear : Left |        |                 |        | Rear : Right |        |                 |
|-------------|--------|-----------------|--------|--------------|--------|-----------------|
| Actual      | Before | Specified Range |        | Actual       | Before | Specified Range |
| -1°34'      | -1°35' | -1°32' -0°02'   | Camber |              |        | -1°32' -0°02'   |
| -0°07'      | -0°07' | -0°01' 0°11'    | Toe    | 0°31'        | 0°32'  | -0°01' 0°11'    |

|              | Actual | Before | Specified Range |
|--------------|--------|--------|-----------------|
| Cross Camber | -0°27' | -0°30' |                 |
| Total Toe    | 0°24'  | 0°25'  | -0°02' 0°22'    |
| Thrust Angle | -0°19' | -0°19' | -0°08' 0°08'    |



# AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

### SPT MOTORING LLP

c/o 46 Lentor Plain  
Singapore 786548

*Not Authorised*  
*LI Long B?*  
*Running After Pain*  
*5 days* Date: 27/06/2018

| QUANTITY | PARTICULARS                                                                                                   | AMOUNT (\$)              |
|----------|---------------------------------------------------------------------------------------------------------------|--------------------------|
|          | <b>RE: JAGUAR XF / SJV 7287 J</b>                                                                             |                          |
| 1 pc     | front bumper                                                                                                  | <i>Bumper</i> 2,486.50 ✓ |
| 1 pc     | front bumper side grille                                                                                      | <i>SL</i> 375.80 X       |
| 1 pc     | front bumper side grille crome                                                                                | 411.00 ✓                 |
| 1 pc     | front bumper side retainer                                                                                    | <i>DI</i> 169.00 ✓       |
| 1 pc     | front head lamp assy                                                                                          | <i>mg car</i> 2,969.30 ✓ |
| 1 pc     | front fender                                                                                                  | <i>B</i> 652.60 ✓        |
| 1 pc     | front fender dust cover                                                                                       | <i>DI</i> 138.20 ✓       |
| 1 pc     | front fender crome air duct grille                                                                            | <i>SA</i> 454.00 ✓       |
| 1 pc     | front door side mirror assy                                                                                   | <i>CM</i> 969.70 ✓       |
| 1 pc     | front door side mirror signal lamp                                                                            | <i>CM</i> 275.80 ✓       |
| 1 pc     | alloy rim                                                                                                     | <i>DI</i> 1,104.00 ✓     |
| 1 pc     | front lower arm                                                                                               | 575.90 ✓                 |
| 1 pc     | front kunckle arm                                                                                             | 636.20 ✓                 |
| 1 pc     | front wheel bearing                                                                                           | 385.70 ✓                 |
| 1 pc     | front upper wish bone                                                                                         | 483.50 ✓                 |
| 1 pc     | front shock absorber                                                                                          | 793.80 ✓                 |
| 1 pc     | front steering tie rod                                                                                        | <i>SL</i> 213.20 X       |
| 1 pc     | front steering tie rod end joint                                                                              | <i>SL</i> 107.50 X       |
| 1 pc     | front forward trust arm                                                                                       | <i>SL</i> 335.30 X       |
|          | Sub-total                                                                                                     | 13,537.00                |
|          | Less 10%                                                                                                      | 1,353.70                 |
|          | Sub-total                                                                                                     | 12,183.30                |
|          | To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas. | <i>500</i> 900.00        |
|          | To check wiring system.                                                                                       | 30.00 <i>200</i>         |
|          | To spray painting on affected areas.                                                                          | <i>700</i> 950.00        |
|          | sub-total                                                                                                     | 14,063.30                |

|  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                  |   |
|--|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|---|
|  | Balance brought forward.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | 14,063.30        |   |
|  | To apply waterproof sealant on weilded panels.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | 2x 120.00        | X |
|  | To apply rust proofing.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 3x 120.00        |   |
|  | To remove and install front undercarriage parts to enable repair.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | ? 250.00         |   |
|  | To replace 1 pc alloy rim & perform wheel balancing.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | 2x 60.00         |   |
|  | To machine press 1 pc wheel bearing.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | ? 60.00          |   |
|  | To perform 4 wheels computerised alignment.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | 8x 100.00        |   |
|  | Diagnostic and re-programme electronic functions.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 220.00           | ? |
|  | <b>Total</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | <b>14,993.30</b> |   |
|  | <div data-bbox="678 996 1173 1388" data-label="Text"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer<br/>Signature:<br/>Date:</p> </div> |                  |   |

Kn

# AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

### SPT MOTORING LLP

c/o 46 Lenton Plain  
Singapore 786548

Not Authorized  
C/Ling 89600h  
Merry After Pain  
5 days

Date: 27/06/2018

| QUANTITY | PARTICULARS                                                                                                   | AMOUNT (\$) |
|----------|---------------------------------------------------------------------------------------------------------------|-------------|
|          | <u>RE: JAGUAR XF / SJV 7287 J</u>                                                                             |             |
| 1 pc     | front bumper                                                                                                  | 2,486.50 ✓  |
| 1 pc     | front bumper side grille                                                                                      | 375.80 X    |
| 1 pc     | front bumper side grille crome                                                                                | 411.00 X    |
| 1 pc     | front bumper side retainer                                                                                    | 169.00 ✓    |
| 1 pc     | front head lamp assy                                                                                          | 2,969.30 ✓  |
| 1 pc     | front fender                                                                                                  | 652.60 ✓    |
| 1 pc     | front fender dust cover                                                                                       | 138.20 ✓    |
| 1 pc     | front fender crome air duct grille                                                                            | 454.00 ✓    |
| 1 pc     | front door side mirror assy                                                                                   | 969.70 ✓    |
| 1 pc     | front door side mirror signal lamp                                                                            | 275.80 ✓    |
| 1 pc     | alloy rim                                                                                                     | 1,104.00 ✓  |
| 1 pc     | front lower arm                                                                                               | 575.90 ✓    |
| 1 pc     | front kunckle arm                                                                                             | 636.20 ✓    |
| 1 pc     | front wheel bearing                                                                                           | 385.70 ✓    |
| 1 pc     | front upper wish bone                                                                                         | 483.50 X    |
| 1 pc     | front shock absorber                                                                                          | 793.80 ✓    |
| 1 pc     | front steering tie rod                                                                                        | 213.20 X    |
| 1 pc     | front steering tie rod end joint                                                                              | 107.50 X    |
| 1 pc     | front forward trust arm                                                                                       | 335.30 Y    |
|          | Sub-total                                                                                                     | 13,537.00   |
|          | Less 10%                                                                                                      | 1,353.70    |
|          | Sub-total                                                                                                     | 12,183.30   |
|          | To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas. | 900.00 500  |
|          | To check wiring system.                                                                                       | 30.00 200   |
|          | To spray painting on affected areas.                                                                          | 950.00 700  |
|          | sub-total                                                                                                     | 14,063.30   |

|  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                  |      |
|--|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|------|
|  | Balance brought forward.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 14,063.30        |      |
|  | To apply waterproof sealant on weilded panels.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | 2x 120.00        | X    |
|  | To apply rust proofing.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | 3cl 120.00       |      |
|  | To remove and install front undercarriage parts to enable repair.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | ? 250.00         | 200l |
|  | To replace 1 pc alloy rim & perform wheel balancing.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 2cl 60.00        |      |
|  | To machine press 1 pc wheel bearing.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | ? 60.00          | 3cl. |
|  | To perform 4 wheels computerised alignment.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | 8cl 100.00       |      |
|  | Diagnostic and re-programme electronic functions.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 220.00           | 12cl |
|  | <b>Total</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>14,993.30</b> |      |
|  | <div data-bbox="692 1008 1117 1348" data-label="Text"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer<br/>Signature:<br/>Date:</p> </div> |                  |      |

Work Order: R026146  
VIN: SJV7287J  
Year: 10  
Date: 3.7.18 16:08



SJV7287J

Jaguar : XF/XFR : 2010-15 (X250) : All Right-hand Drive Models/Japan (except India Diesel) : Rear Wheel Drive (except Supercharged)

Front : Left

| Actual | Before | Specified Range |
|--------|--------|-----------------|
|        |        | -1°21' 0°09'    |
| 5°34'  | 5°34'  | 6°08' 7°38'     |
| -0°53' | -0°53' | 0°01' 0°13'     |
| 6°41'  | 6°41'  |                 |
| 6°26'  | 6°26'  |                 |

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -2°26' | -2°26' | -0°57' 0°33'    |
|        |        | 5°35' 7°05'     |
| -0°39' | -0°39' | 0°01' 0°13'     |
| 9°13'  | 9°13'  |                 |
| 6°47'  | 6°47'  |                 |

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| 2°11'  | 2°11'  | -1°09' 0°21'    |
| -0°59' | -0°59' | -0°12' 1°18'    |
| -2°32' | -2°32' |                 |
| -1°32' | -1°32' | 0°01' 0°25'     |

Rear : Left

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -1°34' | -1°35' | -1°32' -0°02'   |
| -0°07' | -0°07' | -0°01' 0°11'    |

Camber  
Toe

Rear : Right

| Actual | Before | Specified Range |
|--------|--------|-----------------|
|        |        | -1°32' -0°02'   |
| 0°31'  | 0°32'  | -0°01' 0°11'    |

Rear

Cross Camber  
Total Toe  
Thrust Angle

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -0°27' | -0°30' |                 |
| 0°24'  | 0°25'  | -0°02' 0°22'    |
| -0°19' | -0°19' | -0°08' 0°08'    |

## Service Request Details

Claim

S8M00MGD

Reference

None 

Loss Date

June 26, 2018

Request Date

June 28, 2018

28062018 @ 1037am

Due Date

July 5, 2018

Yuki veh not in

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SJV7287J

Make

TPVD JAGUAR

Model

XF 3.0

Service Address

---

...

Primary Contact/Insured

---

G &amp; W READY-MIX PTE LTD

65 SUNGEI KADUT DRIVE, 729564, Singapore

Claim Handler

---

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



G & W READY-MIX PTE LTD

青白石灰

(私人) 有限公司

65 Sungei Kadut Drive

Singapore 729564

Tel : 6365 3388

Fax: 6365 5866

Co. Reg. No: 197902602G

LETTER OF AUTHORIZATION

Wednesday, 22 May 2019

Your Ref : CC4/ASM18011790/wb3

Our Ref : P1858473

Dear Sir / Madam,

Accident involving WC8541P and SJV7287J along Sommerville Walk on 26/06/2018

This is to confirm that, Ng Kiang Chye of NRIC No: S1204237Z is employed as a Driver with G & W Ready-Mix Pte Ltd. He is authorized to drive the Company's vehicle, WC8541P.

We understand based on the circumstance and the merits of the case, AXA Insurance will take conduct of the claim(s) in relation to this accident, subject to the policy terms and conditions attached with the motor insurance policy.

William Quek Ming Hock  
ESH Manager  
G & W Ready-Mix Private Limited  
H/P: 9046 6410  
williamquek@gw-group.com





 **Re:RE: Re:RE: Re:S8M00MGD- seek mandat approval**

Type

 Question

Message

PLS PROCEED COR @ \$9,150.00

[Reply](#)

# AUTOWORX HOUSE

176 Sin Ming Drive, #02-01 Sin Ming Autocare Singapore 575721

Email: [autoworxhouse@hotmail.com](mailto:autoworxhouse@hotmail.com)

•TEL: 6452 8211 •FAX: 6451 7420

## Direct Settlement THIRD PARTY CLAIM

Your ref: WC8541P

Our ref: SJV7287J

AXA INSURANCE PTE LTD

Attn: Officer In Charge

(Motor Claim Department)

19/11/2018

Dear Sir,

**RE : ACCIDENT INVOLVING SJV7287J AND WC8541P ALONG SOMMERVILLE WALK ON 26/06/2018.**

We have been authorized by RENE ANG KIM HUAT, the registered owner of vehicle number SJV7287J, which was involved in the above accident and at the material time to make a 3<sup>rd</sup> party claims against vehicle number WC8541P.

The accident was clearly caused by your insured's negligence. We, therefore seeking compensation from you for our client financial losses as itemized below: -

|                                         |     |           |
|-----------------------------------------|-----|-----------|
| Repair cost                             | S\$ | 9,600.00  |
| Rental Fee (4 days x \$130.00 + 7% GST) | S\$ | 556.40    |
| Search Fee                              | S\$ | 2.00      |
| Total                                   | S\$ | 10,158.40 |

We have enclosed copies of relevant documents to support our claims.

Please settle this matter within 7 days.

Your prompt settlement of our claim would be much appreciated.

Do contact us at 64528211 for any clarification.

Thank you.

Yours faithfully

  
Autoworx House

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

|                   |                     |        |               |
|-------------------|---------------------|--------|---------------|
| Vehicle No:       | WC 8541P (Insd veh) | Model: | JAGUAR XF (A) |
|                   | SJV 7287J (TP veh)  |        |               |
| Date of Accident: | 26/06/2018          |        |               |

|                       |   |                              |                                        |
|-----------------------|---|------------------------------|----------------------------------------|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Repair Estimate       | : | \$                           | 14,993.30                              |
| Final Repair Cost     | : | \$                           | 9,275.00                               |
| Loss of Use           | : | \$                           | days at \$0.00 per day                 |
| Rental (if any)       | : | \$                           | 556.40 4 days                          |
| LTA / GIA Search Fee  | : | \$                           | 2.00                                   |

|         |   |    |  |
|---------|---|----|--|
| Others: | : | \$ |  |
|---------|---|----|--|

|                      |   |    |          |
|----------------------|---|----|----------|
|                      | : | \$ |          |
| Final Settlement Sum | : | \$ | 9,833.40 |

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

| Payment Instruction: Payee's Breakdown |                |   |             |
|----------------------------------------|----------------|---|-------------|
| 1)                                     | AUTOWORX HOUSE | : | \$ 9,833.40 |

NUR SHAQILAH BTE ABDOL  
WAHAB

10/06/2019

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                    |                              |                    |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|------------------------------|--------------------|-------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD                                                                                                                  |                                                                    | Ref : CC4/ASM18011790/Kwb3s2 |                    |                                                                                     |
| 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN: KIAN CHUAN                                                                  |                                                                    | Date : 10-06-2019            |                    |  |
|                                                                                                                                        |                                                                    | Code : ASM                   |                    |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                    |                              |                    |                                                                                     |
| Insured Veh.                                                                                                                           | WC 8541P                                                           | Veh. Inspected               | SVJ 7287J          |                                                                                     |
| Policy No.                                                                                                                             | P1858473                                                           | Coverage (\$)                | 0.00               |                                                                                     |
| Claim No.                                                                                                                              | S8M00MGD                                                           | Excess (\$)                  | 0.00               |                                                                                     |
| Assign From                                                                                                                            | KIAN CHUAN                                                         | Assign Date                  | 28/06/2018         |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                    |                              |                    |                                                                                     |
| Make & Model                                                                                                                           | JAGUAR XF (A)                                                      | c.c                          | 2967               |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                             | Year of Reg.                 | 2010               |                                                                                     |
| Chassis No.                                                                                                                            | SAJAC05D2AFR64932                                                  | Colour                       | METALLIC BLACK     |                                                                                     |
| Odometer                                                                                                                               | 131582                                                             | Steering                     | IN ORDER           |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                           | Modification                 | STANDARD ALLOY RIM |                                                                                     |
| General                                                                                                                                | GOOD                                                               |                              |                    |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                    |                              |                    |                                                                                     |
|                                                                                                                                        | Size                                                               | Make                         | Balance            |                                                                                     |
| R/H Front Tyre                                                                                                                         | 245/40ZR19                                                         | MICHELIN                     | 4 mm               |                                                                                     |
| L/H Front Tyre                                                                                                                         | 245/40ZR19                                                         | MICHELIN                     | 4 mm               |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 245/40ZR19                                                         | MICHELIN                     | 7 mm               |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 245/40ZR19                                                         | MICHELIN                     | 7 mm               |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                    |                              |                    |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                        |                                                                    |                              |                    |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                    |                              |                    |                                                                                     |
| Accident Date                                                                                                                          | 26/06/2018                                                         | Inspection Date              | 03/07/2018         |                                                                                     |
| Survey held at                                                                                                                         | AUTOWORX HOUSE<br>176 SIN MING DRIVE<br>#02-01<br>SINGAPORE 575721 |                              |                    |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                    |                              |                    |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                    |                              |                    |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                    |                              |                    |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                    | <b>5 Working Days</b>        |                    |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 7287J

| Qty                         | Description of Parts                                                                                          | Condition         | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---------------------------------------------------------------------------------------------------------------|-------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                                                                               |                   |                           |                   |
| 1                           | FRONT BUMPER (CONSISTENT)                                                                                     | BUCKLED / CRACKED | 2,486.50                  | 2,486.50          |
| 1                           | FRONT BUMPER SIDE GRILLE (CONSISTENT)                                                                         | SERVICEABLE       | 375.80                    | -                 |
| 1                           | FRONT BUMPER SIDE GRILLE CHROME (CONSISTENT)                                                                  | SERVICEABLE       | 411.00                    | -                 |
| 1                           | FRONT BUMPER SIDE RETAINER (CONSISTENT)                                                                       | DISTORTED         | 169.00                    | 169.00            |
| 1                           | FRONT HEAD LAMP ASSY (CONSISTENT)                                                                             | MTG CRACKED       | 2,969.30                  | 2,969.30          |
| 1                           | FRONT FENDER (CONSISTENT)                                                                                     | BENT              | 652.60                    | 652.60            |
| 1                           | FRONT FENDER DUST COVER (CONSISTENT)                                                                          | DISTORTED         | 138.20                    | 138.20            |
| 1                           | FRONT FENDER CHROME AIR DUCT GRILLE (CONSISTENT)                                                              | SCRATCHED         | 454.00                    | 454.00            |
| 1                           | FRONT DOOR SIDE MIRROR ASSY (CONSISTENT)                                                                      | CRACKED           | 969.70                    | 969.70            |
| 1                           | FRONT DOOR SIDE MIRROR SIGNAL LAMP (CONSISTENT)                                                               | CRACKED           | 275.80                    | 275.80            |
| 1                           | ALLOY RIM (CONSISTENT)                                                                                        | DENTED            | 1,104.00                  | 1,104.00          |
| 1                           | FRONT LOWER ARM (CONSISTENT)                                                                                  | DISTORTED         | 575.90                    | 575.90            |
| 1                           | FRONT KNUCKLE ARM (CONSISTENT)                                                                                | BENT              | 636.20                    | 636.20            |
| 1                           | FRONT WHEEL BEARING (CONSISTENT)                                                                              | NECESSARY         | 385.70                    | 385.70            |
| 1                           | FRONT UPPER WISH BONE (CONSISTENT)                                                                            | SERVICEABLE       | 483.50                    | -                 |
| 1                           | FRONT SHOCK ABSORBER (CONSISTENT)                                                                             | BENT              | 793.80                    | 793.80            |
| 1                           | FRONT STEERING TIE ROD (CONSISTENT)                                                                           | SERVICEABLE       | 213.20                    | -                 |
| 1                           | FRONT STEERING TIE ROD END JOINT (CONSISTENT)                                                                 | SERVICEABLE       | 107.50                    | -                 |
| 1                           | FRONT FORWARD TRUST ARM (CONSISTENT)                                                                          | SERVICEABLE       | 335.30                    | -                 |
|                             | LESS 10% DISCOUNT                                                                                             |                   | -1,353.70                 | -1,161.07         |
|                             |                                                                                                               |                   | 12,183.30                 | 10,449.63         |
| <b>LABOUR</b>               |                                                                                                               |                   |                           |                   |
|                             | TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS. |                   | 900.00                    | 500.00            |
|                             | TO CHECK WIRING SYSTEM.                                                                                       |                   | 30.00                     | 20.00             |
|                             | TO SPRAY PAINTING ON AFFECTED AREAS.                                                                          |                   | 950.00                    | 700.00            |
|                             | TO APPLY WATERPROOF SEALANT ON WEILDED PANELS.                                                                | NOT NECESSARY     | 120.00                    | -                 |

Report Ref No. CC4/ASM18011790/Kwb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                  | Description of Parts                                              | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|-------------------------------------------------------------------|-----------|---------------------------|-------------------|
|                                                                      | TO APPLY RUST PROOFING.                                           |           | 120.00                    | 30.00             |
|                                                                      | TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR. |           | 250.00                    | 200.00            |
|                                                                      | TO REPLACE 1 PC ALLOY RIM & PERFORM WHEEL BALANCING.              |           | 60.00                     | 20.00             |
|                                                                      | TO MACHINE PRESS 1 PC WHEEL BEARING.                              |           | 60.00                     | 30.00             |
|                                                                      | TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT.                       |           | 100.00                    | 80.00             |
|                                                                      | DIAGNOSTIC AND RE-PROGRAMME ELECTRONIC FUNCTIONS.                 |           | 220.00                    | 120.00            |
|                                                                      |                                                                   |           | 2,810.00                  | 1,700.00          |
| GRAND TOTAL                                                          |                                                                   |           | 14,993.30                 | 12,149.63         |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |                                                                   |           |                           | 9,275.00          |

Report Ref No. CC4/ASM18011790/Kwb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.