

*Kw*

# AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721  
 TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

SPT MOTORING LLP  
 c/o 46 Lentor Plain  
 Singapore 786548

*Not Authorized*  
*61 Lp @ 9600p*  
*Remove After Paint*  
*5 days* Date: 27/06/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: JAGUAR XF / SJV 7287 J</u>	
1 pc	front bumper	<i>Buck</i> 2,486.50 ✓
1 pc	front bumper side grille	<i>SL</i> 375.80 X
1 pc	front bumper side grille crome	<i>SL</i> 411.00 X
1 pc	front bumper side retainer	<i>DI</i> 169.00 ✓
1 pc	front head lamp assy	<i>MTG</i> 2,969.30 ✓
1 pc	front fender	<i>B</i> 652.60 ✓
1 pc	front fender dust cover	<i>DI</i> 138.20 ✓
1 pc	front fender crome air duct grille	<i>SL</i> 454.00 ✓
1 pc	front door side mirror assy	<i>CM</i> 969.70 ✓
1 pc	front door side mirror signal lamp	<i>CM</i> 275.80 ✓
1 pc	alloy rim	<i>SL</i> 1,104.00 ✓
1 pc	front lower arm	<i>DI</i> 575.90 ✓
1 pc	front kunckle arm	<i>B</i> 636.20 ✓
1 pc	front wheel bearing	<i>SL</i> 385.70 ✓
1 pc	front upper wish bone	<i>SL</i> 483.50 X
1 pc	front shock absorber	<i>B</i> 793.80 ✓
1 pc	front steering tie rod	<i>SL</i> 213.20 X
1 pc	front steering tie rod end joint	<i>SL</i> 107.50 X
1 pc	front forward trust arm	<i>SL</i> 335.30 Y
	Sub-total	13,537.00
	Less 10%	1,353.70
	Sub-total	12,183.30
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	<i>500</i> 900.00
	To check wiring system.	30.00 <i>200</i>
	To spray painting on affected areas.	<i>Foot</i> 950.00
	sub-total	14,063.30

Balance brought forward.	14,063.30	
To apply waterproof sealant on welded panels.	200 120.00	X
To apply rust proofing.	300 120.00	
To remove and install front undercarriage parts to enable repair.	? 250.00	2000
To replace 1 pc alloy rim & perform wheel balancing.	200 60.00	
To machine press 1 pc wheel bearing.	? 60.00	300
To perform 4 wheels computerised alignment.	800 100.00	
Diagnostic and re-programme electronic functions.	220.00	1200
<b>Total</b>	<b>14,993.30</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer:

Signature:

Date:

Work Order: R026146  
 V#: SJV7287J  
 Year: 10  
 Date: 3.7.18 16:08



SJV7287J

Jaguar : XF/XFR : 2010-15 (X250) : All Right-hand Drive Models/Japan (except India Diesel) : Rear Wheel Drive (except Supercharged)

Front : Left

Actual	Before	Specified Range
		-1°21' 0°09'
5°34'	5°34'	6°08' 7°38'
-0°53'	-0°53'	0°01' 0°13'
6°41'	6°41'	
6°26'	6°26'	

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°26'	-2°26'	-0°57' 0°33'
		5°35' 7°05'
-0°39'	-0°39'	0°01' 0°13'
9°13'	9°13'	
6°47'	6°47'	

Front

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Actual	Before	Specified Range
2°11'	2°11'	-1°09' 0°21'
-0°59'	-0°59'	-0°12' 1°18'
-2°32'	-2°32'	
-1°32'	-1°32'	0°01' 0°25'

Rear : Left

Actual	Before	Specified Range
-1°34'	-1°35'	-1°32' -0°02'
-0°07'	-0°07'	-0°01' 0°11'

Camber  
 Toe

Rear : Right

Actual	Before	Specified Range
		-1°32' -0°02'
0°31'	0°32'	-0°01' 0°11'

Rear

Cross Camber  
 Total Toe  
 Thrust Angle

Actual	Before	Specified Range
-0°27'	-0°30'	
0°24'	0°25'	-0°02' 0°22'
-0°19'	-0°19'	-0°08' 0°08'