

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0727/2018/GW 21-Jul-18 CHANG 1 of 1 SDA 8002 P Audi A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To remove rear exhaust silencers, dismantle and reinstall rear suspension assy. Inspect for damages and renew accordingly. S/N	\$ 2,800.00	✓
TOTAL LABOURS :		\$ 2,800.00	
Parts			
1	REAR STUB AXLE - LH	\$ 250.00	✓
2	REAR WHEEL BEARING - LH	\$ 387.00	✓
3	REAR AXLE BEAM	\$ 1,843.00	✓
4	GEARBOX MOUNTING - LH	\$ 234.00	✓
TOTAL PARTS :		\$ 2,714.00	
GRAND TOTAL :		\$ 5,514.00	

Adrian 23/7/18

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 8002 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>ld</i>	? \$	1,739.00 ✓
2	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE ld	\$	460.00 ld ?
3	FRONT BUMPER GRILLE-CENTRE <i>nee</i>	\$	140.00 +
4	FRONT FENDER-LH <i>Bulleed</i>	\$	746.00 ✓
5	FRONT FENDER BRACKER-LH ?	\$	34.00 ?
6	FRONT FENDER BRACE-LH <i>nee</i>	\$	84.00 X.
7	FRONT FENDER CLOSING ELEMENT-LH ?	\$	29.00 ?
8	FRONT WHEEL HOUSING LINER-LH <i>at</i>	\$	151.00 ✓
9	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$	77.00 ?
10	ALUMINIUM RIM -LH <i>at</i>	2 \$	1,318.00 ✓
11	RUBBER VALVE ?	4 \$	12.00 ?
12	NOISE INSULATION ?	\$	226.00 ? ✓ <i>int</i>
14	ASSEMBLY CARRIER ?	\$	890.00 ? ✓ <i>bt</i>
15	1 SET OF BONDED RUBBER BUSHES ?	\$	90.00 ? ✓ <i>de</i>
16	SPACER PLATE ?	2 \$	19.00 ?
17	CONSOLE-LH ?	\$	169.00 ?
18	FRONT SUSPENSION SUPPORT -LH/RH	2 \$	40.00
19	FRONT CONTROL ARM-LH	\$	320.00 ✓ <i>bt</i>
20	FRONT ANTI ROLL BAR	\$	354.00
SUB-TOTAL SPARE PARTS		\$	6,898.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 8002 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT BEARING HOUSING-LH <i>engd</i>	\$ 507.00	✓
22	FRONT WHEEL BEARING LHS WITH ASSEMBLY PARTS <i>u</i>	\$ 379.00	✓
23	FRONT GUIDE JOINT-LH <i>Best</i>	\$ 111.00	✓
24	COUPLING ROD <i>?</i>	\$ 85.00	?
25	FRONT DRIVE SHAFT-LH <i>Best</i>	\$ 2,131.00	✓
26	FRONT SUSPENSION STRUT STORAGE <i>?</i>	\$ 110.00	?
27	FRONT DEEP GROOVE BALL THRUST BEARING <i>?</i>	\$ 41.00	<i>2nd</i> ✓
28	FRONT GAS SHOCK ABSORBER-LH <i>Best</i>	\$ 243.00	✓
29	SHOCK ABSORBER RUBBER STOP <i>?</i>	\$ 48.00	?
30	BELLOWS <i>?</i>	\$ 37.00	?
31	FRONT LOWER SPRING PAD-LH <i>?</i>	\$ 19.00	?
32	STEERING GEAR <i>?</i>	\$ 4,290.00	<i>bt</i> ✓
33	STEERING REPAIR SET <i>?</i>	\$ 41.00	?
34	FRONT INNER TIE ROD-LH <i>?</i>	\$ 82.00	<i>bt</i> ✓
35	FRONT TIR ROD END -LH <i>?</i>	\$ 113.00	<i>bt</i> ✓
36	PROTECTIVE SLEEVE <i>?</i>	2 \$ 34.00	?
37	FRONT BRAKE CALIPER HOUSING-LH <i>?</i>	\$ 362.00	?
38	FRONT BRAKE CARRIER-LH <i>?</i>	\$ 262.00	?
39	FRONT BRAKE PAD-LH <i>engd</i>	\$ 209.00	✓
40	SOLID LUBRICANT PASTE <i>u</i>	\$ 196.00	✓
SUB - TOTAL SPARE PARTS		\$ 9,300.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 8002 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	LITHIUM LUBRICATING GREASE <i>m</i>	\$ 137.00	✓
42	FRONT BRAKE DICS <i>Bygd</i>	\$ 154.00	✓
41	BRAKE DISC COVER-LH <i>Bygd</i>	\$ 56.00	✓
42	TYRES <i>Involved Front</i>	2 TBC	1/2
43	SUNDRIES <i>?</i>	\$ 1,000.00	?
TOTAL SPARE PARTS		\$ 17,545.00	
TOTAL LABOUR CHARGES		\$ 7,272.00	
GRAND TOTAL		\$ 24,817.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SDA 8002 P

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0727/2018/MAS

20 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SDA 8002 P, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no **SDA 8002 P**, claimant, **Mr. Low Chuen Choi**, please find the related document per attached.

1. A copy of the Original invoice no. 85013119 – S\$24,178.19
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SDA 8002 P

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
 281 Alexandra Road
 Singapore 159938
 Main Telephone: 6366 2223
 Main Telefax: 6471 3733
 Page 5 10:40

Alexandra Service Centre
 281 Alexandra Road
 Singapore 159938
 Telephone: 6388 2223
 Telefax: 6475 1023

Ubi Service Centre
 55 Ubi Road 1
 Singapore 408629
 Telephone: 6388 2223
 Telefax: 6411 1483

Customer Service
 Service Appointment: 6366 2223
 Hour Breakdown Service: 9828 1233
 Email: customer.care@premiumauto.com.sg

INSURANCE TAX INVOICE
 Company Reg. No. 199902271W
 GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013119 Date: 12/11/2010 Order: SDA0002P Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SDA0002P (V 32101) Regn Date: 31/03/2017 Mileage: 17686 WIP No.: 14875
 Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V0H1028692 Engine: CHZ 150698 Dept: U
 VSB No.:
 You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
X	AN 10332002	NUT (Mech) Less 020%	3.00	2.10	5.04
X	AN 10695901	BOLT (Mech) Less 020%	2.00	16.80	26.88
X	AN 90915002	SCREW (Mech) Less 020%	6.00	1.00	4.80
X	AN 01033513	SCREW (Mech) Less 020%	1.00	2.10	1.68
X	AN 90954002	BOLT (Mech) Less 020%	1.00	6.50	5.20
X	AN 91246401	BOLT (Mech) Less 020%	3.00	2.10	5.04
X	AN 10552404	BOLT (REQ2) (Mech) Less 020%	1.00	10.40	8.32
X	AN 10552402	BOLT (Mech) Less 020%	2.00	10.30	16.48
X	AN 10648301	SCREW (Mech) Less 020%	2.00	1.00	1.60
X	AN 91231201	SCREW (Mech) Less 020%	4.00	3.80	12.16

Parts	14,224.44	Sub-Total	22,596.44
Labour	0.00	7% GST	1,581.75
Sublet	8,972.00	Grand Total	24,178.19
Menus	0.00		
Lubricant	0.00		



Received by _____ For & on behalf of Premium Automobiles Pte Ltd

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408660
Telephone: 6388 1233

Customer Service
Service Appointment: 6366 2323
24 hour Breakdown Service: 9828 1233
Email: customer.care@premiumauto.com.sg

INSURANCE TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 10:40

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoices: 85013119 Date : 12/11/2018 Order : SDA0002P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SDA0002P (V 32181) Regn Date: 31/03/2017 Mileage: 17686 WIP No.: 14875
 Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V0H1028692 Engine: CHZ 158698 Dept: U
 VSB No.:

You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FRONT FENDER. INSPECT FRONT LOCK CARRIER FOR DAMAGE. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO DISMANTLE FRONT SUSPENSION ASSY. INSPECT DAMAGES AND RENEW ACCORDINGLY	3200.00	1.00	3,200.00
S	BODYWORK	M: TO RENEW LHS FRONT AND REAR RIMS WITH TYRES.	320.00	1.00	320.00
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Page 2 10:40

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408721
Telephone 6388 2223


Customer Service
Service Appointment
9am Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013119 Date : 12/11/2018 Order : SDA8002P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SDA8002P (V 32181) Regn Date: 31/03/2017 Mileage: 17686 WIP No.: 14875
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V0H1028692 Engine: CHZ 158698 Dept: U
USB No.:
You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
S	BODYWORK	CARRY OUT WHEEL ALIGNMENT M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	2800.00	1.00	2,800.00
		TO REMOVE REAR EXHAUST SILENCERS, DISMANTLE AND REINSTALL REAR SUSPENSION ASSY. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY			
X	A8V0601025DC	RIM 16" C4E (Mech) (G) Less 020%	2.00	659.00	1,054.40
X	A5001993696	SUB FRAME (Mech) (SK) Less 020%	1.00	889.50	711.60
X	A8V0198037	RUBB. BUSH (Mech) (Ge) Less 020%	1.00	89.20	71.36
X	A500199117C	BRACKET (Mech) (SK) (A) Less 020%	1.00	169.00	135.20
X	A500199517E	SUPPORT (Mech) (SK) (A) Less 020%	1.00	20.00	16.00
X	A500407271DC	DRIVESHAFT (Mech) (Ge) Less 020%	1.00	2131.00	1,704.80
X	A500615311B	SHIELD (Mech) (SK) (A) Less 020%	1.00	55.90	44.72
X	A502423055F	STEERING (Ger) (V) Less 020%	1.00	4290.00	3,432.00
X	Z6205/55R1691W	GOODYEAR EFFICIENT G	2.00	295.00	590.00
X	A500501117A	STUB AXLE Less 020%	1.00	251.00	200.80
X	A5005010498F	REAR AXLE (SK) (V) Less 020%	1.00	1856.00	1,484.80
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6425 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408879
Telephone 6388 2223

Customer Service
Service Appointment 6388 2323
Hour Breakdown Service 6828 1223
Email customer.care@premiumauto.com.sg

INSURANCE TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W


Page 3 10:40

Invoice: 05013119 Date : 12/11/2018 Order : SDA0002P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120
---	---

Regn No.: SDA0002P (V 32181)	Regn Date: 31/03/2017	Mileage: 17686	WIP No.: 14875
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V0H1028692	Engine: CHZ 150698	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (87)			

		Details	Qty	Unit Price	Amount
X	ZG205/55R1691W	GOODYEAR EFFICIENT G	-1.00	295.00	-295.00
X	A8V5821105A	FENDER	1.00	746.00	596.80
X	A5Q0825236Q	BAFFLE (Mech)	1.00	226.00	180.80
X	A8V5821171G	WHEEL HOUS	1.00	151.00	120.80
X	A8V5807065R GRU	COVER (Ger) (V)	1.00	1739.00	1,391.20
X	AN 10770701	BOLT (Mech)	1.00	10.40	8.32
X	A5Q0615301H	BRAKE DISC (Mech)	1.00	153.50	122.80
X	A8V0698151G	BRK LINING (Mech)	1.00	209.00	167.20
X	A5Q01995558D	GEAR.MOUNT	1.00	233.50	186.80
X	A5Q0407151R	CONTR ARM (Mech)	1.00	320.00	256.00
X	A5Q0412249E	BEARING (Mech)	1.00	40.10	32.08
X	A5Q0407255Q	HOUSING (Mech) (SK) (A)	1.00	507.00	405.60
X	A1K0423811J	TIEROD END (Mech) (SK)	1.00	112.50	90.80
X	A1K0423810A	TIE ROD (Mech)	1.00	81.60	65.28
X	A5Q0407365A	JOINT (Mech)	1.00	111.00	88.80
X	A8V0598611A	BEARING	1.00	387.00	309.60
X	A8V0498625B	BEARING (Mech) (SK) (A)	1.00	379.00	303.20
X	A311601361	RUBBER VAL (Mech)	4.00	2.00	8.96
				Sub-Total	
				7% GST	
				Grand Total	

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408641
Telephone: 6388 2223

Customer Service
Service Appointment
24-hour Breakdown Service
Email

6386 2323
9828 1233

customer.care@premiumaudia.com.sg

Page 4 10:40

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013119 Date : 12/11/2018 Order : SDA8002P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SDA8002P (V 32181) Regn Date: 31/03/2017 Mileage: 17686 WIP No.: 14875
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V0H1028692 Engine: CHZ 158698 Dept: U
VSB No. :
You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
X	A1K0498970A	REP.SET (Mech) Less 020%	1.00	40.30	32.24
X	AG 000650	LUB PASTE (DG) (Mech) Less 020%	1.00	195.50	156.40
X	AG 052150A2	LITH.GREAS (Mech) Less 020%	1.00	137.00	109.60
X	ASQ0413023EB	GASSHOCKAB (Mech) Less 020%	1.00	242.50	194.00
X	AWHT005437	12 POINTS (Mech) Less 020%	2.00	12.60	20.16
X	AN 0161857	POP-RIVET Less 020%	6.00	2.90	13.92
X	AN 10785401	SCREW (REQ4) (Mech) Less 020%	4.00	9.90	31.68
X	AN 91167101	BOLT (REQ1) (Mech) Less 020%	1.00	7.10	5.68
X	AN 10786901	BOLT (Mech) Less 020%	3.00	3.50	8.40
X	AN 90948802	SCREW (Mech) Less 020%	2.00	10.30	16.48
X	AN 10105402	NUT (Mech) Less 020%	1.00	2.60	2.08
X	AN 91021601	NUT (Mech) Less 020%	1.00	5.70	4.56
X	AN 91066101	BOLT (REQ1) (Mech) Less 020%	1.00	7.10	5.68
X	AWHT006844	PLATE (Mech) (SK) (A) Less 020%	2.00	9.30	14.88
X	AN 01116417	NUT (Mech) Less 020%	2.00	3.10	4.96
X	AN 91201001	BOLT (REQ1) (Mech) Less 020%	1.00	14.30	11.44
X	AN 90991002	BOLT (Mech) Less 020%	6.00	2.60	12.48
X	AN 90942902	NUT (Mech) Less 020%	4.00	2.40	7.68
				Sub-Total	
				7% GST	
				Grand Total	

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SDA 8002 P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0727/2018/TF
18 July 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sedan 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V0H1028692
Vehicle Regn No. : **SDA 8002 P**
Vehicle Mileage : 17686KM
Vehicle Owner : Mr. Low Chue[^]Choi
Certificate No : 2100505086-01
Policy Excess : S\$642.00 (inclusive 7% GST)
Accident Date : 23RD June 2018
Place : Choa Chu Kang
Repair Cost : S 24,178.19
WIP No. : 14875
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 

Time : _____

Date : 21/07/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jun 2018		28 Jun 2018 14:59 Edit Adj Rpt	S\$23,196.44 Edit Estimates	S\$23,196.44 View Rpt		Pending for Survey Report Cancel Case

Main
Reference
Claim Details
Documents
[Show All](#)

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: **LOW CHUEN CHOI**, ID: S1158797F, Tel: +6596310870

Vehicle Reg. No.: **SDA8002P** Date of Loss: 23/06/2018 08:00 - :59
[14 Months and 23 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 4593198563SG** Policy/Cover Note No.: 2100505086-01 (Comprehensive)
Excess: S\$600.00

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Mohd Zawaye, Norsazani**]
Norsazani.Zawaye@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... [Final Rpt due 09/07/2018]

Driver/Custodian: **LOW JIA JUN** (27 / Male), NRIC: S9106364F, Tel: +6582280132

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (15/10/2018): Alert - Adj Mandate Approved (S\$23196.44) - SDA8002P - Claim Handler: Mohd Zawaye...
- AIG_SG (02/07/2018): Alert - Adj Mandate Approved (S\$14249.00) - SDA8002P - Claim Handler: Mohd Zawaye...
- AIG_SG (29/06/2018): SDA8002P / OD / 23/06/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDA8002P (4593198563SG)
 OD
 Jun 23 2018 8:30AM
 [LOW CHUEN CHOI]
 Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser ▼	
			1 per page ▼	<input checked="" type="checkbox"/>	
Assessment Reports					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/06/18 14:13	Adjuster Immediate Advice		Load HTM	<input type="checkbox"/>
2	07/09/18 14:47	Adjuster Immediate Advice		Load HTM	<input type="checkbox"/>
			3 per page ▼	<input checked="" type="checkbox"/>	
Photos/Images					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/06/18 14:08	General View		Load JPG	<input checked="" type="checkbox"/>
2	29/06/18 14:08	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
4	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
5	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
6	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
7	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
8	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
9	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
10	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
11	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
12	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
13	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
14	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
15	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
16	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
17	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
18	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
19	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
20	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
21	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
22	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
23	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
24	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
25	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
26	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
27	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
28	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
29	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
30	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
31	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>
32	29/06/18 14:09	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	06/09/18 16:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	06/09/18 16:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	06/09/18 16:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	06/09/18 16:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	06/09/18 16:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	06/09/18 16:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	06/09/18 16:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	06/09/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
82	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
84	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
90	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
96	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
97	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
98	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
99	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
100	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
101	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
102	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
103	06/09/18 16:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/06/18 14:08	Singapore Accident Statement	Load PDF	
2	29/06/18 14:08	Certificate of Insurance	Load PDF	
3	29/06/18 14:08	Insured's Driving License	Load PDF	
4	29/06/18 14:08	ESTIMATE	Load PDF	
5	07/09/18 14:40	SUPPLEMENTARY LIST	Load PDF	
6	07/09/18 14:43	REVISED ESTIMATE	Load PDF	
7	04/12/18 09:47	DISCHARGE VOUCHER	Load PDF	
8	04/12/18 09:47	WORKSHOP INVOICE	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/06/18 14:15	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
7	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	23/06/18 14:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/06/18 12:41	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	23/06/18 12:41	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18011792/AQBS2
Date: 04/12/2018

REFERENCE

Insured/Claimant: LOW CHUEN CHOI Policy No: 2100505086-01
Date of Loss: 23/06/2018 Nature of Claim: OD Claim No: 4593198563SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDA8002P**
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ158698
Reg. Date: 31/03/2017 (Man. Year: 2016) Chassis No: WAUZZZ8V0H1028692
Colour: Black Odometer: 12686 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$100,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,022.00	14,224.44	5,797.56	28.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,072.00	8,972.00	1,100.00	10.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,094.00	23,196.44	6,897.56	22.92
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	29,494.00	22,596.44	6,897.56	23.39
+ GST 7.00/7.00% (S\$)	2,064.58	1,581.75	482.83	23.39
Nett Amount (S\$)	31,558.58	24,178.19	7,380.39	23.39

INSPECTION

Date of Assignment: 28/06/2018
Date Inspected: 23/06/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,739.00 FS	*1,391.20 FS
2	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	140.00 FS	*- FS
3	1		*FRONT FENDER - LH	Buckled	746.00 FS	*596.80 FS
4	1		*FRONT FENDER BRACKET - LH	Not Necessary	34.00 FS	*- FS
5	1		*FRONT FENDER BRACE - LH	Not Necessary	84.00 FS	*- FS
6	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	29.00 FS	*- FS
7	1		*FRONT WHEEL HOUSING LINER - LH	Cut	151.00 FS	*120.80 FS
8	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	77.00 FS	*- FS
9	2		*ALUMINIUM RIM - LH	Cut	1,318.00 FS	*1,054.40 FS
10	4		*RUBBER VALVE	Necessary	12.00 FS	*8.96 FS
11	1		*NOISE INSULATION	Torn	226.00 FS	*180.80 FS
12	1		*ASSEMBLY CARRIER	Damaged	890.00 FS	*711.60 FS
13	1		*SET OF BONDED RUBBER BUSHES	Necessary	90.00 FS	*71.36 FS
14	2		*SPACER PLATE	Necessary	19.00 FS	*14.88 FS
15	1		*CONSOLE - LH	Damaged	169.00 FS	*135.20 FS
16	1		*FRONT SUSPENSION SUPPORT - LH/RH	N/s Damaged	40.00 FS	*16.00 FS
17	1		*FRONT CONTROL ARM - LH	Bent	320.00 FS	*256.00 FS
18	1		*FRONT ANTI ROLL BAR	Not Necessary	354.00 FS	*- FS
19	1		*FRONT BEARING HOUSING - LH	Damaged	507.00 FS	*405.60 FS
20	1		*FRONT WHEEL BEARING LHS WITH ASSEMBLY PARTS	Necessary	379.00 FS	*303.20 FS
21	1		*FRONT GUIDE JOINT - LH	Bent	111.00 FS	*88.80 FS
22	1		*COUPLING ROD	Not Necessary	85.00 FS	*- FS
23	1		*FRONT DRIVE SHAFT - LH	Bent	2,131.00 FS	*1,704.80 FS
24	1		*FRONT SUSPENSION STRUT STORAGE	Not Necessary	110.00 FS	*- FS
25	1		*FRONT DEEP GROOVE BALL THRUST BEARING	Damaged	41.00 FS	*32.08 FS
26	1		*FRONT GAS SHOCK ABSORBER - LH	Bent	243.00 FS	*194.00 FS
27	1		*SHOCK ABSORBER RUBBER STOP	Not Necessary	48.00 FS	*- FS
28	1		*BELLOWS	Not Necessary	37.00 FS	*- FS
29	1		*FRONT LOWER SPRING PAD - LH	Not Necessary	19.00 FS	*- FS
30	1		*STEERING GEAR	Damaged	4,290.00 FS	*3,432.00 FS
31	1		*SET STEERING REPAIR	Necessary	41.00 FS	*32.24 FS
32	1		*FRONT INNER TIE ROD - LH	Bent	82.00 FS	*65.28 FS
33	1		*FRONT TIE ROD END - LH	Bent	113.00 FS	*90.00 FS
34	2		*PROTECTIVE SLEEVE	Not Necessary	34.00 FS	*- FS
35	1		*FRONT BRAKE CALIPER HOUSING - LH	Not Necessary	362.00 FS	*- FS
36	1		*FRONT BRAKE CARRIER - LH	Not Necessary	262.00 FS	*- FS
37	1		*FRONT BRAKE PAD - LH	Damaged	209.00 FS	*167.20 FS
38	1		*SOLID LUBRICANT PASTE	Necessary	196.00 FS	*156.40 FS
39	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	460.00 FS	*- FS
40	1		*LITHIUM LUBRICATING GREASE	Necessary	137.00 FS	*109.60 FS
41	1		*FRONT BRAKE DISCS	Damaged	154.00 FS	*122.80 FS
42	1		*BRAKE DISC COVER - LH	Damaged	56.00 FS	*44.72 FS
43	2		*TYRES	Punctured	295.00 FS	*295.00 FS
44	1		*SUNDRIES	Necessary	1,000.00 FS	*240.72 FS
45	1		*REAR STUB AXLE - LH	Bent	200.80 FS	*200.80 FS
46	1		*REAR WHEEL BEARING - LH	Necessary	309.60 FS	*309.60 FS
47	1		*REAR AXLE BEAM	Bent	1,484.80 FS	*1,484.80 FS
48	1		*GEARBOX MOUNTING - LH	Torn	186.80 FS	*186.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	20,022.00	14,224.44
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE, TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FRONT FENDER. INSPECT FRONT LOCK CARRIER FOR DAMAGE. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,800.00	1,000.00
3	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER.	New	1,400.00	1,100.00
4	TO DISMANTLE FRONT SUSPENSION ASSY. INSPECT DAMAGES AND RENEW ACCORDINGLY.	New	3,200.00	3,200.00
5	TO RENEW LHS FRONT AND REAR REAR RIMS WITH TYRES. CARRY OUT WHEEL ALIGNMENT.	New	320.00	320.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
7	TO REMOVE AND EXHAUST SILENCERS, DISMANTLE AND REINSTALL REAR SUSPENSION ASSY. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	New	2,800.00	2,800.00
Gross Labour Cost (S\$)			10,072.00	8,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >