

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0705/2018/PH
Date : 21-Jun-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Miss Carolyn Joyce Tie
Address : 19 Taman Serasi
#09-25
Singapore 257723
Telephone : HP +65 98249252
Type of Claim : Own Damage Claim
Policy No. : 1700095001
Vehicle No : **SLV 6048 R**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Jan-18
Engine No : CHZ 592033
Chassis No : WAUZZZ8V3J1029762
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-Jun-18
Place of Accident : Ngee Ann City Parking Basement

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 6048 R.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper. Repair lhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,800.00 750
3	To respray rear bumper and lhs rear fender.	\$ 1,600.00 1100
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>3,872.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2489 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER COVER <i>Repair</i>	\$ 1,697.00	+
2	FIXING PARTS FOR BUMPER	\$ 166.00	X
3	WHEEL HOUSING LINER - LH <i>Free a</i>	\$ 32.00	X
4	GUIDE SECTION - LH <i>Free a</i>	\$ 14.00	+
5	GUIDE SECTION - RH <i>Free a</i>	\$ 14.00	+
6	LOCKING MECHANISM	2 \$ 50.00	+
7	REAR LIGHT REFLECTOR <i>Free a</i>	\$ 35.00	+
8	GUIDE SECTION	\$ 57.00	+
9	SUNDRIES	\$ 200.00	?
TOTAL SPARE PARTS		: \$ 2,265.00	
TOTAL LABOUR CHARGES		: \$ 3,872.00	
GRAND TOTAL		: \$ 6,137.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lg

Surveyed Date

: 28/06/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Authorised Repairs, 04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant