

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/EE8218B/1806102

27th June 2018

The Manager
Motor Claim Department
EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
LKK
The repairer's
Hdy.
28/6/18

Date of Accident : 24th June 2018
Location : Blk 769 Bedok Reservoir View
Third Party Claim Vehicle No : GBG 941 Z
Repair Cost For Vehicle No : EE 8218 B Honda HRV

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bonnet <i>DI/Buc</i>	1	892.30	\$ 892.30 ✓
2	Front bonnet hinge L&RH <i>n</i>	2	48.50	\$ 97.00 X
3	Front bonnet rubber <i>ner</i>	4	23.00	\$ 92.00 ✓
4	Front bonnet rubber clips <i>ner</i>	4set	15.00	\$ 15.00 ✓
5	Front support panel	1	576.20	\$ 576.20 ?
6	Front grille (top) <i>one</i>	1	385.00	\$ 385.00 ✓
7	Front grille (bottom) <i>one</i>	1	351.80	\$ 351.80 ✓
8	Front grille chrome <i>ner</i>	1	75.00	\$ 75.00 ✓
9	Front grille emblem (H) <i>ner</i>	1	28.00	\$ 28.00 ✓
10	Headlamp assy L&RH <i>MS holder one o/s?</i>	2	1,784.50	\$ 3,569.00 <i>one</i>
11	Headlamp lower bracket L&RH	2	38.00	\$ 76.00 ?
12	Front bumper fascia <i>DI/pe</i>	1	801.70	\$ 801.70 ✓
13	Front bumper clips <i>ner</i>	1set	38.00	\$ 38.00 ✓
14	Front bumper side retainer L&RH <i>MS sel</i>	2	25.60	\$ 51.20 <i>one</i>
15	Front bumper bracket L&RH	2	19.60	\$ 39.20 ?
16	Front bumper reinforcement	1	321.00	\$ 321.00 ?
17	Front bumper lower skirt <i>n</i>	1	381.00	\$ 381.00 X
18	Front bumper grille	1	77.50	\$ 77.50 ?
19	Radiator top shield	1	85.00	\$ 85.00 ?
20	Radiator top shield clips	1set	38.00	\$ 38.00 ?
				\$ 7,989.90

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/EE8218B/1806102

27th June 2018

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
	Balance b/f			\$ 7,989.90
21	Front fender LH	1	558.70	\$ 558.70
22	Front fender arch LH	1	195.00	\$ 195.00
23	Front fender arch clips LH	1 set	38.00	\$ 38.00
				\$ 8,781.60
		Less	20%	\$ 1,756.32
				\$ 7,025.28

Labour Charges :-

	<u>Amounts</u>
Cut out, renew, knocking & welding front bonnet, front support panel, front fender L&RH, remove & install all damage parts, straighten & re-align body	\$ 1,380.00
Remove & install air-con system, vacuum & top up gas	\$ 120.00
Tuff-kote on damage parts	\$ 120.00
Spray painting on damage parts	\$ 1,580.00
Check all lighting after repairs	\$ 35.00
Labour Charge	\$ 3,235.00
Total Amount	\$10,260.28

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.