

ASSIGNMENT

Surveyor:

Kenneth

DOI:

28/6/18

Date / Time:

28/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GH 3123J

Name of Insured:

TRANSPORT EXPRESS

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

28/6/18

Claim No.:

13/18/18/1000/020710

Policy No.:

2171000/100 433-001

Make / Model:

T. DYMA

Place of Accident:

YISHUN AVE 1

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

MAMODASKIL B. ABUL GAFUR

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

96157153

(VL: YES / NO)

Insured Liability: %

Final ? Yes / No

GH 3123J



INSRS: WSP: Tel: Liability: RMKS:

Chang Hoe



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date / Time		STAGE	DATE / PIC
4/18	GH 3123J	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
03/08/18	PIG REVIEWED. OLD INVOLVED IN 4 VEH-C.C. & WAS THE LAST DATE. EQUAL LIABILITY CLM. ORIGINAL TP LOD IN	Call OI:	
		After call ltr to OI:	
		Documentation Check List: Handler Typist	
01/09/19	TYPE REPORT FOR WARRANTS APPROVAL REPORT DONE	Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
06/08/19	SENT WARRANTS APPROVAL TO LFC	Car Rental Invoice:	
08/08/19	LFC APPROVED WARRANTS.	Towing Invoice:	
	SENT ACCEPTANCE BUAL TO TP.	LTA / GIA:	
21/10/19	RECEIVED BY. ALL BOCS IN ORDER. TO CLOSE.	Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	

PRELIMINARY ADVICE Date/Time: 03/07/18 Sent By: AS

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: P/P S\$ 15,512.97 ( 10 days) Reduction: 8 % Email Call

FINAL SETTLEMENT Date/Time: 08/10/19 Confirm with: SUNG Email Call

Final Liability: % 100 (Agree / Assessed) BOLA S/N No.: 28 If NO or B 28, Ass. Lia: 100%

Repair Cost: (W/ISS) S\$ 14,461.97 CA VEH. C.C., OLD COST

Loss of Rental (LOR): S\$ ( days)

Loss of Use (LOU): S\$ 1,040.00 (\$80 x 13 days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search S\$ 8.00

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/Independent)

Legal Cost S\$ -

Total: S\$ 15,512.97 Global Sum S\$: -

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: S\$ 15,512.97 Name 1: CHANG HOE MOTOR PTE LTD

Payee 2: (Strike if N.A.) S\$ - Name 2: -

Payee 3: (Strike if N.A.) S\$ - Name 3: -

COPY SENT 23/10/19

ASS. REC. BY:

REF: LPC /

Kenneth

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Cheng Hoo

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBE 3192J Yr Regn: 10, 15

Type: M.Car / M.Cycle / Bus / Van / Korry / Taxi / Prime Mover / Truck / Trailer or \_\_\_\_\_

Make: NIS Cobstar c.c. 2453 3153

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 63996 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN1SC2F2480857757

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 195R15X8

R: 155R12X8(0)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 4 4 mm

L/Bal. 6 mm L/Bal. 4 4 mm

D.O.A. 26/6/18 D.O.I. 28/6/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or 215

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>29/6</u>	<u>File pass to Catherine</u>
<u>3/5</u>	<u>13518-66 email</u> <u>(add: \$1,264.97 (0%))</u>

Date/Time, File Pass to?  : Prell. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

- Add Fee:  : Site Insp (\$ \_\_\_\_\_)
- : Interview (\$ \_\_\_\_\_)
- : Tech Invs (\$ \_\_\_\_\_)
- : Weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
\$ - RS. SI	_____
Fixtads	_____
Others	_____
TOTAL	_____

Report Format : \_\_\_\_\_

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

GBE3192J  
 TP/LONPAC

M/S : LONPAC INSURANCE BERHAD  
 300 BEACH ROAD  
 #17-04/07 THE CONCOURSE  
 SINGAPORE 199555

TEL: 62507388 FAX: 62963767

ATTN: Motor Claim Department

WS Ref: TP/LONPAC/YS *Not Authored*

Claim Type: Third Party *HKP 813518.66*

Accident Date: 26/06/2018 *Recovery After Paint*

TP Veh Reg No: GH3123J *10 days*

Estimate No: ES1890714/YISHUN

Date: 28 Jun 2018

Policy No: 5074859309-02

Veh Reg No: GBE3192J

Make/Model: NISSAN CABSTAR

Chassis No: JN1SC2F24Z0857757

Engine No: ZD30003215N

Reg. Date: 26/10/2015

### Estimate Repair Cost to Vehicle No : GBE3192J

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>Net Price</b>				
1 REAR TAILGATE	1,399.70	1 PC	1,399.70	✓
2 TAILGATE STICKER (NISSAN)	141.80	1 PC	141.80	✓
3 TAILLAMPS	155.40	2 PCS	310.80	✓
4 FRONT BUMPER	1,039.60	1 PC	1,039.60	✓
5 FRONT CHASSIS CROSS MEMBER	449.30	1 PC	449.30	7 R X
6 FRONT GRILLE	578.60	1 PC	578.60	✓
7 FRONT GRILLE LOGO	66.40	1 PC	66.40	✓
8 FRONT PANEL	1,412.70	1 PC	1,412.70	✓
9 FRONT PANEL EMBLEM (CABSTAR)	45.00	1 PC	45.00	✓
10 FRONT WIPER PANEL	494.60	1 PC	494.60	✓
11 FRONT WINDSCREEN GLASS <i>moulding</i>	358.00	1 PC	358.00	✓
12 FRONT WINDSCREEN GLASS SEAL	45.00	1 PC	45.00	✓
13 HEADLAMPS	473.40	2 PCS	946.80	✓
14 HEADLAMP LOWER GARNISH	75.00	1 PC	75.00	✓
15 FRONT RH CORNAL PANEL	448.10	1 PC	448.10	✓
16 FRONT RH SIDE MIRROR STAY GARNISH	111.30	1 PC	111.30	✓
			7,922.70	
		Less 10%	792.27	7,130.43
<b>Special Net</b>				
17 AIR-CON BLOWER	870.40	1 PC	870.40	✓
18 AIR-CON EVAPORATOR UNIT	1,511.60	1 PC	1,511.60	✓
19 REAR SAFETY BAR	350.00	1 PC	350.00	✓ 4220 ✓
20 STICKER (70KM/H)	10.00	1 PC	10.00	✓
21 STICKER (13 PAX)	10.00	1 PC	10.00	✓
22 TAILGATE PROTECTOR	380.00	1 PC	380.00	✓
23 FRONT WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
24 FRONT NUMBER PLATE	18.00	1 PC	18.00	✓
25 REVERSE SENSOR	200.00	1 SET	200.00	✓
			3,390.00	3,390.00

*byp*  
↓

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

GBE 3192J  
 TP/Lonpac  
 pg 2/2

**M/S :** LONPAC INSURANCE BERHAD  
 300 BEACH ROAD  
 #17-04/07 THE CONCOURSE  
 SINGAPORE 199555

TEL: 62507388 FAX: 62963767  
 ATTN: Motor Claim Department  
 WS Ref: TP/LONPAC/YS

Claim Type: Third Party  
 Accident Date: 26/06/2018  
 TP Veh Reg No: GH3123J

**Estimate No:** ES1890714/YISHUN  
**Date:** 28 Jun 2018  
**Policy No:** 5074859309-02  
**Veh Reg No:** GBE3192J  
**Make/Model:** NISSAN CABSTAR  
**Chassis No:** JN1SC2F24Z0857757  
**Engine No:** ZD30003215N  
**Reg. Date:** 26/10/2015

### Estimate Repair Cost to Vehicle No :GBE3192J

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>Labour</b>				
26 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00 ✓	100.00 ✓
27 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00 ✓	100.00 ✓
28 REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00 ✓	250.00 ✓
29 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,FRT WIPER ASSY,HEADLAMPS,TO CUT,WELD & RENEW FRT PANEL,FRT MAIN CHASSIS MEMBER,STRAIGHTEN,KNOCK & REPAIR FRT RH W/SCREEN PILLAR,FRT RH DOOR,PILLAR,FRT MAIN CHASSIS & REALIGN THE SAME	1,200.00	1 LA	950? 1,200.00	950? ✓
30 PUTTY & RESPRAY ON FRT RH CORNAL PANEL,FRT WIPER PANEL,FRT PANEL,GRILLE,GARNISH,FRT RH DOOR,PILLAR,ETC	900.00	1 LA	700? 900.00	700? 720 ✓
31 REMOE & REFIX TAILGATE ASSY,TAILLAMPS,REAR SAFETY BAR,TAILGATE PROTECTOR,STRAIGHTEN,KNOCK & REPAIR TAILGATE LOWER MEMBER,REAR SPARE TYRE HOLDER,REAR CHASSIS & REALIGN THE SAME	800.00	1 LA	700? 800.00	700? 800 ✓
32 PUTTY & RESPRAY ON TAILGATE,LOWER MEMBER,SAFETY LOCK,ETC	600.00	1 LA	500? 600.00	500? ✓
			3,950.00	3,950.00

Parts # 7473.40 N  
 lens id/2 747.34  
 6726.06  
 3260 → SN  
 3350  
 312.60  
 Labour  
 Supp  
 13,648.66

Total S\$ 14,470.43  
 Add GST @ 7% 1,012.93  
 Total Amount Payable S\$ 15,483.36

**For Cheng Hoe Motor Pte Ltd**

AUTHORISED SIGNATURE

14783.03

# Cheng Hoe Motor Pte Ltd

GBE 3192J  
SUPP 1

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

**M/S :** LONPAC INSURANCE BERHAD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

TEL: 62507388 FAX: 62963767  
ATTN: Motor Claim Department  
WS Ref: TP/LONPAC/YS

Claim Type: Third Party  
Accident Date: 26/06/2018  
TP Veh Reg No: GH3123J

**Estimate No:** ES1890714/YISHUN  
**Date:** 04 Jul 2018  
**Policy No:** 5074859309-02  
**Veh Reg No:** GBE3192J  
**Make/Model:** NISSAN CABSTAR  
**Chassis No:** JN1SC2F24Z0857757  
**Engine No:** ZD30003215N  
**Reg. Date:** 26/10/2015

### Estimate Repair Cost to Vehicle No :GBE3192J

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>Supplementary 1</b>				
<b>Net Price</b>				
1 FRONT BUMPER BRACKETS	57.00	2 PCS	114.00	114.00
		Less 10%	11.40	102.60
<b>Special Net</b>				
2 REAR COY ADVERTISEMENT PLATE	180.00	1 PC	180.00	180.00
<b>Labour</b>				
3 RUSTPROOFING	30.00	1 LA	30.00	30.00
			Total	S\$ 312.60
			GST Amount	S\$ 21.88
			Total Amount Payable	S\$ 334.48

**For Cheng Hoe Motor Pte Ltd**

  
 \_\_\_\_\_  
 AUTHORISED SIGNATURE

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

*GBE3192J*  
*TP/LONPAC*

**M/S :** LONPAC INSURANCE BERHAD  
 300 BEACH ROAD  
 #17-04/07 THE CONCOURSE  
 SINGAPORE 199555

TEL: 62507388 FAX: 62963767  
 ATTN: Motor Claim Department  
 WS Ref: TP/LONPAC/YS

Claim Type: Third Party  
 Accident Date: 26/06/2018  
 TP Veh Reg No: GH3123J

**Estimate No:** ES1890714/YISHUN  
**Date:** 28 Jun 2018  
**Policy No:** 5074859309-02  
**Veh Reg No:** GBE3192J  
**Make/Model:** NISSAN CABSTAR  
**Chassis No:** JN1SC2F24Z0857757  
**Engine No:** ZD30003215N  
**Reg. Date:** 26/10/2015

*Not Authorized*  
*11hp 87*  
*Repair After Paint 10 days*

### Estimate Repair Cost to Vehicle No :GBE3192J

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>Net Price</b>				
1 REAR TAILGATE	1,399.70	1 PC	<i>B</i> 1,399.70	✓
2 TAILGATE STICKER (NISSAN)	141.80	1 PC	<i>Ne</i> 141.80	✓
3 TAILLAMPS	155.40	2 PCS	<i>CM</i> 310.80	✓
4 FRONT BUMPER	1,039.60	1 PC	<i>B</i> 1,039.60	✓
5 FRONT CHASSIS CROSS MEMBER	449.30	1 PC	<i>R</i> 449.30	✓
6 FRONT GRILLE	578.60	1 PC	<i>Ne</i> 578.60	✓
7 FRONT GRILLE LOGO	66.40	1 PC	<i>Ne</i> 66.40	✓
8 FRONT PANEL	1,412.70	1 PC	<i>B</i> 1,412.70	✓
9 FRONT PANEL EMBLEM (CABSTAR)	45.00	1 PC	<i>Ne</i> 45.00	✓
10 FRONT WIPER PANEL	494.60	1 PC	<i>Wip</i> 494.60	✓
11 FRONT WINDSCREEN GLASS <i>Midy</i>	<i>Ne</i> 358.00	1 PC	<i>Fit</i> 358.00	✓
12 FRONT WINDSCREEN GLASS SEAL	45.00	1 PC	<i>Ne</i> 45.00	✓
13 HEADLAMPS	473.40	2 PCS	<i>CM</i> 946.80	✓
14 HEADLAMP LOWER GARNISH	75.00	1 PC	<i>Bu</i> 75.00	✓
15 FRONT RH CORNAL PANEL	448.10	1 PC	<i>B</i> 448.10	✓
16 FRONT RH SIDE MIRROR STAY GARNISH	111.30	1 PC	<i>MB/CM</i> 111.30	✓
			7,922.70	
		Less 10%	792.27	7,130.43
<b>Special Net</b>				
17 AIR-CON BLOWER	870.40	1 PC	<i>1 hour CM</i> 870.40	✓
18 AIR-CON EVAPORATOR UNIT	1,511.60	1 PC	<i>CM</i> 1,511.60	✓
19 REAR SAFETY BAR	350.00	1 PC	<i>mis</i> 350.00	✓
20 STICKER (70KM/H)	10.00	1 PC	<i>Ne</i> 10.00	✓
21 STICKER (13 PAX)	10.00	1 PC	<i>Ne</i> 10.00	✓
22 TAILGATE PROTECTOR	380.00	1 PC	<i>Bu</i> 380.00	✓
23 FRONT WINDSCREEN GLASS GUM	40.00	1 PC	<i>Ne</i> 40.00	✓
24 FRONT NUMBER PLATE	18.00	1 PC	<i>B</i> 18.00	✓
25 REVERSE SENSOR	200.00	1 SET	<i>Ne</i> 200.00	✓
			3,390.00	3,390.00

# Cheng Hoe Motor Pte Ltd

Blk 1019, Vishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

**M/S :** LONPAC INSURANCE BERHAD  
 300 BEACH ROAD  
 #17-04/07 THE CONCOURSE  
 SINGAPORE 199555

TEL: 62507388 FAX: 62963767  
 ATTN: Motor Claim Department  
 WS Ref: TP/LONPAC/YS

Claim Type: Third Party  
 Accident Date: 26/06/2018  
 TP Veh Reg No: GH3123J

**Estimate No:** ES1890714/YISHUN  
**Date:** 28 Jun 2018  
**Policy No:** 5074859309-02  
**Veh Reg No:** GBE3192J  
**Make/Model:** NISSAN CABSTAR  
**Chassis No:** JN1SC2F24Z0857757  
**Engine No:** ZD30003215N  
**Reg. Date:** 26/10/2015

### Estimate Repair Cost to Vehicle No :GBE3192J

Description	U/Price	Quantity	List Price SS	Amount SS
<b>Labour</b>				
26 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	✓
27 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
28 REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
29 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,FRT WIPER ASSY,HEADLAMPS,TO CUT,WELD & RENEW FRT PANEL,FRT MAIN CHASSIS MEMBER,STRAIGHTEN,KNOCK & REPAIR FRT MAIN CHASSIS & REALIGN THE SAME	1,000.00	1 LA	1,000.00	7501
30 PUTTY & RESPRAY ON FRT RH CORNAL PANEL,FRT WIPER PANEL,FRT PANEL,GRILLE,GARNISH,ETC	680.00	1 LA	680.00	6001
31 REMOE & REFIX TAILGATE ASSY,TAILLAMPS,REAR SAFETY BAR,TAILGATE PROTECTOR,STRAIGHTEN,KNOCK & REPAIR TAILGATE LOWER MEMBER,REAR SPARE TYRE HOLDER,REAR CHASSIS & REALIGN THE SAME	600.00	1 LA	600.00	5501
32 PUTTY & RESPRAY ON TAILGATE,LOWER MEMBER,SAFETY LOCK,ETC	450.00	1 LA	450.00	4001
			3,180.00	3,180.00
			Total	SS 13,700.43
			Add GST @ 7%	959.03
			Total Amount Payable	SS 14,659.46

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**For Cheng Hoe Motor Pte Ltd**

*[Handwritten Signature]*

\_\_\_\_\_  
 AUTHORISED SIGNATURE



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VC00/020710  
Our ref: CC4/LPC18011802/Kha3

Date: 03.07.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**GBE 3192JJ**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28.06.2018 at the premises of M/s Cheng Hoe Motor Pte Ltd have the following to report:-

Workshop Estimate Amount	: S\$	<u>13,700.43</u>	
Revised Estimate Amount	: S\$	<u>10,383.89</u>	
"Check" Items Amount	: S\$	<u>2,886.54</u>	
Total (Including Check Items)	: S\$	<u>13,270.43</u>	
Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10.0 day

Yours faithfully,

**KENNETH KONG**  
**Licensed Appraiser**

> **Back to OneMotoring**

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	9664D
<b>Vehicle Details</b>	
Vehicle No.:	GBE3192J
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jun 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	ZD30003215N
Chassis No.:	JN1SC2F24Z0857757
Maximum Power Output:	-
Open Market Value:	\$24,033.00
Original Registration Date:	26 Oct 2015
First Registration Date:	26 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$1,202.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	25 Oct 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,501.00
COE Rebate Amount:	\$34,064.00
<b>Total Rebate Amount:</b>	<b>\$34,064.00</b>

The information contained herein is correct as at 27 Jun 2018

OK

**Catherine Chong (LKK Auto)**

---

**From:** ERIC WOO JUN KIAT <ericwoo@lonpac.com>  
**Sent:** Thursday, 28 June, 2018 10:56 AM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** FW: Repair Survey (Single Joint Expert) - GH 3123J Our Ref: 17/18/18/VC00/020710  
**Attachments:** S-chmys18062719050.jpg

Dear Catherine / Nivitha,

Kindly refer to our attachment and email below.

Please proceed to appoint Kenneth Kong conduct a survey of the vehicle GBE 3192J on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

28062018 @ 11:04am

Efecta veh in

Kenneth

---

**From:** Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]  
**Sent:** Wednesday, 27 June, 2018 7:06 PM  
**To:** ERIC WOO JUN KIAT  
**Cc:** MT\_Claim\_SG  
**Subject:** Re: Repair Survey (Single Joint Expert) - GBE3192J Our Ref: 17/18/18/VC00/020710

Hi Eric,

Pls refer attach list of our selection.

Thank you.

Rgds  
June Phua  
Cheng Hoe Motor Pte Ltd  
Tel :67556142  
Fax : 67557719

**From:** ERIC WOO JUN KIAT  
**Sent:** Wednesday, June 27, 2018 5:12 PM  
**To:** Cheng Hoe Motor Pte Ltd (Yishun-June)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Repair Survey (Single Joint Expert) - GBE3192J Our Ref: 17/18/18/VC00/020710

Dear June,

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

---

**From:** Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]  
**Sent:** Wednesday, 27 June, 2018 4:09 PM  
**To:** MT\_Claim\_SG  
**Subject:** Repair Survey (Single Joint Expert) - GBE3192J

Dear Sir,

**OUR CLIENT – GBE3192J**  
**DOA - 26/6/18 @1730hrs**  
**YR INSURED : GH3123J (TRANSPORTER EXPRESS)**

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards  
June  
Cheng Hoe Motor Pte Ltd  
Blk 1019 Yishun Ind Park A  
01-374, Singapore 768761  
Tel :67556142  
Fax : 67557719

## Mei Kwan (LKKAuto)

---

**From:** Mei Kwan (LKKAuto)  
**Sent:** Tuesday, 3 July, 2018 4:48 PM  
**To:** 'ERIC WOO JUN KIAT'  
**Cc:** 'MT\_Claim\_SG'; ONG LI LI; 'GERALD POH WEE BIN'; Vic (LKKAuto); Hsiao Tong (LKKAuto); Admin A  
**Subject:** RE: Repair Survey (Single Joint Expert) - GH 3123J Our Ref: 17/18/18/VC00/020710  
**Attachments:** TP ESTIMATE - MARKED.pdf; TP GIA REPORT.pdf; LKK SURVEY PHOTO.pdf; Preliminary Advice.pdf  
  
**Categories:** HMK

### WITHOUT PREJUDICE

**LPC ref: 17/18/18/VC00/020710**  
**LKK REF: CC4/LPC18011802/Kha3**

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: GBE 3192JJ

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- TP GIA report
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Please take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

***To check availability of the case handler, you may contact the undersigned.***

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 28 June, 2018 11:05 AM  
**To:** 'ERIC WOO JUN KIAT' <ericwoo@lonpac.com>; assignments <assignments@lkkauto.com>  
**Cc:** 'MT\_Claim\_SG' <mt\_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: Repair Survey (Single Joint Expert) - GH 3123J Our Ref: 17/18/18/VC00/020710

Dear Eric,

Thank you for the assignment.

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

---

**From:** Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]  
**Sent:** Wednesday, 27 June, 2018 4:09 PM  
**To:** MT\_Claim\_SG  
**Subject:** Repair Survey (Single Joint Expert) - GBE3192J

Dear Sir,

**OUR CLIENT – GBE3192J**  
**DOA - 26/6/18 @1730hrs**  
**YR INSURED : GH3123J (TRANSPORTER EXPRESS)**

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards  
June  
Cheng Hoe Motor Pte Ltd  
Blk 1019 Yishun Ind Park A  
01-374, Singapore 768761  
Tel :67556142  
Fax : 67557719

**LETTER OF AUTHORISATION**

(FOR PROPERTY DAMAGE CLAIM ONLY)

Re: Motor Insurance Claim GBE3192J  
in respect of the traffic accident on 26/6/2018  
at/along Seletar West Link towards Yishun Ave 8

I/We, 800 Landscape Pte Ltd  
NRIC 200919664D of 14A Senoko Way Singapore 758056

owner of motor vehicle GBE3192J, insured by NTUC Income Insurance  
Co-operative Ltd under policy no. 5074859309-02

hereby authorise M/s **CHENG HOE MOTOR PTE LTD** of Blk 1019 Yishun Industrial Park A #01-374 Singapore 768761, to act as my/our representative in my/our claim against the owner/driver of motor vehicle GH3123J in respect of the above-mentioned accident.


I further authorise that any payment due to me/us from the aforesaid claim is to be directed to my/our abovenamed representative.

And I/We hereby indemnify my/our abovenamed representative against any claim and/or damage which may arise from any action taken on my/our behalf.

I/We affirm all the above by my/our signature below.

Signed : \_\_\_\_\_

Date : \_\_\_\_\_

  
31/7/18





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18011802/Kha3s2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 25-10-2019



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GH 3123J	Veh. Inspected	GBE 3192J
Policy No.	Z/17/VC00/100433-001	Coverage (\$)	0.00
Claim No.	17/18/18/VC00/020710	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	28/06/2018

## 2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JN1SC2F24Z0857757	Colour	WHITE
Odometer	63996	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	YOKOHAMA	6 mm
L/H Front Tyre	195 R15X8	YOKOHAMA	6 mm
R/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	4/4 mm
L/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	4/4 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	26/06/2018	Inspection Date	28/06/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 3192J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR TAILGATE (N)	BENT	1,399.70	1,399.70
1	TAILGATE STICKER (NISSAN) (N)	NECESSARY	141.80	141.80
2	TAILLAMPS @ \$155.40 (N)	CRACKED	310.80	310.80
1	FRONT BUMPER (N)	BENT	1,039.60	1,039.60
1	FRONT CHASSIS CROSS MEMBER (N)	TO REPAIR SEE LABOUR	449.30	-
1	FRONT GRILLE (N)	DENTED	578.60	578.60
1	FRONT GRILLE LOGO (N)	NECESSARY	66.40	66.40
1	FRONT PANEL (N)	BENT	1,412.70	1,412.70
1	FRONT PANEL EMBLEM (CABSTAR) (N)	NECESSARY	45.00	45.00
1	FRONT WIPER PANEL (N)	WARPED	494.60	494.60
1	FRONT WINDSCREEN GLASS MOULDING (N)	NECESSARY	358.00	358.00
1	FRONT WINDSCREEN GLASS SEAL (N)	NECESSARY	45.00	45.00
2	HEADLAMPS @ \$473.40 (N)	CRACKED	946.80	946.80
1	HEADLAMP LOWER GARNISH (N)	BUCKLED	75.00	75.00
1	FRONT RH CORNER PANEL (N)	BENT	448.10	448.10
1	FRONT RH SIDE MIRROR STAY GARNISH (N)	MTG CRACKED	111.30	111.30
2	FRONT BUMPER BRACKETS @ \$57.00 (N) (ADDITIONAL)	BENT	114.00	114.00
	LESS 10% DISCOUNT		-803.67	-758.74
			7,233.03	6,828.66
<b>SPECIAL NETT ITEMS</b>				
1	AIR-CON BLOWER (SN)	HOUSING CRACKED	870.40	870.40
1	AIR-CON EVAPORATOR UNIT (SN)	CRACKED	1,511.60	1,511.60
1	REAR SAFETY BAR (SN)	MISSING	350.00	220.00
1	STICKER (70KM/H) (SN)	NECESSARY	10.00	10.00
1	STICKER (13 PAX) (SN)	NECESSARY	10.00	10.00
1	TAILGATE PROTECTOR (SN)	BUCKLED	380.00	380.00
1	FRONT WINDSCREEN GLASS GUM (SN)	NECESSARY	40.00	40.00
1	FRONT NUMBER PLATE (SN)	BENT	18.00	18.00
1	SET REVERSE SENSOR (SN)	DENTED	200.00	200.00

Report Ref No. CC4/LPC18011802/Kha3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR COY ADVERTISEMENT PLATE (SN) (ADDITIONAL)	NECESSARY	180.00	180.00
			3,570.00	3,440.00
	<b>LABOUR</b>			
	REMOVE AND REFIX FRONT WINDSCREEN GLASS.		100.00	100.00
	REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS.		100.00	100.00
	REMOVE & REFIX DASHBOARD, METER ASSY & CHECK WIRING.		250.00	250.00
	REMOVE & REFIX FRT BUMPER ASSY, GRILLE, FRT WIPER ASSY, HEADLAMPS, TO CUT, WELD & RENEW FRT PANEL, FRT MAIN CHASSIS MEMBER, STRAIGHTEN, KNOCK & REPAIR FRT RH W/SCREEN PILLAR, FRT RH DOOR, PILLAR, FRT MAIN CHASSIS & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT CHASSIS CROSS MEMBER.		1,200.00	950.00
	PUTTY & RESPRAY ON FRT RH CORNAL PANEL, FRT WIPER PANEL, FRT PANEL, GRILLE, GARNISH, FRT RH DOOR, PILLAR, ETC.		900.00	720.00
	REMOVE & REFIX TAILGATE ASSY, TAILLAMPS, REAR SAFETY BAR, TAILGATE PROTECTOR, STRAIGHTEN, KNOCK & REPAIR TAILGATE LOWER MEMBER, REAR SPARE TYRE HOLDER, REAR CHASSIS & REALIGN THE SAME.		800.00	600.00
	PUTTY & RESPRAY ON TAILGATE, LOWER MEMBER, SAFETY LOCK, ETC.		600.00	500.00
	RUSTPROOFING. (ADDITIONAL)		30.00	30.00
			3,980.00	3,250.00
<b>GRAND TOTAL</b>			<b>14,783.03</b>	<b>13,518.66</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>13,518.66</b>

Report Ref No. CC4/LPC18011802/Kha3s2

KSC

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.