

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5239K**AAD1806-241***Not Authorised*
11 Sep 8

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5239K
VF1ABL15AUC276785
RENAULT
LATITUDE
24.6.2018
CHINA TAIPING

PART		LIST	
1	BUMPER COVER FRT	\$	<i>CMA</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
1	BUMPER RETAINER FRT LH	\$	<i>D/I</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77 X
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80 X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP LH	\$	<i>MJCM</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>D/I</i> 278.84 —
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79
1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84
1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	RADIATOR FAN COWLING	\$	<i>SL</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>SL</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>SL</i> 1,479.46
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	AIR CLEANER BOX	\$	<i>SL</i> 464.20
1	AIR CLEANER HOSE	\$	<i>SL</i> 175.85

Trans-cab Auto Services Pte Ltd

AAD1806-241

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5239K

1	LOWER ARM LH L70Y	\$	685.76	7
1	KUNCKLE ARM LH L70Y	\$	846.98	7
1	ABSORBER FRT LH L70Y	\$	360.54	7

TOTAL	\$	20,784.28
10%	\$	2,078.43
	\$	18,705.85

Specical Nett

1SET	BUMPER CLIP FRT	\$	na	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1SET	WHEELARCH CLIP FRT RH	\$	na	30.50	✓
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	X
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	X
1	FRONT LEFT TYRE	\$	na	300.00	608.00 (WRN)
1	FRONT LEFT TYRE RIM	\$	na	380.00	✓
TOTAL		\$		1,118.00	

TOTAL PARTS	\$	19,823.85
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	400
Putty and spray painting of the affected portion.	\$	3,000.00	440
To rust-proofing of the affected areas.	\$	170.00	30
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X

Trans-cab Auto Services Pte Ltd**AAD1806-241**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5239K

To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00	X
To replace, refix and top up coolant for radiator	\$	nn 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00	X

TOTAL	\$	8,710.00
--------------	-----------	-----------------

Over All Total	\$	28,533.85
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~10 DAYS~~
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: