

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 24R**AAD1806-245***Not Authorized*
*Li Song & 3001*Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :**SHD 24R**
VF1ABL15AUC281528
RENAULT
LATITUDE
25.6.2018
III

PART		LIST	
1	1 BUMPER COVER REAR	\$	1,108.46
2	1 BUMPER LOWER REAR	\$	768.84
3	1 BUMPER BRACKET CTR REAR	\$	113.47
4	1 BUMEP R BRACKET SIDE RH REAR	\$	135.97
5	1 BUMEP R RETAINER RH REAR	\$	44.99
6	1 BUMPER REFLECTOR RH	\$	43.61
7	1 BUMEP R BRACKET SIDE LH REAR	\$	135.97
8	1 BUMEP R RETAINER LH REAR	\$	44.99
9	1 BUMPER REFLECTOR LH	\$	43.61
10	1 BUMPER BEAM REAR	\$	777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$	225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	225.95
13	1 BOOT REAR	\$	2,872.68
14	1 BOOT FINISHER	\$	470.06
15	1 BOOT WHEATERSTRIP	\$	323.05
16	1 BOOT REFLECTOR LAMP LH	\$	493.35
17	1 BOOT REFLECTOR LAMP RH	\$	493.35
18	1 BOOT BADGE 'RENAULT'	\$	225.36
19	1 BOOT BADGE	\$	225.36
20	1 BOOT STRUT LH	\$	276.08
21	1 BOOT STRUT RH	\$	276.08
22	1 BOOT HINGE LH	\$	367.84
23	1 BOOT HINGE RH	\$	367.84
24	1 BOOT INNER TRIM	\$	586.45
25	1 BOOT SWITCH	\$	168.13
26	1 BOOT LOCK	\$	202.67
27	1 BOOT LOCK CATCH	\$	74.40
28	2 LICENCE PLATE LAMP	\$	50.52
29	2 BOOT RUBBER PLUG	\$	221.81

Trans-cab Auto Services Pte Ltd**AAD1806-245**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 24R

30	1 DOOR PANEL REAR LH	\$	2,844.66	}
31	1 FENDER PANEL INNER TRIM REAR LH	\$	671.45	
32	1 FENDER PANEL REAR LH	\$	3,299.13	
33	1 WHEELARCH REAR LH	\$	543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	671.45	
35	1 FENDER PANEL REAR RH	\$	3,299.13	
36	1 WHEELARCH REAR RH	\$	543.47	
37	1 TAILLAMP RH	\$	552.55	
38	1 TAILLAMP PANEL RH	\$	986.70	
39	1 TAILLAMP LH	\$	552.55	
40	1 TAILLAMP PANEL LH	\$	986.70	
41	1 OUTER PANEL REAR (End Panel)	\$	1,471.77	
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	404.56	
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	2,189.88	
44	1 SPARE WHEEL PANEL TRIM	\$	612.21	
45	1 EXHAUST REAR	\$	7,489.05	
46	1 EXHAUST CAP REAR	\$	230.49	
47	1 FUEL FLAP L70Y	\$	343.57	
48	1 CHASSIS PANEL REAR LH	\$	3,766.43	
TOTAL		\$	42,823.60	
10%		\$	4,282.36	
		\$	38,541.24	

Special Nett

1	1SET PARKING AID	\$	700.00	}
2	1SET REAR BUMPER CLIP	\$	66.00	
3	1SET BUMPER BRACKET CTR CLIP	\$	33.00	
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	
5	1SET BUMPR RETAINER RH CLIP RR	\$	20.00	
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	10.00	
7	1SET BUMPR RETAINER CLIP LH RR	\$	20.00	
8	1SET BUMPER LOWER REAR RIVET	\$	22.00	
9	1SET BUMPER LOWER REAR CLIP	\$	66.00	
10	1 EXHAUST MOUNTING REAR	\$	17.82	
11	1SET BOOT FINISHER CLIP	\$	24.20	
12	1 BOOT STICKER "Trans-cab"	\$	30.00	
13	1 BOOT STICKER "6555-3333"	\$	30.00	

Trans-cab Auto Services Pte Ltd**AAD1806-245**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 24R

14	1 BOOT INNER TRIM CLIP	\$	na 45.00	}	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	35.00		
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	35.00		
17	1 FENDER INNER TRIM CLIP LH	\$	28.00		
18	1 FENDER INNER TRIM CLIP LH	\$	28.00		
19	1 TAILLAMP CLIP RH	\$	5.00		
20	1 TAILLAMP CLIP LH	\$	5.00		
21	2 REAR WINDSCREEN SELANT	\$	80.00		
22	1 WINDSCREEN MOULDING	\$	100.00		
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00		
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na 385.00	}	
25	1 SPARE TYRE	\$	na 330.00		

TOTAL \$ 2,225.02**TOTAL PARTS \$ 40,766.26****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	201
To Rust-Proofing Of The Affected Areas.	\$	na 170.00	X
To reinstall rear bumper parking sensor.	\$	na 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1806-223**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5823Z

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>L</i> 170.00	<i>X</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>L</i> 380.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>L</i> 380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>L</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>S</i> 220.00	<i>X</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>L</i> 380.00	<i>X</i>
TOTAL	\$	12,540.00	

Over All Total \$ 53,306.26**(LUMP SUM)****Repair Days****20-DAYS***1 day***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: