

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 128A

AAD1806-256

*Not Authorised
Running B4 paint 83505.51*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 128A

VF1ABL15AUC282229

RENAULT

LATITUDE

25.6.2018

Alt.

PART		LIST	
1	BUMPER COVER FRT	\$	<i>11</i> 1,259.42
1	BUMPER SPOILER FRT	\$	<i>12</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>12</i> 394.68
1	BUMPER RETAINER FRT LH	\$	<i>12</i> 151.41
1	BUMPER SUPPORT FRT	\$	<i>12</i> 123.88
1	BUMPER RETAINER FRT RH	\$	<i>12</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>12</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>12</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>12</i> 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	<i>12</i> 207.21
1	BUMPER FOG LAMP GRILLE RH	\$	<i>12</i> 207.21
1	BUMPER BEAM FRT	\$	<i>11</i> 914.08
1	FENDER PANEL FRT LH	\$	<i>12</i> 783.83
1	WHEELARCH FRT LH	\$	<i>12</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>12</i> 15.79
1	FENDER INSULATOR LH	\$	<i>12</i> 130.84
1	DOOR PANEL FRT LH	\$	<i>11</i> 2,844.66
1	DOOR HINGE UPPER LH	\$	<i>11</i> 261.28
1	DOOR HINGE LOWER LH	\$	<i>11</i> 300.55
1	DOOR CHECK FRT LH	\$	<i>12</i> 194.77
1	DOOR LOCK FRT LH	\$	<i>11</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>12</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>12</i> 477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>12</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>12</i> 133.60
1	DOOR REGULATOR FRT LH	\$	<i>12</i> 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>12</i> 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>12</i> 120.97
1	DOOR PANEL REAR LH	\$	<i>11</i> 2,844.66
1	DOOR GUIDE REAR LH	\$	<i>12</i> 176.82

Trans-cab Auto Services Pte Ltd**AAD1806-256**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 128A

1	DOOR HINGE UPPER LH	\$	274.50
1	DOOR HINGE LOWER LH	\$	300.55
1	DOOR CHECK REAR LH	\$	203.06
1	DOOR LOCK REAR LH	\$	908.75
1	DOOR HANDLE OUTER REAR LH	\$	126.49
1	DOOR HANDLE CAP REAR LH	\$	35.52
1	DOOR HANDLE SEAL REAR LH	\$	7.89
1	DOOR HANDLE COVER REAR LH	\$	13.22
1	DOOR HANDLE MODULE REAR LH	\$	133.60
1	DOOR REGULATOR REAR LH	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	893.75
1	DOOR REGULATOR NUT REAR LH	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR LH	\$	423.10
1	DOOR MOULDING REAR LH	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR LH	\$	1,509.06
1	DOOR WATER SHIELD REAR LH	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR LH	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR GRAB HANDLE REAR LH	\$	210.96
1	DOOR BLIND REAR LH	\$	741.80
1	DOOR WHEATHESTRIIP REAR LH	\$	410.66
1	DOOR SEAL REAR LH	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31
1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69
1	DOOR WAIST SEAL INNER REAR LH	\$	115.64
1	FENDER PANEL REAR LH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR LH	\$	543.47
1	DOOR MIRROR ASSY LH	\$	1,483.40
1	ROCKER PANEL INNER GARNISH LH	\$	466.51

Trans-cab Auto Services Pte Ltd

AAD1806-256

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 128A

1	ROCKER PANEL INNER LH	\$	R	1,024.79	}
1	ROCKER PANEL CENTER LH	\$	R	990.25	
1	LOWER ARM LH L70Y	\$	Sn	685.76	
1	KUNCKLE ARM LH L70Y	\$	Sn	846.98	
1	ABSORBER FRT LH L70Y	\$	Sn	360.54	
1	HEADLAMP LH	\$	Sn	1,184.43	
1	AIR CLEANER BOX	\$	Sn	464.20	
1	AIR CLEANER HOSE	\$	Sn	175.85	
		\$		36,471.15	
10%		\$		3,647.11	
		\$		32,824.03	

Specical Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	}
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	} 605n
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	} 605n
1	DOOR CHECK BOLT	\$	Sn	22.69	
1	DOOR GUIDE SCREW	\$	na	10.85	}
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	
1SET	BUMPER CLIP FRT	\$	na	66.00	
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
1	TOW COVER FRT	\$	Sn	14.50	
1SET	RADAITOR GRILLE SCREW	\$	na	16.00	

Trans-cab Auto Services Pte Ltd

AAD1806-256

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 128A

1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00 <i>X</i>
1	FRONT LEFT TYRE	\$	<i>nn</i> 330.00 <i>X</i>
1	FRONT LEFT TYRE RIM	\$	<i>nn</i> 380.00 <i>X</i>

TOTAL \$ 1,434.63**TOTAL PARTS \$ 32,893.03****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>4000</i> 6,000.00
Putty and spray painting of the affected portion.	\$	5,000.00 <i>8800</i>
To rust-proofing of the affected areas.	\$	170.00 <i>300</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1806-256**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 128A

To transfer of front door fittings, attachment and perform water seepage test. \$ *in* 380.00 X

To transfer of Rear door fittings, attachment and perform water seepage test. \$ 380.00 X

Towing Fees. \$ 120.00 X

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack. \$ 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. \$ 380.00 X

TOTAL \$ 14,890.00

Over All Total \$ 47,783.03

LUMP SUM (REPAIR DAY)~~20 DAYS~~*3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: