

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

18/06/18
09:20am

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0242/2018
DATE : 16-JUN-2018

QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY
#29-10 SOUTH TOWER
S(048583)
TEL : 62246633
FAX : 65345356
ATTN:MS JENNY TOH/YEE PING

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

I/P : 94568832 FAX : 64697472

OWNER'S NAME : MR LI SHUIPENG
ADDRESS : BLK 217 BUKIT BATOK STREET 21
#01-365
S(650217)
TELEPHONE NO : 90016865

Yee

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-SDS3138U
VEHICLE NO : SLS6865P
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2497970A
CHASSIS NO : SJNFEAJ11U2038608
MILEAGE : 1 KM
DATE IN : 16/06/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 06/06/2018

Tanfik 97495749
WP
24/7/18 21045
Resurvey before paint
03 days
sur@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLS6865P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	?
2	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	/
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 02	200.00	?
4	ZZ/001	REPAIR END PANEL,RH REAR FENDER AND RENEW REAR BUMPER	1200.00	390
5	ZZ/002	S/PAINT END PANEL,RH REAR FENDER AND REAR BUMPER	1200.00	250
6	ZZ/003	CHEKC LIGHTING	48.00	/
TOTAL LABOUR CHARGES			3118.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLS6865P

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00	?
2	SUNDRIES	NPN			100.00	?
3	STAY ASSY-REAR RH	H5210-4EAMA	126.00	?		
4	CLIP BUMPER \$1.20 EA X 02	01553-05933	2.40	ng		
5	GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40	ng
6	RETAINER-BUMPER RH	79184-4EA0A	23.80	?		
7	BRACKET-BUMPER RH	85220-4EA0A	35.90	?		
8	RETAINER-BUMPER LH	79185-4EA0A	23.80	X		
9	BRACKET-BUMPER LH	85221-4EA0A	35.90	X		
10	STAY ASSY-REAR LH	H5211-4EAMA	126.00	X		
11	REINF-BUMPER RR	H5030-4EAMA	619.20	?		
12	ENERGY ABSORBER	85090-HV00A	126.40	?		
13	CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20	ng		
14	CANOE RIVET BUMPER \$6.50 EA X 02	76882-0M000	13.00	ng		
15	FINISHER-REAR BUMPER TOW	85071-HV00A	16.80	cut		
16	FASCIA-RR BUMP	85022-HV00H	717.00	de		
17	CLIP END PANEL GARNISH \$1.20 EA X 02	01553-05323	2.40	?		
18	CLIP END PANEL GARNISH \$1.20 EA X 04	01554-00181	4.80	?		
19	PLATE-LUGGAGE	84992-4EA0A	63.50	?		
20	GROMMET ARC	01281-00831	1.50	?		
21	CLIP ARC \$1.20 EA X 05	01553-05131	6.00	?		
22	PROTECTOR-REAR FENDER	76748-4EA2A	186.40	?		
23	FENDER ARC RH REAR	93828-4EA0A	483.00	?		
24	ORNAMENT ASSY RH BUMPER	26560-JJ90A	55.00	?		

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLS6865P

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
SUB TOTAL		2691.00	0.00	314.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		538.20	0.00	0.00
GRAND TOTAL		2152.80	0.00	314.40
OVERALL TOTAL		2467.20		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLS6865P

TOTAL LABOUR CHARGES	3118.00
TOTAL SPARE PARTS CHARGES	2467.20

GRAND TOTAL	5585.20 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.