

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305180575

REGN NO : SHB3232Y

MILEAGE : 0000000000

MAKE : HYUNDAI

MODEL : I-40

DATE OF REGN : 15.12.2017

DATE/TIME IN : 27.06.2018 11:30

ACCIDENT DATE : 26.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0600-G WING MIRROR LH 1 980.50 20.00 784.40

Front Bumper x repair
Front LH Fender x repair

SUB-TOTAL : 784.40

JOB NATURE

0000 L PANEL BEATING

0001 23-502 Spraypaint-Frt Bumper/LHF Fender

0002 17-01 CHECK ALL LIGHTING

0003 20-00 TUFF COAT ON AFFECTED PARTS.

~~300.00~~ 200~~500.00~~ 450~~40.00~~ x 2~~40.00~~ x 2

SUB-TOTAL : 880.00

TOTAL : 1,664.40

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Kalvin LKK
27/6/18 1505h
2 Pys
P/P
Before Part photo

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: