



Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6Ark@KB
Singapore 417892
Email: contact@vfixauto.com.sg
Tel: 64489268 Fax: 64452368

M/S AIG ASIA PACIFIC INS PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

ESTIMATE

DATE : 28/06/2018
ACC DATE : 25/06/2018
REF NO. : VFIX-TP20180494
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :XD5777D VOLVO FMX

DESCRIPTION	AMOUNT S\$
1 1 HEADLAMP HOUSING RH <i>510</i>	392.60 ✓
2 1 HEADLAMP HOUSING INDICATOR RH <i>310</i>	202.80 ✓
3 1 HEADLAMP HOUSING INDICATOR COVER RH <i>510</i>	44.20 ✓
4 1 HEADLAMP TOP	278.20 7
5 1 HEADLAMP CENTER	108.16 7
6 1 HEADLAMP LOWER	430.95 7
7 1 HEADLAMP COVER RH <i>1310</i>	358.00 ✓
8 1 HEADLAMP COVER BRACKET RH <i>311</i>	36.40 ✓
9 3 HEADLAMP BULD <i>111</i>	44.20 132.60 X
10 1 HEADLAMP WIRE HARNESS RH <i>111</i>	190.06 X
11 1 HEADLAMP PANEL RH	543.40 ?
12 1 HEADLAMP PANEL BRACKET RH	57.20 ?
13 1 HEADLAMP PANEL BRACKET TOP	81.12 ?
14 1 HEADLAMP PANEL END GARNISH RH	117.80 ?
15 1 FRONT PANEL	1,488.50 ?
16 1 FRONT PANEL TOP GRILLE <i>one</i>	610.35 ✓
17 1 FRONT PANEL CENTER GRILLE	715.00 ?
18 1 FRONT BUMPER <i>111 RH 111</i>	411.45 ✓
19 1 FRONT BUMPER BRACKET RH <i>111</i>	44.20 ✓
20 1 FRONT BUMPER HOLE PLUG RH <i>111</i>	36.00 ✓
21 1 FRONT BUMPER MAIN BEAM <i>R</i>	941.40 X
22 1 FRONT BUMPER REINFORCEMENT <i>R</i>	1,223.80 X?
23 1 FRONT BUMPER REINFORCEMENT BRACKET <i>111</i>	85.80 ?
24 1 FRONT BUMPER GUARD <i>111</i>	679.25 X
25 1 FRONT BUMPER GUARD OUTER PLATE <i>111</i>	863.20 X
26 1 FRONT BUMPER END GARNISH NO1 RH <i>111</i>	128.00 ✓
27 1 FRONT BUMPER END GARNISH NO2 RH <i>111</i>	128.00 ✓
28 1 FRONT STEP BOARD RH <i>111</i>	450.00 X
29 1 FRONT STEP BOARD GARNISH RH <i>one</i>	680.00 ✓
	\$ 11,458.44

102

LABOUR & MISCELLANEOUS:		AMOUNT S\$
1	To remove damaged parts with all necessary components/attachments apply hot-works where necessary replace new parts refit align into position with all necessary components attachments	2,400.00 <i>for</i>
2	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	2,000.00 <i>650</i>
3	To conduct headlamp alignment	50.00 <i>20</i>
		<u>\$ 4,450.00</u>
GRAND TOTAL :		\$ 15,908.44

SINGAPORE DOLLARS : FIFTEEN THOUSAND NINE HUNDRED EIGHT &
CENTS FORTY FOUR ONLY

Vfix Auto Service Pte Ltd



*Not done
2/5/18
3 days
2/7/18
The prob the eye*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: