

REF: CS/FWD18011822/Krbez

Special Instructions:

S.V. 06/18

ASSIGNMENT (Office)

Mandate

From (Person): Josey loh of FWD Date/Time: 28062018 258pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKU 8527D Insured:

at Workshop w/s An Lim Motor Tel: 6483 1244

of Blk 10 AMK Ind Park 2A #01-09

Policy No: PN PV 2017 - 00008944 Claim No: 1201800007949

Sum Insured: Excess: \$500.00

Make of Veh: D.O.A. 25062018

(Client's Record)

CA / BLV / REP. / REV 24 HRS

29-06-2018

H.O.D. Endorsement:

Date/Time: 28062018 352pm Person Contacted: Aila Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKU 8527D - x
29/6/18	Revert thru merimen
29/6/18 (5.11pm)	Joscy approve mandate
2/7/18	Authorise repair & inform 2/la

ASS REC BY

REF: FWD

ASSIGNMENT

From: Date: 29/6/18

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKU 8527D

at Workshop n/s: Ah Lim Motor

of BIK 10, AMK Ind. Park 2A #01-09

Insured

Policy No.

Claims No.

Sum Insured Excess: \$ 500.00

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 67k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res: Yes or No

Lum Sum: 1.3.1 % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKU 8527D Yr Regn: 08 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki Solio Wagon C.C. 1242

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 39240 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WA 155 - 262189

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 165/60 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continents

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 25/6/18

Survey held at

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/7 File pass to Catherine

8-668-50

27/9/18 Finalize with muihong \$ 6778.50 @ 6 days
Red: \$ 2784.50, 29%
RECEIVED 1 OCT 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

200

50

50+50

10

360

Report Format: 00

Lum Sum / I.B.I: (\$ 6778.50)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS/FWD18011822/Krb

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 28-06-2018



Code : FWD

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKU 8527D
Policy No.	PNPV2017-00008944	Coverage (\$)	0.00
Claim No.	1201800007949	Excess (\$)	500.00
Assign From	MERIMEN (JOSEY LOH)	Assign Date	28/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	25/06/2018	Inspection Date	29/06/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2018 Sendback Est	28 Jun 2018 14:43 \$59,492.00	28 Jun 2018 14:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	NICHOLAS LO HAN PHENG, ID: S7902112A, Tel: +6593685564, Email: NIC290179@GMAIL.COM		
Vehicle Reg. No.:	SKUB527D	Date of Loss:	25/06/2018 07:00 - :59 [34 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800007949	Policy/Cover Note No.:	PNPV2017-00008944 (Comprehensive)
		Excess:	\$5500.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/07/2018]		
Driver/Custodian:	NICHOLAS LO HAN PHENG (39 / Male), NRIC: S7902112A, Tel: +6593685564		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 29 Jun 2018

Preliminary Advice

Vehicle No	: SKU8527D	Accident Date	: 25/06/2018
Make	: SUZUKI SOLIO	Policy No.	: PNPV2017-00008944
Assignment Date	: 28/06/2018	Excess	: S\$500.00
Date of Inspection	: 29/06/2018	Est. Duration of Repair	: 6.00
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,482.00
Revised Amount	:S\$	5,122.50
Check Items (Estimated)	:S\$	2,273.50
Total	:S\$	7,396.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	57,000.00
COE / PARF Rebate	:S\$	45,592.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,408.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

SKU8527D (1201800007949)

OD

Jun 25 2018 7:00AM

[NICHOLAS LO HAN PHENG]

Ah Lim Motor Company

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 29/06/2018 17:11 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7396.00) - SKU8527D - Claim Handler: Josey Loh

Approved:7396.00.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, July 02, 2018 9:54 AM
To: 'zila@ahlimmotor.com.sg'
Cc: SUR
Subject: SKU 8527D FWD OD DOA: 25/6/2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKU 8527D (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2112A

Vehicle Details

Vehicle No.: SKU8527D
Vehicle to be Exported: Yes
Intended De-registration Date: 25 Jun 2018
Vehicle Make: SUZUKI
Vehicle Model: SOLIO 1.2 CVT
Primary Colour: White
Manufacturing Year: 2014
Engine No.: K12B1929000
Chassis No.: MA15S262189
Maximum Power Output: 67.0 kW (89 bhp)
Open Market Value: \$12,201.00
Original Registration Date: 20 Aug 2015
First Registration Date: 20 Aug 2015
Transfer Count: 1
Actual ARF Paid: \$7,201.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 Aug 2025
PARF Rebate Amount: \$5,400.00

Intended COE Rebate Details

COE Expiry Date: 19 Aug 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,209.00
COE Rebate Amount: \$40,192.00
Total Rebate Amount: \$45,592.00

The information contained herein is correct as at 25 Jun 2018

OK

5th

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/06/2018 13:29
Date Of Accident	25/06/2018 07:45
Exact Location Of Accident	CTE TOWARDS AYE NEAR BALESTIER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU8527D
Insured/Policyholder	
Name Of Registered Owner	NICHOLAS LO HAN PHENG
NRIC No	S7902112A
Email Address	NIC290179@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93685564
Alternative Phone No	OTHERS-93685564

Vehicle Particulars

Manufacturer	SUZUKI
Model	SOLIO-1.2 CVT (A)

Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
--	-------------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00008944
Cover Note Number	29/11/2017 - 28/11/2018


Driver

Name of Driver	NICHOLAS LO HAN PHENG
NRIC No	S7902112A
Date Of Birth	29/01/1979
Occupation	INDOOR
Date Of Driving Pass	17/03/2008
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93685564
Fax Number	
Contact Number	OTHERS-93685564
Email Address	NIC290179@GMAIL.COM

Vehicle Registration Number	SJL8660K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 2

Date of accident: 25/06/18 Time: 7.45 am Location: CTE (Toward AYE) NBN Bektier.
 My Vehicle A: SRW 8527D Vehicle B: SHC 8057Z Vehicle C: SJL 866OK
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on the second lane towards CTE (Toward AYE). Travelling speed about 60-70 km/h. Car B and relatively a good distance from Car B.

Upon realising Car B was completely stopped ~~at~~ ^{the} Car A due to a light accident with Car C, I tried to jam brake but car seems to skid on the wet road and hit straight to Car B.

Car C driver claimed that his car has nothing wrong and he attempted to drive off. I stopped him and Car B driver took a photo of his carplate and the back of his car.

Both Car B and I would like to claim the insurance of Car C.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address : nic290179@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Officer's Signature
 Name:
 NRIC/FIN No.:
 AH LIM MOTOR COMPANY

Sketch Plan Pg. 4

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7902112A



Name

NICHOLAS LO HAN PHENG
(LU HANPING)

卢汉平

Race

CHINESE

Date of birth 29-01-1979

Sex

M

Country of birth
SINGAPORE

K4502112A

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S7902112A

NICHOLAS LO HAN PHENG
(NICHOLAS LU HANPING)

Birth Date 29 Jan 1979

Issue Date 17 Mar 2008



Ipax
Video-yes
no in jing
raining

93685568



NRIC No S7902112A



Date of issue

02-02-2009

APT BLK 135 LORONG AH SOO #10-474
SINGAPORE 530135

NRIC No: S7902112A

Date: 05/12/2017

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 3500kg 17 Mar 2008



License No: S7902112A

RP 425A

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A

#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg

GST Reg No: M9-0009639-E

INSURER: FWD Singapore Pte. Ltd. (HQ)

SURVEYOR COPY

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00008944	Date of Loss:	25/06/2018
Vehicle Reg. No.:	SKU8527D	Driveable?	
Driver Age/Info:	39 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NICHOLAS LO HAN PHENG	Contact No:	+6593685564
Driver:	NICHOLAS LO HAN PHENG		
Make/Model:	SUZUKI SOLIO, 1.2 CVT (A)	Vehicle Reg. Date:	20/08/2015
Vehicle Colour:	WHITE		
Engine No:	K12B1929000	Chassis No:	MA15S262189
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18/6 days		
Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER		
Remarks:	CAR IN @ ALM AMK AUTOPOINT WORKSHOP		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS

Parts		Amount
Miscellaneous Items		5,922.00
Labour		0.00
Paintwork Labour		3,560.00
Towing		0.00
		0.00
	Gross Total (S\$)	9,482.00
	+ GST 7.00% (S\$)	663.74
	Nett Amount (S\$)	10,145.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jun 2018)
 Parts: 144 SUZUKI SOLIO 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SKU8527D/28/06/2018 14:43
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No. Particulars	%Disc	%Depr	Amount	
1	2	*FRONT WIPER SIDE GARNISH LH & RH - CHECK PRICE	0.00	0.00	*F	X
2	1	*FRONT BONNET	0.00	0.00	*330.00 F	✓
3	2	*FRONT BONNET HINGE LH & RH	0.00	0.00	*36.00 F	✓
4	1	*FRONT BONNET INSULATOR	0.00	0.00	*55.00 F	✓
5	9	*FRONT BONNET INSULATOR CLIPS	0.00	0.00	*13.50 F	✓
6	1	*FRONT BONNET STAND CLIPS (AT BONNET) - CHECK PRICE	0.00	0.00	*F	X
7	1	*FRONT BONNET INNER LOCK	0.00	0.00	*25.00 F	✓
8	1	*FRONT BONNET INNER LOCK CABLE	0.00	0.00	*18.00 F	X
9	1	*FRONT GRILLE INNER GARNISH	0.00	0.00	*105.00 F	✓
10	1	*FRONT GRILLE OUTER COVER TRANSPARENT WITH EMBLEM	0.00	0.00	*380.00 F	✓
11	10	*FRONT GRILLE CLIPS	0.00	0.00	*15.00 F	✓
12	2	*HEADLAMP WITH HID LH & RH	0.00	0.00	*1,100.00 F	✓
13	2	*HEADLAMP HID MODULE - CHECK PRICE	0.00	0.00	*F	X
14	2	*HEADLAMP HID BULB - CHECK PRICE	0.00	0.00	*F	X
15	2	*HEADLAMP SIGNAL BULB - CHECK PRICE	0.00	0.00	*F	X
16	4	*HEADLAMP CLIPS	0.00	0.00	*8.00 F	✓
17	1	*FRONT BUMPER	0.00	0.00	*430.00 F	✓
18	2	*FRONT BUMPER SIDE RETAINER	0.00	0.00	*20.00 F	✓
19	12	*FRONT BUMPER CLIPS	0.00	0.00	*18.00 F	✓
20	1	*FRONT BUMPER LOWER AIR GRILLE CTR	0.00	0.00	*105.00 F	✓
21	1	*FRONT BUMPER LOWER LIP CTR	0.00	0.00	*180.00 F	✓
22	1	*FRONT BUMPER LOWER LIP CTR SIDE COVER LH	0.00	0.00	*13.00 F	X
23	1	*FRONT BUMPER LOWER AIR GRILLE SIDE COVER RH	0.00	0.00	*13.00 F	X
24	1	*ENGINE UNDER COVER CTR - CHECK PRICE	0.00	0.00	*F	X
25	2	*FOGLAMP	0.00	0.00	*230.00 F	X
26	2	*FOGLAMP OUTER COVER	0.00	0.00	*26.00 F	X
27	2	*FRONT FENDER	0.00	0.00	*320.00 F	✓
28	2	*FRONT FENDER COWLING	0.00	0.00	*46.00 F	X
29	20	*FRONT FENDER COWLING CLIPS	0.00	0.00	*30.00 F	X
30	1	*RADIATOR SUPPORT PANEL TOP	0.00	0.00	*75.00 F	✓
31	2	*RADIATOR SUPPORT PANEL SIDE	0.00	0.00	*130.00 F	✓
32	1	*RADIATOR SUPPORT PANEL LOWER	0.00	0.00	*120.00 F	✓
33	1	*RADIATOR SUPPORT PANEL TOP CTR GARNISH	0.00	0.00	*23.00 F	✓
34	8	*RADIATOR SUPPORT PANEL TOP CTR GARNISH CLIPS	0.00	0.00	*12.00 F	✓
35	2	*RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE - CHECK PRICE	0.00	0.00	*F	X
36	2	*RADIATOR SUPPORT PANEL TOP SIDE STOPPER ADJUSTER	0.00	0.00	*6.00 F	X
37	1	*RADIATOR SUPPORT PANEL TOP CTR STOPPER RUBBER	0.00	0.00	*2.50 F	X
38	2	*HORN	0.00	0.00	*70.00 F	✓
39	1	*HORN BRACKET RH - CHECK PRICE	0.00	0.00	*F	X
40	1	*TEMPERATURE SENSOR - CHECK PRICE	0.00	0.00	*F	X
41	1	*TEMPERATURE SENSOR CLIPS - CHECK PRICE	0.00	0.00	*F	X
42	1	*A/C COMPRESSOR ASSY - CHECK PRICE	0.00	0.00	*F	X
43	1	*A/C COMPRESSOR BELT - CHECK PRICE	0.00	0.00	*F	X
44	1	*AIR CON CONDENSER ASSY	0.00	0.00	*250.00 F	✓
45	1	*AIR CON CONDENSER PIPE (COND-COMP) - CHECK PRICE	0.00	0.00	*F	✓

Ah Lim Motor Company/SKU8527D/28/06/2018 14:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
46	1		*AIR CON CONDENSER PIPE (COND-VALVE) - CHECK PRICE	Sm	0.00	0.00	*-F	X
47	1		*AIR CON CONDENSER PIPE (COMP-VALVE) - CHECK PRICE	Sm	0.00	0.00	*-F	X
48	1		*RADIATOR ASSY	BY/Sm	0.00	0.00	*430.00 F	X
49	1		*RADIATOR TOP HOSE	Sm	0.00	0.00	*18.00 F	X
50	1		*RADIATOR BOTTOM HOSE	Sm	0.00	0.00	*15.00 F	X
51	1		*RADIATOR TOP CAP	Sm	0.00	0.00	*22.00 F	X
52	1		*RADIATOR SPARE TANK	NU Sm	0.00	0.00	*18.00 F	X
53	1		*RADIATOR SPARE TANK HOSE - CHECK PRICE	Sm	0.00	0.00	*-F	X
54	2		*RADIATOR TOP BRACKET - CHECK PRICE	Sm	0.00	0.00	*-F	X
55	2		*RADIATOR TOP BUSH	Sm	0.00	0.00	*8.00 F	X
56	1		*RADIATOR FAN COWLING	CM	0.00	0.00	*75.00 F	X
57	1		*RADIATOR FAN MOTOR	Sm	0.00	0.00	*280.00 F	X
58	1		*RADIATOR FAN BLADE	O/S	0.00	0.00	*45.00 F	X
59	1		*ENGINE VALVE COVER - CHECK PRICE	Sm	0.00	0.00	*-F	X
60	1		*ENGINE VALVE COVER GASKET	Sm	0.00	0.00	*18.00 F	X
61	1		*EXHAUST MANIFOLD - CHECK PRICE	Sm	0.00	0.00	*-F	X
62	1		*EXHAUST MANIFOLD HEAT PLATE - CHECK PRICE	Sm	0.00	0.00	*-F	X
63	1		*EXHAUST MANIFOLD O2 SENSOR	Sm	0.00	0.00	*230.00 F	X
64	1		*AIR CLEANER BOX COMPLETE	mg CM Sm	0.00	150	*130.00 F	X
65	1		*AIR DUCT OUTER	NU	0.00	0.00	*78.00 F	X
66	1		*BATTERY TRAY - CHECK PRICE	Sm	0.00	0.00	*-F	X
67	1		*BATTERY TRAY OUTER COVER - CHECK PRICE	Sm	0.00	0.00	*-F	X
68	1		*BATTERY	Sm	0	0.00	*220.00 FS	X
69	1		*RADIATOR COOLANT	NU	0	0.00	*35.00 FS	X
70	1		*ENGINE VALVE COVER SEALANT	Sm	0	0.00	*60.00 FS	X
71	1		*NUMBER PLATE	BY	0	0.00	*35.00 FS	X

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **5,922.00**

Ah Lim Motor Company/SKU8527D/28/06/2018 14:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jul 2018)
 Parts: 144 SUZUKI SOLIO 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SKU8527D/06/07/2018 16:22
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*GRILLE AIR GUIDE	0.00	0.00	cm *25.00F ✓
2	2		*HEADLAMP BULB COVER	0.00	0.00	8x > *-F 36
Total Parts (S\$)						25.00

F=Franchise part.

Ah Lim Motor Company/SKU8527D/06/07/2018 16:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Ah Lim Motor Company/SKU8527D/06/07/2018 16:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 200
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	150.00 100
3	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	nn 80.00 x
4	TO REMOVE & REINSTALL/REPLACE EXHAUST MANIFOLD;O2 SENSOR	New	nn 150.00 x
5	TO REMOVE & REINSTALL/REPLACE AIR CLEANER BOX;AIR DUCT OUTER	New	nn 80.00 400
6	TO REMOVE & REINSTALL/REPLACE WIPER ENGINE VALVE COVER;VALVE COVER GASKET	New	nn 180.00 x
7	TO RESET FRONT HEADLAMP HID;O2 SENSOR;FOGLIGHT	New	280.00 120
8	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL TOP;SIDE;LOWER.TO KNOCK & REPAIR FRONT DOOR LH & RH;FRONT WHEELHOUSE;FRONT CHASSIS FRAME;FRONT DOOR PILLAR INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	1,300.00 700
9	TO SPRAY FRONT BONNET;FRONT BUMPER;FRONT FENDER LH & RH;FRONT DOOR LH & RH;FRONT WHEELHOUSE;FRONT CHASSIS FRAME;FRONT DOOR PILLAR;RADIATOR SUPPORT PANEL TOP;SIDE;LOWER.	New	900 1,300.00
Gross Labour Cost (S\$)			3,560.00

Ah Lim Motor Company/SKU8527D/28/06/2018 14:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

8 6691.50 BY excess



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL: 67275700

FAX: 67275799

ATTN: Motor Claim Department

Your Ref No: SKU8527D

Claim Type: Own Damage

Accident Date: 25/06/2018

Claim No: MC0913220

Ref No: MF0911339

Date: 19 Sep 2018

Policy No: PNPV2017-00008944

Veh Reg No: SKU8527D

Make/Model: SUZUKI SOLIO 1.2 CVT

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SKU8527D

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET		1 PC	330.00	
2 FRONT BONNET HINGE LH & RH		2 PC	36.00	
3 FRONT BONNET INSULATOR		1 PC	55.00	
4 FRONT BONNET INSULATOR CLIPS		9 PC	13.50	
5 FRONT BONNET INNER LOCK		1 PC	25.00	
6 FRONT GRILLE OUTER COVER TRANSPARENT WITH EMBLEM		1 PC	380.00	
7 FRONT GRILLE CLIPS		10 PC	15.00	
8 HEADLAMP WITH HID (LH -680 RH-550)		2 PC	1,230.00	
9 HEADLAMP CLIPS		4 PC	8.00	
10 FRONT BUMPER		1 PC	430.00	
11 FRONT BUMPER SIDE RETAINER		2 PC	20.00	
12 FRONT BUMPER CLIPS		12 PC	18.00	
13 FRONT BUMPER LOWER AIR GRILLE CTR		1 PC	105.00	
14 FRONT BUMPER LOWER LIP CTR		1 PC	180.00	
15 FRONT FENDER LH		1 PC	160.00	
16 RADIATOR SUPPORT PANEL TOP		1 PC	75.00	
17 RADIATOR SUPPORT PANEL SIDE		2 PC	130.00	
18 RADIATOR SUPPORT PANEL LOWER		1 PC	120.00	
19 HORN		1 PC	35.00	
20 AIR CON CONDENSER ASSY		1 PC	250.00	
21 AIR CON CONDENSER PIPE (COND-COMP)		1 PC	76.00	
22 RADIATOR ASSY		1 PC	430.00	
23 RADIATOR SPARE TANK		1 PC	18.00	
24 RADIATOR FAN COWLING		1 PC	75.00	
25 RADIATOR FAN MOTOR		1 PC	280.00	
26 RADIATOR FAN BLADE		1 PC	45.00	
27 AIR CLEANER BOX COMPLETE		1 PC	150.00	
28 AIR DUCT OUTER		1 PC	78.00	
29 GRILLE AIR GUIDE		1 PC	25.00	
30 HEADLAMP BULB COVER X 2		2 PC	36.00	
				4,828.50
Special Nett				
31 RADIATOR COOLANT		1 PC	35.00	
32 NUMBER PLATE		1 PC	35.00	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

70.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmo@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL: 67275700

FAX: 67275799

ATTN: Motor Claim Department

Your Ref No: SKU8527D

Claim Type: Own Damage

Accident Date: 25/06/2018

Claim No: MC0913220

Ref No: MF0911339

Date: 19 Sep 2018

Policy No: PNPV2017-00008944

Veh Reg No: SKU8527D

Make/Model: SUZUKI SOLIO 1.2 CVT

AFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SKU8527D

Description	U/Price	Quantity	Cost S\$	Amount S\$
LABOUR				
33 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
34 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	
35 TO REMOVE & REINSTALL/REPLACE AIR CLEANER BOX,AIR DUCT OUTER		1 PC	80.00	
36 TO RESET FRONT HEADLAMP HID,O2 SENSOR,FOGLIGHT		1 PC	280.00	
37 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL TOP,SIDE,LOWER.TO KNOCK & REPAIR FRONT DOOR LH & RH,FRONT WHEELHOUSE,FRONT CHASSIS FRAME,FRONT DOOR PILLAR INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	700.00	
38 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH & RH,FRONT DOOR LH & RH,FRONT WHEELHOUSE,FRONT CHASSIS FRAME,FRONT DOOR PILLAR,RADIATOR SUPPORT PANEL TOP,SIDE,LOWER.		1 PC	900.00	
				2,080.00

Amount Before Excess	S\$ 6,978.50
Less Excess	S\$ 500.00
Amount Before GST	S\$ 6,478.50
Add GST @ 7%	453.50
Total Amount payable	S\$ 6,932.00

TOTAL: SINGAPORE DOLLAR SIX THOUSAND NINE HUNDRED THIRTY TWO ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 29/06/2018

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A

#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg

GST Reg No: M9-0009639-E

INSURER: FWD Singapore Pte. Ltd. (HQ)

SURVEYOR COPY

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00008944	Date of Loss:	25/06/2018
Vehicle Reg. No.:	SKU8527D	Driveable?	
Driver Age/Info:	39 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NICHOLAS LO HAN PHENG	Contact No:	+6593685564
Driver:	NICHOLAS LO HAN PHENG		

Make/Model:	SUZUKI SOLIO, 1.2 CVT (A)	Vehicle Reg. Date:	20/08/2015
Vehicle Colour:	WHITE	Chassis No:	MA15S262189
Engine No:	K12B1929000		
Odometer:	0 KM		

Paint Type:

Total Loss? NO

Est. Duration of Repair (day) 6 days

FM

[Signature]

Not Authorized

Running Bk paint

Ex 8500

Description of Accident/Loss: REFER TO THE SKETCH PLAN BY DRIVER

Ref: 62564315

Remarks: CAR IN @ ALM AMK AUTOPOINT WORKSHOP

Present Location: AH LIM MOTOR COMPANY (AMK)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	5,922.00
Labour	0.00
Paintwork Labour	3,560.00
Towing	0.00
	0.00
	9,482.00
	+ GST 7.00% (\$\$)
	663.74
	Nett Amount (\$\$)
	10,145.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This claim is handled by: ZILA

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jun 2018)
 Parts: 144 SUZUKI SOLIO 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SKU8527D/28/06/2018 14:43

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No. Particulars		%Disc	%Depr	Amount	
1	2	*FRONT WIPER-SIDE GARNISH-LH & RH-CHECK PRICE		0.00	0.00	*F	?
2	1	*FRONT BONNET	Bu	0.00	0.00	*330.00 F	✓
3	2	*FRONT BONNET HINGE LH & RH		0.00	0.00	*36.00 F	7 (P) 7
4	1	*FRONT BONNET INSULATOR	CM	0.00	0.00	*55.00 F	✓
5	9	*FRONT BONNET INSULATOR CLIPS	M	0.00	0.00	*13.50 F	✓
6	1	*FRONT BONNET STAND CLIPS (AT BONNET)-CHECK PRICE	A	0.00	0.00	*F	X
7	1	*FRONT BONNET INNER LOCK	D. 1	0.00	0.00	*25.00 F	✓
8	1	*FRONT BONNET INNER LOCK CABLE		0.00	0.00	*18.00 F	?
9	1	*FRONT GRILLE INNER GARNISH	CM	0.00	0.00	*105.00 F	✓
10	1	*FRONT GRILLE OUTER COVER TRANSPARENT WITH EMBLEM	CM	0.00	0.00	*380.00 F	✓
11	10	*FRONT GRILLE CLIPS	M	0.00	0.00	*15.00 F	✓
12	2	*HEADLAMP WITH HID LH & RH	CM	0.00	0.00	*1,100.00 F	✓
13	2	*HEADLAMP HID MODULE-CHECK PRICE		0.00	0.00	*F	?
14	2	*HEADLAMP HID BULB-CHECK PRICE		0.00	0.00	*F	?
15	2	*HEADLAMP SIGNAL BULB-CHECK PRICE		0.00	0.00	*F	?
16	4	*HEADLAMP CLIPS	M	0.00	0.00	*8.00 F	✓
17	1	*FRONT BUMPER	Bu	0.00	0.00	*430.00 F	✓
18	2	*FRONT BUMPER SIDE RETAINER	D. 1 Bu	0.00	0.00	*20.00 F	✓
19	12	*FRONT BUMPER CLIPS	M	0.00	0.00	*18.00 F	✓
20	1	*FRONT BUMPER LOWER AIR GRILLE CTR	CM	0.00	0.00	*105.00 F	✓
21	1	*FRONT BUMPER LOWER LIP CTR		0.00	0.00	*180.00 F	2 (P) 7
22	1	*FRONT BUMPER LOWER LIP CTR SIDE COVER LH		0.00	0.00	*13.00 F	?
23	1	*FRONT BUMPER LOWER AIR GRILLE SIDE COVER RH		0.00	0.00	*13.00 F	?
24	1	*ENGINE UNDER COVER CTR-CHECK PRICE		0.00	0.00	*F	?
25	2	*FOGLAMP	Sm	0.00	0.00	*230.00 F	X
26	2	*FOGLAMP OUTER COVER		0.00	0.00	*26.00 F	?
27	21	*FRONT FENDER	CM Bu	0.00	0.00	*320.00 F	4
28	2	*FRONT FENDER COWLING	Bu	0.00	0.00	*46.00 F	X
29	20	*FRONT FENDER COWLING CLIPS	M	0.00	0.00	*30.00 F	X
30	1	*RADIATOR SUPPORT PANEL TOP	Bu	0.00	0.00	*75.00 F	✓
31	2	*RADIATOR SUPPORT PANEL SIDE	Bu	0.00	0.00	*130.00 F	✓
32	1	*RADIATOR SUPPORT PANEL LOWER		0.00	0.00	*120.00 F	7 (P) 7
33	1	*RADIATOR SUPPORT PANEL TOP CTR GARNISH	CM	0.00	0.00	*23.00 F	✓
34	8	*RADIATOR SUPPORT PANEL TOP CTR GARNISH CLIPS	M	0.00	0.00	*12.00 F	✓
35	2	*RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE-CHECK PRICE		0.00	0.00	*F	?
36	2	*RADIATOR SUPPORT PANEL TOP SIDE STOPPER ADJUSTER		0.00	0.00	*6.00 F	?
37	1	*RADIATOR SUPPORT PANEL TOP CTR STOPPER RUBBER		0.00	0.00	*2.50 F	?
38	2	*HORN		0.00	0.00	*70.00 F	7 (P) 7
39	1	*HORN BRACKET RH-CHECK PRICE	A	0.00	0.00	*F	X
40	1	*TEMPERATURE SENSOR-CHECK PRICE	Sm	0.00	0.00	*F	X
41	1	*TEMPERATURE SENSOR CLIPS-CHECK PRICE	M	0.00	0.00	*F	X
42	1	*A/C COMPRESSOR ASSY-CHECK PRICE	A	0.00	0.00	*F	X
43	1	*A/C COMPRESSOR BELT-CHECK PRICE	Sm	0.00	0.00	*F	X
44	1	*AIR CON CONDENSER ASSY	Bu	0.00	0.00	*250.00 F	✓
45	1	*AIR CON CONDENSER PIPE (COND-COMP)-CHECK PRICE		0.00	0.00	*F	7 (P) 7

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
46	1		*AIR CON CONDENSER PIPE (COND-VALVE) - CHECK PRICE	0.00	0.00	*F	?
47	1		*AIR CON CONDENSER PIPE (COMP-VALVE) - CHECK PRICE	0.00	0.00	*F	?
48	1		*RADIATOR ASSY	0.00	0.00	*430.00 F	? <i>Plat</i>
49	1		*RADIATOR TOP HOSE	0.00	0.00	*18.00 F	?
50	1		*RADIATOR BOTTOM HOSE	0.00	0.00	*15.00 F	?
51	1		*RADIATOR TOP CAP	<i>Sm</i> 0.00	0.00	*22.00 F	X
52	1		*RADIATOR SPARE TANK	<i>Sm</i> 0.00	0.00	*18.00 F	X <i>Plat</i>
53	1		*RADIATOR SPARE TANK HOSE - CHECK PRICE	0.00	0.00	*F	?
54	2		*RADIATOR TOP BRACKET - CHECK PRICE	0.00	0.00	*F	?
55	2		*RADIATOR TOP BUSH	0.00	0.00	*8.00 F	?
56	1		*RADIATOR FAN COWLING	0.00	0.00	*75.00 F	? <i>Plat</i>
57	1		*RADIATOR FAN MOTOR	0.00	0.00	*280.00 F	? <i>Plat</i>
58	1		*RADIATOR FAN BLADE	0.00	0.00	*45.00 F	? <i>Plat</i>
59	1		*ENGINE VALVE COVER - CHECK PRICE	0.00	0.00	*F	?
60	1		*ENGINE VALVE COVER GASKET	0.00	0.00	*18.00 F	?
61	1		*EXHAUST MANIFOLD - CHECK PRICE	0.00	0.00	*F	?
62	1		*EXHAUST MANIFOLD HEAT PLATE - CHECK PRICE	0.00	0.00	*F	?
63	1		*EXHAUST MANIFOLD O2 SENSOR	0.00	0.00	*230.00 F	?
64	1		*AIR CLEANER BOX COMPLETE	<i>Sm</i> 0.00	0.00	*130.00 F	X <i>Plat</i>
65	1		*AIR DUCT OUTER	<i>Not</i> 0.00	0.00	*78.00 F	—
66	1		*BATTERY TRAY - CHECK PRICE	<i>Sm</i> 0.00	0.00	*F	X
67	1		*BATTERY TRAY OUTER COVER - CHECK PRICE	0.00	0.00	*F	?
68	1		*BATTERY	<i>Sm</i> 0	0.00	*220.00 ES	X
69	1		*RADIATOR COOLANT	<i>Not</i> 0	0.00	*35.00 FS	—
70	1		*ENGINE VALVE COVER SEALANT	0	0.00	*60.00 ES	?
71	1		*NUMBER PLATE	<i>Not</i> 0	0.00	*35.00 FS	—

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

5,922.00

Ah Lim Motor Company/SKU8527D/28/06/2018 14:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 <i>200</i>
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	150.00 <i>100</i>
3	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	80.00 <i>x</i>
4	TO REMOVE & REINSTALL/REPLACE EXHAUST MANIFOLD; O2 SENSOR	New	150.00 <i>7</i>
5	TO REMOVE & REINSTALL/REPLACE AIR CLEANER BOX; AIR DUCT OUTER	New	<i>22</i> 80.00 <i>x plus</i>
6	TO REMOVE & REINSTALL/REPLACE WIPER ENGINE VALVE COVER; VALVE COVER GASKET	New	180.00 <i>7</i>
7	TO RESET FRONT HEADLAMP HID; O2 SENSOR; FOGLIGHT	New	280.00 <i>7 plus</i>
8	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL TOP; SIDE; LOWER. TO KNOCK & REPAIR FRONT DOOR LH & RH; FRONT WHEELHOUSE; FRONT CHASSIS FRAME; FRONT DOOR PILLAR INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	1,300.00 <i>For</i>
9	TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH & RH; FRONT DOOR LH & RH; FRONT WHEELHOUSE; FRONT CHASSIS FRAME; FRONT DOOR PILLAR; RADIATOR SUPPORT PANEL TOP; SIDE; LOWER.	New	<i>900</i> 1,300.00
Gross Labour Cost (S\$)			3,560.00

Ah Lim Motor Company/SKU8527D/28/06/2018 14:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jul 2018)
 Parts: 144 SUZUKI SOLIO 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SKU8527D/06/07/2018 16:22
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*GRILLE AIR GUIDE	0.00	0.00	*25.00 F
2	2		*HEADLAMP BULB COVER	0.00	0.00	*12.00 F
Total Parts (S\$)						25.00

F=Franchise part.

Ah Lim Motor Company/SKU8527D/06/07/2018 16:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Ah Lim Motor Company/SKU8527D/06/07/2018 16:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450618 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 726672
TEL: 6365 1255 FAX: 6365 2580

Email: jeeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : PETER



Dept Direct: 6417 9701 / 6416 9800



Dept Direct: 6417 9702



Dept Direct: 6417 9703



Dept Direct: 6417 9704



Dept Direct: 6417 9705



Dept Direct: 6417 9706



Dept Direct: 6417 9707



Dept Direct: 6417 9708



Dept Direct: 6417 9709



Dept Direct: 6417 9710



Dept Direct: 6417 9711

Wiper blade: HWE (Nippon Wiper blade) Super (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201807-02641
DATE : 05/07/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKU8527D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1/ Z09409-08327	CLIP,BUMPER	MO	10	1.50	15.00
SOLIO ZC11 ZC21 ZC31		2H20			
2/ Z09409-07332/40	CLIP,	MO	4	2.00	8.00
ZC11 ZC21 ZC31		2E8R			

Page 10

SUB-TOTAL :	23.00
ADD GST 7.00 %	1.61
E. & O.E	
TOTAL AMOUNT SGD :	24.61

[P] 05/07/2018 11:36:17AM

[E] 05/07/2018 11:24:28AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : NIN



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaesauto@pacific.net.sg

GST REG. NO: M2-0119201-3 CO. REG. NO: 199307741M

AH LIM MOTOR COMPANY

10 ANG MO KIO PARKS 2A

#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL: 64831244 FAX: 64836170

ATTN: PETER

WINDSHIELD GLASS
Dept Direct: 6417 8791 / 8749 1225



Dept Direct: 6288 8818

Dept Direct: 6285 3313

Dept Direct: 6417 8752



Dept Direct: 6417 8754

Dept Direct: 6417 8755

Dept Direct: 6417 8756

Dept Direct: 6417 8757

Wiper blade: NWB (Ribbon Wiper blade, Silver (Made in Korea).

Forch (Made in Germany)

Spark plug: Bosch (Bosch, High Grade)

TAX INVOICE: AR201807-01936

DATE: 04/07/2018

CUSTOMER ID: AHL008

VEH REG. NO.: SKU185271

TERMS: 30 days

PO NO.:

PAGE NO.:

CURR.:

Page 1 of 1

SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	UTPRICE	AMOUNT
1. Z13870-61P00 MA15 SOL10	PIPE, AIR CLNR SUCT	MO SUPPLIER	1	78.00	78.00

Page 9

SUB-TOTAL: 78.00
ADD GST 7.00 % 5.46

E & O E TOTAL AMOUNT SGD: 83.46

[P] 04/07/2018 11:46:25AM

[E] 04/07/2018 11:36:34AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: NIN



* AR201807-01936 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 406710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGAI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 8181 / 6742 9828



Wiper blades: NWB (Nippon Wiper blades, Silver / Made in Korea),
Forch / Made in Germany /
Spark plug: Nippon Denso, NGK (Made in Japan)

AHLIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : PETER

TAX INVOICE : AR201807-01947
DATE : 04/07/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKU8527D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. Z13700-71L00 ZC82,MA15 SOLIO	CLEANER ASSY,AIR	PA PL3-K1-070	1	150.00	150.00

10728

SUB-TOTAL : 150.00
ADD GST 7.00 % 10.50

E & OE TOTAL AMOUNT SGD: 160.50

[P] 04/07/2018 11:44:12AM

[E] 04/07/2018 11:43:23AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: NIN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

(Signature)

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AHLIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : PETER

MINICAR CLASS
Seat Direct: 6417 9791 / 9745 0021



Seat Direct: 6365 3610

Seat Direct: 6365 3611

Seat Direct: 6417 9792



Seat Direct: 6417 9794

Seat Direct: 6417 9795

Seat Direct: 6417 9796

Seat Direct: 6417 9797

Wiper blade: HWB (Hippin Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)

Spark plug: Hicon Denso, NGK (Made in Japan)

TAX INVOICE : AR201807-01061
DATE : 03/07/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKU8527D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	Z95720-54M20 MA15 SOLIO	HOSE.DISCHARGE	MO SUPPLIER	1	76.00	76.00

paper

SUB-TOTAL : 76.00
ADD GST 7.00 % : 5.32

E & O E TOTAL AMOUNT SGD : 81.32

[P] 03/07/2018 10:57:32AM

[E] 03/07/2018 10:57:00AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : NIN



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450615 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL: 64831244 FAX: 64836170
ATTN: PETER



Dept Direct 6208 8218

Dept Direct 6208 8211

Dept Direct 6417 9752

Dept Direct 6417 9759

Dept Direct 6417 9758

Dept Direct 6417 9756

Dept Direct 6417 9758

Wiper blade: NYG Nippon Viper Blade (Silver / Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201807-00864
DATE : 03/07/2018
CUSTOMER ID : AIL008
VEH REG. NO. : SKU8527D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
1. Z35320-34M12/3 MA15 SOLIO	HEADLAMP LH	MO SUPPLIER	1	680.00	680.00

Page 6

SUB-TOTAL : 680.00
ADD GST 7.00 % 47.60

E & O E TOTAL AMOUNT SGD : 727.60

[P] 03/07/2018 9:25:10AM

[E] 03/07/2018 9:20:26AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : NIN



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct 6417 8701 / 8743 8020



Dept Direct 6417 8701



Dept Direct 6417 8701



Dept Direct 6417 8701



Dept Direct 6417 8701



Dept Direct 6417 8701



Dept Direct 6417 8701



Dept Direct 6417 8701



Dept Direct 6417 8701



Dept Direct 6417 8701



Dept Direct 6417 8701



Dept Direct 6417 8701

Wiper blades: 16/18 (Hapoon Wiper blades: Striper 1 Made in Korea)
Ford: Made in Germany
Spark plug: Hapoon Cense: 16/18 Made in Japan

AHLIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : PETER

TAX INVOICE : AR201807-01049
DATE : 03/07/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKU8527D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	Z71772-54M60 MA15 SOLIO	GUIDE,GRILLE AIR	PA PL3-K1-08P	✓	25.00	25.00 ✓
2.	Z17111-71L00 ZC82,MA15 SOLIO	FAN,COOLING	PA PL3-M1-110	1	45.00 ✓	45.00
3.	Z38500-65J00/31 TE54,MA15 SOLIO	HORN	PA PL3-K1-05B	1	35.00 ✓	35.00
4.	Z52711-54M10 MA15 SOLIO	FR FENDER LH	PA PA-FLZ3	1	160.00 ✓	160.00
5.	Z17931-71L00 ZC32,MA15 SOLIO	TANK,WATER RELEASE	PA PL3-K1-08B	1	18.00 ✓	18.00

P: 11
N 0925

SUB-TOTAL :	283.00
ADD GST 7.00 %	19.81
E & O E	TOTAL AMOUNT SGD : 302.81

[P] 03/07/2018 10:56:49AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 03/07/2018 10:49:51AM

JAE Auto Pte. Ltd.

Sales Executive: NIN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Col Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6385 1255 FAX: 6385 2580

Email: jaeauto@pacilio.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD BLADE
Dept Direct 6417 9751 / 6745 9028



Dept Direct 6385 0631

Dept Direct 6385 0611

Dept Direct 6417 9752



Dept Direct 6417 9754

Dept Direct 6417 9756

Dept Direct 6417 9758

Dept Direct 6417 9759

Wiper blade: HVB (Nippon Wiper blade), Bilster (Made in Korea).

Fauch (Made in Germany)

Spark plug: Nippon Duro, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : PETER

TAX INVOICE : AR201807-01023
DATE : 03/07/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKU8527D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	Z77250-54M60-CMT MA15 SOLIO	EXTENSION,FR BUMPER	CC CC8-F-03E	1	180.00	180.00
2.	Z17760-71L00 ZC82,MA15 SOLIO	SHROUD	CC CC8-A-02F	1	75.00	75.00
3.	Z17120-80J00 ZC31 ZC82 ZC32 SOLIO	FAN MOTOR	CC CC8-A-02C	1	280.00	280.00

Page 1 of 1

SUB-TOTAL :			535.00
ADD GST 7.00 %			37.45
E & O E	TOTAL AMOUNT SGD :		572.45

[P] 03/07/2018 10:58:43AM

[E] 03/07/2018 10:31:44AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: NIN

This is computer generated document.
No signature is required.



Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

STUREQ NO: N90110201-3 CO. REG. NO.: 199307741M
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL.: 64831244 FAX: 64836170
ATTN: PETER

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

WIPER BLADES
Dept Direct: 0417 9701 / 9745 9833

Wiper blade: HWS (Happon Wiper blade, Siper (Made in Korea).
Forch (Made in Germany)

Spark plug: HWS (Happon Spark plug, Siper (Made in Korea).

TAX INVOICE: AK201807-00431

DATE: 02/07/2018

CUSTOMER ID: AHL008

VEH REG. NO.: SK1J85271

TERMS: 30 days

PO NO.:

PAGE NO.:

Curr. Page 1 of 1

SGD

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. Z82110-58J01	BONNET LOCK	MO	1	25.00	25.00
HA24 MA15 S(O)IC)		1LS17			
2. Z72440-54M00	SILENCER, FRT HOOD	MO	1	55.00	55.00
MA15 S(O)IC)		2H24			
3. Z09409-07332/40	CLIP INSULATOR	MO	9	1.50	13.50
ZC11 ZC21 ZC31		2H8R			

SUB-TOTAL: 93.50
ADD GST 7.00 % 6.55

E & O E TOTAL AMOUNT SGD: 100.05

[P] 02/07/2018 12:56:16PM

[E] 02/07/2018 12:52:02PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: NIN



AR201807-00431

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date
2/7/18



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450516 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6385 1255 FAX: 6385 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 6417 9101 / 6745 8100



Dept Direct: 6385 0010

Dept Direct: 6385 0011

Dept Direct: 6417 9102



Dept Direct: 6417 9104

Dept Direct: 6417 9105

Dept Direct: 6417 9106

Dept Direct: 6417 9107

Wiper blade: HVB (Nippon Wiper blade: Super (Made in Korea),
Forch (Made in Germany))
Spark plug: Nippon Denso, NGK (Made in Japan)

AHLIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : PETER

TAX INVOICE : AR201807-00386
DATE : 02/07/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKU8527D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1.	Z71711-54M70-799 MA15 SOLIO	FR BUMPER	CC CC8-F-10B	1	430.00	430.00
2.	Z95310-54M00 MA15 SOLIO	A/C CONDENSER ASSY	CC CC8-A-06F	1	250.00	250.00
3.	Z17700-71L00 ZC32, MA15 SOLIO	RADIATOR ASSY	CC CC8-A-06F	1	430.00	430.00

SUB-TOTAL : 1,110.00
ADD GST 7.00 % 77.70

E. & O.E TOTAL AMOUNT SGD: 1,187.70

[P] 02/07/2018 12:40:59PM

[E] 02/07/2018 12:01:36PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: NIN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)


WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Arrange By _____ Driver _____



Wiper blade: RWB (Japan) Wiper blades, 30" (Made in Korea)
Forsch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : PETER

TAX INVOICE : AR201807-00388
DATE : 02/07/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKU8527D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	Z71731-54M01 MA15 SOLIO	FR BUMPER SIDE BRACKET RH	PA PL3-K1-09E	1	10.00✓	10.00
2.	Z71732-54M01 MA15 SOLIO	FR BUMPER SIDE BRACKET LH	PA PL3-K1-09G	1	10.00✓	10.00
3.	Z09409-08327 HX51 ZC11 ZC21 ZC31	CLIP,BUMPER	PA PL3-K1-09Z	12	1.50✓	18.00
4.	Z71771-54M60-5PK MA15 SOLIO	NET,FR BUMPER LOWER	PA PL3-L1-080	1	105.00✓	105.00
5.	Z58230-54M00 MA15 SOLIO	PANEL ,HOOD LOCK	PA PL3-N1-09B	1	75.00✓	75.00
6.	Z58110-54M01 MA15 SOLIO	BRACE,LAMP SUPPORT R	PA PL3-K1-06B	1	65.00✓	65.00
7.	Z58120-54M01 MA15 SOLIO	BRACE,LAMP SUPPORT L	PA PL3-K1-06D	1	65.00✓	65.00
8.	Z72380-54M01 MA15 SOLIO	CROSSMEMBER,FRT LOWER	PA PL3-Q1-07B	1	120.00✓	120.00
9.	Z13870-71L00 ZC82 MA15 SOLIO	PIPE,AIR CLEANER SUCT	PA PL3-K1-07A	1	78.00✓	78.00
10.	Z57300-54M00 MA15 SOLIO	HOOD ASSY	PA PL3-L1-070	1	330.00✓	330.00
11.	Z57410-58J01 MH22S,MA15 SOLIO	HINGE,HOOD,RH	PA PL3-K1-07F	1	18.00✓	18.00
12.	Z57420-58J01 MH22S,MA15 SOLIO	BONNET HINGE LH	PA PL3-K1-07E	1	18.00✓	18.00
13.	Z72110-54M60-0PG MA15 SOLIO	GRILLE,RADIATOR (CHROME)	PA PL3-Q1-090	1	380.00✓	380.00
14.	Z339120-54M12 MA15 SOLIO	HEADLAMP RH	PA PL3-K1-080	1	550.00✓	550.00

100



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119291-3 CO. REG. NO.: 199307741M



Wiper blade: r/w/b (Nippon Wiper blade), Siliper i (Made in Korea)
Forch i (Made in Germany)
Spark plug: Nippon-Denso NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : PETER

TAX INVOICE : AR201807-00388
DATE : 02/07/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKU8527D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
------------	-------------	--------	-----	---------	--------

SUB-TOTAL : 1,842.00
ADD GST 7.00 % 128.90

E & O E TOTAL AMOUNT SGD : 1,970.90

[P] 02/07/2018 1:58:19PM

[E] 02/07/2018 12:04:41PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : NIN



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGAI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO: M2-0119201-3 CO. REG. NO: 199307741M

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL: 64831244 FAX: 64836170
ATTN: SIMON 96205405

SPECIAL ORDER



Wiper blade: HVB (Nippon Wiper blade), Sigei (Made in Korea L)
Forch (Made in Germany)

Spock plug: Nippon Denso, HPS (Made in Japan)

TAX INVOICE : AR201807-11571
DATE : 21/07/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKU8527D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	Z35267-66K10 MA15 SOLIO	COVER ASSY,BACK	U1 BY AIR	2	18.00	36.00

SUB-TOTAL : 36.00
ADD GST 7.00 % 2.52

E & O E TOTAL AMOUNT SGD : 38.52

[P] 21/07/2018 8:42:17AM

[E] 21/07/2018 8:41:06AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: NIN



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

Kenneth Kong (LKKAUTO)

From: muihong@ahlimmotor.com.sg
Sent: Tuesday, 25 September, 2018 11:13 AM
To: Kenneth Kong (LKKAUTO)
Subject: Re: PHOTO & SUPP ITEM FOR VEHICLE SKU8527D

Dear Kenneth,

I refer to your attached but cannot arrive at your amount of \$6,691.50

Total parts – \$4,828.50

SN – \$70

Labour – \$1,880

Total – \$6,778.50

Pls advise discrepancy

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

6456 3637

From: Kenneth Kong (LKKAUTO)
Sent: Tuesday, September 25, 2018 9:45 AM
To: muihong@ahlimmotor.com.sg
Subject: RE: PHOTO & SUPP ITEM FOR VEHICLE SKU8527D

Attach finalised for SKU 8527D. Kenneth

From: muihong@ahlimmotor.com.sg [mailto:muihong@ahlimmotor.com.sg]
Sent: Monday, 24 September, 2018 11:33 AM
To: Kenneth Kong (LKKAUTO)
Subject: Fw: PHOTO & SUPP ITEM FOR VEHICLE SKU8527D

Dear Kenneth,

Resend as per request

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint

Singapore 568047
Tel : 64831244 Fax : 64836170

From: Eileen Chua
Sent: Friday, July 6, 2018 4:57 PM
To: LKK - Kenneth Kong
Subject: Fw: PHOTO & SUPP ITEM FOR VEHICLE SKU8527D

Hi Kenneth,

sorry forgot to put the vehicle no. on the subject early email.

Best Regards,
Eileen Chua
Ah Lim Motor Company
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint S(568047)
Tel: 64831244 Fax: 64836170

From: Eileen Chua
Sent: Friday, July 06, 2018 4:54 PM
To: LKK - Kenneth Kong
Subject: PHOTO & SUPP ITEM FOR VEHICLE

Hi Kenneth,

Please see attached photo as request. supp item & question mark item.

Best Regards,
Eileen Chua
Ah Lim Motor Company
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint S(568047)
Tel: 64831244 Fax: 64836170

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2018 Sendback Est	28 Jun 2018 14:43 \$59,482.00	28 Jun 2018 14:58 Edit Adj Rpt	\$56,778.50 Edit Estimates	\$56,778.50 View Rpt		Pending for Survey Report Cancel Case
Supp #1	06 Jul 2018 16:21	06 Jul 2018 16:22 \$525.00	06 Jul 2018 16:22			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	NICHOLAS LO HAN PHENG, ID: S7902112A, Tel: +6593685564, Email: NIC290179@GMAIL.COM		
Vehicle Reg. No.:	SKU8527D	Date of Loss:	25/06/2018 07:00 - :59 [34 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800007949	Policy/Cover Note No.:	PNPV2017-00008944 (Comprehensive)
		Excess:	\$4500.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/07/2018]		
Driver/Custodian:	NICHOLAS LO HAN PHENG (39 / Male), NRIC: S7902112A, Tel: +6593685564		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- FWD_SG (29/06/2018): Alert - Adj Mandate Approved (\$57396.00) - SKU8527D - Claim Handler: Josey Loh

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

**SKU8527D (1201800007949)
OD**

**Jun 25 2018 7:00AM
[NICHOLAS LO HAN PHENG]
Ah Lim Motor Company**

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	28/06/18 14:43	Repairer Estimates	Load HTM	
2	06/07/18 16:22	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/06/18 16:48	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/09/18 12:51	Reinspection Photo	Load PDF	
2	27/09/18 12:51	Reinspection Photo	Load PDF	
3	27/09/18 12:51	General View	Load PDF	
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/06/18 16:57	SKU 8527D ESTIMATE	Load PDF	
2	05/10/18 08:40	Parts Invoice	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	25/06/18 14:44	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	25/06/18 13:33	Accident Photo	Load JPG	☒
2	25/06/18 13:33	Accident Photo	Load JPG	☒
3	25/06/18 13:33	Accident Photo	Load JPG	☒
4	25/06/18 13:33	Accident Photo	Load JPG	☒
5	25/06/18 13:33	Accident Photo	Load JPG	☒
6	25/06/18 13:33	Accident Photo	Load JPG	☒
7	25/06/18 13:33	Accident Photo	Load JPG	☒
8	25/06/18 13:33	Accident Photo	Load JPG	☒
9	25/06/18 13:33	Accident Photo	Load JPG	☒
10	25/06/18 13:33	Accident Photo	Load JPG	☒
11	25/06/18 13:33	Accident Photo	Load JPG	☒
12	25/06/18 13:33	Accident Photo	Load JPG	☒
13	25/06/18 13:33	Accident Photo	Load JPG	☒
14	25/06/18 13:33	Accident Photo	Load JPG	☒
15	25/06/18 13:33	Accident Photo	Load JPG	☒
Documentation			1 per page	☒

Assessment Reports				1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	25/06/18 14:44	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18011822/KRBE2

Date: 05/10/2018

REFERENCE

Insured/Claimant: NICHOLAS LO HAN PHENG Policy No: PNPV2017-00008944
Date of Loss: 25/06/2018 Nature of Claim: OD Claim No: 1201800007949

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU8527D	Engine No:	K12B1929000
Make & Model:	SUZUKI SOLIO, 1.2 CVT (A)	Chassis No:	MA15S262189
Reg. Date:	20/08/2015 (Man. Year: 2014)	Odometer:	39240 km
Colour:	White		
Engine Capacity:	1242 cc		
Market Value/New Car Price:	S\$67,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/60 R15	Rear Tyre Size:	165/60 R15
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,947.00	4,898.50	1,048.50	17.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	1,880.00	1,680.00	47.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,507.00	6,778.50	2,728.50	28.70
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	9,507.00	6,278.50	3,228.50	33.96
+ GST 7.00/7.00% (S\$)	665.49	439.50	225.99	33.96
Nett Amount (S\$)	10,172.49	6,718.00	3,454.49	33.96

INSPECTION

Date of Assignment:	28/06/2018 Present Location:	Ah Lim Motor Company (AMK)
Date Inspected:	29/06/2018 Inspected At:	Ah Lim Motor Company (AMK)
		10 Ang Mo Kio Industrial Park 2A, #01-09
		AMK Autopoint
		Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2018)
Parts:	144	SUZUKI SOLIO 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU8527D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT WIPER SIDE GARNISH LH & RH - CHECK PRICE	Serviceable	0.00 F	*- F
2	1		*FRONT BONNET	Buckled	330.00 F	*330.00 F
3	2		*FRONT BONNET HINGE LH & RH	Distorted	36.00 F	*36.00 F
4	1		*FRONT BONNET INSULATOR	Cracked	55.00 F	*55.00 F
5	9		*FRONT BONNET INSULATOR CLIPS	Necessary	13.50 F	*13.50 F
6	1		*FRONT BONNET STAND CLIPS (AT BONNET) - CHECK PRICE	Serviceable	0.00 F	*- F
7	1		*FRONT BONNET INNER LOCK	Distorted	25.00 F	*25.00 F
8	1		*FRONT BONNET INNER LOCK CABLE	Serviceable	18.00 F	*- F
9	1		*FRONT GRILLE INNER GARNISH	Serviceable	105.00 F	*- F
10	1		*FRONT GRILLE OUTER COVER TRANSPARENT WITH EMBLEM	Cracked	380.00 F	*380.00 F
11	10		*FRONT GRILLE CLIPS	Necessary	15.00 F	*15.00 F
12	1		*HEADLAMP WITHHID LH & RH (2PCS)(N/S-\$680.00)(O/S-\$550.00)	Cracked	1,100.00 F	*1,230.00 F
13	2		*HEADLAMP HID MODULE - CHECK PRICE	Serviceable	0.00 F	*- F
14	2		*HEADLAMP HID BULB - CHECK PRICE	Serviceable	0.00 F	*- F
15	2		*HEADLAMP SIGNAL BULB - CHECK PRICE	Serviceable	0.00 F	*- F
16	4		*HEADLAMP CLIPS	Necessary	8.00 F	*8.00 F
17	1		*FRONT BUMPER	Bent	430.00 F	*430.00 F
18	2		*FRONT BUMPER SIDE RETAINER	Distorted	20.00 F	*20.00 F
19	12		*FRONT BUMPER CLIPS	Necessary	18.00 F	*18.00 F
20	1		*FRONT BUMPER LOWER AIR GRILLE CTR	Cracked	105.00 F	*105.00 F
21	1		*FRONT BUMPER LOWER LIP CTR	Buckled	180.00 F	*180.00 F
22	1		*FRONT BUMPER LOWER LIP CTR SIDE COVER LH	Serviceable	13.00 F	*- F
23	1		*FRONT BUMPER LOWER AIR GRILLE SIDE COVER RH	Serviceable	13.00 F	*- F
24	1		*ENGINE UNDER COVER CTR - CHECK PRICE	Serviceable	0.00 F	*- F
25	2		*FOGLAMP	Serviceable	230.00 F	*- F
26	2		*FOGLAMP OUTER COVER	Serviceable	26.00 F	*- F
27	1		*FRONT FENDER	O/S Repair / N/S Buckled	320.00 F	*160.00 F
28	2		*FRONT FENDER COWLING	Serviceable	46.00 F	*- F
29	20		*FRONT FENDER COWLING CLIPS	Not Necessary	30.00 F	*- F
30	1		*RADIATOR SUPPORT PANEL TOP	Buckled	75.00 F	*75.00 F
31	2		*RADIATOR SUPPORT PANEL SIDE	Bent	130.00 F	*130.00 F
32	1		*RADIATOR SUPPORT PANEL LOWER	Bent	120.00 F	*120.00 F
33	1		*RADIATOR SUPPORT PANEL TOP CTR GARNISH	Serviceable	23.00 F	*- F
34	8			Not Necessary	12.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*RADIATOR SUPPORT PANEL TOP CTR GARNISH CLIPS			
35	2		*RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE - CHECK PRICE	Serviceable	0.00 F	*- F
36	2		*RADIATOR SUPPORT PANEL TOP SIDE STOPPER ADJUSTER	Serviceable	6.00 F	*- F
37	1		*RADIATOR SUPPORT PANEL TOP CTR STOPPER RUBBER	Serviceable	2.50 F	*- F
38	1		*HORN (2PCS)	Dented-1pc only	70.00 F	*35.00 F
39	1		*HORN BRACKET RH - CHECK PRICE	Repair	0.00 F	*- F
40	1		*TEMPERATURE SENSOR - CHECK PRICE	Serviceable	0.00 F	*- F
41	1		*TEMPERATURE SENSOR CLIPS - CHECK PRICE	Not Necessary	0.00 F	*- F
42	1		*A/C COMPRESSOR ASSY - CHECK PRICE	Repair	0.00 F	*- F
43	1		*A/C COMPRESSOR BELT - CHECK PRICE	Serviceable	0.00 F	*- F
44	1		*AIR CON CONDENSER ASSY	Bent	250.00 F	*250.00 F
45	1		*AIR CON CONDENSER PIPE (COND-COMP) - CHECK PRICE	Bent	0.00 F	*76.00 F
46	1		*AIR CON CONDENSER PIPE (COND-VALVE) - CHECK PRICE	Serviceable	0.00 F	*- F
47	1		*AIR CON CONDENSER PIPE (COMP-VALVE) - CHECK PRICE	Serviceable	0.00 F	*- F
48	1		*RADIATOR ASSY	Bent / Punctured	430.00 F	*430.00 F
49	1		*RADIATOR TOP HOSE	Serviceable	18.00 F	*- F
50	1		*RADIATOR BOTTOM HOSE	Serviceable	15.00 F	*- F
51	1		*RADIATOR TOP CAP	Serviceable	22.00 F	*- F
52	1		*RADIATOR SPARE TANK	Dented	18.00 F	*18.00 F
53	1		*RADIATOR SPARE TANK HOSE - CHECK PRICE	Serviceable	0.00 F	*- F
54	2		*RADIATOR TOP BRACKET - CHECK PRICE	Serviceable	0.00 F	*- F
55	2		*RADIATOR TOP BUSH	Serviceable	8.00 F	*- F
56	1		*RADIATOR FAN COWLING	Cracked	75.00 F	*75.00 F
57	1		*RADIATOR FAN MOTOR	Jammed	280.00 F	*280.00 F
58	1		*RADIATOR FAN BLADE	Distorted	45.00 F	*45.00 F
59	1		*ENGINE VALVE COVER - CHECK PRICE	Serviceable	0.00 F	*- F
60	1		*ENGINE VALVE COVER GASKET	Serviceable	18.00 F	*- F
61	1		*EXHAUST MANIFOLD - CHECK PRICE	Serviceable	0.00 F	*- F
62	1		*EXHAUST MANIFOLD HEAT PLATE - CHECK PRICE	Serviceable	0.00 F	*- F
63	1		*EXHAUST MANIFOLD O2 SENSOR	Serviceable	230.00 F	*- F
64	1		*AIR CLEANER BOX COMPLETE	MTG Cracked	130.00 F	*150.00 F
65	1		*AIR DUCT OUTER	Dented	78.00 F	*78.00 F
66	1		*BATTERY TRAY - CHECK PRICE	Serviceable	0.00 F	*- F
67	1		*BATTERY TRAY OUTER COVER - CHECK PRICE	Serviceable	0.00 F	*- F
68	1		*BATTERY	Serviceable	220.00 FS	*- FS
69	1		*RADIATOR COOLANT	Necessary	35.00 FS	*35.00 FS
70	1		*ENGINE VALVE COVER SEALANT	Serviceable	60.00 FS	*- FS
71	1		*NUMBER PLATE	Bent	35.00 FS	*35.00 FS
Supplementary #1						
72	1		*GRILLE AIR GUIDE	Cracked	25.00 F	*25.00 F
73	2		*HEADLAMP BULB COVER	Necessary	0.00 F	*36.00 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 5,947.00 4,898.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	20.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	150.00	100.00
3	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	80.00	0.00
4	TO REMOVE & REINSTALL/REPLACE EXHAUST MANIFOLD;O2 SENSOR	New	150.00	0.00
5	TO REMOVE & REINSTALL/REPLACE AIR CLEANER BOX;AIR DUCT OUTER	New	80.00	40.00
6	TO REMOVE & REINSTALL/REPLACE WIPER ENGINE VALVE COVER;VALVE COVER GASKET	New	180.00	0.00
7	TO RESET FRONT HEADLAMP HID;O2 SENSOR;FOGLIGHT	New	280.00	120.00
8	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL TOP;SIDE;LOWER.TO KNOCK & REPAIR FRONT DOOR LH & RH;FRONT WHEELHOUSE;FRONT CHASSIS FRAME;FRONT DOOR PILLAR INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	1,300.00	700.00
9	TO SPRAY FRONT BONNET;FRONT BUMPER;FRONT FENDER LH & RH;FRONT DOOR LH & RH;FRONT WHEELHOUSE;FRONT CHASSIS FRAME;FRONT DOOR PILLAR;RADIATOR SUPPORT PANEL TOP;SIDE;LOWER.	New	1,300.00	900.00
Gross Labour Cost (S\$)			3,560.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >