

REF: CS/CT18011826 / R1rbn2 Special Instruction:

SS. REC. BY:

Surveyor

Rasul

ASSIGNMENT (Office)

Munim

From (Person):

Irene Tay

of

CT

Date/Time: 28062018 1.19 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 7497U

Insured:

SLP 5926U

at Workshop m/s

Kah Motor

Tel:

of

255 Alexandra Rd

Policy No:

DmPCSN 3047751700

Claim No:

SNM18 D03209 C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26062018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

28062018 1.55 pm

Person Contacted:

Sin Hui

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMA 7497U - X

SLP 5926U - X

Confirm \$8844.82, 8 days
 (Red: \$2752.67, 24%.)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA 7497Uat Workshop m/s KAH MOTORof 2555, BUCHANAN STInsured: CTI / up

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA 7497U Yr Regn: 2018 JunType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CIVIC 1.6 VTI C.C. 1597Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 000740 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHFC 5650 JT 000842Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R16R: N

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/06/18 D.O.I. 28/06/18Survey held at KAH MOTORDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orREAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 02 OCT 2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 81) typist☒ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$

Transportation:

☐ : Interview (\$

Photos

☐ : Tech. Invs (\$

Others

☐ : Weekend (\$Report Format: TPLump Sum / I.B.I: (\$ 8844.82)

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18011826/R1rb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 28-06-2018

Code : CTI



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 5926U	Veh. Inspected	SMA 7497U
Policy No.	DMPCSN3047751700	Coverage (\$)	0.00
Claim No.	SNM18D03209C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	28/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/06/2018	Inspection Date	28/06/2018
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2018		28 Jun 2018 13:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	KONG TUCK EE (JIANG DEYU), ID: S7809595D			[Created by insurer]
Main Claimant:	MARGONO BIN SOEJONO, ID: S1801150F			
Vehicle Reg. No.:	SMA7497U	Date of Loss:	26/06/2018 21:00 - :59	
Claim Type:	TP / SNM18D03209C02	Policy/Cover Note No.:	DMPCSN3047751700 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLP5926U	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hul Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/07/2018]			
Adj Asg. Remarks:	EST \$12,409.34, CASE WITH SJE.			

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

Janice Lee (LKKAUTO)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Tuesday, July 10, 2018 8:45 AM
To: Rasul (LKKAUTO); SUR
Subject: RE: Submission Pre-Invoice for vehicle SMA7497U
Attachments: 3724_001.pdf; DSCF6297.jpg; DSCF6295.jpg; DSCF6296.jpg; DSCF6101.jpg; DSCF6102.jpg; DSCF6103.jpg; DSCF6104.jpg; DSCF6105.jpg; DSCF6106.jpg; DSCF6107.jpg; DSCF6097.jpg; DSCF6098.jpg; DSCF6099.jpg; DSCF6100.jpg

Dear Rasul,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : \$8,844.82 (before GST)

No of working days : 08 days. (LOR)

We will proceed for closing after 1 week of submission to you.
Kindly contact me if there is any discrepancy.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

7465 28/6/18
0900

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SMA7497U

Chassis No : MRHFC5650JT000842

Model : CIVIC 1.6 VTI YM2018

Owner's Name : MARGONO BIN SOEJONO

Ins Policy No. :

Date of Accident :

Document No. : SQT18002645 Page 1

Date : 27. Jun 2018

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : R16B25500916

Date | Time : 27. Jun 2018 1:32:55 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:MARGONO BIN SOEJONO OWNER INSURER:TOKIO MARINE ACC DATE:26/06/2018 SURVEYED BY: DATE:27/06/2018 REF NO: TP INSURER:CHINA TAIPING INSURANCE (S'PORE) PTE LT TP VEH:SLP5926U						
66100-TEC-307ZZ	PANEL SETRR.	1	236.00	25	177.00	12.39	189.39
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10	25	354.07	24.78	378.85
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74851-TEA-003	LOCK ASSYTRUNK	1	72.20	25	54.15	3.79	57.94
74862-TEA-003	STRIKERTRUNK LID	1	6.90	25	5.17	0.36	5.53
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	97.70	25	73.27	5.13	78.40
75701-TBA-A10	EMBLEM,H-MARK	1	11.90	25	8.92	0.62	9.54
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
75722-TBA-A00	EMBLEM SETRR.	1	11.50	25	8.62	0.60	9.22
75725-TEA-T01	EMBLEMRR.	1	10.60	25	7.95	0.56	8.51
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	25	28.65	2.01	30.66
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	173.00	25	129.75	9.08	138.83
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.20	25	1.65	0.12	1.77
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.20	25	1.65	0.12	1.77
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
33505-TEA-T01	REFLECTOR ASSYR.RR.	1	7.00	25	5.25	0.37	5.62

do glass coating after repair

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SMA7497U

Chassis No : MRHFC5650JT000842

Model : CIVIC 1.6 VTI YM2018

Owner's Name : MARGONO BIN SOEJONO

Ins Policy No. :

Date of Accident :

Document No. : SQT18002645

Date : 27. Jun 2018

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : R16B25500916

Date | Time : 27. Jun 2018 1:32:55 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
33555-TEA-T01	REFLECTOR ASSYL.RR.	1	7.00	25	5.25	0.37	5.62
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
84521-TEA-Q01ZA	LID ASSYSPARE TIRE	1	58.40	25	43.80	3.07	46.87
84601-TEA-Q01ZA	LINING ASSYR.TRUNK SIDE	1	47.40	25	35.55	2.49	38.04
84651-TEA-Q01ZA	LINING ASSYL.TRUNK SIDE	1	47.40	25	35.55	2.49	38.04
34150-TEX-Y01	LIGHT ASSYR.LID	1	118.70	25	89.02	6.23	95.25
34155-TEX-Y01	LIGHT ASSYL.LID	1	118.70	25	89.02	6.23	95.25
33500-TEA-T01	TAILLIGHT ASSYR.	1	253.80	25	190.35	13.32	203.67
33550-TEA-T01	TAILLIGHT ASSYL.	1	273.10	25	204.82	14.34	219.16
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS	1	27.20	25	20.40	1.43	21.83
39680-TEX-Y41ZT	SENSOR ASSYPARKING	4	79.80	25	239.40	16.76	256.16
39670-TEX-Y01	SENSOR UNITPARKING	1	60.70	25	45.52	3.19	48.71
Sum Item					2477.49	173.45	2,650.94

BOSUN	SUNDRIES	1	100.00	30	70.00	7.00	107.00
BOJSE	SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR TRUNK	1	80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOMISC1	REMOVE, CHECK AND INSTALL SMART ENTRY SENSOR.	1	560.00	280	560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	4000.00	2800	4000.00	280.00	4280.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	3000.00	2700	3000.00	210.00	3210.00
BOMISC1	REMOVE, INSTALL AND CALIBRATE REAR CAMERA	1	380.00		380.00	26.60	406.60
Sum Labor					9120.00	638.40	9,758.40

Survey By

Rasul - Hp 90010068

Date & Time

28/06/18 @ 1430

Total Amount 11,597.49 811.85 12,409.34

Printed on 27/6/2018 1:40:16 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SMA7497U

Chassis No : MRHFC5650JT000842

Model : CIVIC 1.6 VTI YM2018

Owner's Name : MARGONO BIN SOEJONO

Ins Policy No. :

Date of Accident :

Document No. : SQT18002645 Page 3

Date : 27. Jun 2018

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : R16B25500916

Date | Time : 27. Jun 2018 1:32:55 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Excess							
Status							
Signature							

Total (Inclusive of GST)

12,409.34

8 days

Per

Resurvey & paint

29/6/2018

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 27/6/2018 1:40:16 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SMA7497U
Chassis No : MRHFC5650JT000842
Model : CIVIC 1.6 VTI YM2018
Owner's Name : MARGONO BIN SOEJONO
Ins Policy No :
Date of Accident :

Document No. : SQT18002834
Date : 10. Jul 2018
Customer No. : WZC008
Svc Advisor :
Engine No : R16B25500916
Date | Time : 10. Jul 2018 8:40:19 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH: SUPPLEMENTARY						
71506-TEX-Y00	COVERRRR.TOWING HOOK /DE	1	8.70	25	6.52	0.46	6.98
				Sum Item	<u>6.52</u>	<u>0.46</u>	<u>6.98</u>

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 6.52 0.46 6.98
Total (Inclusive of GST) 6.98

Printed on 10/7/2018 8:41:34 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: MRHFC5650JT000842
License No: SMA7497U
Mileage: 8
Engine No: R16B25500916

Document No: SVO18037607
Printed By: SHNG
Order Date: 28. June 2018
Order Time: 4:40:52 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:MARGONO BIN SOEJONO OWNER INSURER:TOKIO MARINE ACC DATE:26/06/2018 SURVEYED BY:RASUL (LKK) DATE:27/06/2018 REF NO: TP INSURER:CHINA TAIPING INSURANCE (S'PORE) PTE LT TP VEH:SLP5926U ADDITIONAL PART						
66100-TEC-307ZZ	PANEL SETRR.	1	236.00	25	177.00	12.39	189.39
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10	25	354.07	24.78	378.85
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74861-TEA-003	LOCK ASSYTRUNK	1	72.20	25	54.15	3.79	57.94
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	25	28.65	2.01	30.66
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	173.00	25	129.75	9.08	138.83
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
33550-TEA-T01	TAILLIGHT ASSYL	1	273.10	25	204.82	14.34	219.16
71506-TEX-Y00	COVERRR.TOWING HOOK (A) DE✓	1	8.70	25	6.52	0.46	6.98
	SUM PARTS:				1,574.82	110.25	1,685.07
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BOJSE	0701 SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	0701 SEALANT FOR TRUNK	1	80.00		80.00	5.60	85.60
BML02I	1757 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BA02R	0669 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOMISC1	0669 REMOVE, CHECK AND INSTALL SMART ENTRY SENSOR. RESET MEMORY. (N)	1	280.00		280.00	19.60	299.60
BMI03D	0669 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	560.00		560.00	39.20	599.20
BKRP02M	0669 CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,800.00		2,800.00	196.00	2,996.00



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPIG
Chassis No: MRHFC5650JT000842
License No: SMA7497U
Mileage: 8
Engine No: R16B25500916

Document No: SVO18037607
Printed By: SHNG
Order Date: 28. June 2018
Order Time: 4:40:52 PM
Service Advisor: NG SIN HAI

BP05R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,700.00	2,700.00	189.00	2,889.00
BOMISC1	1610 REMOVE, INSTALL AND CALIBRATE REAR CAMERA	1	380.00	380.00	26.60	406.60
			SUM LABOUR:	7,270.00	508.90	7,778.90
			TOTAL SGD	8,844.82	619.15	9,463.97

Total Payable (SGD) 9,463.97

GST Amount is calculated from individual line(s)

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18011826/R1RBN2

Date: 02/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3047751700
Claimant Vehicle No :	SMA7497U	Insured Vehicle No :	SLP5926U
Date of Loss:	26/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D03209C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA7497U	Engine No:	R16B25500916
Make & Model:	HONDA CIVIC, 1.6 (A)	Chassis No:	MRHFC5650JT000842
Reg. Date:	18/06/2018 (Man. Year: 2018)	Odometer:	740 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R16	Rear Tyre Size:	215/55R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,584.01	1,604.82	979.19	37.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,020.00	7,240.00	1,780.00	19.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,604.01	8,844.82	2,759.19	23.78
+ GST 7.00/7.00% (S\$)	812.28	619.14	193.14	23.78
Nett Amount (S\$)	12,416.29	9,463.96	2,952.33	23.78

INSPECTION

Date of Assignment:	28/06/2018	
Date Inspected:	28/06/2018	Inspected At: Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD Singapore -
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2018)
Parts: 143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMA7497U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SETRR	Bent	177.00 FS	*177.00 FS
2	1		*STIFFENER.R RR PANEL SIDE	Bent	19.50 FS	*19.50 FS
3	1		*STIFFENERL RR PANEL SIDE	Bent	19.50 FS	*19.50 FS
4	1		*LID COMP TRUNK	Bent	354.07 FS	*354.07 FS
5	1		*WEATHERSTRIP TRUNK LID	Necessary	52.50 FS	*52.50 FS
6	1		*LOCK ASSY TRUNK	Bent	54.15 FS	*54.15 FS
7	1		*STRIKER TRUNK LID	Not Necessary	5.17 FS	*- FS
8	1		*GARNISH ASSYRR LICENSE	Not Necessary	73.27 FS	*- FS
9	1		*EMBLEM,H-MARK	Not Necessary	8.92 FS	*- FS
10	2		*NUTPUSH 3MM	Not Necessary	2.85 FS	*- FS
11	1		*EMBLEM SETRR	Not Necessary	8.62 FS	*- FS
12	1		*EMBLEMRR	Not Necessary	7.95 FS	*- FS
13	1		*FACE ASSY,RR BUMPER	Deformed	462.90 FS	*462.90 FS
14	1		*GARNISH,RR BUMPER LOWER	Deformed	28.65 FS	*28.65 FS
15	1		*BEAM COMPRR BUMPER	Bent	129.75 FS	*129.75 FS
16	1		*BRACKETR RR BUMPER SIDE	Not Necessary	1.65 FS	*- FS
17	1		*BRACKETL RR BUMPER SIDE	Not Necessary	1.65 FS	*- FS
18	1		*SPACERR RR BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
19	1		*SPACERL RR BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
20	1		*REFLECTOR ASSYR RR	Serviceable	5.25 FS	*- FS
21	1		*REFLECTOR ASSYL RR	Serviceable	5.25 FS	*- FS
22	7		*CLIPBUMPER	Necessary	10.50 FS	*10.50 FS
23	1		*LINING ASSYRR PANEL	Deformed	37.72 FS	*37.72 FS
24	1		*LID ASSYSPARE TIRE	Not Necessary	43.80 FS	*- FS
25	1		*LINING ASSYR TRUNK SIDE	Not Necessary	35.55 FS	*- FS
26	1		*LINING ASSYL TRUNK SIDE	Not Necessary	35.55 FS	*- FS
27	1		*LIGHT ASSYR LID	Not Necessary	89.02 FS	*- FS
28	1		*LIGHT ASSYL LID	Not Necessary	89.02 FS	*- FS
29	1		*TAILLIGHT ASSYR	Not Necessary	190.35 FS	*- FS
30	1		*TAILLIGHT ASSYL	Cracked	204.82 FS	*204.82 FS
31	1		*SUB CORDRR BUMPER CORNER SENS	Not Necessary	20.40 FS	*- FS
32	4		*SENSOR ASSYPARKING	Not Necessary	239.40 FS	*- FS
33	1		*SENSOR UNITPARKING	Not Necessary	45.52 FS	*- FS
34	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
35	1		*COVERRR TOWING HOOK	Deformed	6.52 FS	*6.52 FS
					Total Parts (\$\$)	2,584.01 1,604.82

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SEALANT FOR REAR END PANEL	New	80.00	80.00
2	SEALANT FOR TRUNK	New	80.00	80.00
3	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	180.00	180.00
4	REMOVE & RENEW REVERSE SENSORS-4PCS	New	180.00	180.00
5	REMOVE,CHECK AND INSTALL SMART ENTRY SENSOR	New	560.00	280.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	560.00	560.00
7	CUT OFF & RENEW RR PANEL STRAIGHTEN	New	4,000.00	2,800.00
8	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	New	3,000.00	2,700.00
9	REMOVE,INSTALL AND CALIBRATE REAR CAMERA	New	380.00	380.00
Gross Labour Cost (\$\$)			9,020.00	7,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >