

Surveyor:

KSC

DOI:

3/21/2018

Date / Time

28/6/18

Registered in Merimen:

28/6/18

Pre-assign / CCU / FTE

SHB 4481M



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Zeh Chong Han

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

91738964 (V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHB 4481M

SLX 4742Y

SLP 9703U



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

617480

7P



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
2/6/18	Non-Reporting ltr (1st):	
2/6/18	Non-Reporting ltr (2nd):	
2/6/18	Non-Reporting ltr (Final):	
2/6/18	Notification ltr (if non-pickup):	
2/6/18	Call OI:	
2/6/18	After call ltr to OI:	
2/6/18	Documentation Check List: Handler Typist	
2/6/18	Notification ltr (if non-pickup)	☒
2/6/18	After call ltr to OI:	☒
2/6/18	Authorisation To Act:	☒
2/6/18	Release Voucher:	☒
2/6/18	Final Repair Bill:	☒
2/6/18	Car Rental Invoice:	☒
2/6/18	Towing Invoice:	☒
2/6/18	LTA / GIA:	☒
2/6/18	Medical Bill:	☒
2/6/18	PIR:	☒
2/6/18	Mandate/Reject Instruction:	☒
2/6/18	LOD:	☒
2/6/18	Payment Breakdown Form:	☒
2/6/18	Post-Repair Photos:	☒
2/6/18	Others:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:
2/6/18	11:30am	Yun Shi

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: \$18,289.90	14 days	Reduction: %	Email ☐ Call ☐

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.:	28/6/18	28/6/18	
Repair Cost: \$19,570.10			
Loss of Rental (LOR): \$50.00 (1 days)			
Loss of Use (LOU): \$50.00 x 19 days			
Loss of Income (LOI): \$50.00 x 19 days			
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]			
GIA/LTA Search: \$7.65			
Medical: \$50.00			
Disbursement: \$50.00 (e.g. Tow/ Independent)			
Legal Cost: \$50.00			
Total: \$20,520.00		Global Sum \$5: 20,520.00	

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1: \$20,520.00		Name 1: BH AUTO SERVICES PTE LTD	
Payee 2: (Strike if N.A.) \$50.00		Name 2: -	
Payee 3: (Strike if N.A.) \$50.00		Name 3: -	



BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOH Building
Singapore 049711
ATTN: MOTOR CLAIM DEPARTMENT
Tel: 63476100 Fax: 62244174
DEAR SIR / MADAM

Not Authorised
Passing By point
14 day

ACCIDENT REPAIR ON: SLX4742Y

MODEL: HONDA SHUTTLE

POLICY NO: 599212491

CHASSIS NO: GP71121414

YEAR OF MANUFACTURE: 2018

DATE / TIME OF ACCIDENT: 25/06/2018 Time: 0920Hrs at ALONG AYE (MCE) AT 9.9KM MARK

THIRD PARTY VEHICLE NO: SHB4481M

Date: 02/07/2018

Page: 1 of 3

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
SS		SS		SS
1 Bonnet	1	634.40	Dented	634.00
2 Bonnet hinge LH	1	54.90	Bented	54.90
3 Bonnet hinge RH	1	54.90	Bented	54.90
4 Bonnet lock assy	1	161.17	Dented	161.17
5 Bonnet insulator	1	198.80	Kinked	198.80
6 Bonnet insulator clips	5	300.00	Necessary	15.00
7 Bonnet rubber	1	165.80	Necessary	165.80
8 Bonnet stopper LH	1		Necessary	
9 Bonnet stopper RH	1		Necessary	
10 Front grille	1		Necessary	
11 Front grille upper moulding chrome	1	363.60	Broken	363.60
12 Front grille lower moulding chrome	1	292.60	Broken	292.60
13 Front grille emblem	1	267.80	Broken	267.80
14 Front grille clips	1	58.30	Necessary	58.30
15 Headlamp LH	10	5.80	Necessary	58.00
16 Headlamp RH	1	2,128.70	Cracked	2,128.70
17 Headlamp lower bracket LH	1	2,128.70	Cracked	2,128.70
18 Headlamp lower bracket RH	1	58.40	Broken	58.40
19 Front bumper	1	58.40	Broken	58.40
20 Front bumper reinforcement	1	1,841.10	Torn	1,841.10
21 Front bumper sponge	1	387.60	Dented	387.60
22 Front bumper lower grille	1		Broken	
23 Front bumper tow cover	1	150.70	Torn	150.70
24 Front bumper side grille LH	1	44.80	Cut	44.80
25 Front bumper side grille RH	1	58.18	Cut	58.18
26 Front bumper clips	1	58.18	Cut	58.18
27 Front bumper side retainer LH	12	5.80	Necessary	69.60
28 Front bumper side retainer RH	1	50.40	Necessary	50.40
29 Front support panel	1	50.40	Necessary	50.40
30 Front support panel top garnish	1	811.20	Dented	811.20
31 Front support panel top garnish clips	1	62.30	Kinked	62.30
32 Horn	10	5.80	Necessary	69.60
33 Aircon condenser	1		To Check	
34 Aircon condenser air guard LH	1	775.30	Dented	775.30
			Kinked	

35	Aircon condenser air guard RH
36	Aircon condenser fan cowling
37	Aircon condenser fan motor
38	Aircon condenser fan blade
39	Radiator
40	Radiator fan cowling
41	Radiator fan motor
42	Radiator fan blade
43	Radiator top support bracket LH
44	Radiator top support bracket RH
45	Radiator tank
46	Air filter assembly
47	Battery holder bracket
48	Battery tray
49	Wiper tank
50	Front fender LH
51	Front fender RH
52	Front fender shield LH
53	Front fender shield RH
54	Front fender shield clips
55	Tailgate
56	Tailgate lock assy
57	Tailgate striker
58	Tailgate inner upper trim
59	Tailgate inner lower trim
60	Tailgate lamp LH
61	Tailgate lamp RH
62	Tailgate emblem
63	Tailgate lettering "SHUTTLE"
64	Tailgate lettering "HYBRID"
65	Tailgate license garnish chrome
66	Tailgate hinge LH
67	Tailgate hinge RH
68	Tailgate stand absorber LH
69	Tailgate stand absorber RH
70	Tailgate weatherstrip
71	Rear windscreen moulding set
72	Rear tail lamp assy LH
73	Rear tail lamp assy RH
74	Rear bumper
75	Rear bumper side retainer LH
76	Rear bumper side retainer RH
77	Rear bumper reflector LH
78	Rear bumper reflector RH
79	Rear bumper tow cover
80	Rear bumper reflector backing LH
81	Rear bumper reflector backing RH
82	Rear bumper clips
83	Rear end panel
84	Rear end panel top garnish
85	Rear fender shield LH
86	Rear fender shield RH
87	Rear fender shield clips
88	Rear fender inner lower trim LH
89	Rear fender inner lower trim RH
90	Spare tyre panel
91	Spare tyre wheel cover board

\$ 14813.53 - 20%

= \$ 11850.82

	Kinked		
	Cracked		
292.00	Malfunction	292.00	
149.20	To Check	149.20	
1,847.30	Broken	1,847.30	
220.30	Cracked	220.30	
275.70	Malfunction	275.70	
163.10	To Check	163.10	
	Bent		
	Bent		
78.81	Kinked	78.81	
	To Check		
	Bent		
	Dented		
156.60	Kinked	156.60	
390.80	Dented	390.80	
390.80	Dented	390.80	
195.80	Torn	195.80	
195.80	Torn	195.80	
5.80	Necessary	116.00	
845.80	Dented	845.80	
176.60	Bent	176.60	
124.70	Bent	124.70	
	Kinked		
	Kinked		
369.10	Scratches	369.10	
369.10	Scratches	369.10	
57.23	Necessary	57.23	
144.70	Necessary	144.70	
154.70	Necessary	154.70	
324.50	Scratches	324.50	
57.90	Bent	57.90	
57.90	Bent	57.90	
130.96	Bent	130.96	
130.96	Bent	130.96	
170.80	Cut	170.80	
128.60	Necessary	128.60	
369.10	Scratches	369.10	
369.10	Scratches	369.10	
785.70	Broken	785.70	
50.50	Necessary	50.50	
50.50	Necessary	50.50	
50.10	Scratches	50.10	
50.10	Scratches	50.10	
109.10	Cut	109.10	
50.10	Torn	50.10	
50.10	Torn	50.10	
5.80	Necessary	69.60	
599.40	Dented	599.40	
182.40	Kinked	182.40	
	Cut		
	Cut		
	Necessary		
	Kinked		
	Kinked		
1,367.60	Dented	1,367.60	
521.00	Kinked	521.00	

Sub-Total 23,375.65
Less 20% discount 4,675.13
Total Parts after 20% discount: 18,700.52

LRH Auto Consultants hence notify
the Repairer of the following

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to market condition
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary details must be destroyed and is subject to final approval from Insurance Company

Special Nett Items

- 1 Anti-rust coating
- 2 Front number plate with casing
- 3 Rear number plate with casing
- 4 Radiator coolant
- 5 Windscreen sealant
- 6 Rear end panel sealant
- 7 Spare tyre panel sealant
- 8 Rear bumper sensor set

Acknowledged by Repairer 80.00
Signature: 1 80.00
Date: 1 80.00
1 60.00
1 120.00
1 100.00
1 100.00
1 250.00

nn 640.00 X
CAM 80.00 85.00
In 80.00 X
nn 60.00 X
m 120.00 65.00
m 100.00 30.00
am 100.00 X
Shen 250.00 200.00

\$315

1,430.00

Total Parts: 20,130.52

Labour Charges For Front & Rear Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs
- 5 Dismantle and transfer tailgate fittings and mechanism to new/facilitate repair
- 6 Provide skill labour to remove and replace aircon condenser, pipes and radiator Vacuum aircon system and refill gas
- 7 Provide skill labour to remove and refit rear windscreen
- 8 Provide skill labour to remove and refit rear undercarriage to facilitate repair
- 9 Provide skill labour to remove and replace bumper sensor
- 10 Provide skill labour to remove and refit exhaust pipe/system to facilitate repair
- 11 Provide skill labour to mount vehicle onto chassis alignment bench

3,000.00 1600
2,500.00 2000
60.00 40
150.00 80
80.00 60
150.00 100
150.00 130
300.00 X
60.00 30
nn 120.00 X
350.00 850

Total Labour:

\$4300

Total Parts & Labour:
GST 7%
Grand Total:

5,940.00
26,070.52
1,824.94
27,895.46

Estimate Repair Duration

22 days

ACCIDENT VEHICLE OF: SLX4742Y

Page: 3 of 3

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

TA cash
14 days ✓ o/c

Survey attended by:

Name: Henrich
Company: LRH
Date: 3/7/18
Title: 10.5m
Contact No: 96910663
Email: _____

Part: \$11850.82 + \$1474.08 (Supp)

SIN: \$315.00

Labour: \$4300.00 + \$300.00 (Supp) +50

Total: \$18239.90

\$18289.90

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 Tel: 6559 8044 Fax: 6269 2801

THIRD PARTY VEHICLE NO: SHB4481M

Grand Total:	147.29
	<u>2,254.27</u>

Page 1 of 1



BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-111/113/115/117
SINGAPORE 575636 TEL: (65) 6559 8944 FAX: (65) 62692404
CO. REG. NO.: 200917512K GST REG. NO.: 200917512K

TAX INVOICE

TO: INDIA INTERNATIONAL INSURANCE PTE LTD
ADDR: 64 CECIL STREET #04 / #05
108 BUILDING SINGAPORE 049711
Singapore

NUMBER: BAC/201808/1011
DATE: 14-Aug-2018
WORK ORDER: AC/201808/1781
VEHICLE NO: SLX4742Y - HONDA SHUTTLE HYBRID

MOBILE NO: 6347 6100
CHASSIS NO: GP71121414
ENGINE NO: LEB6326401
DATE IN: 14-Aug-18
MILEAGE:

TERM: CASH ON DELIVERY
RECOMMENDED BY:
DONE BY: JACELYN LOH CAI LING

SN	DESCRIPTION	QTY	UNIT PRICE	DISCOUNT	AMOUNT
1	UNLOCK ECU SYSTEM	1 PCS	S\$300.00	0.00	S\$300.00

SINGAPORE DOLLARS THREE HUNDRED TWENTY ONE ONLY

SUB TOTAL: S\$300.00
ADD GST @7%: S\$21.00
GRAND: S\$321.00

Remark: ACCIDENT ON 25/06/2018 *BA911*



BH Auto Services Pte Ltd

RECEIVED BY

* TRANSFER ACCOUNT NO : DBS CURRENT- 027 904 0912 , MAY BANK CURRENT- 042 110 20567. PLEASE SMS/WHATAPPS TO (9621 2045) / EMAIL TO "info@bhauto.com.sg" AFTER PAYMENT IS DONE.
1) WE ACCEPT MASTER, VISA, CASH, NETS AND CHEQUE.
2) ALL CHEQUE SHOULD BE CROSSED AND MADE PAYABLE TO: BH AUTO SERVICES PTE LTD
3) INTEREST OF 1.5% PER MONTH WILL BE CHARGED ON OVERDUE ACCOUNTS.
4) SERVICE WARRANTY DOES NOT APPLY:
(a) TO DAMAGE CAUSED BY ACCIDENT, ABUSE, MISUSE, MISAPPLICATION, OR NON-BH AUTO SERVICES' PRODUCTS;
(b) TO DAMAGE CAUSED BY SERVICE PERFORMED BY ANYONE OTHER THAN BH AUTO SERVICES;
(c) TO A PRODUCT OR PART THAT HAS BEEN MODIFIED WITHOUT THE WRITTEN PERMISSION OF BH AUTO SERVICES.
5) PLEASE ALWAYS REFER TO THE TERMS AND CONDITIONS PUBLISHED IN OUR WEBSITE: <http://www.bhauto.com.sg/>
6) PLEASE BE INFORM THAT WITH EFFECTIVE FROM 1ST JAN 2017, WE WILL BE INCURRING CHARGES OF SGD \$30.00 FOR COLLECTION/DELIVERY OF YOUR VEHICLE TO OUR WORKSHOP.

Print Date Time : 14-Aug-2018 15:37:53 PM

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

DEAR SIR / MADAM :

Not At home
Resurvey By painting
10-12 days

ACCIDENT REPAIR ON: SLX4742Y

MODEL : HONDA SHUTTLE

POLICY NO : 599212491

CHASSIS NO : GP71121414

YEAR OF MANUFACTURE : 2018

DATE / TIME OF ACCIDENT: 25/06/2018 Time: 0920Hrs at ALONG AYE (MCE)AT 9.9KM MARK.

THIRD PARTY VEHICLE NO: SHB4481M

Date: 02/07/2018

Page : 1 of 3

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		SS		SS
1 Bonnet	1	634.40	Dented	<i>Bu</i> 634.60 ✓
2 Bonnet hinge LH	1	54.90	Bented	54.90 ?
3 Bonnet hinge RH	1	54.90	Bented	54.90 ?
4 Bonnet lock assy	1	161.17	Dented	161.17 ?
5 Bonnet insulator	1	198.80	Kinked	<i>Sm</i> 198.80 X
6 Bonnet insulator clips	1		Necessary	<i>sm</i> X
7 Bonnet rubber	1	165.80	Necessary	165.80 ?
8 Bonnet stopper LH	1		Necessary	<i>sm</i> X
9 Bonnet stopper RH	1		Necessary	<i>sm</i> X
10 Front grille	1	363.60	Broken	<i>cm</i> 363.60 —
11 Front grille upper moulding chrome	1	292.60	Broken	<i>cm</i> 292.60 —
12 Front grille lower moulding chrome	1	267.80	Broken	<i>cm</i> 267.80 —
13 Front grille emblem	1	58.30	Necessary	<i>sm</i> 58.30 —
14 Front grille clips	10	5.80	Necessary	<i>sm</i> 58.00 —
15 Headlamp LH	1	2,128.70	Cracked	2,128.70 ✓
16 Headlamp RH	1	2,128.70	Cracked	2,128.70 ✓
17 Headlamp lower bracket LH	1	58.40	Broken	58.40 ?
18 Headlamp lower bracket RH	1	58.40	Broken	58.40 ?
19 Front bumper	1	1,841.10	Torn	<i>Bu</i> 1,841.10 ✓
20 Front bumper reinforcement	1	387.60	Dented	387.60 ?
21 Front bumper sponge	1		Broken	? ?
22 Front bumper lower grille	1	150.70	Torn	150.70 ?
23 Front bumper tow cover	1	44.80	Cut	<i>sm</i> 44.80 X
24 Front bumper side grille LH	1	58.18	Cut	<i>sm</i> 58.18 X
25 Front bumper side grille RH	1	58.18	Cut	<i>sm</i> 58.18 X
26 Front bumper clips	12	5.80	Necessary	<i>sm</i> 69.60 —
27 Front bumper side retainer LH	1	50.40	Necessary	<i>Dir</i> 50.40 —
28 Front bumper side retainer RH	1	50.40	Necessary	<i>Dir</i> 50.40 —
29 Front support panel	1	811.20	Dented	811.20 ?
30 Front support panel top garnish	1	62.30	Kinked	62.30 ?
31 Front support panel top garnish clips	10	5.80	Necessary	69.60 ?
32 Horn	1		To Check	? ?
33 Aircon condenser	1	775.30	Dented	775.30 ?
34 Aircon condenser air guard LH	1		Kinked	? ?

ms can
ms dir

35	Aircon condenser air guard RH	1		Kinked		?
36	Aircon condenser fan cowling	1		Cracked		?
37	Aircon condenser fan motor	1	292.00	Malfunction	292.00	?
38	Aircon condenser fan blade	1	149.20	To Check	149.20	?
39	Radiator	1	1,847.30	Broken	1,847.30	X
40	Radiator fan cowling	1	220.30	Cracked	220.30	?
41	Radiator fan motor	1	275.70	Malfunction	275.70	?
42	Radiator fan blade	1	163.10	To Check	163.10	?
43	Radiator top support bracket LH	1		Bented		?
44	Radiator top support bracket RH	1		Bented		?
45	Radiator tank	1	78.81	Kinked	78.87	?
46	Air filter assembly	1		To Check		X
47	Battery holder bracket	1		Bented		X
48	Battery tray	1		Dented		X
49	Wiper tank	1	156.60	Kinked	156.60	?
50	Front fender LH	1	390.80	Dented	390.80	✓
51	Front fender RH	1	390.80	Dented	390.80	✓
52	Front fender shield LH	1	195.80	Torn	195.80	?
53	Front fender shield RH	1	195.80	Torn	195.80	?
54	Front fender shield clips	20	5.80	Necessary	116.00	?
55	Tailgate	1	845.80	Dented	845.80	✓
56	Tailgate lock assy	1	176.60	Bented	176.60	✓
57	Tailgate striker	1	124.70	Bented	124.70	?
58	Tailgate inner upper trim	1		Kinked		?
59	Tailgate inner lower trim	1		Kinked		?
60	Tailgate lamp LH	1	369.10	Scratches	369.10	?
61	Tailgate lamp RH	1	369.10	Scratches	369.10	?
62	Tailgate emblem	1	57.23	Necessary	57.23	✓
63	Tailgate lettering "SHUTTLE"	1	144.70	Necessary	144.70	✓
64	Tailgate lettering "HYBRID"	1	154.70	Necessary	154.70	✓
65	Tailgate license garnish chrome	1	324.50	Scratches	324.50	?
66	Tailgate hinge LH	1	57.90	Bented	57.90	X
67	Tailgate hinge RH	1	57.90	Bented	57.90	✓
68	Tailgate stand absorber LH	1	130.96	Bented	130.96	X
69	Tailgate stand absorber RH	1	130.96	Bented	130.96	✓
70	Tailgate weatherstrip	1	170.80	Cut	170.80	?
71	Rear windscreen moulding set	1		Necessary		✓
72	Rear tail lamp assy LH	1	369.10	Scratches	369.10	X
73	Rear tail lamp assy RH	1	369.10	Scratches	369.10	?
74	Rear bumper	1	785.70	Broken	785.70	✓
75	Rear bumper side retainer LH	1	50.50	Necessary	50.50	X
76	Rear bumper side retainer RH	1	50.50	Necessary	50.50	✓
77	Rear bumper reflector LH	1	50.10	Scratches	50.10	?
78	Rear bumper reflector RH	1	50.10	Scratches	50.10	?
79	Rear bumper tow cover	1	109.10	Cut	109.10	✓
80	Rear bumper reflector backing LH	1	50.10	Torn	50.10	?
81	Rear bumper reflector backing RH	1	50.10	Torn	50.10	?
82	Rear bumper clips	12	5.80	Necessary	69.60	✓
83	Rear end panel	1	599.40	Dented	599.40	?
84	Rear end panel top garnish	1	182.40	Kinked	182.40	?
85	Rear fender shield LH	1		Cut		X
86	Rear fender shield RH	1		Cut		X
87	Rear fender shield clips	20		Necessary		X
88	Rear fender inner lower trim LH	1		Kinked		?
89	Rear fender inner lower trim RH	1		Kinked		?
90	Spare tyre panel	1	1,367.60	Dented	1,367.60	?
91	Spare tyre wheel cover board	1	521.00	Kinked	521.00	?

Sub-Total:	23,375.65
Less: 20% discount -	4,675.13
Total Parts after 20% discount:	18,700.52

Special Nett Items

1	Anti-rust coating	8	80.00	640.00	?
2	Front number plate with casing	1	80.00	80.00	45m
3	Rear number plate with casing	1	80.00	80.00	X
4	Radiator coolant	1	60.00	60.00	?
5	Windscreen sealant	1	120.00	120.00	40m
6	Rear end panel sealant	1	100.00	100.00	30m
7	Spare tyre panel sealant	1	100.00	100.00	?
8	Rear bumper sensor set	1	250.00	250.00	200m
				1,430.00	

Total Parts: 20,130.52**Labour Charges For Front & Rear Portion**

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	3,000.00	?
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	2,500.00	2000
3	Provide skill labour to disconnect and check electrical wiring	60.00	40
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs	150.00	80
5	Dismantle and transfer tailgate fittings and mechanism to new/facilitate repair	80.00	60
6	Provide skill labour to remove and replace aircon condenser, pipes and radiator Vacuum aircon system and refill gas	150.00	?
7	Provide skill labour to remove and refit rear windscreen	150.00	120
8	Provide skill labour to remove and refit rear undercarriage to facilitate repair	300.00	?
9	Provide skill labour to remove and replace bumper sensor	60.00	50
10	Provide skill labour to remove and refit exhaust pipe/system to facilitate repair	120.00	?
11	Provide skill labour to mount vehicle onto chassis alignment bench	350.00	?

Total Labour:**5,940.00****Total Parts & Labour:****26,070.52****GST 7%****1,824.94****Grand Total:****27,895.46****Estimate Repair Duration****22 days ?**
TA car hire

ACCIDENT VEHICLE OF : SLX4742Y

Page : 3 of 3

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Survey attended by:

Name : Kenneth
 Company : LKK
 Date : 3/7/18
 Time : 10:15am
 Contact No : 96910663
 Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

SATISFACTION CERTIFICATE / DISCHARGE VOUCHER

I, AGGRAB18 hereby state that the repairs

to my Vehicle No : SLX4742Y have been carried out to my entire satisfaction

and I am to agree that the discharge to the account of Messrs. **BH AUTO SERVICES PTE LTD**

for by the (Insurance) India International Insurance Pte Ltd shall be in full discharge of all

claims under Vehicle No. SHB4481M with regard to the damages to my vehicle

as a result of accident which occurred on 25 / 06 / 2018 Time: 0920 Hrs

at ALONG AYE (MCE) AT 9.9KM MARK



Signature: _____

Name: AGGRAB18

NRIC: 53337833L

Date: 28 / 07 / 2018

Time: 15:30 Hrs

- New 2018 BMW X3
- A New Chapter - Skoda Singapore
- Djitsun Mall @ Bedok, where Princess Theatre used...

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

2009 Forester XI 2.5 (New 10 Year COE)



Extreme Low Mileage, New Matt
Parkview Stock
Engine Expensive Audio
System, Full
Direct Owner



Browse by Category

Sort by Date Posted 20 results/page

4 vehicles

SHUTTLE HYBRID

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	SHUTTLE HYBRID	Any	Any	2018	Any	Any	Any	Available
	Honda Shuttle Hybrid 1.5A	\$86,800	\$8,630 /yr	03-Apr-2018	1,496 cc	-	Stationwagon	Available
Fuel Type: Petrol-Electric Low Fuel Consumption, In House Loan Available, 3 Years Or 100,000km Warranty, 3 x Free Servicing, Call Our Friendly Salesperson Now!								
Posted: 23-Jun-2018 Tags: 2018 Honda Shuttle, Honda Shuttle, Honda, Shuttle, Used Honda								
	Honda Shuttle Hybrid 1.5A	\$86,800	\$8,470 /yr	07-Jun-2018	1,496 cc	30 km	Stationwagon	Available
Fuel Type: Petrol-Electric Almost Brand New, Low Fuel Consumption With Hybrid, Flexible In-House Loan Packages Available, Drive Away With Minimum Down Payment.								
Posted: 05-Jun-2018 Tags: 2018 Honda Shuttle, Honda Shuttle, Honda, Shuttle, Used Honda								
	Honda Shuttle Hybrid 1.5A X	\$87,988	\$8,670 /yr	07-May-2018	1,496 cc	30 km	Stationwagon	Available
Fuel Type: Petrol-Electric Almost Brand New Condition, Low Fuel Consumption With Hybrid, Drive Away With Minimum Down Payment, Come With Warranty, Call Us Now.								
Posted: 08-Jun-2018 Tags: 2018 Honda Shuttle, Honda Shuttle, Honda, Shuttle, Used Honda								
	Honda Shuttle Hybrid 1.5A X	\$87,800	\$8,720 /yr	06-Apr-2018	1,496 cc	-	Stationwagon	Available
Fuel Type: Petrol-Electric Flawless And Mint Condition, Almost Brand New Condition, Low Fuel Consumption With Hybrid, Drive Away With Minimum Down Payment, Come With Warranty, Call Us To Make An Appointment To View This Car.								
Posted: 23-Apr-2018 Tags: 2018 Honda Shuttle, Honda Shuttle, Honda, Shuttle, Used Honda								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used SHUTTLE HYBRID, SHUTTLE HYBRID Singapore, used SHUTTLE HYBRID Singapore, used SHUTTLE HYBRID, used vehicles Singapore or even buy used SHUTTLE HYBRID Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

Compare

Print Received Message

This mail is associated with :

***SLX4742Y (MCT18060737)**
[SHB4481M]

TP

AGGRAB18

Jun 25 2018 9:00AM

[-]

BH Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 29/04/2019 10:54 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20717.65) - SLX4742Y - Claim Handler: Zuhaidah Bte Samsuri

Approved:20717.65.

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SHB4481M

Our Reference: SLX4742Y

Date: 09/01/2018

M/s India International Insurance Pte Ltd
64 Cecil Street
#05-01 IOB Building
Singapore 049711

BY POST & EMAIL

Attention: Claims Department

CLAIMANT: AGGRAB18

PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25/06/2018 ALONG AYE (MCE) AT 9.9KM MARK. INVOLVING VEHICLE NO SLX4742Y & SHB4481M

We act for **AGGRAB18** who was the owner of motor vehicle no. SLX4742Y

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 25/06/2018 involving our client's vehicle registration number SLX4742Y and vehicle registration number SHB4481M, driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair (Included 7% GST)	\$ 19,570.20
2	Loss of Use (\$ 120.00 x 21days) 2 days PRI 1 day survey , 1 day re-survey 3 days Sunday	\$ 2520.00
3	LTA Search Fee	\$ 7.45
	Total :	\$ 22,097.65

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA/ Police report lodged by driver of ;
- (b) Final Repair Bill
- (c) Rental Invoice / Loss Of Use
- (d) LTA Search Fee Invoice
- (e) Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,

Yun Shi
(O): 6559 8944 (F): 6269 2404



AUTHORISATION

Name of owner of m/vehicle: AGGRAB 18
 Address: CHUA CHU KANG STREET 64 Singapore 689097
 NRIC No: 53337833L
 RE: ACCIDENT ON 25/06/18 ALONG AYE (MCE) AT 9.9KM MARK
 INVOLVING SLX4742Y YS SHB4481M

In consideration of **BH AUTO SERVICES PTE LTD** ("the Workshop") repairing my/our vehicle no. SLX4742Y at my/our request, I/We the abovenamed owner of motor vehicle no. SLX4742Y hereby authorise the Workshop to demand claim, negotiate, settle my/our claim for cost of repairs loss of use and all other expenses and damages arising out of the above accident.

I/We further authorise the Workshop to appoint solicitors to demand, claim, negotiate, settle and/or commence legal proceedings in my/our name for the above purpose and at the sole discretion of the Workshop. All sums recovered therefrom shall belong to the Workshop absolutely and I/We further authorise the Workshop to give absolute discharge on my/our behalf and to sign all discharge vouchers and other documents in relation to the same on my/our behalf. I/We further agree to fully co-operate with the solicitors appointed by the Workshop on my/our behalf and attend all Court hearings that are necessary to prosecute the claims maintained by the Workshop.

I/We agree that in the event that the claim is rejected for whatsoever reason or the Workshop decides not to proceed with legal proceedings or for whatsoever reason the Workshop is unable to recover all of the repair costs or are only able to recover a portion of the same I/we hereby undertake to pay them the full repair costs and or any portion thereof that cannot be recovered and all expenses including legal costs that they may have incurred in pursuing the claim within 7 days from the date of the written notice for payment by them to my/our last known address.

I/We hereby declare that I/we will always remain and be liable to the Workshop for the cost of repair to my/our motor vehicle and expenses incurred on my/our behalf. In the event that Workshop has to issue any notice or commence legal proceedings against me/us to enforce this undertaking against me/us, I/we shall be liable for the Workshop's expenses and legal cost (including solicitor and client cost) on an indemnity basis.

I/We further authorise the Workshop to give to the other party/parties absolute discharge in respect of any liability and any sum, whether agreed or not made the Workshop or to the law firm appointed by the Workshop towards full settlement of my/our claim it shall be regarded as full and final discharge of the claim.

I/We further authorise the Workshop to settle the above mentioned claim in a manner that they deem fit and the Workshop is further authorised to receive payment further to settlement of my claim with payment cheque/s being made in favour of the Workshop.


 Signed:

Date this 26 (day) of 06 (month) 18 (year)

Owner of m/vehicle: SLX4742Y

HP: 96364879



Cecil19

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18060737
Claimant Ref: SLX 4742Y

We/I, BH AUTO SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANT PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 20,520.00 (global sum) ~~(repair cost)~~ S\$ 20,520.00 (amount paid), vehicle no. SLX 4742Y that was damaged pursuant to the accident which occurred on 25/06/2018 (date) at AYE (location) involving vehicle no. 3HE 4481M (insured vehicle). This is pursuant to the inspection conducted on 03/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner AGGRAB18 ("the third party claimant") of vehicle no. SLX 4742Y to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLX 4742Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 20,520.00 to BH AUTO SERVICES PTE LTD

Dated this 22 day of 06 2019

CLAIMANT:

Signature: [Signature]

Signed by "the workshop" (with chop)

Name: Chan Yung Shi

NRIC: G7674078Q

Address: BH Auto Services Pte Ltd

Nationality: Malaysia

Occupation: Self-employed

WITNESS:

Signature: [Signature]

Signed by appointed Surveyor

Name: LKK AUTO CONSULTANT PTE LTD

NRIC: 199607198R

Address: 51 UBI AVE 1 #02-25

PAYA UBI INDUSTRIAL PARK S(408933)

Nationality:

Occupation:

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE
SECTOR C #01-115 SINGAPORE 575636

Tel: 6743 3494

Fax: 6269 2404

CO. REG. NO. 201006106C

GST REG NO. 201006106C

TAX INVOICE

Final Repair Bill

Our Ref: SLX4742Y

Date: 03/04/2018

M/s India International Insurance Pte Ltd
64 Cecil Street
#05-01 IOB Building
Singapore 049711

BY POST & EMAIL

Vehicle No : SLX4742Y
Make/ Model : HONDA SHUTTLE
Year of Manufacture : 2017
Chassis No. : GP71121414
Colour : BLUE
D.O.A : 25/06/2018

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

1. Repair Cost for Motor Vehicle No. SLX4742Y
Type of repair: Part By Part :S\$ 18289.90

GST @ 7% : S\$ 1280.30

GRAND TOTAL:S\$ 19570.20

Total : Singapore Dollars Nineteen Thousand Five Hundred Seventy Dollars and
Twenty Cents Only.

Company's Stamp & Signature



> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 27 Jun 2018 / 11:34:48

Receipt Date/Time : 27 Jun 2018 / 11:34:48

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180627-000842

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
	Result of Insurance Enquiry - SHB4481M As at 25 Jun 2018/09:20:00 Insurance Co: INDIA INT'L INS PTE LTD			
1	Insurance Enquiry - SHB4481M Enquiry Fee 20180627113300926241	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx0796 Credit Card: Visa/MasterCard			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jun 2018 Edit Reg		28 Jun 2018 00:00 Edit Adj Rpt	S\$18,289.90 Edit Estimates	S\$18,289.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, ID: 199303821R								
Main Claimant:	AGGRAB18, Co. Reg. No.: 53337833L								
Vehicle Reg. No.:	SLX4742Y	Date of Loss:	25/06/2018 09:00 - :59 [2 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18060737	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHB4481M	Policy No. (Claimant):	5099212491						
		Excess:							
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (29/04/2019): Alert - Adj Mandate Approved (S\$20717.65) - SLX4742Y - Claim Handler: Zuhaidah B... - III_SG (29/04/2019): Alert - Adj Mandate Approved (S\$20717.64) - SLX4742Y - Claim Handler: Zuhaidah B... - III_SG (28/03/2019): Alert - Adj Mandate Maintained - SLX4742Y - Claim Handler: Zuhaidah Bte Samsuri - III_SG (01/02/2019): Alert - Adj Mandate Maintained - SLX4742Y - Claim Handler: Zuhaidah Bte Samsuri - III_SG (05/07/2018): Alert - Adj Mandate Approved (S\$0.00) - SLX4742Y - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX4742Y (MCT18060737)
[SHB4481M]
TP
AGGRAB18
Jun 25 2018 9:00AM
[COMFORT TRANSPORTATION PTE LTD]
BH Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/01/19 10:56	Odometer Reading		Load JPG	☒
2	14/01/19 10:56	Chassis Number		Load JPG	☒
3	14/01/19 10:57	General View		Load JPG	☒
4	14/01/19 10:57	General View		Load JPG	☒
5	14/01/19 10:57	General View		Load JPG	☒
6	14/01/19 10:57	General View		Load JPG	☒
7	14/01/19 10:57	General View		Load JPG	☒
8	14/01/19 10:57	General View		Load JPG	☒
9	14/01/19 10:57	General View		Load JPG	☒
10	14/01/19 10:57	General View		Load JPG	☒
11	14/01/19 10:57	General View		Load JPG	☒
12	14/01/19 10:57	General View		Load JPG	☒
13	14/01/19 10:57	General View		Load JPG	☒
14	14/01/19 10:57	General View		Load JPG	☒
15	14/01/19 10:57	General View		Load JPG	☒
16	14/01/19 10:57	General View		Load JPG	☒
17	14/01/19 10:57	General View		Load JPG	☒
18	14/01/19 10:57	General View		Load JPG	☒
19	14/01/19 10:57	General View		Load JPG	☒
20	14/01/19 10:57	General View		Load JPG	☒
21	14/01/19 10:57	General View		Load JPG	☒
22	14/01/19 10:57	General View		Load JPG	☒
23	14/01/19 10:57	General View		Load JPG	☒
24	14/01/19 10:57	General View		Load JPG	☒
25	14/01/19 10:57	General View		Load JPG	☒
26	14/01/19 10:57	General View		Load JPG	☒
27	14/01/19 10:57	General View		Load JPG	☒
28	14/01/19 10:57	General View		Load JPG	☒
29	14/01/19 10:57	General View		Load JPG	☒
30	14/01/19 10:57	General View		Load JPG	☒
31	14/01/19 10:57	General View		Load JPG	☒
32	14/01/19 10:59	Reinspection Photo		Load JPG	☒
33	14/01/19 10:59	Reinspection Photo		Load JPG	☒
34	14/01/19 10:59	Reinspection Photo		Load JPG	☒
35	14/01/19 10:59	Reinspection Photo		Load JPG	☒
36	14/01/19 10:59	Reinspection Photo		Load JPG	☒
37	14/01/19 10:59	Reinspection Photo		Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	14/01/19 10:59	Reinspection Photo	 Load JPG	☒
39	14/01/19 10:59	Reinspection Photo	 Load JPG	☒
40	14/01/19 10:59	Reinspection Photo	 Load JPG	☒
41	14/01/19 10:59	Reinspection Photo	 Load JPG	☒
42	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
43	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
44	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
45	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
46	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
47	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
48	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
49	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
50	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
51	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
52	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
53	22/03/19 16:46	Reinspection Photo	 Load JPG	☒
54	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
55	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
56	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
57	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
58	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
59	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
60	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
61	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
62	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
63	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
64	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
65	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
66	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
67	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
68	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
69	24/04/19 16:46	Reinspection Photo	 Load JPG	☒
70	24/04/19 17:02	Reinspection Photo	 Load JPG	☒
71	24/04/19 17:02	Reinspection Photo	 Load JPG	☒
72	24/04/19 17:02	Reinspection Photo	 Load JPG	☒
73	24/04/19 17:02	Reinspection Photo	 Load JPG	☒
74	24/04/19 17:02	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/06/18 17:11	TP GIA REPORT	 Load PDF	
2	28/06/18 17:11	NOTIFICATION FROM WORKSHOP	 Load JPG	☒
3	28/06/18 17:11	ACKNOWLEDGEMENT EMAIL TO III DD 28.06.2018	 Load PDF	
4	04/07/18 18:27	TP ESTIMATE - MARKED	 Load PDF	
5	23/01/19 11:07	LTA SEARCH	 Load PDF	
6	01/07/19 15:27	WORKSHOP INVOICE	 Load PDF	
7	01/07/19 15:27	AUTHORISATION TO ACT FORM	 Load PDF	
8	01/07/19 15:27	DISCHARGE VOUCHER	 Load PDF	
9	01/07/19 15:27	LOD	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	29/06/18 14:55	Singapore Accident Statement-IV	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18011833/KGA3Q2

Date: 01/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: SLX4742Y

Insured Vehicle No: SHB4481M

Date of Loss: 25/06/2018

Nature of Claim: TP

Claim No: MCT18060737

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX4742Y

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB6326401

Reg. Date: 28/03/2018 (Man. Year: 2017)

Chassis No: GP71121414

Colour: Metallic Dark Blue

Odometer: 16453 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,719.00	13,639.90	8,079.10	37.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,550.00	4,650.00	2,900.00	38.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,269.00	18,289.90	10,979.10	37.51
+ GST 7.00/7.00% (S\$)	2,048.83	1,280.29	768.54	37.51
Nett Amount (S\$)	31,317.83	19,570.19	11,747.64	37.51
+ Loss of Use (19.0 x S\$50.00/day) (S\$)		950.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		20,527.64		
Global Sum Settlement (S\$)		20,520.00		

INSPECTION

Date of Assignment: 28/06/2018

Date Inspected: 03/07/2018 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C,
#01/111/113/115/117
Singapore 575636

Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Jan 2019)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX4742Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	634.60 FL	*634.60 FL
2	1		*BONNET HINGE LH	Distorted	54.90 FL	*54.90 FL
3	1		*BONNET HINGE RH	Distorted	54.90 FL	*54.90 FL
4	1		*BONNET LOCK ASSY	Repair	161.17 FL	*- FL
5	1		*BONNET INSULATOR	Serviceable	198.80 FL	*- FL
6	5		*BONNET INSULATOR CLIPS	Necessary	15.00 FL	*15.00 FL
7	1		*BONNET RUBBER	Cut	165.80 FL	*165.80 FL
8	1		*BONNET STOPPER LH (NPA)	Serviceable	0.00 FL	*- FL
9	1		*BONNET STOPPER RH (NPA)	Serviceable	0.00 FL	*- FL
10	1		*FRONT GRILLE	Cracked	363.60 FL	*363.60 FL
11	1		*FRONT GRILLE UPPER MOULDING CHROME	Cracked	292.60 FL	*292.60 FL
12	1		*FRONT GRILLE LOWER MOULDING CHROME	Cracked	267.80 FL	*267.80 FL
13	1		*FRONT GRILLE EMBLEM	Necessary	58.30 FL	*58.30 FL
14	10		*FRONT GRILLE CLIPS	Necessary	58.00 FL	*58.00 FL
15	1		*HEADLAMP LH	Mtg Cracked	2,128.70 FL	*2,128.70 FL
16	1		*HEADLAMP RH	Mtg Distorted	2,128.70 FL	*2,128.70 FL
17	1		*HEADLAMP LOWER BRACKET LH	Distorted	58.40 FL	*58.40 FL
18	1		*HEADLAMP LOWER BRACKET RH	Distorted	58.40 FL	*58.40 FL
19	1		*FRONT BUMPER	Buckled	1,841.10 FL	*1,841.10 FL
20	1		*FRONT BUMPER REINFORCEMENT	Bent	387.60 FL	*387.60 FL
21	1		*FRONT BUMPER SPONGE (NPA)	No such part	0.00 FL	*- FL
22	1		*FRONT BUMPER LOWER GRILLE	Serviceable	150.70 FL	*- FL
23	1		*FRONT BUMPER TOW COVER	Serviceable	44.80 FL	*- FL
24	1		*FRONT BUMPER SIDE GRILLE LH	Serviceable	58.18 FL	*- FL
25	1		*FRONT BUMPER SIDE GRILLE RH	Serviceable	58.18 FL	*- FL
26	12		*FRONT BUMPER CLIPS	Necessary	69.60 FL	*69.60 FL
27	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	50.40 FL	*50.40 FL
28	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	50.40 FL	*50.40 FL
29	1		*FRONT SUPPORT PANEL	Bent	811.20 FL	*811.20 FL
30	1		*FRONT SUPPORT PANEL TOP GARNISH	Dented	62.30 FL	*62.30 FL
31	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	69.60 FL	*69.60 FL
32	1		*HORN (NPA)	Serviceable	0.00 FL	*- FL
33	1		*AIRCON CONDENSER	Bent	775.30 FL	*775.30 FL
34	1		*AIRCON CONDENSER AIR GUARD LH (NPA)	Serviceable	0.00 FL	*- FL
35	1		*AIRCON CONDENSER AIR GUARD RH (NPA)	Serviceable	0.00 FL	*- FL
36	1		*AIRCON CONDENSER FAN COWLING (NPA)	Serviceable	0.00 FL	*- FL
37	1		*AIRCON CONDENSER FAN MOTOR	Serviceable	292.00 FL	*- FL
38	1		*AIRCON CONDENSER FAN BLADE	Serviceable	149.20 FL	*- FL
39	1		*RADIATOR	Serviceable	1,847.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*RADIATOR FAN COWLING	Serviceable	220.30 FL	*- FL
41	1		*RADIATOR FAN MOTOR	Serviceable	275.70 FL	*- FL
42	1		*RADIATOR FAN BLADE	Serviceable	163.10 FL	*- FL
43	1		*RADIATOR TOP SUPPORT BRACKET LH (NPA)	Repair	0.00 FL	*- FL
44	1		*RADIATOR TOP SUPPORT BRACKET RH (NPA)	Repair	0.00 FL	*- FL
45	1		*RADIATOR TANK	Serviceable	78.87 FL	*- FL
46	1		*AIR FILTER ASSEMBLY (NPA)	Serviceable	0.00 FL	*- FL
47	1		*BATTERY HOLDER BRACKET (NPA)	Repair	0.00 FL	*- FL
48	1		*BATTERY TRAY (NPA)	Serviceable	0.00 FL	*- FL
49	1		*WIPER TANK	Serviceable	156.60 FL	*- FL
50	1		*FRONT FENDER LH	Buckled	390.80 FL	*390.80 FL
51	1		*FRONT FENDER RH	Buckled	390.80 FL	*390.80 FL
52	1		*FRONT FENDER SHIELD LH	Serviceable	195.80 FL	*- FL
53	1		*FRONT FENDER SHIELD RH	Serviceable	195.80 FL	*- FL
54	20		*FRONT FENDER SHIELD CLIPS	Not Necessary	116.00 FL	*- FL
55	1		*TAILGATE	Bent	845.80 FL	*845.80 FL
56	1		*TAILGATE LOCK ASSY	Jammed	176.60 FL	*176.60 FL
57	1		*TAILGATE STRIKER	Repair	124.70 FL	*- FL
58	1		*TAILGATE INNER UPPER TRIM (NPA)	Serviceable	0.00 FL	*- FL
59	1		*TAILGATE INNER LOWER TRIM (NPA)	Serviceable	0.00 FL	*- FL
60	1		*TAILGATE LAMP LH	Serviceable	369.10 FL	*- FL
61	1		*TAILGATE LAMP RH	Serviceable	369.10 FL	*- FL
62	1		*TAILGATE EMBLEM	Necessary	57.23 FL	*57.23 FL
63	1		*TAILGATE EMBLEM SHUTTLE	Necessary	144.70 FL	*144.70 FL
64	1		*TAILGATE EMBLEM HYBRID	Necessary	154.70 FL	*154.70 FL
65	1		*TAILGATE LICENSE GARNISH CHROME	Serviceable	324.50 FL	*- FL
66	1		*TAILGATE HINGE LH	Repair	57.90 FL	*- FL
67	1		*TAILGATE HINGE RH	Repair	57.90 FL	*- FL
68	1		*TAILGATE STAND ABSORBER LH	Serviceable	130.96 FL	*- FL
69	1		*TAILGATE STAND ABSORBER RH	Serviceable	130.96 FL	*- FL
70	1		*TAILGATE WEATHERSTRIP	Dented / Cut	170.80 FL	*170.80 FL
71	1		*SET REAR WINDSCREEN MOULDING	Necessary	128.00 FL	*128.00 FL
72	1		*REAR TAIL LAMP ASSY LH	Serviceable	369.10 FL	*- FL
73	1		*REAR TAIL LAMP ASSY RH	Serviceable	369.10 FL	*- FL
74	1		*REAR BUMPER	Bent	785.70 FL	*785.70 FL
75	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	50.50 FL	*- FL
76	1		*REAR BUMPER SIDE RETAINER RH	Distorted	50.50 FL	*50.50 FL
77	1		*REAR BUMPER REFLECTOR LH	Serviceable	50.10 FL	*- FL
78	1		*REAR BUMPER REFLECTOR RH	Cracked	50.10 FL	*50.10 FL
79	1		*REAR BUMPER TOW COVER	Dented	109.10 FL	*109.10 FL
80	1		*REAR BUMPER REFLECTOR BACKING LH	Serviceable	50.10 FL	*- FL
81	1		*REAR BUMPER REFLECTOR BACKING RH	Dented	50.10 FL	*50.10 FL
82	12		*REAR BUMPER CLIPS	Necessary	69.60 FL	*69.60 FL
83	1		*REAR END PANEL	Bent	599.40 FL	*599.40 FL
84	1		*REAR END PANEL TOP GARNISH	Dented	182.40 FL	*182.40 FL
85	1		*REAR FENDER SHIELD LH (NPA)	Serviceable	0.00 FL	*- FL
86	1		*REAR FENDER SHIELD RH (NPA)	Serviceable	0.00 FL	*- FL
87	20		*REAR FENDER SHIELD CLIPS (NPA)	Not Necessary	0.00 FL	*- FL
88	1		*REAR FENDER INNER LOWER TRIM LH (NPA)	Serviceable	0.00 FL	*- FL
89	1		*REAR FENDER INNER LOWER TRIM RH (NPA)	Serviceable	0.00 FL	*- FL
90	1		*SPARE TYRE PANEL	Repair	1,367.60 FL	*- FL
91	1		*SPARE TYRE WHEEL COVER BOARD	Serviceable	521.00 FL	*- FL
92	1		*ANTI-RUST COATING	Not Necessary	640.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*FRONT NUMBER PLATE WITH CASING	Cracked	80.00 FS	*45.00 FS
94	1		*REAR NUMBER PLATE WITH CASING	Serviceable	80.00 FS	*- FS
95	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
96	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
97	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
98	1		*SPARE TYRE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
99	1		*SET REAR BUMPER SENSOR	Shorted	250.00 FS	*200.00 FS
100	1		*TAILGATE PULL POCKET	Dented	19.90 FL	*19.90 FL
101	1		*TAILGATE INNER TRIM	Dented / Cut	320.00 FL	*320.00 FL
102	1		*REAR TAIL LAMP PANEL RH	Bent	210.20 FL	*210.20 FL
103	1		*BONNET LOCK TOP COVER	Dented	65.00 FL	*65.00 FL
104	1		*OUTER TEMPERATURE SENSOR HOLDER CLIP	Necessary	6.50 FL	*6.50 FL
105	1		*REAR FENDER INNER TRIM RH	Cracked	455.00 FL	*455.00 FL
106	1		*REAR BUMPER SIDE SPONGE RH	Cracked	89.50 FL	*89.50 FL
107	1		*FRONT BUMPER SIDE DUCT LH	Dented	50.10 FL	*50.10 FL
108	1		*FRONT BUMPER SIDE DUCT RH	Dented	50.10 FL	*50.10 FL
109	1		*FRONT GRILLE RETAINER LH	Distorted	15.40 FL	*15.40 FL
110	1		*FRONT GRILLE RETAINER RH	Distorted	15.40 FL	*15.40 FL
111	1		*REAR FLOOR LID TOOL	Cracked	295.00 FL	*295.00 FL
112	1		*REAR FLOOR UNDER BOX	Cracked	165.00 FL	*165.00 FL
113	1		*REAR FLOOR LID JACK GARNISH	Cracked	85.50 FL	*85.50 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	26,791.25	16,971.13
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,072.25	3,331.23
Total Parts (\$\$)	21,719.00	13,639.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	3,000.00	1,800.00
2	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	2,500.00	2,000.00
3	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	60.00	40.00
4	REMOVE AND REINSTALL CUSHIONS ,SEATS ,BACKREST ,INNER TRIM GARNISH ,ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	80.00
5	DISMANTLE AND TRANSFER TAILGATE FITTINGS AND MECHANISM TO NEW /FACILITATE REPAIR	New	80.00	60.00
6	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE AIRCON CONDENSER ,PIPES AND RADIATOR VACUUM AIRCON SYSTEM AND REFILL GAS	New	150.00	100.00
7	PROVIDE SKILL LABOUR TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
8	PROVIDE SKILL LABOUR TO REMOVE AND REFIT REAR UNDERCARRIAGE TO FACILITATE REPAIR	New	300.00	0.00
9	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE BUMPER SENSOR	New	60.00	50.00
10	PROVIDE SKILL LABOUR TO REMOVE AND REFIT EXHAUST PIPE /SYSTEM TO FACILITATE REPAIR	New	120.00	0.00
11	PROVIDE SKILL LABOUR TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH	New	350.00	250.00
12	TOWING CHARGES	New	180.00	50.00
13	TO RESET AND UNLOCK ECU & ABS WITH DIAGNOSTIC FAULT	New	450.00	300.00
Gross Labour Cost (S\$)			7,550.00	4,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >