INS. CASE OWNER:	cc 6, LAC 1843,	Aea3 n2 LKK: IDAC:
Surveyor:	DOI: ASSIGNMENT B	Date / Time
Pre-assign / CCU / Insured Vehicle No. Name of Insured Insured Tel No. Excess Sec II :SS Is driver the owner?	Claim No. INTERCENTING OF THE Policy No. HP: Make / Model D.O.A: N - 6 - 18 Place of Accident	TIN VAI
If NO, Driver Name Driver Tel N		RT: YES / NO; TP GIA REPORT: YESY NO sy: % Final? Yes / No
Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS: INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:
Date/ Time	X176767 X; 4M6973M-X	STAGE DATE / PIC Non-Reporting ltr (1st): Non-Reporting ltr (2nd):
	EMAIL WYP LIABILTY CIBAR.	Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI:
81-21-10	FILE PASS TO TYPIST TO PREPAIRE PERFORT.	After call ltr to OI: Documentation Check List: Handler Typist Notification ltr (if non-pickup)
	110 ITA FORMUNES	After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice LTA / GIA : Medical Bill: PIR: Mandate/Reject Instruction: LOD Payment Breakdown Form:
PRELIMINARY ADVICE	Date/Time: Sent By:	Post-Repair Photos: Others:
Repair Cost: 45	Date/Time: Confirm with: S\$3.000 (5 days) Reduction: 5\ %	Confirm by: WP Email Call
Final Liability: Repair Cost: Loss of Rental (LOR): Loss of Use (LOU):	Date/Time: I7-1-19 Confirm with June % 100 (Agreed / Assessed) BOLA S/N No.: NIL S\$3,000.00 010 REVERSED +117 TP S\$ - (days) S\$ 1,360.00 (\$ 300 x 6 days) S\$ - (\$ x days) LOR + LOU LOR + LOI Tick only one	Email Call If NO or B 28, Ass. Lia:
GIA/LTA Search Medical: Disbursement: Legal Cost	\$\$ 7.49 \$\$	1) Claim status: Normal/Reject/Private Settle 2) Report Format: TP 3) Survey fee: \$\Pi 450\$
	S\$ 4.201.49 Global Sum S\$: Date/Time: 17.1.19 Confirm with: JUNE	Email Call
Payee 2: (Strike if N.A.)	S\$ 4,007.49 Name 1: THUR MENG SPRRY PRINTING WORL S\$ Name 2: Name 3:	KSHOP

ASSIGNMENT

From: Date:	Veh No: 7P76767. Yr Regn: 2017 / Sept
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van Corty / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Isuzy NPRSS c.c 2989.
at Workshop m/s	Colour Blue A/C: Insured / Std / NI / NA
of	Sp.Reading 5A)&7 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/NO: JAANPRSSHH7/00262
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: *	Steering: Ingreer / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nin / S/Rim / STD A/Rim or
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: 5 days Res.: Yes or No Lum Sum: \$\int_0 \text{%} 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date / Time Action / Instruction TY Log Page 1.	R: 195/85 R16 C Yolco R: 195/85 R16 C B/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Front Rear R/Bal. Of mm R/Bal. of mm L/Bal. Of mm D.O.A. D.O.I. 27/06/18 Survey held at Hua Mery Des. of Damages: Frt / Rear / O/S / N/S/ U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision.
1/s:+3,000 (Red: +3,156.50 51%)	
4	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
Internal Committee Committ	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee:	: Site Insp (\$) _ s + RS _ SI '.
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / LB.I: (\$:Weekend (\$
	TOTAL

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883 Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ISLAND RECOVERY SERVICES 3026 Ubi Rd 1 #04-146 S 408719

TPLOnPore Asher.

Date Vehicle no Make/Model Accident date

:18.07.2018 :YP 7676 Z :ISUZU NPR :20.06.2018

JAAN PRAS

No				
	DESCRIPTION	Qty	•	Amount (S\$)
	<u>List Items</u>			
1	Front windscreen rubber	1	\$	-500 142
2	Front wiper panel Reput	1	\$	180 ×
3	Front wiper panel nozzle @ \$30.00) He New	2	\$	60 €
4	Front body panel Dented	1	\$	900 🖈
5	Front body reward-NP sticker Nec	1	\$	40 /
6	Front ISUZU emblem Her	1	\$	190 /
7	Front grille Couled	1	\$	560 /
8	Front grille lower lamp @ \$55.00	2	\$	110 ×
9	Front LH corner panel Ordice	1	\$	320 /
	Front LH side lamp Cauled	1	\$	130
11	Front LH side head lamp Couled 2682	1	\$	400
12	Front LH side head lamp Coulded Front LH side mirror round 2 Front LH side mirror bracket 22797	1	\$	60 X
13	Front LH side mirror bracket (New 22791)	1	\$	400
14	Front LH side mirror top cover	1	\$	40 4
			\$	3890
		Less 15%	\$	583.5
		Total	\$	3306.5

1 To supply front windscreen sealant
2 Remove & reinstall front windscreen
3 Remove & reinstall dashboard
4 Remove ,replace & repair consistent to the accident
5 Respray painting
6 Tuff kote

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting

- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and s subject to final approval from Insurance Company

hand by Repairer

	\$ 50 ×
	\$ 150 X. 120.
	\$ 300 ₹.
1520	\$ 1200 600
	\$ 1000 7000
	\$ 150 ×
Total	\$ 2850
_	

Grand Total 6156.5



O SOTO MED ID: 55 LEV

7007/007

Sketch Plan #3 Pg. 1

LETTER OF UNDERTAKING

I/We, I Sland Rec	iovery survice	, the owner of vehicle no	4776762
My/Our Insurance is un	der M/s AXA Insura	nce Singapore Pte Ltd, I/we Third Party and if the form	shall decide whether
claim to M/s AXA Insura 14(fourteen) days of	ince Singapore Pte I occurrence or dis	Ltd with all relevant facts an covery of damage.	d documents within
My/Our Third Party claim	is handle by my/our	preferred workshop, Hna	meny
Signed and Acknowledge			
S2n>t) 0 SST	Company Stamp	Date

Mei Kwan (LKKAuto)

From:

GERALD POH WEE BIN < geraldpoh@lonpac.com>

Sent:

Thursday, 5 July, 2018 10:46 AM

To:

Mei Kwan (LKKAuto)

Cc:

MT_Claim_SG

Subject:

RE: Direct Settlement - Accident Involving YM6973M (OI: LPC - TBA) and YP7676Z

(TP: LKK REF - CC6/LPC18011843/Aea3) on 20/06/2018

Attachments:

05072018104301.pdf

Follow Up Flag:

Follow up

Flag Status:

Completed

Categories:

HMK

Our Ref

: 18/18/18/VC00/020693

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

The premium for the policy has been settled.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Thursday, 5 July, 2018 10:02 AM

To: MT_Claim_SG

Cc: GERALD POH WEE BIN; ERIC WOO JUN KIAT; ONG LI LI; Asher Sng (LKKAuto); Joy Irene (LKKAuto); Hsiao

Tong (LKKAuto); Admin A

Subject: RE: Direct Settlement - Accident Involving YM6973M (OI: LPC - TBA) and YP7676Z (TP: LKK REF -

CC6/LPC18011843/Aea3) on 20/06/2018

Dear Sir / Madam,

We refer to the above matter.

Kindly assist to verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: $\underline{\text{MeiKwan@lkkauto.com}}$ | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Tuesday, 3 July, 2018 5:37 PM

Asher Sng (LKKAuto)

From:

Asher Sng (LKKAuto)

Sent:

Thursday, 12 July 2018 11:07 AM

To:

'Hua Meng'

Subject:

Accident Involving YP 7676Z & YM 6973M on 20/06/2018

WTHOUT PREJUDICE

Your Ref: YP 7676Z

Our Ref: CC6/LPC18011843/Aea3

Dear Sir/Madam,

Accident Involving YP 7676Z & YM 6973M on 20/06/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: <u>ashersng@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En Automob	pile
LONPAC	INSURANCE	BHD	Ref : CC6/LPC1801184	13/Aea3n2
	CH ROAD 7 THE CONC	DURSESINGAPORE 199555	Date: 11-02-2019 Code: LPC2	
1.		Policy Particulars	:- THIRD PARTY CLAIM	
Ins	sured Veh.	YM 6973M	Veh. Inspected	YP 7676Z
Po	olicy No.	Z/18/VC00/101722	Coverage (\$)	0.00
CI	aim No.	18/18/18/VC00/020693	Excess (\$)	0.00
As	sign From		Assign Date	27/06/2018
2.		Vehicle Parti	culars & Condition	
Ma	ake & Model	ISUZU NPR85	c.c	2999
Er	ngine No.	HIDDEN	Year of Reg.	2017
Ch	nassis No.	JAANPR85HH7100262	Colour	BLUE
Oc	dometer	54287	Steering	IN ORDER
Br	akes	IN ORDER	Modification	NIL
Ge	eneral	GOOD		
3.		Condit	ons of Tyres	
		Size	Make	Balance
R/	H Front Tyre	205/75 R16C	YOKOHAMA	6 mm
L/I	H Front Tyre	205/75 R16C	YOKOHAMA	6 mm
R/	H Rear Tyre	195/85 R16C	BRIDGESTONE	6 mm
L/I	H Rear Tyre	195/85 R16C	BRIDGESTONE	6 mm
4.		Descripti	on of Damages	
TH	IE VEHICLE SU	STAINED DAMAGES AT THE FR	ONT PORTION.	
DA	MAGES SEE D	ETAILS.		
5.		Genera	I Information	
Ac	cident Date	20/06/2018	Inspection Date	27/06/2018
Sı	rvey held at	HUA MENG SPRAY PAINTING	WKSP	
		1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		ν,
5a.		R	emarks	
		ON WAS CONDUCTED ON A"WITCE TO YOUR INSTRUCTIONS, W		
5b.		Estimate	Days of Repair	

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 7676Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WINDSCREEN RUBBER	NECESSARY	500.00	142.00
1	FRONT WIPER PANEL	TO REPAIR SEE LABOUR	180.00	-
2	FRONT WIPER PANEL NOZZLE @\$30.00	NOT NECESSARY	60.00	
1	FRONT BODY PANEL	DENTED	900.00	900.00
1	FRONT BODY REWARD -NP STICKER	NECESSARY	40.00	40.00
1	FRONT ISUZU EMBLEM	NECESSARY	190.00	190.00
1	FRONT GRILLE	CRACKED	560.00	560.00
2	FRONT GRILLE LOWER LAMP @\$55.00	NOT NECESSARY	110.00	
1	FRONT LH CORNER PANEL	CRACKED	320.00	320.00
1	FRONT LH SIDE LAMP	CRACKED	130.00	130.00
1	FRONT LH SIDE HEAD LAMP	CRACKED	400.00	400.00
1	FRONT LH SIDE MIRROR ROUND	NOT NECESSARY	60.00	
1	FRONT LH SIDE MIRROR BRACKET	NOT NECESSARY	400.00	(-
1	FRONT LH SIDE MIRROR TOP COVER	NOT NECESSARY	40.00	u=
	LESS 15% DISCOUNT		-583.50	-402.30
			3,306.50	2,279.70
	LABOUR			
	TO SUPPLY FRONT WINDSCREEN SEALANT .	NOT NECESSARY	50.00	n=
	REMOVE & REINSTALL FRONT WINDSCREEN.		150.00	120.00
	REMOVE & REINSTALL DASHBOARD .	NOT NECESSARY	300.00	-
	REMOVE ,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF FRONT WIPER PANEL .		1,200.00	700.00
	RESPRAY PAINTING.		1,000.00	700.00
	TUFF KOTE.	NOT NECESSARY	150.00	
			2,850.00	1,520.00
	GRAND TOTAL		6,156.50	3,799.70

RECOMMENDED COST OF LUMP SUM REPAIRS		3,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/LPC18011843/Aea3n2





Report Ref No. CC6/LPC18011843/Aea3n2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.