

REF: CS/MS(118011844/Kvb02) Special Instruction:

S. REC. BY:

ASSIGNMENT (Office)

SUNVAJOY

Medimen

From (Person): Irene Tan

of MS1h

Date/Time: 28062018 403pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDL 8138Z

Insured:

SLJ 4562Z

at Workshop m/s

Cheng Hoe Motor

Tel:

6755 6142

of

Bik T019 Yishun Ind Park A #61-374

Policy No:

2905 8678 DMY

Claim No:

562629

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27062018

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

28062018 452pm

Person Contacted:

Sharon

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SDL 8138Z - OK / WR 17022299 / Kwbs
	SLJ 4562Z - X
27/18	Send preli revised via merimen
27/8/18	11 Pm 81800 Cabana E feed P (Rec) 1831.50, 5090

DA: 201117

*Kenneth*

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s *Cheng Hoe*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: *04* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: *SDL 81382* Yr Regn: *04:10*

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: *MIT Lanza* c.c. *1584*

Colour: *M. Silver* A/C: Insured / Std / NI / NA

Sp. Reading: *262590* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *JMY SNC S3A AU 000283*

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi:  Nil /  S/Rim / STD A/Rim or

Tyre Size: *F: Kaplen 185/65R15*

*Rear: Riva*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. *7* mm

L/Bal. *7* mm

D.O.A. *27/6/18*

Rear

R/Bal. *8* mm

L/Bal. *8* mm

D.O.I. *28/6/18*

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or *015 B*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*2/7 File pass to Catherine, GIA & client ready*

*11 Sep @ 1800 Confirm E heads*

RECEIVED 27 AUG 2018

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2) *27/8 - typist*

Days Of Repair: *4*

Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

*S - R.S. \$*

Fixtots

Others

TOTAL

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format:

*merimen*

Lump Sum / I.B.I. (\$ \_\_\_\_\_)

*1800*

<i>150</i>
<i>10</i>
<i>160</i>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jun 2018		28 Jun 2018 16:03 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	LEE SIEW TIN, ID: S1285070J		
Main Claimant:	CHIANG FUI LONG @CHIANG FEI LONG, ID: S0137431A		
Vehicle Reg. No.:	SDL8138Z	Date of Loss:	27/06/2018 14:00 - :59 [98 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 562629	Policy/Cover Note No.:	29058678QMY (Comprehensive) Coverage: 13/12/2017 - 12/12/2018
Vehicle Reg. No. (Insured):	SLJ4562Z	Policy No. (Claimant):	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/06/2018]		
Driver/Custodian (Insured):	ANDY TAN POH LYE (), NRIC: S1262379H, Tel: +6598164926		
Adj Asg. Remarks:	Liability 100% SJE agree - Kenneth Kong from LKK Contact : June at 6755 6142		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

<b>To:</b> MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
<b>Attn:</b> Irene Tan Gek Ing	
<b>Date:</b> 02 Jul 2018	
<h3 style="margin: 0;"><u>Preliminary Advice</u></h3>	

Insured Vehicle No	: SLJ4562Z		
TP Vehicle No	: SDL8138Z	Accident Date	: 27/06/2018
Make	: MITSUBISHI LANCER	Assignment Date	: 28/06/2018
Date of Inspection	: 28/06/2018	Est. Duration of Repair	: 0
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,631.50
Revised Amount	:S\$	1,245.00
Check Items (Estimated)	:S\$	1,540.80
Total	:S\$	2,785.80

Lump Sum Repair :S\$

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

## PARF/COE Rebate Enquiry

&gt; Back to OneMotoring

SDL8138Z  
70/MS1G

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7431A
Vehicle Details	
Vehicle No.:	SDL8138Z
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jun 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 GLX 5MT AIRBAG 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	4G18KD4575
Chassis No.:	JMYSNCS3AAU000283
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,373.00
Original Registration Date:	01 Apr 2010
First Registration Date:	01 Apr 2010
Transfer Count:	0
Actual ARF Paid:	\$12,373.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2020
PARF Rebate Amount:	\$6,805.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$22,401.00
COE Rebate Amount:	\$3,519.00
<b>Total Rebate Amount:</b>	<b>\$10,324.00</b>

The information contained herein is correct as at 27 Jun 2018

OK

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SDL 8138Z

TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)  
 16 RAFFLES QUAY  
 #24-01 HONG LEONG BUILDING  
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

*Not withash*

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 27/06/2018

TP Veh Reg No: SLJ4562Z

*1/1 Sing & Resurvey After Paint*

Estimate No: ES1890718/YISHUN

Date: 28 Jun 2018

Policy No: 5042837235-08

Veh Reg No: **SDL8138Z**

Make/Model: MITSUBISHI LANCER  
 1.6 GLX 5MT

Chassis No: JMYSNCS3AAU000283

Engine No: 4G18KD4575

Reg. Date: 01/04/2010

## Estimate Repair Cost to Vehicle No :SDL8138Z

Description	U/Price	Quantity	List Price SS	Amount SS
<b>Net Price</b>				
1 FRONT RH FENDER	573.00	1 PC	<i>RM</i> 573.00 ✓	
2 FRONT RH FENDER LAMP	28.00	1 PC	<i>RM</i> 28.00 ✗	
3 FRONT RH FENDER INNER SHIELD	104.00	1 PC	<i>RM</i> 104.00 ✓	
4 FRONT RH SHOCK ABSORBER	353.00	1 PC	<i>RM</i> 353.00 ✓	
5 FRONT RH KNUCKLE ARM	335.00	1 PC	<i>RM</i> 335.00 ✗	
6 FRONT RH WHEEL BEARING	120.00	1 PC	<i>RM</i> 120.00 ✗	
7 RH HEADLAMP	572.00	1 PC	<i>RM</i> 572.00 ✗	
			2,085.00	
		Less 10%	208.50	1,876.50
<b>Special Net</b>				
8 FRONT RH FENDER <del>GRILLS</del> MOULDING	120.00	1 PC	<i>RM</i> 120.00 =	
9 FRONT RH FENDER EMBLEM	35.00	1 PC	<i>RM</i> 35.00 =	
10 FRONT RH SPORT RIM	280.00	1 PC	<i>RM</i> 280.00 <i>250.00</i>	
			435.00	435.00
<b>Labour</b>				
11 REMOVE & REFIX FENDER,RH HEADLAMP,FRT BUMPER,RH SIDE SKIRT,KNOCK & REPAIR FRT RH FENDER INNER PANEL & REALIGN THE SAME	500.00	1 LA	500.00	<i>350.00</i>
12 REMOVE & REFIX FRT RH UNDER CARRIAGE	180.00	1 LA	180.00	<i>100.00</i>
13 PUTTY & RESPRAY ON FRT RH FENDER,BUMPER,LOWER SKIRT,FRT RH FENDER INNER PANEL	550.00	1 LA	550.00	<i>400.00</i>
14 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
15 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,320.00	1,320.00

Total SS 3,631.50

Add GST @ 7% 254.21

Total Amount Payable SS 3,885.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011844/KVBN2

Date: 28/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29058678QMY
Claimant Vehicle No :	SDL8138Z	Insured Vehicle No :	SLJ4562Z
Date of Loss:	27/06/2018	Nature of Claim:	TP
		Claim No:	562629

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDL8138Z	Engine No:	4G18KD4575
Make & Model:	MITSUBISHI LANCER, 1.6 GLX 5MT AIRBAG 2WD (M)	Chassis No:	JMYSNCS3AAU000283
Reg. Date:	01/04/2010 (Man. Year: 2009)	Odometer:	262590 km
Colour:	Metallic Silver		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	KAPSEN 7 mm	Rear Left Side:	Roadwear 8 mm
Front Right Side:	KAPSEN 7 mm	Rear Right Side:	Roadwear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,311.50	1,332.00	979.50	42.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	940.00	380.00	28.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,631.50</b>	<b>2,272.00</b>	<b>1,359.50</b>	<b>37.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
(S\$)	3,631.50	1,800.00	1,831.50	50.43
+ GST 7.00/7.00% (S\$)	254.21	126.00	128.21	50.43
<b>Nett Amount (S\$)</b>	<b>3,885.71</b>	<b>1,926.00</b>	<b>1,959.71</b>	<b>50.43</b>

INSPECTION

Date of Assignment: 28/06/2018

Date Inspected: 28/06/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun Industrial  
Park A  
Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2018)
<b>Parts:</b> 143	MITSUBISHI LANCER 1.6 GLX 5MT AIRBAG 2WD (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDL8138Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Bent	573.00 FN	*573.00 FN
2	1		*FRONT RH FENDER LAMP	Serviceable	28.00 FN	*- FN
3	1		*FRONT RH FENDER INNER SHIELD	Cracked	104.00 FN	*104.00 FN
4	1		*FRONT RH SHOCK ABSORBER	Bent	353.00 FN	*353.00 FN
5	1		*FRONT RH KNUCKLE ARM	Serviceable	335.00 FN	*- FN
6	1		*FRONT RH WHEEL BEARING	Not Necessary	120.00 FN	*- FN
7	1		*RH HEADLAMP	Serviceable	572.00 FN	*- FN
8	1		*FRONT RH FENDER MOULDING	Necessary	120.00 FS	*120.00 FS
9	1		*FRONT RH FENDER EMBLEM	Necessary	35.00 FS	*35.00 FS
10	1		*FRONT RH SPORT RIM	Dented	280.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>2,520.00</b>	<b>1,435.00</b>
- Nett Item Discount on N Items 10.00/10.00% (S\$)	208.50	103.00
<b>Total Parts (S\$)</b>	<b>2,311.50</b>	<b>1,332.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX FENDER,RH HEADLAMP,FRT BUMPER,RH SIDE SKIRT,KNOCK & REPAIR FRT RH FENDER INNER PANEL & REALIGN THE SAME	New	500.00	350.00
2	REMOVE & REFIX FRT RH UNDER CARRIAGE	New	180.00	100.00
3	PUTTY & RESPRAY ON FRT RH FENDER,BUMPER,LOWER SKIRT,FRT RH FENDER INNER PANEL	New	550.00	400.00
4	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
5	RUSTPROOFING	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,320.00</b>	<b>940.00</b>

Report was unsubmitted during this print-out.
-----------------------------------------------

&lt; END OF ESTIMATES &gt;