

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 340C

AAD1806-274

Not Authored
Resumy B4 paint @3034.34

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 340C

VF1ABL15AUC282746

RENAULT

LATITUDE

27.6.2018

EQ**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bulld</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Goldis</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1 BUMPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1 BUMPR RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1 BOOT REAR	\$	<i>R</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>ra</i> 225.36 X
19	1 BOOT BADGE	\$	<i>ra</i> 225.36
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81

Trans-cab Auto Services Pte Ltd**AAD1806-274**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 340C

30	1 DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66	}	<i>X</i>	
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45			
32	1 FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13			
33	1 WHEELARCH REAR LH	\$	<i>Sn</i> 543.47			
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45			
35	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13			
36	1 WHEELARCH REAR RH	\$	<i>Sn</i> 543.47			
37	1 TAILLAMP RH	\$	<i>Sn</i> 552.55			
38	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70			
39	1 TAILLAMP LH	\$	<i>Sn</i> 552.55			
40	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70			
41	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77			
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56			
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88			
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i> 612.21			
45	1 EXHAUST REAR	\$	<i>R</i> 7,489.05			
46	1 EXHAUST CAP REAR	\$	<i>R</i> 230.49			
47	1 FUEL FLAP L70Y	\$	<i>Sn</i> 343.57			
48	1 CHASSIS PANEL REAR LH	\$	<i>R</i> 3,766.43			
TOTAL		\$	42,823.60			
10%		\$	4,282.36			
		\$	38,541.24			

Specical Nett

1	1SET PARKING AID	\$	<i>Sn</i> 700.00	<i>X</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	<i>X</i>
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00	<i>X</i>
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	<i>X</i>
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00	<i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00	<i>X</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82	<i>X</i>
11	1SET BOOT FINISHER CLIP	\$	<i>na</i> 24.20	<i>X</i>
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00	<i>X</i>
13	1 BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1806-274

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 340C

14	1 BOOT INNER TRIM CLIP	\$	na	45.00	}
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
19	1 TAILLAMP CLIP RH	\$	na	5.00	
20	1 TAILLAMP CLIP LH	\$	na	5.00	
21	2 REAR WINDSCREEN SELANT	\$	na	80.00	
22	1 WINDSCREEN MOULDING	\$	na	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na	385.00	}
25	1 SPARE TYRE	\$	na	330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 40,766.26****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	2200
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	2000
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	600
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00 X
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1806-274

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 340C

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>170.00</i>	<i>X</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>170.00</i>	<i>X</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>380.00</i>	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>380.00</i>	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>170.00</i>	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>220.00</i>	<i>X</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>380.00</i>	<i>X</i>

TOTAL \$ 12,540.00**Over All Total \$ 53,306.26****(PART-BY-PART)****Repair Days***20 DAYS**2 days***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: