

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 151G**AAD1806-238***Not Notified
Reserve B&P only*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 151G

VF1ABL15AUC282259

RENAULT

LATITUDE

23.6.2018

III**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Tn</i> 1,108.46	<i>✓</i>
2	1 BUMPER LOWER REAR	\$	<i>Dis/mt</i> 768.84	<i>✓</i>
3	1 BUMPER BRACKET CTR REAR	\$	<i>mt</i> 113.47	<i>✓</i>
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>cm</i> 135.97	<i>✓</i>
5	1 BUMEP R RETAINER RH REAR	\$	<i>cm</i> 44.99	<i>✓</i>
6	1 BUMPER REFLECTOR RH	\$	<i>Bn</i> 43.61	<i>✓</i>
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	<i>X</i>
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99	<i>X</i>
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	<i>X</i>
10	1 BUMPER BEAM REAR	\$	<i>Bn</i> 777.52	<i>✓</i>
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	<i>X</i>
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Bn</i> 225.95	<i>✓</i>
13	1 BOOT REAR	\$	<i>Bn</i> 2,872.68	<i>✓</i>
14	1 BOOT FINISHER	\$	<i>Bn</i> 470.06	<i>✓</i>
15	1 BOOT WHEATERSTRIP	\$	<i>Dis/mt</i> 323.05	<i>✓</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>vt / mt</i> 493.35	<i>✓</i>
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Bn</i> 493.35	<i>✓</i>
18	1 BOOT BADGE 'RENAULT'	\$	<i>Bn</i> 225.36	<i>✓</i>
19	1 BOOT BADGE	\$	<i>Bn</i> 225.36	<i>✓</i>
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	<i>X</i>
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	<i>X</i>
22	1 BOOT HINGE LH	\$	<i>Bn</i> 367.84	<i>✓</i>
23	1 BOOT HINGE RH	\$	<i>Bn</i> 367.84	<i>✓</i>
24	1 BOOT INNER TRIM	\$	<i>Tn</i> 586.45	<i>✓</i>
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	<i>X</i>
26	1 BOOT LOCK	\$	<i>Bn</i> 202.67	<i>✓</i>
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	<i>X</i>
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	<i>X</i>
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1806-238**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 151G

30	1 FENDER PANEL REAR LH	\$	<i>R</i>	3,299.13	X
31	1 WHEELARCH REAR LH	\$	<i>SL</i>	543.47	X
32	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>SL</i>	671.45	X
33	1 FENDER PANEL REAR RH	\$	<i>Bu</i>	3,299.13	✓
34	1 WHEELARCH REAR RH	\$	<i>CM</i>	543.47	✓
35	1 TAILLAMP RH	\$	<i>Bu</i>	552.55	✓
36	1 TAILLAMP PANEL RH	\$	<i>Bu</i>	986.70	✓
37	1 OUTER PANEL REAR (End Panel)	\$	<i>Bu</i>	1,471.77	✓
38	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Re</i>	404.56	✓
39	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i>	2,189.88	X
40	1 SPARE WHEEL PANEL TRIM	\$	<i>SL</i>	612.21	X
41	1 EXHAUST REAR	\$	<i>R</i>	7,489.05	X
42	1 EXHAUST CAP REAR	\$	<i>Re</i>	230.49	✓
43	1 CHASSIS PANEL REAR RH	\$	<i>R</i>	3,766.43	X
44	1 KUCKLE ARM REAR RH L70Y	\$	<i>SL</i>	736.67	
45	1 BRAKE DISC REAR L70Y	\$	<i>SL</i>	525.91	
46	1 WHEEL HUB NUT L70Y	\$	<i>SL</i>	51.11	
47	1 WHEEL HUB CAP L70Y	\$	<i>SL</i>	57.82	
48	1 ABS SENSOR REAR RH L70Y	\$	<i>SL</i>	255.75	
49	1 REAR AXLE L70Y	\$	<i>SL</i>	4,167.03	
50	1 AXLE ARM RH L70Y	\$	<i>SL</i>	117.22	
51	1 LOWER ARM REAR RH L70Y	\$	<i>SL</i>	905.99	
52	1 ABSORBER REAR	\$	<i>SL</i>	389.75	
53	1 STABILIZER BAR REAR RH	\$	<i>SL</i>	604.65	
54	1 BRAKE CALIPER REAR RH	\$	<i>SL</i>	1,300.67	
55	1 WINDSCREEN REAR L70Y	\$	<i>Shonan</i>	1,463.28	✓
56	1 WINDSCREEN GARNISH INNER LH	\$	<i>SL</i>	263.74	X
57	1 WINDSCREEN GARNISH INNER RH	\$	<i>Dis</i>	263.74	✓
58	1 CHASSIS PANEL REAR RH	\$	<i>R</i>	3,766.43	X
59	1 WHEEL HOUSING PANEL REAR RH	\$	<i>R</i>	4,682.09	
60	1 KUCKLE ARM REAR RH L70Y	\$	<i>SL</i>	736.67	
61	1 BRAKE DISC REAR L70Y	\$	<i>SL</i>	525.91	
62	1 WHEEL HUB NUT L70Y	\$	<i>SL</i>	51.11	
63	1 WHEEL HUB CAP L70Y	\$	<i>SL</i>	57.82	
64	1 ABS SENSOR REAR RH L70Y	\$	<i>SL</i>	255.75	
65	1 REAR AXLE L70Y	\$	<i>Myelin</i>	4,167.03	
66	1 AXLE ARM RH L70Y	\$	<i>SL</i>	117.22	✓
67	1 LOWER ARM REAR RH L70Y	\$	<i>SL</i>	905.99	

Trans-cab Auto Services Pte Ltd

AAD1806-238

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 151G

68	1 ABSORBER REAR	\$	Sm	389.75	X
69	1 STABILIZER BAR REAR RH	\$	Sm	604.65	X
70	1 BRAKE CALIPER REAR RH	\$	Sm	1,300.67	X

TOTAL	\$	48,528.01
10%	\$	4,852.80
	\$	43,675.21

Specical Nett

1	1SET PARKING AID	\$	Shart	700.00	Goorn
2	1SET REAR BUMPER CLIP	\$	nn	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	nn	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	nn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	nn	24.20	—
12	1 BOOT STICKER "Trans-cab"	\$	nn	30.00	—
13	1 BOOT STICKER "6555-3333"	\$	nn	30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	nn	45.00	—
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
18	1 FENDER INNER TRIM CLIP RH	\$	nn	28.00	X
19	1 TAILLAMP CLIP RH	\$	nn	5.00	✓
20	1 TAILLAMP CLIP LH	\$	nn	5.00	X
21	2 REAR WINDSCREEN SELANT	\$	nn	80.00	Goorn
22	1 WINDSCREEN MOULDING	\$	nn	100.00	—
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	300
24	1 RIGHT REAR TYRE	\$	nn	330.00	Goorn
25	1 RIGHT REAR TYRE RIM	\$	nn	385.00	X

TOTAL \$ 2,225.02

Trans-cab Auto Services Pte Ltd**AAD1806-238**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 151G

TOTAL PARTS	\$	45,900.23
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	13201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	14001
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	} 601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1001
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	na 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201

Trans-cab Auto Services Pte Ltd**AAD1806-238**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 151G

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X

To transfer of rear door fittings, attachment and
perform water seepage test.

\$ *nn* 380.00X**TOTAL \$ 12,540.00****Over All Total \$ 58,440.23****(PART-BY-PART)****Repair Days**~~20 DAYS~~*11 days*

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**