

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

28-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6428 A

1 pc	Rear bumper	X	\$	696.00
1 pc	Rear bumper lower cover	—	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X	\$	58.00
1 pc	Rear bumper inner sponge	X	\$	114.00
1 pc	Rear bumper reinforcement	X	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	X	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	X	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	X	\$	92.00
				\$ 1,953.00
				Less 10%
				\$ 195.30
				\$ 1,757.70

S/NETT

1 set	Rear bumper clips	X	\$	48.00
1 set	Reverse sensor	X	\$	280.00
Sundry				\$ 50.00
To dismantle / replace reverse sensor to new bumper and reset to the same				\$ 120.00
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.				\$ 180.00
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.				\$ 650.00
To putty and spray painting on rear bumper, end panel				\$ 400.00
To apply rustproofing on the repaired and replaced panels.				\$ 150.00
				\$ 3,635.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Date:

Ka hui 11/6/18
28/6/18 1600h
2 Aug
L/S
After Repair photo