

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6403P

MAKE : HYUNDAI

MODEL : SONATA IKO

Date : 28.06.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Front Bumper <i>X repair</i>			\$ 1,052.20
1	Front Bumper Top Bracket - LH <i>X</i>			\$ 22.40
1	Front Bumper Side Bracket - LH <i>Y</i>			\$ 14.30
10	Front Bumper clips <i>X</i>		\$2.20	\$ 22.00
1	Front Fender - LH <i>X repair</i>			\$ 593.00
1	Front Steel Wheel <i>X</i>			\$ 351.90
1	Rear Door - LH <i>X repair</i>			\$ 1,351.10
	<i>Front Door - LH X repair</i>			
	<i>Rear Fender - LH X repair</i>			
	SUB TOTAL			\$ 3,406.90
	LESS 20%			681.38
	DISCOUNTED TOTAL			\$ 2,725.52
	<i>Front Door Comfort Striker</i>			<i>75.00</i>
1	Rear Door APP - LH			80.00 Nett
				\$ 80.00
	Labour Charge			
1	Panel Beating			\$ <i>400</i> 500.00
1	Spray Painting Charge			\$ <i>1400</i> 1500.00
1	Wiring Charge			\$ 50.00 <i>X</i>
1	Tuff Kote			\$ 80.00 <i>X</i>
	TOTAL LABOUR			\$ 1,380.00
	ESTIMATE TOTAL			\$ 4,185.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Kalvin IKK
28/6/18 1045hrs.
3 Reps.
P/P
After Repair photo

hence notify
 To display damaged parts(s) during survey
 Parts prices are subject to confirmation
 Third party survey is on a "Without Prejudice" basis
 No illegal modification(s) is allowed
 Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: