

12/03/2012

ASS. REC. BY:

REF: CS/FCI18011889/Ksd3ⁿ²

Zhe wei. Kek @

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

cus

From (Person):

Sithara

of

FCI

Date/Time: 29/6/18 @ 1:52pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 3332

Insured:

SHB 2533K

at Workshop m/s

Trans-cab

Tel:

6287 6666

of

No. 2 AMK of-63

Policy No:

Claim No:

D18005067MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/06/2018

CA / REV

REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

1:57pm @ 29/6/18

Person Contacted:

Kek zhe wei

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 3332-X

SHB 2533K- CS/FCI17003213/Kth3n2

D.O.A: 15/02/2017

02/07/18 @ 17:20 p.m. revised as to Sithara v.s email.

ASS. REC. BY:

REF:

F021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.13.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 3332 Yr Regn: 12, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M 2220 c.c. 2143

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 269184 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 212 00123 222215

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/55R6

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 26/6/18 D.O.I. 29/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/7 File pass to Catherine

30/1/18 Confirmed P/P \$ 1,342.00 @ 2 days with Kenneth.
(\$ 39,665.97 Red - 97%)

RECEIVED 30 NOV 2018

Date/Time, File Pass to?

30/1/18

1) Typist

Date/Time, File Return to?

2)

☐ : Prel. Report☒ : Final Report

Report Format :

Lump Sum / I.B.I. (\$) 1,342.00 P/P

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Fees

Others

580

657

TOTAL

31/12/18

31x15=465

170+465

50

14

699



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005067MFSH

Date: 02 July 2018

Our Ref: CS/FCI18011889/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 333Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/06/2018 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>41,007.97</u> .
Revised Estimate Amount	: S\$ <u>1,342.00</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 2 Days

Yours faithfully,
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-06-2018	Our Ref No. D18005067MFSH
Accident Date	26-06-2018	Claim Type. Third Party
Insured Vehicle	SHB2533K	Third Party Vehicle. SHD333Z
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241880)



PRI Documents



Close



PRI Header Details

Claim No	D18005067MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : KEK ZHEWEI)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: ZHEWEI.KEK@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2533K	TP Vehicle No	SHD333Z
PRI Recieved Date	29-06-2018 03:09:59 PM	Surveyor Appointed Date	29-06-2018 01:50:59 PM	Surveyor Accept Date	29-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	29-06-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD333Z

Vehicle to be Exported: Yes

Intended De-registration Date: 27 Jun 2018

Vehicle Make: MERCEDES BENZ

Vehicle Model: E220 BLUETEC

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 65192432926082

Chassis No.: WDD2120012B222215

Maximum Power Output: 130.0 kW (174 bhp)

Open Market Value: \$43,891.00

Original Registration Date: 16 Dec 2015

First Registration Date: 16 Dec 2015

Transfer Count: 0

Actual ARF Paid: \$45,948.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Dec 2023

PARF Rebate Amount: \$34,461.00

Intended COE Rebate Details

COE Expiry Date: 15 Dec 2023

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$45,466.00

COE Rebate Amount: \$31,060.00

Total Rebate Amount: \$65,521.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Jun 2018

OK

Shirley Hiew (LKK Auto)

From: Zhe Wei <zhewei.kek@transcab.com.sg>
Sent: Friday, 30 November 2018 4:07 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: 'Ng Wai Yin'; 'SUR'
Subject: RE: TCS REF: AAD1806-270--Accident involving SHD 333Z & SHB 2533K on 26.06.18

Hi Shirley,

COR confirmed @ \$1342.00 excluding GST.

Thank you.

Best Regards,
Kek Zhewei
Claims Officer



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, November 30, 2018 10:03 AM
To: zhewei.kek@transcab.com.sg
Cc: 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; SUR <sur@lkkauto.com>
Subject: TCS REF: AAD1806-270--Accident involving SHD 333Z & SHB 2533K on 26.06.18

Hi Zhe Wei,

Please confirm final fig of \$1,342.00 (part by part) @ 2 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 2 July 2018 5:20 PM
To: SITHARA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18005067MFSH/1
Attachments: SHD 333Z - Preli Advise.pdf

Dear Sithara,

Enclosed preliminary revised for SHD 333Z.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 29 June 2018 1:57 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18005067MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 29 June 2018 1:51 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005067MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

6/27/2018

Vehicle Insurance Particulars Enquiry

[> Back to OneMotoring](#)

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SHB2533K	26 Jun 2018 / 16:45:00	MS FIRST CAPITAL INSURANCE LIMITED

[Print](#)

[OK](#)

[Save as PDF](#)

Trans-cab Auto Services Pte Ltd

AAD1806-270

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 333Z*Not Authen*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 333Z

WDD2120012B222215

MERCEDES BENZ

E 220 BLUETEC

26.6.2018

FCIL**PART****LIST**

1	1	Rear Bumper	\$	<i>N</i> 3,105.00 X
2	1	Rear Bumper Lower	\$	<i>not list</i> 1,080.00 ✓
3	1	Rear Bumper Reinforcement	\$	<i>N</i> 910.00
4	1	Rear Bumper Centre Pad	\$	<i>N</i> 307.83
5	1	Rear Bumper Side Pad	\$	<i>N</i> 186.33
6	1	Rear Bumper Tow Hook Cover	\$	<i>SH</i> 42.00
7	1	Rear Bumper Bracket	\$	<i>N</i> 22.50
8	1	Rear Bumper Side Retainer Bracket	\$	<i>N</i> 132.00
9	1	Rear Bumper Inner Frame	\$	<i>SH</i> 297.00
10	1	Rear Bumper Bottom Bracket	\$	<i>N</i> 60.00
11	1	Rear Bumper Top Bracket	\$	<i>N</i> 129.00
12	1	Rear Bumper Side Holder Bracket	\$	<i>N</i> 135.00
13	1	Rear Bumper Inner Bracket LH	\$	<i>N</i> 198.00
14	1	Rear Bumper Inner Bracket RH	\$	<i>N</i> 198.00
15	1	Rear Bumper Beam	\$	<i>N</i> 1,215.00
16	1	Rear Bumper Beam Bracket LH	\$	<i>SH</i> 307.50
17	1	Rear Bumper Beam Bracket RH	\$	<i>SH</i> 307.50
18	1	Rear Bumper Bracket Centre	\$	<i>SH</i> 461.75
19	1	Rear Bumper Tow Hook Cover	\$	<i>SH</i> 63.00
20	1	Rear Bumper Retainer Bracket LH	\$	<i>SH</i> 202.50
21	1	Rear Bumper Retainer Bracket RH	\$	<i>SH</i> 202.50
22	1	Bootlid	\$	<i>N</i> 4,140.00
23	1	Bootlid 'E220' Badge	\$	<i>N</i> 153.00
24	1	Bootlid 'BLUETEC' Badge	\$	<i>N</i> 153.00
25	1	Bootlid Centre Logo Badge	\$	<i>SH</i> 153.00

Trans-cab Auto Services Pte Ltd

AAD1806-270

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 333Z

26	1	Bootlid Protector Garnish With Chrome	\$	Sn	732.00	}
27	1	Bootlid Weatherstrip	\$	Sn	360.00	
28	1	Bootlid Lock - Top	\$	N	300.00	
29	1	Bootlid Lock - Bottom	\$	N	216.00	
30	1	Bootlid Lock Actuator	\$	Sn	420.00	
31	1	Bootlid Weatherstrip	\$	Sn	240.00	
32	1	Bootlid Third Brake Lamp	\$	Sn	577.50	
33	1	Rear End Panel Outer	\$	N	1,971.00	
34	1	Rear End Panel Inner	\$	N	324.00	
35	1	Rear End Panel Inner Trim	\$	Sn	630.00	
36	1	Rear End Panel Inner Trim Flap	\$	Sn	360.00	
37	1	Rear Lamp RH	\$	Sn	1,170.00	
38	1	Rear Lamp Panel Outer RH	\$	N	382.95	
39	1	Rear Lamp LH	\$	Sn	1,170.00	
40	1	Rear Lamp Panel Outer LH	\$	N	382.95	
41	1	Rear Luggage Floor Panel Tray	\$	Sn	762.00	}
42	1	Rear Luggage Floor Compartment Tray	\$	Sn	116.00	
43	1	Rear Luggage Floor Panel Trim Board	\$	Sn	420.00	
44	1	Rear Fender RH	\$	N	3,620.00	

	\$	28,315.81
10%	\$	2,831.58
	\$	25,484.22

Specical Nett

1	1 SET	Rear Bumper Parking Sensor	\$	Sn	1,200.00	X
2	1 SET	Bootlid Inner Trim Clip	\$	N	90.00	X
3	1 SET	Rear End Panel Inner Trim Clip	\$	N	90.00	X
4	1 SET	Rear Bumper Fastener Clip	\$	N	101.54	X
5	1 SET	Rear Fender Top Garnish Clip	\$	N	90.00	X
6	1 SET	Rear Fender Inner Trim Clip	\$	N	45.00	X
7	1 SET	License plate	\$	Sn	225.00	X
8	1	Rear Windscreen Glass Sealant	\$	N	225.00	X

Trans-cab Auto Services Pte Ltd

AAD1806-270

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 333Z

9	1	Rear Windscreen Glass Inner Seal	\$	<i>nn</i> 180.00 X
10	1	Tyre Mechanical Jack	\$	<i>nn</i> 605.48 X
11	1	Tyre Mechanical Jack Holder Bracket	\$	<i>nn</i> 177.98 X
12	1	Rear Bootlid 'DYNASTY' Sticker	\$	<i>nn</i> 33.75 X

TOTAL \$ 3,063.74**GRAND TOTAL \$ 28,547.97****LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	5,250.00 <i>150l</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 120.00 X
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>220l</i>
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	<i>nn</i> 270.00 X
To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 X
To Transfer Of Tire, Rim And On Wheel Balancing.	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1806-270

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 333Z

To Transfer Of Fender Fittings, Attachment And Perform Water Seepage Test.	\$	~ 170.00 X
Towing Fee	\$	~ 250.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	~ 170.00 X
To Dismantle And Refit Rear Undercarriage Parts, Final Checking And Testing.	\$	~ 380.00 X
To Repair And Realign Rear Exhaust Pipe.	\$	~ 170.00 X
To Reinstall Rear Bumper Parking Sensor.	\$	~ 170.00 X
To Supply And Re-Do Rear Luggage Floor Panel Insulation Padding.	\$	~ 380.00 X
To Reseal Sealant On Gap	\$	~ 120.00 X

TOTAL	\$	12,460.00
(PART-BY-PART)		
Over all total	\$	41,007.97

2 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011889/Ksd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 03-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2533K	Veh. Inspected	SHD 333Z	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005067MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	29/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES E220 (A)	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD2120012B222215	Colour	WHITE	
Odometer	269184	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R16	GITI	9 mm	
L/H Front Tyre	225/55 R16	GITI	9 mm	
R/H Rear Tyre	225/55 R16	GITI	9 mm	
L/H Rear Tyre	225/55 R16	GITI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/06/2018	Inspection Date	29/06/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 333Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	3,105.00	-
1	REAR BUMPER LOWER	DENTED / CUT	1,080.00	1,080.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	910.00	-
1	REAR BUMPER CENTRE PAD	NO SUCH PARTS	307.83	-
1	REAR BUMPER SIDE PAD	NO SUCH PARTS	186.33	-
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	42.00	-
1	REAR BUMPER BRACKET	TO REPAIR SEE LABOUR	22.50	-
1	REAR BUMPER SIDE RETAINER BRACKET	TO REPAIR SEE LABOUR	132.00	-
1	REAR BUMPER INNER FRAME	SERVICEABLE	297.00	-
1	REAR BUMPER BOTTOM BRACKET	TO REPAIR SEE LABOUR	60.00	-
1	REAR BUMPER TOP BRACKET	TO REPAIR SEE LABOUR	129.00	-
1	REAR BUMPER SIDE HOLDER BRACKET	TO REPAIR SEE LABOUR	135.00	-
1	REAR BUMPER INNER BRACKET LH	TO REPAIR SEE LABOUR	198.00	-
1	REAR BUMPER INNER BRACKET RH	TO REPAIR SEE LABOUR	198.00	-
1	REAR BUMPER BEAM	TO REPAIR SEE LABOUR	1,215.00	-
1	REAR BUMPER BEAM BRACKET LH	SERVICEABLE	307.50	-
1	REAR BUMPER BEAM BRACKET RH	SERVICEABLE	307.50	-
1	REAR BUMPER BRACKET CENTRE	SERVICEABLE	461.75	-
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	63.00	-
1	REAR BUMPER RETAINER BRACKET LH	SERVICEABLE	202.50	-
1	REAR BUMPER RETAINER BRACKET RH	SERVICEABLE	202.50	-
1	BOOTLID	TO REPAIR SEE LABOUR	4,140.00	-
1	BOOTLID "E220" BADGE	NOT NECESSARY	153.00	-
1	BOOTLID "BLUETEC" BADGE	NOT NECESSARY	153.00	-

Report Ref No. CS/FCI18011889/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID CENTRE LOGO BADGE	SERVICEABLE	153.00	-
1	BOOTLID PROTECTOR GARNISH WITH CHROME	SERVICEABLE	732.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	360.00	-
1	BOOTLID LOCK-TOP	TO REPAIR SEE LABOUR	300.00	-
1	BOOTLID LOCK-BOTTOM	TO REPAIR SEE LABOUR	216.00	-
1	BOOTLID LOCK ACTUATOR	SERVICEABLE	420.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	240.00	-
1	BOOTLID THIRD BRAKE LAMP	SERVICEABLE	577.50	-
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	1,971.00	-
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	324.00	-
1	REAR END PANEL INNER TRIM	SERVICEABLE	630.00	-
1	REAR END PANEL INNER TRIM FLAP	SERVICEABLE	360.00	-
1	REAR LAMP RH	SERVICEABLE	1,170.00	-
1	REAR LAMP PANEL OUTER RH	TO REPAIR SEE LABOUR	382.95	-
1	REAR LAMP LH	SERVICEABLE	1,170.00	-
1	REAR LAMP PANEL OUTER LH	TO REPAIR SEE LABOUR	382.95	-
1	REAR LUGGAGE FLOOR PANEL TRAY	SERVICEABLE	762.00	-
1	COMPARTMENT TRAY	SERVICEABLE	116.00	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	420.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	3,620.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	120.00	-
	LESS 10% DISCOUNT		-2,831.58	-108.00
			25,604.23	972.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER PARKING SENSOR (SN)	SERVICEABLE	1,200.00	-
1	SET BOOTLID INNER TRIM CLIP (SN)	NOT NECESSARY	90.00	-
1	SET REAR END PANEL INNER TRIM CLIP (SN)	NOT NECESSARY	90.00	-
1	SET REAR BUMPER FASTENER CLIP (SN)	NOT NECESSARY	101.54	-

Report Ref No. CS/FCI18011889/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER TOP GARNISH CLIP (SN)	NOT NECESSARY	90.00	-
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET LICENSE PLATE (SN)	SERVICEABLE	225.00	-
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	225.00	-
1	REAR WINDSCREEN GLASS INNER SEAL (SN)	NOT NECESSARY	180.00	-
1	TYRE MECHANICAL JACK (SN)	SERVICEABLE	605.48	-
1	TYRE MECHANICAL JACK HOLDER BRACKET (SN)	TO REPAIR SEE LABOUR	177.98	-
1	REAR BOOTLID "DYNASTY" STICKER (SN)	NOT NECESSARY	33.75	-
			3,063.75	-
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME. }		5,250.00	150.00
	INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR BUMPER REINFORCEMENT,REAR BUMPER BRACKET,REAR BUMPER SIDE RETAINER BRACKET,REAR BUMPER BOTTOM BRACKET,REAR BUMPER TOP BRACKET,REAR BUMPER SIDE HOLDER BRACKET,REAR BUMPER INNER BRACKET LH,REAR BUMPER INNER BRACKET RH,REAR BUMPER BEAM,BOOTLID,BOOTLID LOCK-TOP,BOOTLID LOCK-BOTTOM,REAR END PANEL OUTER,REAR END PANEL INNER,REAR LAMP PANEL OUTER RH,REAR LAMP PANEL OUTER LH,REAR FENDER RH AND TYRE MECHANICAL JACK HOLDER BRACKET . }			-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	220.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	270.00	-
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TOWING FEE.	NOT NECESSARY	250.00	-

Report Ref No. CS/FCI18011889/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODY WORK REPAIR.	NOT NECESSARY	170.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO RESEAL SEALANT ON GAP.	NOT NECESSARY	120.00	-
			12,340.00	370.00
GRAND TOTAL			41,007.98	1,342.00

RECOMMENDED COST OF REPAIRS			1,342.00
-----------------------------	--	--	----------

Report Ref No. CS/FCI18011889/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.