

(05/11/11)

REF:

Surveyor:

ASSIGNMENT

COB April 2022

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 3772 KYr Regn: 2014, AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40C.C. 1685Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 564861

T/Radio: Insured / Std / NI / NA

Eng/No: D4FDEU409570C/No: KMHLB4HMEU052487Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 29/12/2017D.O.I. 29/06/2018Survey held at Chumi AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or.

o/s Front y o/s Body y o/s Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

AIG SFS 14P

25/09/18 Jmmw +/s 24000/- with 14 days 2ra

29-DOA 2017
30/5
31/514 days
3 WEEKENDS

Oct 1 -

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. _____ SI

Photos _____

Others _____

TOTAL

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 3772K

DATE : 28.06.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039 AIG

To Survey by (LKL)

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover <i>Dented</i>			\$ 562.30	✓
	Front Bumper Bracket (RH) <i>3/2</i>			\$ 24.60	X
	Headlamp Support Panel Assy <i>2 crack</i>			\$ 1,067.50	✓
	Headlamp (RH) <i>monrity broken</i>			\$ 1,388.00	✓
	Radiator Expansion Tank <i>new</i>			\$ 48.00	X
	Front Fender (RH) <i>new</i>			\$ 619.00	✓
	Front Fender Apron Panel (RH) <i>2 Dented</i>			\$ 1,575.50	✓
	Front Fender Shield (RH) <i>deformed</i>			\$ 169.80	✓
	Front Door (RH) <i>new</i>			\$ 1,403.00	✓
	Front Door Rubber <i>new</i>			\$ 290.50	✓
	Front Door Gear / Regulator (RH) <i>2 crack</i>			\$ 785.50	✓
	Front Door Hinge Upper (RH) <i>2 1/2</i>			\$ 53.40	✓
	Front Door Hinge Lower (RH) <i>2 1/2</i>			\$ 53.40	✓
	Front Door Check (RH) <i>2 1/2</i>			\$ 110.15	✓
	Front Door Inner Lock (RH) <i>2 Dam</i>			\$ 348.95	✓
	Front Door Key Lock Set (RH) <i>2 new</i>			\$ 186.50	X
	Front Door Outer Handle (RH) <i>broken</i>			\$ 98.75	✓
	Front Door Outer Moulding (LRH) <i>1/2</i>			\$ 63.70	✓
	Front Door Mirror (RH) <i>new</i>			\$ 980.50	X
	Front Door Power Motor <i>new</i>			\$ 950.90	X
	Door Centre Pillar Outer (RH) <i>Dented</i>			\$ 1,786.20	✓
	Front Wheel Rim (RH) <i>2 distorted</i>			\$ 351.90	✓
	Front Wheel Hub Cap (RH) <i>cut</i>			\$ 150.70	✓
	Front Wheel Bearing <i>2 Dam</i>			\$ 258.50	✓
	Front Shock Absorber (Assy) (RH) <i>2 distorted</i>			\$ 342.20	✓
	Front Shock Absorber Mounting (RH) <i>new</i>			\$ 75.10	X
	Front Drive Shaft (RH) <i>2 distorted</i>			\$ 1,069.55	X
	Rack & Pinion Assy <i>2 Dam</i>			\$ 2,184.00	X
	STG Tie End <i>2 distorted</i>			\$ 69.50	✓
	Front Suspension Lower Arm (RH) <i>2 distorted</i>			\$ 715.10	✓
	Knuckle Arm (RH) <i>2 distorted</i>			\$ 582.95	✓
	Engine Under Cover <i>new</i>			\$ 343.10	X
	Engine Crossmember <i>2 distorted</i>			\$ 2,236.90	X
	Dashboard Complete <i>2 crack/deformed</i>			\$ 2,688.00	X
	ABS Sensor <i>new</i>			\$ 261.50	X
SUB TOTAL				\$ 23,895.15	
LESS 20%				\$ 4,779.03	
DISCOUNTED TOTAL				\$ 19,116.12	
				21787.50	
				21024.95	
				16819.96	

SHA 3772K

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Door Comfort Logo (RH) <i>ent</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (RH) <i>ent</i>			\$ 100.00	Nett ✓
	Front Tyre (RH) <i>SVC</i>		175.00	\$ 216.00	Nett X
				\$ 391.00	
	Rear Bumper <i>new</i>			\$ 603.60	X
	Rear Bumper Clip 10 pcs <i>SVC</i>			\$ 22.00	X
	Rear Bumper Bracket, RH <i>NH</i>			\$ 49.00	X
	Rear Fender With Housing (RH) <i>Replaced</i>			\$ 4,736.80	✓
	Rear Fender Inner Lining (RH) <i>SVC</i>			\$ 164.40	X
	Rear Windscreen Moulding <i>new</i>			\$ 60.00	✓
	Rear Door (RH) <i>new</i>			\$ 1,351.10	✓
	Rear Door Rubber (RH) <i>new</i>			\$ 280.50	✓
	Rear Door Outer Moulding (LRH) <i>SVC</i>			\$ 212.15	X
	Rear Door Gear/Regulator (RH) <i>new crack</i>			\$ 785.50	X ✓
	Rear Door Power Motor (RH) <i>NH</i>			\$ 530.50	X
	Rocker Panel Outer Garnish (RH) <i>new crack</i>			\$ 483.60	X ✓
	Rear Tyre Rim (RH) <i>new distributed</i>			\$ 351.90	X ✓
	Rear Wheel Hup-Cap (RH) <i>new</i>			\$ 150.70	✓
	Rear Wheelbearing IN & Hub <i>new</i>			\$ 401.40	X ✓
	Rear Trailing Arm (RH) <i>new distributed</i>			\$ 120.00	X ✓
	Rear Assist (RH) <i>new distributed</i>			\$ 120.00	X ✓
	Rear Shock Absorber (RH) <i>new distributed</i>			\$ 342.20	X ✓
	Rear Shock Absorber Mounting (RH) <i>new</i>			\$ 57.70	X
	Stabilizer Bar <i>new</i>			\$ 204.60	X
	Stabilizer Link <i>new</i>			\$ 68.15	X
	Rear Upper Arm (RH) <i>new distributed</i>			\$ 335.75	X ✓
	Rear Lower Arm (RH) <i>new distributed</i>			\$ 204.35	X ✓
	Rear Knuckle Arm (RH) <i>new distributed</i>			\$ 574.80	X ✓
			10298.60		
			8238.88		
	SUB TOTAL			\$ 12,210.70	
	LESS 20%			\$ 2,442.14	
	DISCOUNTED TOTAL			\$ 9,768.56	
	Rear Bumper Advertisement Logo <i>new</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>new</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>new</i>			\$ 46.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>new</i>			\$ 80.00	Nett ✓
	Rear Tyre (RH) <i>SVC</i>		376.00	\$ 216.00	Nett X
				\$ 592.00	

SHA 3772K

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,700.00 1200/-
	Spray Painting Charge			\$ 1,400.00 1000/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 80.00 60/-
	Towing Charge			\$ 50.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 80.00 ✓
	Remove/Refix Rear Windscreen Glass			\$ 100.00 40/- 80/-
	Remove/Refix Reverse Sensor			\$ 80.00 40/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Transfer of Door		\$ 80.00	\$ 160.00 120/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	Four Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Dashboard			\$ 200.00 180/-
	Remove/Refix Front Windscreen Glass			\$ 100.00 80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 40/-
			3270/-	
	TOTAL LABOUR			\$ 4,610.00
	ESTIMATE TOTAL		35952.16	\$ 34,477.68
				28879.84
			Supp	1474.48
				30354.32
			L/S	24000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

29/06/2018 @ 1600hrs
Not Actual
L/S until 14 days.ryan
LKK Auto

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

REPAIR ESTIMATE*

γ_1 Bee Leo

TEL : 6542 5119

FAX : 6542 6039 AIG

✓