	Hwang Shrang Ti		Date/Time 29/6/18 63.13pm
To Inspect Ve	hicle No. FG 8353	VICS Inst	· ured: SGW 11494 Tel: 6481 5567 / 9388 6867
Policy No:	MHCSN 1746281700	Claim No: SN	IMISD03238CO2
Sum Insured:	, , , , , , , , , , , , , , , , , , , ,	Excess:	
Make of Veh (Client's Record CA / REV	REP. / REV 24 HRS lup)	1725	D.O.A 21 06 2018 107 2018 H.O.D. Endorsement
Date/Time:	3.52pm 39/6/18 Person Contac	ted pawire	Vehicle IN OUT
Date/Time	Action/Instruction (X) Estim		
		G13015754/A	100)3011C ANA (20)

ASSIGNMENT

From: Date:	Volt No. FG 8353	X Yr Regni / No retord.
Estimated Cost:	Type: M.Car / N.Cycle / Bus / Van / I	
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or	
To Inspect Vehicle No:	Make: Vespa	C.C
at Workshop m/s	Colour Blue	A/C: Insured / Std / NI / NA
of	Sp.Reading 51750	T/Radio: Instired / Std / NI / NA
Insured	Eng/No:	4)
Policy No.	C/No:	
Claims No.	Gen, Cond. Gool / Fair / Poor / Bur	nt
Sum Insured: Excess:	Steering: Ino Her / Jammed / Leake	
(Client's Record)	Brake: Ingreer / Jammed / Leake	ed/Burnt or
Make of Veh:	Modi : Mi / S/Rim / STD A/Rim	or
	Tyre Size: F:	3.50 -10
(Policy Condition)	R:	-11-
Remark: The veh had commenced its N/S	BS / DUN / EXNOVA / GY / FS / LIZ	ZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or	Wohlm
Bal, or Market Value:	Front	Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 2 mm	R/Bal. 2 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. mm	L/Bal, mm
Est. Repairs: 3 days Res.: Yes or No	D.O.A. 27/06/2018	D.O.I. 02/07/2018
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at Spec	edy MAN
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / C	9
Vehicle: I	NIOUT 0 5 Front	70/1 Bory
Date: Person Contacted:	The U/C / Chassis frame / E	Body Structure affected due to collision.
Date / Time Action / Instruction Chre Tapin PRS	86W 1149W)
HO TP GIA.		
Row same about	1K to 1.5k , ~ 2 3	4. xm-
, 8 -		
18/10/18 SUBMA PRS REPRO		
Date/Time, File Pass to7 : Preli. Report	Days Of Repair: 3	
i) : Final Report	Resurvey No. of Trip:	Survey Fee: 150
Oato/Time, File Return to?		Transportation:
2) A	dd Fee: Site Insp (\$)5 +R8,Sl
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$)	Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	The second secon	00/Dz4d3	
HINA	TAIPING INSURA	ANCE (S) PTE LTD	Ref : CS3/CTI1801190	J0/D2400	
ANS	ON ROAD #16-00	INGAPORE 079909	Date: 29-06-2018		
EKI	IGEEA TOWERS		Code: CTI		
		Policy Particulars :	- (THIRD PARTY CLAIF	M)	
•	Insured Veh.	SGW 1149U	Veh. Inspected	FG 8353X	
		DMHCSN1746281700	Coverage (\$)	0.00	
-		SNM18D03238C02	Excess (\$)	0.00	
		MERIMEN (HWANG SHIANG)	Assign Date	29/06/2018	
		Vehicle Parti	culars & Condition		
	Make & Model	\$ P. L. S. W. C. S. C. S	c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes	Modification			
	General				
3.		Condi	tions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre		ii -fD-mages		
4.		Descrip	tion of Damages	HPHE CAN THE PARTY OF THE PARTY	
		Como	ral Information		
5.	January Mar	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW	Inspection Date	02/07/2018	
	Accident Date	27/06/2018 SPEEDY MOTOR CYCLE SE			
	Survey held at	BLK 10 ANG MO KIO IND.PA	RK 2A #05-21 SINGAPOR	E 568047	
		BLK 10 ANG INO RIO IND.	Remarks		
5a.		ION WAS CONDUCTED ON A	WITHOUT PREJUDICE" B	ASIS.	
	I THE DEDAID D	ION WAS CONDUCTED ON A ESTIMATE WAS NOT PRESENT WAS TOLD TO PREPARE THE	ED MILITE TIME OF	PECTION.	

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status		
Main	29 Jun 2018		29 Jun 2018 15:13 Assign					New	Assignmer el Case	t
1	4ain	Re	ference		Claim Details		Docume	ents		show All
CLAIM SU	BFOLDER DE	TAILS	Annual to the same and the same		AND REAL PROPERTY.	[Creat	ed by insurer]	CHARLES WILLIAM	- North Control	
Insured: Main Claimant:	FONSEKA	LAWRENCE								
Vehicle Reg No.:	FG8353	x			Date of Loss:	27/06/2	018 00:00 - :59			
Claim Type:	: TP / SNM18D03238C02				Policy/Cover Note No.:	DMHCSN1746281700				
Vehicle Reg No. (Insured):	SGW1149	νυ			Policy No. (Claimant);					
					Excess:	S\$0.00				
Repairer:	Speedy M	lotor Cycle Service	e Centre (HQ)	10 ANG MO	KIO IND PARK 2	2A #05-2	1, 568047 Ang M	o Kio - Tel:		
Handling Insurer:	China Tai	ping Insurance (Singapore) Pte	Ltd. (HQ)	- Tel: 6389 611	1 [Har	dled by Hwang	Shiang Yi	- 63896541]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	due 10/	07/2018]			
Adj Asg. Remarks:		ASE W/O SJE.								
ASSOCIAT	ED MAIL RE	CEIVED						View All	Compose	Case Mai
There are no	mail for this	case.							Donnpose	2230 1101
ALL ASSO	CIATED TAS	ks⊟				View A	II Search Tasks	Create	New Task	Complete
Due Date	Priority	Type Task (Group Subj	ect Han	dler Assign		Completed (eated On	Done

Lucas Lee

From:

meilinyu@gmail.com on behalf of Tan Mei Ling <ml_tan@juseq.com.sg>

Sent:

Friday, 29 June, 2018 2:21 PM

To:

Lucas Lee

Subject:

Re: PRS FOR FG8353X (CTI REF: SNM18D03238C02)

Dear Sirs

We refer to your email of even date.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) UNITED Appraisal And Management Pte Ltd
- 2) SK Auto Consultants
- 3) Chartered Auto Assessors
- 4) LCW APPRAISER PTE LTD
- 5) Sincere Appraisal Services
- 6) Pal's Appraisal Pte Ltd
- Mc-Coy Appraiser Pte Ltd
- 8) CM Automotive Consultancy

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for prerepair inspection at the under-stated workshop:-

Speedy Motor Cycle Service Centre

Blk 10 Ang Mo Kio Industrial Park 2A

#05-21 Singapore 568047

Person In-Charge: Mr Lim Sam Hee at Tel: 6481 5567 / 9388 6867

Fax No. 6482 5567

*Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.

On Fri, Jun 29, 2018 at 2:03 PM, Lucas Lee < lucas.lee@sg.cntaiping.com > wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN

XING QUO QIANG	
KENNETH KONG	
SIMON HO	
CHUA WEIJIE	
MARCUS CHUA	
HENRY NG	

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Hwang Shiang Yi

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181 Fax (65) 6222 7175/6224 7478

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: meilinyu@gmail.com [mailto:meilinyu@gmail.com] On Behalf Of Tan Mei Ling

Sent: Thursday, 28 June, 2018 5:52 PM

To: Claims Dept of CTI

Subject: Notice of Accident - FG8353X

Dear Sirs

Please see attached Notice of Accident for your attention.

Warmest Regards Tan Mei Ling Legal Division

JusEquity Law Corporation Advocates & Solicitors

Commissioner For Oaths
171 Chin Swee Road #02-06 CES Centre Singapore 169877

Main: (65) 6506 9339 | DID: (65) 6506 0945

Fax : (65) 6536 5368 Email: ml tan@juseq.com.sg

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

Warmest Regards Tan Mei Ling Legal Division

JusEquity Law Corporation Advocates & Solicitors Commissioner For Oaths 171 Chin Swee Road #02-06 CES Centre Singapore 169877

Main: (65) 6506 9339 | DID: (65) 6506 0945

Fax : (65) 6536 5368 Email : ml tan@juseq.com.sq

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you,

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

Main 29	9 Jun 2018		20 10 2010						
			29 Jun 2018 15:13 Edit Adj Rpt	S\$0.00 Edit Estimate	S\$0.0 View	Section 1988		Report Cancel Ca	for Survey
Ma	ain	Re	ference	CI	aim Details		Docume	nts	Show All
CLAIM SUBI	FOLDER DE	TAILS		100000000000000000000000000000000000000	NO LOCAL DESCRIPTION OF THE PARTY OF THE PAR	[Creat	ed by insurer]		
Insured:	-, Co. Re	g. No.: -				- Transfering			
Main Claimant:	FONSEKA	LAWRENCE							
Vehicle Reg. No.:	FG8353	x			Date of Loss	And the second second	2018 00:00 - :59 lonths and 26 Days	s From LTA Re	g Date (Man Yr)]
Claim Type:	Policy/Cours								
Vehicle Reg. No. (Insured):	SGW1149	U			Policy No. (Claimant):				
		NOT			Excess:	S\$0.00			
Repairer:	Speedy M	otor Cycle Service	e Centre (HQ)	10 ANG MO K	IO IND PARK	2A #05-2	1, 568047 Ang Mo	Kio - Tel:	
Handling Insurer:	China Tai	ping Insurance (Singapore) Pte	a. Ltd. (HQ) -	Tel: 6389 61	11 [Ha	ndled by Hwang S	hiang Yi - 63	8896541]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Handled by	BRYAN T	ANI] [Final F	Rpt due 10/	07/2018]
Adj Asg. Remarks:	NO EST, C	ASE W/O SJE.			X				1-200-1-2-200
ASSOCIATE	D MAIL RE	CEIVED						View All C	Compose Case Mai
There are no	mail for this	case.							
ALL ASSOC	IATED TAS	KS⊟				View	All Search Tasks	Create New	Task Complete
Due Date	Priority	Type Task	Group Subj	ect Handl	er Assic	ned By	Completed O	-	ed On Done
No results.		A Water Company		1110000					

Claim Documents

*FG8353X (SNM18D03238C02)

[SGW1149U]

TP

FONSEKA LAWRENCE
Jun 27 2018 12:00AM

[-]

Speedy Motor Cycle Service Centre

Ph	otos/Images		3 per p	page v	•
Νo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	111,000
1	17/08/18 13:59	General View	0	Load JPG	•
2	17/08/18 13:59	General View	0	Load JPG	•
3	17/08/18 13:59	General View	0	Load JPG	•
4	17/08/18 13:59	General View	0	Load JPG	•
5	17/08/18 13:59	General View	0	Load JPG	•
6	17/08/18 13:59	General View	0	Load JPG	•
7	17/08/18 13:59	General View	0	Load JPG	•
8	17/08/18 13:59	General View	0	Load JPG	•
9	17/08/18 13:59	General View	0	Load JPG	•
10	17/08/18 13:59	General View	0	Load JPG	•
11	17/08/18 13:59	General View	0	Load JPG	•
12	17/08/18 13:59	General View	0	Load JPG	•
13	17/08/18 13:59	General View	0	Load JPG	•
14	17/08/18 13:59	General View	0	Load JPG	•
15	17/08/18 13:59	General View	0	Load JPG	•
16	17/08/18 13:59	General View	0	Load JPG	1
17	17/08/18 13:59	General View	0	Load JPG	•
18	17/08/18 13:59	General View	0	Load JPG	•
19	17/08/18 13:59	General View	0	Load JPG	•
20	17/08/18 13:59	General View	0	Load JPG	4
21	17/08/18 13:59	General View	0	Load JPG	•
22	17/08/18 13:59	General View	0	Load JPG	•
23	17/08/18 13:59	General View	0	Load JPG	•
24	17/08/18 13:59	General View	0	Load JPG	•
25	17/08/18 13:59	General View	0	Load JPG	•
26	17/08/18 13:59	General View	0	Load JPG	•
27	17/08/18 13:59	General View	0	Load JPG	•
28	17/08/18 13:59	General View	0	Load JPG	
29	17/08/18 13:59	General View	0	Load JPG	•
30	17/08/18 13:59	General View	0	Load JPG	•
31	17/08/18 13:59	General View	0	Load JPG	•
32	17/08/18 13:59	General View	0	Load JPG	•
33	17/08/18 13:59	General View	0	Load JPG	•
34	17/08/18 13:59	General View	0	Load JPG	•
35	17/08/18 13:59	General View	0	Load JPG	•

Pho	tos/Images		3 per	page ▼	~
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
36	17/08/18 13:59	General View	0	Load JPG	•
37	17/08/18 13:59	General View	0	Load JPG	•
38	17/08/18 13:59	General View	0	Load JPG	•
39	17/08/18 13:59	General View	0	Load JPG	•
40	17/08/18 13:59	General View	0	Load JPG	•
41	17/08/18 13:59	General View	0	Load JPG	•
42	17/08/18 13:59	General View	0	Load JPG	•
43	17/08/18 13:59	General View	0	Load JPG	•
44	17/08/18 13:59	General View	0	Load JPG	•
45	17/08/18 13:59	General View	0	Load JPG	•
46	17/08/18 13:59	Odometer Reading	0	Load JPG	•
Dod	cumentation		1 per	page ▼	•
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	29/06/18 15:12	PRS	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	принципальной дирентиров выпользоний
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/CTI18011900/DZ4D3S2

Date:

05/10/2018

REFERENCE

Handling Insurer:

Ltd.

China Taiping Insurance (Singapore) Pte. Policy No:

DMHCSN1746281700

Claimant Vehicle

No:

FG8353X

Insured Vehicle No SGW1149U

Date of Loss:

27/06/2018

Nature of Claim:

TP

Claim No:

SNM18D03238C02

51750 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour:

FG8353X

Make & Model:

VESPA PX150, 150cc 01/01/1990 (Man. Year: 1990)

Engine No: HIDDEN

Reg. Date:

Blue

Engine Capacity: Market Value/New Car Price: 0 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Inspected At:

Footbrake (Serviceable):

Chassis No:

Odometer:

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

3.50-10

Rear Tyre Size:

3.50-10

Front Left Side:

Michelin 2 mm

Rear Left Side:

Michelin 2 mm

Front Right Side:

0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date Inspected:

Date of Assignment:

29/06/2018

02/07/2018

Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21

Singapore 568047

Estimated Period of Repair:

3.0 days

Adjuster:

BRYAN TANI

Manager:

Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00 - \$1,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 05 Oct 2018)

VESPA PX150 150cc (Model not available in database) Parts: N/A

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for FG8353X)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >