

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18011935/KQBN2
Date: 11/07/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MW005670		
Claimant Vehicle No :	SHC5432T	Insured Vehicle No :	YN8126Z		
Date of Loss:	26/06/2018	Nature of Claim:	TP	Claim No:	M1803214

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5432T	Engine No:	M9R8839C002132
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC279858
Reg. Date:	19/11/2014 (Man. Year: 2014)	Odometer:	311607 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,158.90	3,239.98	17,918.92	84.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,710.00	830.00	7,880.00	90.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,868.90	4,069.98	25,798.92	86.37
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	29,868.90	3,250.00	26,618.90	89.12
+ GST 7.00/7.00% (S\$)	2,090.82	227.50	1,863.32	89.12
Nett Amount (S\$)	31,959.72	3,477.50	28,482.22	89.12

INSPECTION

Date of Assignment:	02/07/2018		
Date Inspected:	28/06/2018	Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jul 2019)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SHC5432T/11/07/2019 17:03	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Dented/Cut	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*- FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*- FL
7	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
10	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
11	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
12	1		*HEADLAMP LH	Serviceable	1,184.43 FL	*- FL
13	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
14	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
15	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
16	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
17	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
18	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
19	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
20	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
21	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
22	1		*RADIATOR FAN COWLING	Serviceable	820.54 FL	*- FL
23	1		*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*- FL
24	1		*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*- FL
25	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
26	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
27	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
28	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
29	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
30	1		*LOWER ARM LH L70Y	Serviceable	685.76 FL	*- FL
31	1		*KNUCKLE ARM LH L70Y	Serviceable	846.98 FL	*- FL
32	1		*ABSORBER FRT LH L70Y	Serviceable	360.54 FL	*- FL
33	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
34	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
35	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
36	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
37	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
38	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
39	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
40	1		*SET WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
41	1		*FRONT DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
42	1		*FRONT DOOR STICKER CHASSIS	Not Necessary	50.00 FS	*- FS
43	1		*FRONT LEFT TYRE	Serviceable	300.00 FS	*- FS
44	1		*FRONT LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
45	1		*DOOR MIRROR ASSY LH	Cracked	1,483.40 FL	*1,483.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) **23,385.67** **3,592.65**

- List Item Discount on L Items 10.00/10.00% (S\$)	2,226.77	352.67
Total Parts (S\$)	21,158.90	3,239.98

LKK Auto Consultants Pte Ltd/SHC5432T/11/07/2019 17:03. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,500.00	300.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	480.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	-
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
6	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
9	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	-
10	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	-
11	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	-
Gross Labour Cost (S\$)			8,710.00	830.00

LKK Auto Consultants Pte Ltd/SHC5432T/11/07/2019 17:03. Not valid without Reference section.

< END OF ESTIMATES >