

22/06/2018

ASS. REC. BY:

REF: CS/CTI18011939/T1rd3

Special Instruction:

Surveyor's  
Name

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

02/07/18 @ 10:57am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

YP 37142

Insured:

YM 6661M

at Workshop m/s

Sin Sheng Engineering

Tel:

68639595

of

3 tech park Crescent

Policy No:

DMCVSN3041151800

Claim No:

SNM18D03201C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/06/2018

CA / REV / REP. / REV 24 HRS

1 up

H.O.D. Endorsement:

Date/Time:

11:19am @ 2/7/18

Person Contacted:

susan

Vehicle IN / ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

YP 37142 - x

YM 6661 M - NA / HNC12001671 / 52

D.O.A: 27/01/2012

Confirm

L/s \$11,000.00 @ 8 days

Red: \$16,652.50, 60 %

Surveyor

Tan Jia

REF:

CTI

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YP3714Z

Yr Regn:

246 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Fuso FK62.

c.c 7545

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

66431

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FK62 FMA 30154

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

245/70R19

R:

2 - (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

2

mm

Rear

R/Bal.

2/8

mm

L/Bal.

2

mm

L/Bal.

2/8

mm

D.O.A.

D.O.I.

4/7/18 P1545

Survey held at

Sin Sheng

Des. of Damages: Frt / Rear / O/S / N/S / LUC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

1)

typist



Preli. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + PS \$

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum / I.B. (\$

11,000.00

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jun 2018		02 Jul 2018 10:57 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	WEI SHENG ENGINEERING PTE LTD, Co. Reg. No.: 201027414H		
Main Claimant:	GOLDBELL LEASING PTE LTD		
Vehicle Reg. No.:	YP3714Z	Date of Loss:	27/06/2018 06:00 - :59
Claim Type:	TP / SNM18D03201C02	Policy/Cover Note No.:	DMCVSN3041151800 (Third Party Only)
Vehicle Reg. No. (Insured):	YM6661M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/07/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN CHUA WEIJIE AS SJE.		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your Insured's vehicle : YM6661M

Our customer's vehicle : **YP3714Z**

Date : 29/06/2018

## CHIAN TAIPING INSURANCE (SINGAPORE) PTE LTD

Dear Sirs,

**DATE OF ACCIDENT : 27 JUN 2018**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION/SURVEY & SEEK ATTENTION**

We have been appointed by Goldbell Leasing Pte Ltd repair their vehicle no. YP3714Z

Please be informed that the said vehicle can be inspected at :

Workshop : Sin Sheng Engineering Services

Address : 3 Tech Park Crescent, Tuas Tech Park, Singapore 638129

Contact : Ms Susan / Ms Cheryl Yuan

Tel / Fax : 6863 9595 / 6863 6477

Pursuant to ePractice Direction No 2 of 2011, we hereby give you notice to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday failing which we will commence repairs thereafter without any further notice or reference to you. Kindly acknowledge upon inspection in the acknowledgement box below, Alternatively kindly inform us in writing if you are waiving your rights to an inspection of our customer's vehicle.

*NB. Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damage only and shall not preclude client's driver/passanger from claiming injury-related damage arising from this accident.*

Your sincerely,

*Susan*

### Acknowledgement

This is to confirm that I ..... \[Full Name of Surveyor]  
of ..... \[Surveyor's Company]  
have completed the pre-repair inspection on ..... \[Date if Inspection]  
at ..... \[Time of Inspection]

*Susan*

.....  
Signature of Appointed Surveyor

.....  
Witnessed By:

Company Stamp

Date

### Waiver

We waive our rights to an inspection/survey of the above vehicle.

.....  
Signature

Name :

Date :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 28/06/2018 14:53  
 Date Of Accident 27/06/2018 06:45  
 Exact Location Of Accident ALONG SLE  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number YP3714Z  
**Insured/Policyholder**  
 Name Of Registered Owner GOLDBELL LEASING PTE LTD  
 Co Reg No 199001196N  
 Email Address NOEMAIL  
 Mobile Phone No  
 Alternative Phone No OFFICE-64942833  
**Vehicle Particulars**  
 Manufacturer MITSUBISHI  
 Model FUSO FIGHTER-7.5 D FK62 SERIES (FK62FMZ1RDEB) (M)  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category COMMERCIAL VEHICLE  
**Insurance Company**  
 Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.  
 Type Of Coverage THIRD PARTY  
 Fleet Policy YES  
 Policy Number 29004183  
 Cover Note Number  
**Driver**  
 Name of Driver SUTHREE BIN NAI WAY  
 NRIC No S1169966I  
 Date Of Birth 14/03/1956  
 Occupation OUTDOOR  
 Date Of Driving Pass 01/09/2009  
 Driving Experience 8 YEARS AND 9 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-91285980  
 Fax Number  
 Contact Number  
 EMail Address NOEMAIL

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

FRONT PORTION

## Sketch Plan #2

SKETCH PLAN



1. Accident Date & Time  
2. Location of Accident

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT NO. T/20180627/2191

### DECLARATION

(We declare the foregoing particulars are true in every respect.)



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/ID No.:

## Police Report


**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999



T/20180627/2191

2 of 3

Report No. T/20180627/2191

## CONTINUATION OF REPORT

Driver Name	RENGASAMY DEKSHINIAMOORTHY	ID No.	G2482659M
Related Vehicle	YM8661M (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver Name	SUTHREE BIN NAI WAY	ID No.	S11699661
Related Vehicle	YP3714Z (Lorry)	Contact No.	91285980
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 27/06/2018 at about 0645hrs, I was driving along SLE to my workplace by myself on the third lane. There was an accident in front between a motorcycle and a car. The traffic in front of me just stop. My lorry was stationary. Suddenly, I heard a loud bang from my rear. I came out and saw a lorry behind me. I approached the driver and exchange particulars. I did not hear any braking sound. I checked with everybody and no was injured. My lorry suffered dents at the rear and his lorry suffered cracked screen and front panel dented.



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 1196N

**Vehicle Details**

Vehicle No.: YP3714Z

Vehicle to be Exported: No

Intended De-registration Date: 31 Dec 2018

Vehicle Make: MITSUBISHI

Vehicle Model: FUSO FK62FMZ1RDEB

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 6M60216524

Chassis No.: FK62FMA30154

Maximum Power Output: -

Open Market Value: \$57,191.00

Original Registration Date: 23 Aug 2016

First Registration Date: 23 Aug 2016

Transfer Count: 0

Actual ARF Paid: \$2,860.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 22 Aug 2026

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 10

QP Paid: \$48,302.00

COE Rebate Amount: \$36,914.00

**Total Rebate Amount: \$36,914.00**

The information contained herein is correct as at 29 Jun 2018

OK



ISUZU

WEI SHENG ENGINEERING PTE LTD

威盛工程私人有限公司

RE: PRS FOR YP3714Z (CTI REF: SNM18D03201C02) \*\*\* LKK REF:  
CS/CTI18011939/T1rd3

MK

Mei Kwan (LKKAuto)

Today, 1:38 PM

sinsheng engineering services <sinsheng1981@gmail.com>; +4 more

Reply all |

Inbox



Show all 6 attachments (2 MB) Download all

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/CTI18011939/T1rd3	Janice

Our respective case handler will look into the matter and revert to you in due course.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

Mei Kwan | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** sinsheng engineering services [mailto:sinsheng1981@gmail.com]

**Sent:** Thursday, 19 July, 2018 1:15 PM

**To:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

**Subject:** Re: PRS FOR YP3714Z (CTI REF: SNM18D03201C02)

Hi Mr Taufikh,

Please find attached and have your finalized please.

Thank You

Regards

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002528

Date : 11/07/2018

Vehicle Num. : YP3714Z

Make/Model : MITSUBISHI FK 62-2016

Chassis/Eng# : FK62FMA30154/6M60216524

Accident Date : 27/06/2018

Claim No. : SNM18D03201C02

Reference : YM6661M

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1	REAR BUMPER		650.00 <i>bt</i>
2.	1	TAILGATE BRACKET <i>bt</i>		3,500.00 <i>SN 500k</i>
3.	2	BUMPER BRACKET	180.00	360.00 <i>bt</i>
4.	2	HYDRAULIC CYLINDER, SMALL	2,200.00	4,400.00 <i>bt</i>
5.	2	HYDRAULIC CYLINDER, BIG	2,600.00	5,200.00 <i>x nn</i>
6.	1	BUMPER, RHS		450.00 <i>bt</i>
7.	1	NUMBER PLATE		20.00 <i>bt</i>
8.	1	NUMBER PLATE LAMP		75.00 <i>x nn</i>
9.	1	WOODEN STEP		250.00 <i>x nn</i>
10.	1	TAILGATE		6,500.00 <i>SN 300</i>
11.	1	60km/h Sticker		20.00 <i>nn</i>
12.	1	22 PAX STICKER		20.00 <i>nn</i>
13.	3	RED/WHITE STICKER	80.00	240.00 <i>nn</i>
14.	1	DHOLLANDIA LOGO		150.00 <i>nn</i>
15.	1	HYDRAULIC OIL		120.00 <i>nn</i>
16.	2	REAR LAMP	180.00	360.00 <i>x nn</i>
17.	1	BLACK/YELLOW STICKER		80.00 <i>nn</i>
18.	2	REAR DOOR ASSY <i>LH-bt</i> ✓, <i>RH-RY</i>	1,800.00 ✓	3,600.00
19.	2	CONTAINER LOCK <i>LH-bt</i> ✓, <i>RH-X nn</i>	550.00 ✓	1,100.00
20.	4	DOOR HINGE <i>LH-bt</i> ✓, <i>RH-X nn</i>	120.00 ✓	480.00
21.	2	T LOCK	75.00 <i>nn</i>	150.00
Nett Total S\$ :			89.00	27,725.00
10.00% Discount S\$ :			10% - 801.0	2,772.50
			SN - 3500	24,952.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002528

Date : 11/07/2018

Vehicle Num. : YP3714Z

Make/Model : MITSUBISHI FK 62-2016

Chassis/Eng# : FK62FMA30154/6M60216524

Accident Date : 27/06/2018

Claim No. : SNM18D03201C02

Reference : YM6661M

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO PANEL BEAT/REPAIR REAR BODY

TO REPAIR REAR ALUMINUM BOX

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

TO REPAIR TAIL GATE

TO CHECK TAILGATE POWER PACK FUNCTION

SPRAY PAINTING

LOSS OF USE : 10 DAYS @ \$ 200/DAY

Labour Total S\$ :

850.  
950.00

600  
850.00

750  
900.00

2200

2,700.00

Tan Jia 92495749  
WP'

4/7/18 @ 1545

Lumpsum  
Resum after repair  
sur @ 11/11/18

13710  
+ \$ 10,950

8 days.

Total S\$ : 27,652.50

=====

SIN SHENG ENGINEERING SERVICES

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jun 2018		02 Jul 2018 10:57 <a href="#">Edit Adj Rpt</a>	<b>S\$11,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$11,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>WEI SHENG ENGINEERING PTE LTD</b> , Co. Reg. No.: 201027414H								
Main Claimant:	<b>GOLDBELL LEASING PTE LTD</b>								
Vehicle Reg. No.:	<b>YP3714Z</b>	Date of Loss:	27/06/2018 06:00 - :59 <b>[22 Months and 4 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / SNM18D03201C02</b>	Policy/Cover Note No.:	DMCVSN3041151800 (Third Party Only)						
Vehicle Reg. No. (Insured):	<b>YM6661M</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Sin Sheng Engineering Services (HQ)</b> 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... <b>[Final Rpt due 11/07/2018]</b>								
Adj Asg. Remarks:	NO EST, ASSIGN CHUA WEIJIE AS SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents



















































\*YP3714Z (SNM18D03201C02)  
[YM6661M]  
TP  
GOLDBELL LEASING PTE LTD  
Jun 27 2018 6:00AM  
[WEI SHENG ENGINEERING PTE LTD]  
Sin Sheng Engineering Services

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)













View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print	
1	27/06/18 16:36	Accident Statement	 Load HTM		
2	28/06/18 10:17	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>	
3	28/06/18 10:27	Accident Statement Addm. #1	 Load HTM		
4	29/06/18 10:50	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>	
5	29/06/18 10:51	Accident Statement Addm. #2	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print	
1	27/06/18 16:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
2	27/06/18 16:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
3	27/06/18 16:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
4	27/06/18 16:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
5	27/06/18 16:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
6	27/06/18 16:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
7	27/06/18 16:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
8	27/06/18 16:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
9	27/06/18 16:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>	
























Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
18	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
54	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
55	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
56	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
57	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
58	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
59	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
60	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
61	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
62	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
63	23/07/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
64	23/07/18 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	23/07/18 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	23/07/18 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	23/07/18 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
68	23/07/18 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	23/07/18 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	23/07/18 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/07/18 10:56	PRS	 Load PDF	
2	02/07/18 10:56	OI GIA	 Load PDF	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/06/18 16:05	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	27/06/18 16:05	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	28/06/18 10:18	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	28/06/18 10:18	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	28/06/18 10:18	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	28/06/18 10:18	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	28/06/18 10:18	Driving Licence [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/06/18 16:36	Accident Statement	 Load HTM	
2	28/06/18 10:17	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
3	28/06/18 10:27	Accident Statement Addm. #1	 Load HTM	
4	29/06/18 10:50	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
5	29/06/18 10:51	Accident Statement Addm. #2	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/06/18 16:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	27/06/18 16:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	27/06/18 16:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	27/06/18 16:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	27/06/18 16:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	27/06/18 16:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	27/06/18 16:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	27/06/18 16:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	27/06/18 16:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/06/18 16:05	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	27/06/18 16:05	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	28/06/18 10:18	Police Report	 Load JPG	<input checked="" type="checkbox"/>
4	28/06/18 10:18	Police Report	 Load JPG	<input checked="" type="checkbox"/>
5	28/06/18 10:18	Police Report	 Load JPG	<input checked="" type="checkbox"/>
6	28/06/18 10:18	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
7	28/06/18 10:18	Driving Licence	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

**DOCUMENTS CHECKLIST**[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18011939/RD3Q2

Date: 26/07/2018

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN3041151800

Claimant Vehicle  
No: YP3714ZInsured Vehicle  
No: YM6661M

Date of Loss: 27/06/2018

Nature of Claim: TP

Claim  
No: SNM18D03201C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP3714Z

Make & Model: MITSUBISHI FUSO FIGHTER, 7.5 D FK62 Series  
(FK62FMZ1RDEB) (M)

Engine No: 6M60216524

Reg. Date: 23/08/2016 (Man. Year: 2016)

Chassis No: FK62FMA30154

Colour: White

Odometer: 66431 km

Engine Capacity: 7545 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/70 R19

Rear Tyre Size: 245/70 R19 (D)

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,952.50	11,582.00	13,370.50	53.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	2,200.00	500.00	18.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,652.50</b>	<b>13,782.00</b>	<b>13,870.50</b>	<b>50.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>11,000.00</b>		
<b>(S\$)</b>	27,652.50	11,000.00	16,652.50	60.22
<b>+ GST 7.00/7.00% (S\$)</b>	1,935.68	770.00	1,165.68	60.22
<b>Nett Amount (S\$)</b>	<b>29,588.18</b>	<b>11,770.00</b>	<b>17,818.18</b>	<b>60.22</b>

### INSPECTION

Date of Assignment: 02/07/2018

Date Inspected: 11/07/2018 Inspected At:

Sin Sheng Engineering Services (HQ)  
3 Tech Park Crescent, Tuas Tech Park  
Singapore 638129

Estimated Period of Repair: 8.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 25 Jul 2018)	
<b>Parts:</b>	N/A	mitsubishi fuso fighter 7.5 D FK62 Series (FK62FMZ1RDEB) (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP3714Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	650.00 FN	*650.00 FN
2	1		*TAILGATE BRACKET (LOCAK REPAIR)	Bent	3,150.00 FS	*500.00 FS
3	2		*BUMPER BRACKET	Bent	360.00 FN	*360.00 FN
4	2		*HYDRAULIC CYLINDER SMALL	Bent	4,400.00 FN	*4,400.00 FN
5	2		*HYDRAULIC CYLINDER ,BIG	Not Necessary	5,200.00 FN	*- FN
6	1		*BUMPER ,RHS	Bent	450.00 FN	*450.00 FN
7	1		*NUMBER PLATE	Bent	20.00 FN	*20.00 FN
8	1		*NUMBER PLATE LAMP	Not Necessary	75.00 FN	*- FN
9	1		*WOODEN STEP	Not Necessary	250.00 FN	*- FN
10	1		*TAILGATE (LOCAL REPAIR)	Dented	5,850.00 FS	*3,000.00 FS
11	1		*60KM/H STICKER	Necessary	20.00 FN	*20.00 FN
12	1		*22 PAX STICKER	Necessary	20.00 FN	*20.00 FN
13	3		*RED /WHITE STICKER	Necessary	240.00 FN	*240.00 FN
14	1		*DHOLLANDIA LOGO	Necessary	150.00 FN	*150.00 FN
15	1		*HYDRAULIC OIL	Necessary	120.00 FN	*120.00 FN
16	2		*REAR LAMP	Not Necessary	360.00 FN	*- FN
17	1		*BLACK/YELLOW STICKER	Necessary	80.00 FN	*80.00 FN
18	1		*REAR DOOR ASSY	N/S Bent / O/S Repair	3,600.00 FN	*1,800.00 FN
19	1		*CONTAINER LOCK	N/S Bent / O/S Not Necessary	1,100.00 FN	*550.00 FN
20	1		*DOOR HINGE	N/S Bent / O/S Not Necessary	480.00 FN	*120.00 FN
21	2		*T LOCK	Not Necessary	150.00 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$) **26,725.00**    **12,480.00**  
 - Nett Item Discount on N Items 10.00/10.00% (S\$)    1,772.50    898.00

Total Parts (S\$) **24,952.50**    **11,582.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT /REPAIR REAR BODY TO REPAIR REAR ALUMINIUM BOX TO DISMANTLE /REPLACE ABOVEMENTIONED PARTS	New	950.00	850.00
2	TO REPAIR TAIL GATE TO CHECK TAILGATE POWER PACK FUNCTION	New	850.00	600.00
3	SPRAY PAINTING	New	900.00	750.00
Gross Labour Cost (S\$)			<b>2,700.00</b>	<b>2,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >