

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INSF	PECTION REPORT		
AUT	O & GENERAL IN	SURANCE (S) PL	Ref: CS3/AGI18011944/N	z4d3e2	
		URANCE)190 CLEMENCEAU SINGAPORE 239924	Date: 30-08-2018		
			Code: AGI		
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKW 5778E	Veh. Inspected	SKN 2199T	
	Policy No.	C10001728/AH	Coverage (\$)	0.00	
	Claim No.	MKR/404/8009/2018	Excess (\$)	0.00	
	Assign From	JULIE MANGUBAT	Assign Date	29/06/2018	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA CIVIC TYPE-R	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	FD21401915	Colour	WHITE	
	Odometer	221409 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
I				6 mm	
	L/H Front Tyre	225/45 R17	BRIDGESTONE		
	L/H Front Tyre R/H Rear Tyre	225/45 R17 225/45 R17	BRIDGESTONE BRIDGESTONE	6 mm	
	 				
4.	R/H Rear Tyre	225/45 R17 225/45 R17	BRIDGESTONE	6 mm	
4.	R/H Rear Tyre L/H Rear Tyre	225/45 R17 225/45 R17	BRIDGESTONE BRIDGESTONE on of Damages	6 mm	
4.	R/H Rear Tyre L/H Rear Tyre	225/45 R17 225/45 R17 Description STAINED DAMAGES AT THE REA	BRIDGESTONE BRIDGESTONE on of Damages	6 mm	
	R/H Rear Tyre L/H Rear Tyre	225/45 R17 225/45 R17 Description STAINED DAMAGES AT THE REA	BRIDGESTONE BRIDGESTONE on of Damages AR PORTION.	6 mm	
	R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	225/45 R17 225/45 R17 Description STAINED DAMAGES AT THE REA	BRIDGESTONE BRIDGESTONE on of Damages AR PORTION. I Information Inspect Date / Time	6 mm 6 mm	
	R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS Accident Date	225/45 R17 225/45 R17 Description STAINED DAMAGES AT THE REA Genera 26/06/2018	BRIDGESTONE BRIDGESTONE on of Damages AR PORTION. I Information Inspect Date / Time	6 mm 6 mm	
	R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS Accident Date Survey held at	225/45 R17 225/45 R17 Description STAINED DAMAGES AT THE REA Genera 26/06/2018 TEAM AUTO PRO-NO.8 KAKI BU	BRIDGESTONE BRIDGESTONE on of Damages AR PORTION. I Information Inspect Date / Time	6 mm 6 mm	
5.	R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS Accident Date Survey held at Repairer A) THE INSPECTION B) THE REPAIR ESTHE REPAIRER W C) ENCLOSED PLI	225/45 R17 225/45 R17 Description STAINED DAMAGES AT THE REA Genera 26/06/2018 TEAM AUTO PRO-NO.8 KAKI BU	BRIDGESTONE BRIDGESTONE on of Damages AR PORTION. I Information Inspect Date / Time JKIT AVE 4 #01-07 PREMIER HOUT PREJUDICE" BASIS. AT THE TIME OF INSPECTION IMATE. PHOTOGRAPHS.	6 mm 6 mm 02/07/2018 (02:49 PM)	

Report Ref No. CS3/AGI18011944/Nz4d3e2

Inspected By

Automotive Assessor

MUHAMMAD NAZRIL BIN ABDULLAH

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

7 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.