

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #08-16
Singapore (079120)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6419 3000 Fax : 6835 7416
DEAR SIR / MADAM :

*Not withains
1. B.1
Resumy B4 p.111*

ACCIDENT REPAIR ON: SDM828M
MODEL : MERCEDES BENZ ML350A
POLICY NO : GA333683/1
CHASSIS NO : WDC1660572A118477
YEAR OF MANUFACTURE : 2013
DATE / TIME OF ACCIDENT: 26/06/2018 Time: 1830Hrs at Along Scotts Rd Towards Orchard Rd.
THIRD PARTY VEHICLE NO: SMA1237T

Date: 05/07/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price S\$	Condition	Amount S\$
S/N					
1	Front bumper <i>Ben</i>	1			
2	Front bumper side retainer LH <i>D.1 ✓</i>	1			
3	Front bumper side retainer RH <i>Sn X</i>	1			
4	Front bumper rivet <i>ne -</i>	1			
5	Front bumper lower garnish <i>cm -</i>	1			
6	Front bumper lower centre grille <i>Sn X</i>	1			
7	Front bumper lower cover <i>?</i>	1			
8	Front bumper nozzle LH <i>Sn X</i>	1			
9	Front bumper nozzle cover LH <i>Sn X</i>	1			
10	Front bumper sensor <i>?</i>	1			
11	Front bumper sensor ring <i>?</i>	1			
12	Front bumper sensor retainer <i>?</i>	1			
13	Front bumper fog lamp LH <i>Sn X</i>	1			
14	Front bumper fog lamp grille LH <i>Sn X</i>	1			
15	Front bumper fog lamp garnish LH <i>Sn X</i>	1			
16	Front bumper sponge <i>Sn X</i>	1			
17	Front bumper reinforcement <i>R X</i>	1			
18	Headlamp LH <i>?</i>	1			
19	Headlamp control unit LH <i>?</i>	1			
20	Headlamp LED LH <i>?</i>	1			
21	Headlamp lower bracket LH <i>?</i>	1			
22	Front fender LH <i>R X</i>	1			
23	Front fender shield front section LH <i>D.1 ✓</i>	1			
24	Front fender shield rear section LH <i>Sn X</i>	1			
25	Front fender shield clips <i>ne -</i>	12			
26	Front wheel rim LH <i>Det ✓</i>	1			
27	Front absorber LH <i>Sn X</i>	1			
28	Front absorber mounting LH <i>Sn X</i>	1			
29	Front absorber stopper LH <i>Sn X</i>	1			
30	Front lower arm LH <i>Sn X</i>	1			
31	Front upper arm LH <i>Sn X</i>	1			
32	Front stabiliser link LH <i>Sn X</i>	1			
33	Front tie rod LH <i>Sn X</i>	1			
34	Front tie rod end LH <i>Sn X</i>	1			

35	Front knuckle arm LH	<i>sn x</i>	1
36	Front knuckle arm bearing LH	<i>mx</i>	1

Sub-Total:	-
Less: 10% discount	-
Total Parts after 10% discount:	-

Special Nett Items

1	Anti-rust coating	2	80.00	<i>nn</i>	160.00	<i>x</i>
2	Front tyre LH	1	450.00	<i>sn</i>	450.00	<i>x</i>
					610.00	

Total Parts: 610.00

Labour Charges For LH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	900.00	<i>500</i>
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	900.00	<i>800</i>
3	Provide skill labour to disconnect and check electrical wiring	80.00	<i>20</i>
4	Provide skill labour to remove and replace/refit front LH undercarriage	250.00	<i>x</i>
5	Provide skill labour to check and re-adjust wheel alignment	80.00	<i>60</i>
6	Provide skill labour to remove and replace bumper sensors	80.00	<i>60</i>
7	Provide skill labour to remove, refit, balancing wheel rim and install tyre	80.00	<i>20</i>
Total Labour:		2,370.00	
Total Parts & Labour:		2,980.00	
GST 7%		208.60	
Grand Total:		3,188.60	

Estimate Repair Duration 08 days

ACCIDENT VEHICLE OF : **SDM828M**

Page : 2 of 2

5 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : *Kenneth*
 Company : *LKK*
 Date : *6/7/18*
 Time : *10:35am*
 Contact No : *9681 0663*
 Email : _____

Date: _____

Signature: _____

Acknowledged by Repairer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company