

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date : 28/06/2018
Vehicle No : SJA902Z
Veh Make/Model : Toyota Vios E Auto
YOM : 2007
Chassis No : MR053HY9305030314
Date of Accident : 27/06/2018

Not Notified
6/1/18
Resurvey After Repair
3 days

No	Qty	Description	Amount \$
List Items:-			
1	1	Bootlid	\$ 627.50
2	1	Bootlid logo	\$ 50.70
3	1	Bootlid "VIOS" emblem	\$ 57.50
4	1	Bootlid outer garnish	\$ 233.60
5	1	Bootlid wetherstrip	\$ 188.20
6	1	Bootlid inner lock	\$ 199.01
7	1	Rear bumper	\$ 470.10
8	2	Rear bumper side retainer	\$ 366.18
9	10	Rear bumper clip	\$ 50.00
10	1	Rear bumper reflector - LH	\$ 74.62
11	1	Rear bumper reflector - RH	\$ 74.62
12	1	End panel	\$ 517.51
13	1	End panel top garnish	\$ 182.10
14	6	End panel top garnish clip	\$ 30.00
Total - List Item			\$ 3,121.64
Less 25%			\$ 780.41
Total			\$ 2,341.23
Special Nett Items:-			
1	1	Front number plate with holder	\$ 55.00
2	1 Set	Rear reverse sensor	\$ 380.00
Total - SN Item			\$ 435.00
Balance b/f			\$ 2,776.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date : 28/06/2018
Vehicle No : SJA902Z
Veh Make/Model : Toyota Vios E Auto
YOM : 2007
Chassis No : MR053HY9305030314
Date of Accident : 27/06/2018

No	Qty	Description	Amount \$
		Balance c/f	\$ 2,776.23
		<u>Labour Charges:-</u>	
1		Spray painting on all affected area.	\$ 900.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 900.00
3		To apply anti rust treatment.	\$ 100.00
4		To check wiring system & light.	\$ 80.00
5		To remove and replace reverse sensor.	\$ 120.00
6		To remove and replace/reinstall bootlid attachment and test water leaking.	\$ 100.00
		Total - L/C	\$ 2,200.00
Sub-Total			\$ 4,976.23
7% GST			\$ 348.34
Total			\$ 5,324.57

3601
2501
X
156
501
X