

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800195
Date: 29 Jun 2018
Veh Reg No: SKH5343E
Make/Model: VOLKSWAGEN PASSAT 1.4 TSI
Chasis No: WVVZZZ3CZDE066351
Reg. Date: 19/12/2012
Your Ref No: SKP4970J

Claim Type: Third Party
Accident Date: 27/06/2018
TP Veh Reg No: SKP4970J

Vic

Estimate Repair Cost to Vehicle No :SKH5343E

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR BUMPER <i>{ Distorted.</i>	2,852.15 <i>1699.20</i>	
2	1 PC REAR LOWER BUMPER	880.12 <i>360</i>	
3	1 PC REAR BUMPER REINFORCEMENT <i>Bent</i>	768.15 ✓	
4	2 PCS REAR BUMPER BRACKET <i>not nec</i>	360.30 ✗	
5	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	390.42 ✓	
6	1 PC REAR BUMPER CHROME RH <i>{ cracked.</i>	414.20 <i>233.60</i>	
7	1 PC REAR BUMPER CHROME LH	414.20 <i>233.60</i>	
8	1 PC REAR BUMPER TOWING COVER <i>{ not new</i>	82.60 ✗	
9	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	150.40 ✗	
10	6 PCS REVERSE SENSORS <i>3 pieces damaged</i>	1,320.60 <i>660.30</i>	
11	1 PC REAR BUMPER SIDE HEAT SHIELD LH <i>torn</i>	126.70 ✓	
12	1 PC BOOT LID <i>Buckled.</i>	3,815.00 <i>1883.60</i>	
13	1 PC BOOTLID "PASSAT" EMBLEM <i>new</i>	101.60 ✓	
14	1 PC BOOT LID CHROME <i>ut</i>	280.15 ✓	
15	1 PC BOOT LID RUBBER <i>new</i>	288.15 ✓	
16	1 PC BOOT LID LOCK <i>Damaged</i>	380.00 ✓	
17	1 PC BOOT LID LOCK CHECKER <i>not new</i>	110.20 ✗	
18	1 PC BOOT LID LAMP LH <i>{ not new</i>	980.00 ✗	
19	1 PC BOOT LID LAMP RH	980.00 ✗	
20	1 PC REAR PANEL <i>Distorted</i>	1,050.00 ✓	
21	1 PC REAR PANEL TRIM <i>cracked</i>	236.70 ✓	
22	1 PC SPARE TYRE PANEL <i>torn</i>	880.00 ✓	
23	1 PC REAR SPARE TYRE PANEL LH SPONGE <i>torn</i>	486.70 ✓	
24	1 PC TAIL LAMP LH <i>{ cracked.</i>	980.12 <i>730.10</i>	
25	1 PC TAIL LAMP - RH	980.12 <i>730.10</i>	
26	1 PC SPARE TYRE HEAT SHIELD <i>torn</i>	196.70 ✓	
27	1 PC EXHAUST PIPE <i>Bent</i>	2,838.00 <i>1107.60</i>	
28	1 PC REAR EXHAUST HEAT COVER <i>torn</i>	341.80 ✓	
29	2 PCS EXHAUST PIPE MOUNTING <i>torn</i>	134.20 ✓	

Rear Bumper Top Beam *cracked*

216.90 ✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800195
Date: 29 Jun 2018
Veh Reg No: SKH5343E
Make/Model: VOLKSWAGEN PASSAT 1.4 TSI
Chasis No: WVWZZZ3CZDE066351
Reg. Date: 19/12/2012
Your Ref No: SKP4970J

Claim Type: Third Party
Accident Date: 27/06/2018
TP Veh Reg No: SKP4970J

Estimate Repair Cost to Vehicle No :SKH5343E

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC EXHAUST PIPE MOUNTING BRACKET <i>Not New</i>	155.80 <i>x</i>	
31	1 PC CENTRE EXHAUST PIPE <i>Not New</i>	1,336.70 <i>x</i>	
32	1 PC REAR LH FENDER COWLING <i>Deformed</i>	299.70 <i>✓</i>	
33	1 PC CENTRE EXHAUST PIPE HEAT SHIELD <i>2 Not New</i>	380.10 <i>x</i>	
34	1 PC FRONT EXHAUST CONVERTER	2,997.60 <i>x</i>	
35	1 PC FRONT EXHAUST CONVERTER BRACKET	166.80 <i>x</i>	
	<i>13816.47</i>	28,155.98	
	<i>113,125.64</i>	Less 5%	1,407.80
			26,748.20
	Special Net		
36	1 SET REAR BUMPER CLIPS <i>New</i>	40.00 <i>-</i>	
37	1 PC REAR NUMBER PLATE <i>Bent</i>	50.00 <i>30</i>	
38	1 PC REAR NUMBER PLATE BASE <i>crushed</i>	50.00 <i>30</i>	
39	1 SET BOOTLID TRIM CLIPS <i>2 Not New</i>	40.00 <i>x</i>	
40	1 SET REAR FENDER TRIM CLIPS <i>2 Not New</i>	40.00 <i>x</i>	
	<i>2 set Tyre w/ Sealant</i>	220.00	220.00
41	1 TO CHECK WIRING	100.00 <i>30</i>	
42	1 TOWING	120.00 <i>✓</i>	
43	1 TO REMOVE AND REFIT REVERSE SENSOR	100.00 <i>60</i>	
44	1 TO REMOVE AND REFIX REAR & CENTRE EXHAUST PIPE	250.00 <i>160</i>	
45	1 TO SPRAY UNDERSEAL	150.00 <i>60</i>	
46	1 (REAR) TO SPRAY PAINTING	1,200.00 <i>1800</i>	
47	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00 <i>1400</i>	
	<i>To transfer bootlid fittings. 200 80</i>	3,520.00	3,520.00
	<i>To remove upholstery. 150 80</i>		
	<i>To perform diagnostic test 180 120</i>		

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 27/06/2018
TP Veh Reg No: SKP4970J

Estimate No: EST1800195
Date: 29 Jun 2018
Veh Reg No: SKH5343E
Make/Model: VOLKSWAGEN PASSAT
1.4 TSI
Chasis No: WVVZZZ3CZDE066351
Reg. Date: 19/12/2012
Your Ref No: SKP4970J

Estimate Repair Cost to Vehicle No :SKH5343E

Quantity	Description	List Price	Amount
		SS	SS
	Total		SS 30,488.20
	Add GST @ 7%		2,134.17
	Total Amount Payable		SS 32,622.37

TOTAL: SINGAPORE DOLLAR THIRTY TWO THOUSAND SIX HUNDRED TWENTY TWO AND CENTS THIRTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian King
+/- 29/06/18
18 Days

total: 16875.64
+/- 13.5K.

13.5K 18 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: