

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4361X
 Ref. No : TAX/06/18/2132
 Reg. Date : 09/04/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : SWEE GEOK CHING
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 27/06/2018 07:25:00 PM
 Accident Reported Date / Time : 28/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096759
 Special Instruction to ARC, if any :
 SLM7677R
 Prepared Date : 28/06/2018 10:56:23 AM



Satya Sai
 29/6/2018

3 days

- Lump Sum Repair
- Question mark item photo
- Photo ~~before~~ after paint

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKN36U005740883

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 756.00	0.00
Total Material Charges	: 2,030.92	2,030.92
Other Charges	: 676.88	0.00
TOTAL	: 4,477.80	0.00
Lum Sum Total	: 4,500.00	0.00
No. of Repair Days	: 6.00	0.00 3 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 29/06/2018 10:54:29 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/06/2018 10:53:04 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 6/29/2018 10:54:24 AM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY REAR DOOR LH	378.00	0.00 200
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO TRANSFER DOOR MECHANISM	240.00	0.00 100
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
TO WASH AND VACUUM	60.00	0.00 ✗
Total Other Costs	676.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
67002-47070		6505529	DOOR FRT/LH R	1	894.40	25.00	670.80	Replace	Replace	No
			STICKER DECAL SMRT (DOOR) ✓NEC	1	60.00	0.00	60.00	Replace	Replace	No
69210-74030			DOOR OUTER HANDLE FRT/LH ✓INT	1	370.80	25.00	278.10	Replace	Replace	No
69206-47050			DOOR INNER HANDLE FRT/LH ?	1	84.70	25.00	63.52	Replace	Replace	No
69040-47070			DOOR LOCK FRT/LH ?	1	575.80	25.00	431.85	Replace	Replace	No
69410-33010			DOOR LOCK STRIKER ?	1	40.50	25.00	30.37	Replace	Replace	No
67004-47080		6505487	DOOR RR/LH R	1	954.50	25.00	715.87	Replace	Replace	No
			PIXEL STICKER ✓	1	60.00	0.00	60.00	Replace	Replace	No
68760-20122			HINGE UPPER LHR, DOOR ✓	1	81.70	25.00	61.27	Replace	Replace	No
68780-52031			HINGE LOWER LHR, DOOR ✓	1	72.20	25.00	54.15	Replace	Replace	No
68630-47031			CHECK ASSY, RR DOOR, ✓	1	150.30	25.00	112.72	Replace	Replace	No
TOTAL MATERIALS								2,538.68	2,538.65	
TOTAL MATERIALS(Discounted)							2,030.92	2,030.92		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									