

ASS. REC. BY:

REF: CS/FCL18011956/UTbn2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): W3 Sitthara of FCL Date/Time: 13/07/2018 337pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKG 9061Y Insured: SHA 8162M

at Workshop m/s Fasteleh Auto Tel: 6746 5405

of Blok 1 Kaki Bukit Ave 6 #01-46

Policy No: _____ Claim No: D180D5114MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29/06/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>SKG 9061Y - x</u>
	<u>SHA 8162M - CS/FCL18003382 / Ggd3</u> <u>D.O.A. 16/02/2018</u>
<u>16/7/18</u>	<u>@ 2.03pm - revert pending estimate</u>

(08/11/13) wef

ASS REC BY: Marcus

REF:

Fei/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKG 9061Y

at Workshop m/s ff

of SHIA 8162M

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 54k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS LIA 46368

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

have 6.4 Yrs. 4ml. dep 9800 m47632

20/7/18 confirmed L/S \$7500 with Alin. Cred 20933 (73%)

RECEIVED 24 JUL 2018

Date/Time, File Pass to? ☐ : Prel. Report

1) 24/7 Typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Report Format: TP

Lump Sum / I.B.I: (\$ 7500/-)

Days Of Repair: 9

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + BS, SI

Photos: 580

Others: 050

TOTAL

18x15=270

170+270

50

139

629

Veh No: SKG 9061Y Yr Regn: 10 / 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Peugeot 5008 c.c. 1598

Colour: Grey A/C: insured / Std / Nil / NA

Sp. Reading: 74056 T/Radio: insured / Std / Nil / NA

Eng/No: _____

C/No: VF30E5FVACS136483

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 0 mm

D.O.A. 29/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

MOTOR SURVEY ASSIGNMENT

Date	29-06-2018	Our Ref No. D18005114MFSH
Accident Date	29-06-2018	Claim Type. Third Party
Insured Vehicle	SHA8162M	Third Party Vehicle. SKG9061Y
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 16 July 2018 2:03 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005114MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKG 9061Y on 2/7/2018
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 3 July 2018 4:20 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005114MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 3 July, 2018 3:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005114MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CAR NUMBER PLATES FOR SALE!

Find the unique car number plate that represents you!

Click here to start the hunt!

Peugeot 5008

Price Range

Depreciation

2012

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Lake View Credit Pte Ltd » Peugeot 5008 1.6A Turbo Luxury

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

CL LEASING

YOUR PREFERRED CAR LEASING OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

Trim your debts and enjoy interest rate from as low as 4.70% p.a. (EIR: 8.48% p.a.)

Maybank Debt Consolidation Plan

FIND OUT MORE

Terms and Conditions apply.

Compare

Peugeot 5008 1.6A Turbo Luxury

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Lake View Credit Pte Ltd

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price

\$50,800

Depreciation

\$9,430 /yr

View models with similar depreciation

Reg Date

06-Aug-2012

(4yrs 1mth 3days COE left)

Manufactured

2012

Mileage

50,475 km (8.5k /yr)

Transmission

Auto

Engine Cap

1,598 cc

Road Tax

\$742 /yr

Power

115.0 kW (154 bhp)

View specs of the Peugeot 5008 (2010-2014)

Curb Weight

1,540 kg

Features

1.6L Turbo-Charged Engine, 154 BHP, 6 Speed Automatic With Tiptronic, Auto Headlights And Rain Sensors, SRS Airbags, ABS, Rear Aircon, Cruise Control.

Accessories

16" Alloy Wheels, Brown Leather Upholstery, Reverse Sensors, Built In Audio System With GPS, Retractable Side Mirrors, Fog Lights, Panoramic Roof.

Description

Fuel Efficient 1.6L MPV Built With Advanced Features For A Safe And Enjoyable Ride. Well Kept By Fussy Owner. Low Mileage Done 8600km Annually. 100% Accident Free. In House Loan Available. Call Now!

COE

\$59,421

OMV

\$24,312

ARF

\$24,312

Dereg Value

\$41,357 as of today (change)

No. of Owners

2

Type of Veh

MPV

Category

PARF Car, Premium Ad Car, Low Mileage Car

Availability

Available

Add to Shortlist

Add to Compare

Add a Note

Location Map

Price Analysis

Seller Information

Company

Lake View Credit Pte Ltd

• dealer's pricelist

• 150 vehs sold | 55 vehs available

Address

61 Ubi Avenue 2 #03-08/09

Search cars nearby this location

Location

Automobile Megamart

Website

www.lakeviewcredit.com.sg

Office No

67499895

Contact Person(s)

Daniel 96896097

John 90478223

Chun Kit 81338870

http://www.sgcarmart.com/used_cars/info.php?ID=743134&DL=1001

02-Jul-18

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0095J

Vehicle Details

Vehicle No.: SKG9061Y
Vehicle to be Exported: No
Intended De-registration Date: 09 Jul 2018
Vehicle Make: PEUGEOT
Vehicle Model: 5008 1.6 TURBO LUXURY
Primary Colour: Grey
Manufacturing Year: 2012
Engine No.: 10FJBW1538828
Chassis No.: VF30E5FVACS136483
Maximum Power Output: 115.0 kW (154 bhp)
Open Market Value: \$24,110.00
Original Registration Date: 19 Oct 2012
First Registration Date: 19 Oct 2012
Transfer Count: 0
Actual ARF Paid: \$24,110.00 / lost

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Oct 2022
PARF Rebate Amount: \$16,877.00

Intended COE Rebate Details

COE Expiry Date: 18 Oct 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$69,000.00
COE Rebate Amount: \$29,491.00
Total Rebate Amount: \$46,368.00

The information contained herein is correct as at 02 Jul 2018

OK

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES)

PASSENGER

and all Tractors the weight of
not exceed 2500 kilograms

20 JUN 2012

Licence No: S7470095J

NP 428A



NRIC No: S7470095J



Date of issue

30-05-2012

Address

APT BLK 1G CANTONMENT ROAD
#24-83
SINGAPORE 085701

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S7470095J

Name

LION NAWAWI

Birth Date: 15 May 1974

Issue Date: 22 Nov 2003



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7470095J



Name

LION NAWAWI



Race

CHINESE

Date of birth

15-05-1974

Country of birth

INDONESIA

Sex

M

S7470095J

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46,48,50 Autobay

SINGAPORE 417883

VEHICLE NO:SKG 9061Y

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Allowed
1/5 * 7500/-
2/7/18
gdy.

QTY	PARTICULAR	AMOUNT
1 PCS	TAILGATE 1950	Bodysid \$2,120.00
1 PCS	TAILGATE '5008' EMBLEM	ren \$100.00
1 PCS	TAILGATE 'PEUGEOT' EMBLEM	ren \$108.00
1 PCS	TAILGATE OUTER GARNISH	11 \$420.00 X
1 PCS	TAILGATE INNER LOCK 245	Tw/ym \$395.00
1 PCS	TAILGATE INNER TRIM BOARD 650	Re/cu \$688.00
1 PCS	TAILGATE WEATHERSTRIP 299	To/in \$325.00
1 PCS	TAILGATE WINDSCREEN INNER SEAL	ren \$52.00
1 PCS	REAR BUMPER 1280	Dis \$1,880.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$85.00	11 \$170.00 X
1 SET	REAR BUMPER CLIPS	ren \$50.00
1 PCS	REAR BUMPER REINFORCEMENT 455	Sub \$650.00
2 PCS	REAR BUMPER REINFORCEMENT BRACKETS @\$150.00	NS \$300.00 X
2 PCS	REAR BUMPER TOWING COVER	R \$32.00 X
4 PCS	REAR BUMPER PDC SENSORS @\$180.00 150 x 3 = 450	Shut \$720.00 3pcs
2 PCS	REAR BUMPER REVERSE LAMPS @\$185.00 165	o/s, Brio \$370.00 1pc
1 PCS	REAR END PANEL OUTER	S. of 500 \$1,100.00
1 PCS	REAR END PANEL TOP TRIM	twi \$288.00
2 PCS	TAILLAMPS @\$605.00	11 \$1,210.00 X
2 PCS	REAR FENDER INNER TRIM BOARDS @\$385.00	11 \$770.00 X
1 PCS	REAR EXHAUST MUFFLER 890	0/324 \$1,205.00
2 PCS	REAR EXHAUST MUFFLER MOUNTING @\$30.00	ren \$60.00
1 PCS	REAR EXHAUST HEAT SHIELD	n \$115.00 X
1 PCS	REAR FLOOR PANEL	n \$1,485.00 X
1 PCS	FRONT BUMPER 1250	0/101n \$1,650.00
2 PCS	FRONT BUMPER SIDE RETAINERS @\$85.00	11 \$170.00 X
1 SET	FRONT BUMPER CLIPS	ren \$50.00
1 PCS	FRONT BUMPER LOWER GRILLE 305	ren \$320.00
1 PCS	FRONT BUMPER REINFORCEMENT 488	Sub \$650.00
1 PCS	FRONT BUMPER REINFORCEMENT PROTECTOR 145	Dis \$210.00
1 PCS	FRONT GRILLE 415	con \$520.00
2 PCS	HEADLAMPS @\$950.00 825	o/s, con \$1,900.00 1pc
1 PCS	FRONT SUPPORT PANEL	Sub/con \$690.00
1 PCS	AIR CON CONDENSER	11 \$1,250.00 X

107.

\$22,023.00

	S.NETT		
1 PCS	REAR WINDSCREEN SEALANT	<i>ru</i>	\$50.00 40
1 PCS	REAR LICENCE PLATE W/HOLDER	<i>But</i>	\$50.00 40
1 PCS	FRONT LICENCE PLATE W/HOLDER	<i>But</i>	\$50.00 40
LABOUR CHARGES:			
	TO CHECK WIRING		\$80.00 30
	TO DISMENTLE & REPLACING PDC SENSOR		\$80.00 50
	TO DISMENTLE & REFIX REAR WINDSCREEN		\$150.00 120
	TO DISMENTLE & REFIX REAR EXHAUST		\$100.00 60
	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTREY		\$150.00 80
	TO DISMENTLE & REFIX TAILGATE MECHANISM		\$100.00 60
	TO REFILL AIR CON GAS		\$150.00 100
	TO SPRAY RUST PROOFING		\$150.00 80
	LABOUR FOR PANEL BEATING,CUT,WELD STRAIGHTENED		\$2,800.00 1300
	& REPLACING PARTS		
	TO PUTTY & SPRAY PAINTING		\$2,500.00 1600
TOTAL			\$28,433.00

3600

P-12310
102
11079
14679
11743



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011956/Utbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8162M	Veh. Inspected	SKG 9061Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005114MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	03/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	PEUGEOT 5008 (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	VF30E5FVACS136483	Colour	GREY	
Odometer	74056	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R16	MICHELIN	6 mm	
L/H Front Tyre	215/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	215/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	215/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/06/2018	Inspection Date	03/07/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 9061Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BADLY DENTED	2,120.00	1,950.00
1	TAILGATE "5008" EMBLEM	NECESSARY	100.00	100.00
1	TAILGATE "PEUGEOT" EMBLEM	NECESSARY	108.00	108.00
1	TAILGATE OUTER GARNISH	NOT NECESSARY	420.00	-
1	TAILGATE INNER LOCK	TWISTED / JAMMED	395.00	245.00
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	688.00	650.00
1	TAILGATE WEATHERSTRIP	TORN	325.00	299.00
1	TAILGATE WINDSCREEN INNER SEAL	NECESSARY	52.00	52.00
1	REAR BUMPER	DISTORTED	1,880.00	1,280.00
2	REAR BUMPER SIDE RETAINERS @\$85.00	NOT NECESSARY	170.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER REINFORCEMENT	BENT	650.00	455.00
2	REAR BUMPER REINFORCEMENT BRACKETS @\$150.00	NO SUCH PARTS	300.00	-
2	REAR BUMPER TOWING COVER	TO REPAIR SEE LABOUR	32.00	-
4	REAR BUMPER PDC SENSORS @\$180.00	SHORTED (3 PCS ONLY)	720.00	450.00
2	REAR BUMPER REVERSE LAMPS @\$185.00	O/S BROKEN	370.00	165.00
1	REAR END PANEL OUTER	BADLY DENTED	1,100.00	1,100.00
1	REAR END PANEL TOP TRIM	TWISTED	288.00	288.00
2	TAILLAMPS @\$605.00	NOT NECESSARY	1,210.00	-
2	REAR FENDER INNER TRIM BOARDS @\$385.00	NOT NECESSARY	770.00	-
1	REAR EXHAUST MUFFLER	DENTED / BENT	1,205.00	890.00
2	REAR EXHAUST MUFFLER MOUNTING @\$30.00	NECESSARY	60.00	60.00
1	REAR EXHAUST HEAT SHIELD	TO REPAIR SEE LABOUR	115.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,485.00	-
1	FRONT BUMPER	DENTED / TORN	1,650.00	1,250.00
2	FRONT BUMPER SIDE RETAINERS @\$85.00	NOT NECESSARY	170.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00

Report Ref No. CS/FCI18011956/Utbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOWER GRILLE	TORN	320.00	305.00
1	FRONT BUMPER REINFORCEMENT	BENT	650.00	488.00
1	FRONT BUMPER REINFORCEMENT PROTECTOR	DISTORTED	210.00	145.00
1	FRONT GRILLE	CRACKED	520.00	415.00
2	HEADLAMPS @\$950.00	O/S CRACKED	1,900.00	825.00
1	FRONT SUPPORT PANEL	BENT / CRACKED	690.00	690.00
1	AIR CON CONDENSER	NOT NECESSARY	1,250.00	-
	LESS 10% DISCOUNT		-	-1,231.00
			22,023.00	11,079.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
			150.00	120.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMENTLE & REPLACING PDC SENSOR.		80.00	50.00
	TO DISMENTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMENTLE & REFIX REAR EXHAUST.		100.00	60.00
	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMENTLE & REFIX TAILGATE MECHANISM.		100.00	60.00
	TO REFILL AIR CON GAS.		150.00	100.00
	TO SPRAY RUST PROOFING.		150.00	80.00
	LABOUR FOR PANEL BEATING,CUT,WELD STRAIGHTENED & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER TOWING COVER,REAR EXHAUST HEAT SHIELD AND REAR FLOOR PANEL.		2,800.00	1,300.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,600.00
			6,260.00	3,480.00
	GRAND TOTAL		28,433.00	14,679.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,500.00



Report Ref No. CS/FCI18011956/Utbn2

A handwritten signature in black ink, appearing to read 'Chua' followed by a stylized surname.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.