

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0745/2018/PH
Date : 2-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SMA 1125 H

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr.Tan Wei Peng
Address : 11 Holland Link
#01-13
Singapore 275764
Telephone : HP +65 97352928
Type of Claim : Third Party Claims
Policy No. : 2100286258-06
Vehicle No : **SKE 8861 Y**
Model Code : Audi S3 SB 2.0 TFSI QU
Model / Year : Jan-12
Engine No : CDL 068642
Chassis No : WAUZZZ8P4CA084130
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Jul-18
Place of Accident : Star Vista (B2 Parking Area)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKE 8861 Y .

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper. Re-organise front crash management components. Reinstall all parts removed.	\$ 900.00 500
3	To respray front bumper .	\$ 800.00 550
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>2,252.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 8861 Y .

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	BUMPER COVER <i>Deland</i>	\$ 2,205.00	✓
2	FIXING PARTS FOR BUMPER <i>new</i>	\$ 155.00	✗
3	SPOILER PLATINUM GREY	\$ 333.00	✗
4	GUIDE SECTION - RH <i>new</i>	\$ 33.00	✗
5	FOAM FILLER PIECE <i>new</i>	\$ 111.00	✗
6	BUMPER CARRIER	\$ 587.00	✗
7	AIR GUIDE GRILLE - RH <i>new</i>	\$ 287.00	✗
8	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		\$ 4,011.00	
TOTAL LABOUR CHARGES		\$2,252.00	
GRAND TOTAL		\$6,263.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 04/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant